

**CF6-80C2 ENGINE LIFE LIMITED PARTS STATUS REPORT**

<b>ENGINE S/N :</b>		<b>TT : 63384.28</b>		<b>TC : 11537</b>			
<b>NOMENCALATURE</b>	<b>P/N</b>	<b>S/N</b>	<b>MAX/H</b>	<b>TT</b>	<b>MAX/C</b>	<b>TC</b>	<b>RC</b>
<b>FAN ROTOR ASSEMBLY</b>		P/N: 9265M21G03		TT : 67796.87		TC : 12154	
		S/N:		TSO : 20652.20		CSO : 4023	
DISK - STAGE 1 FAN	1703M77P03		NIL	67796.87	20000	12154	7846
SPOOL - STAGE 2-5 FAN	1856M71P06		NIL	67796.87	20000	12154	7846
SHAFT - FAN FORWARD	1855M57G01		NIL	67796.87	20000	12154	7846
<b>FAN MID SHAFT ASSEMBLY</b>		P/N: 80CFANFWDMI		TT : 67796.87		TC : 12154	
		S/N:		TSO : 67796.87		CSO : 12154	
SHAFT - FAN MIDDLE	1862M48P01		NIL	67796.87	20000	12154	7846
<b>HPC ROTOR ASSEMBLY</b>		P/N: 1457M53G03		TT : 67796.87		TC : 12154	
		S/N:		TSO : 20652.20		CSO : 4023	
DISK - SATGE 1 HPCR	1644M21P04		NIL	67796.87	20000	12154	7846
DISK - STAGE 2 HPCR	9380M27P08		NIL	67796.87	20000	12154	7846
SPOOL - STG 3-9 HPCR	1856M15G02		NIL	47480.33	20000	8329	11671
SEAL - ROTATING-CDP	1347M31P01		NIL	67796.87	20000	12154	7846
SPOOL SHAFT - STG 10 ~ 14 HPC ROTOR	1703M49G04		NIL	47480.33	20000	8329	11671
<b>HIGH PRESSURE TURBINE ROTOR ASSEMBLY</b>		P/N: 9255M20G04		TT : 63384.28		TC : 11537	
		S/N:		TSO : 20652.20		CSO : 4023	
DISK - HPT STAGE 1 ROTOR	1531M84G12		NIL	47407.07	15000	8486	6514
SPACER IMPELLER-HPT	1539M12P02		NIL	67796.87	15000	12154	2846
DISK - HPT STAGE 2 ROTOR	9362M43P09		NIL	47480.33	15000	8329	6671
VANE - DIFFUSER RING	9290M28P15		NIL	63384.28	15000	11537	3463
<b>LPT ROTOR ASSEMBLY</b>		P/N: 80CLPTRTR		TT : 67796.87		TC : 12154	
		S/N:		TSO : 20652.20		CSO : 4023	
DISK - LPT STAGE 1 ROTOR	1863M21P01		NIL	67796.87	20000	12154	7846
DISK - LPT STAGE 2 ROTOR	1863M22P01		NIL	67796.87	20000	12154	7846
DISK - LPT STAGE 3 ROTOR	1863M23P01		NIL	67796.87	20000	12154	7846
DISK - LPT STAGE 4 ROTOR	1863M24P01		NIL	67796.87	20000	12154	7846
DISK - LPT STAGE 5 ROTOR	1863M25P01		NIL	67796.87	20000	12154	7846
SHAFT - TORQUE CONE	9382M59P10		NIL	67796.87	20000	12154	7846

"\*" This item with the serial number was installed with unacceptable flow parking.