MARKETING SUMMARY / September 2025

Preliminary Engine Data										
Engine Model:	CFM56-5B6/P									
Engine Total Time:	41,240 Hours									
Engine Total Cycles:	32,661 Cycles									
Since Repair:	0.0 Hrs. / 0 Cyc.									
Limiter at 5B6/P:	6,491 CR									
EGT Margin:	81.9°C @ 23.5K									
	72.6°C @ 27K									
	72.6°C @ 27K									
	39.2°C @ 32K									
Current Status:	Fresh out of Shop Visit									
Available on:	Immediate Delivery									
List Price:	\$7,950,000									
Refundable Deposit:	20% of purchase price due 3 days after LOI									
	Signature									
Workmanship Warranty:	Engine comes with GEM's Workmanship									
	Warranty, whichever occurs									
first of:	18 months in operation									
	 24 months after delivery 									
	1,800 cycles in operation									
Terms:	All other terms and conditions will be defined in									
Terris.	the LOI									
Projected Engine Configuration:										
Shipping Stand:	Not included (Loaner available)									
QEC: Neutral QEC except for:	Hydraulic Pump, IDG, Starter, Anti-Ice Valve									
Records:	Full BTB									
Certification:	FAA/EASA Dual Release									
Delivered at:	USA, FL									

Workscope Summary:

Disassembly and Repair

The subject engine was repaired in accordance with the CFM56-5 Engine Shop Manual CFMI. TP. SM. 9 Rev. 81 dated March 15, 2025.

Fan Major Module (ATA 72-00-01)

The module was inspected per Task 72-00-00-800-110 Special Procedure 110 to make serviceable.

HPC Rotor Module (ATA 72-31)

The module was partially disassembled, cleaned, NDT, inspected and repaired as necessary to include the following:

- HPC Blades Stg. 1: Installed 38 each in Overhauled condition.
- HPC Blades Stg. 2: Installed 41 each in Overhauled condition and 12 each in repaired condition.
- HPC Blades Stg. 3: Installed 20 each in Overhauled condition and 40 each in repaired condition.
- HPC Blades Stg. 4: Installed 1 each in New condition and 67 each in Overhauled condition.
- HPC Blades Stg. 5: Installed 50 each in Overhauled condition and 25 each inspected to make serviceable.
- HPC Blades Stg. 6: Installed 29 each in Overhauled condition and 53 each inspected to make serviceable.
- HPC Blades Stg. 7: Installed 82 each in Overhauled condition.
- HPC Blades Stg. 8: Installed 4 in New Condition and 76 each in Overhauled condition.
- HPC Blades Stg. 9: Installed 2 each in New condition and 74 each in Overhauled condition.
- HPC Rotor was reassembled, match ground to the Stator Cases, and dynamically balanced.

HPC Forward Assy (ATA 72-32)

HPC Forward Stator Case Assembly was partially disassembled, cleaned, NDT, inspected and repaired as necessary to include the following:

- HPC Stator Vane (IGV): Inspected 42 each to make serviceable.
- HPC Stator Variable Vanes Stg. 1: Installed 9 each in Overhauled condition,23 each inspected and 50 each in repaired condition.
- HPC Stator Variable Vanes Stg. 2: Inspected 84 each to make serviceable. 84 each
- HPC Stator Variable Vanes Stg. 3: Inspected 72 each to make serviceable.
- HPC Stator Seal Stg. 1: Installed 4 each in Overhauled condition.
- HPC Stator Seal Stg. 2: Installed 4 each in Overhauled condition.
- HPC Stator Seal Stg. 3: Installed 4 each in Overhauled condition.
- HPC Stator Shroud IGV: Inspected 2 each to make serviceable.
- HPC Stator Shrouds Stg. 1: Installed 12 each in Overhauled condition.
- HPC Stator Shroud Stg. 2: Installed 12 each in Overhauled condition
- HPC Stator Shroud Stg. 3: Installed 2 each in New condition and 8 each in Overhauled condition.
- HPC Forward Stator Case Assembly was match ground to HPC Rotor.

HPC Rear Stator Case (ATA 72-33)

HPC Rear Stator Case Assembly was cleaned inspected and repaired as necessary to make serviceable.

Combustion Core Major Module (ATA 72-41 and 72-42)

The Combustion Case Assembly was partially disassembled, cleaned, inspected per Special procedure 110 task 72-00-00-800-110 and repaired

as necessary to include the

following:

- Fuel Nozzles: Installed 7 each in Overhauled condition and 13 each inspected and tested.
- HPT Inner Stationary Seal: Installed in Overhauled condition.
- Combustion Chamber Assembly: Inspected to make serviceable.

HPT Turbine Nozzle (ATA 72-51)

The HPT Turbine Nozzle assembly was partially disassembled, cleaned, inspected per Special procedure 110 task 72-00-00-800-110 and repaired

as necessary to include the

following:

HPT AFT Outer Stationary Seal: Inspected to make serviceable.

HPT Rotor Module (ATA 72-52)

The HPT Rotor was cleaned, inspected per Special procedure 110 task 72-00-00-800-110 and repaired as necessary to include the following:

HPT Rotor Assembly was tip ground and dynamically balanced

HPT Shroud and LPT Nozzle Assembly (ATA 72-53)

The HPT Shroud and LPT Nozzle Assembly was partially disassembled, cleaned, inspected per Special procedure 110 task 72-00-00-800-110 and repaired

as necessary to include the following:

- HPT Stator Shrouds: Installed 42 each in Overhauled condition.
- The unit was assembled and match ground the shrouds to the HPT Rotor.

LPT Major Module (ATA 72-00-03)

LPT Major Module was partially disassembled, cleaned, inspected per Special procedure 110 task 72-00-00-800-110 and repaired as necessary to

include the following:

- LPT Disk Stg. 4: Installed in Overhauled condition.
- LPT Blades Stg. 4: Installed 134 each in Overhauled condition.
- LPT Shaft Module: Repaired to make serviceable.
- No. 4 Bearing: Installed in Overhauled condition.
- No. 5 Bearing: Inspected to make serviceable.
- LPT Rear Frame Assy: Repaired to make serviceable
- The LPT Module was reassembled and dynamically balanced.

Transfer Gearbox (ATA 72-62)

Transfer Gearbox Module: Inspected as exposed per Task 72-00-00-800-110 Special Procedure 110.

Accessory Gearbox (ATA 72-63)

The Accessory Gearbox Assembly: Inspected as exposed per Task 72-00-00-800-110 Special Procedure 110.

Accessories

Actuator Variable Stator: Overhauled (2 each)

Fuel Flow Transmitter: Overhauled.

LPT ACC Valve: Overhauled.

EGT Harness (4 each): Inspected and Tested.

EGT Coupling: Inspected and Tested.

EGT Coupling Upper: Inspected and Tested.

TC Wiring Harness: Overhauled.

Harness Wiring J12: Repaired and tested.

Igniter Plug: New (2 each)

The Following Airworthiness Directives / Service Bulletins were accomplished at this shop visit:

Airworthiness Directives:

- 2002-13-03 LPT Stg. 4 Disk
- 2006-26-01 Installed Filters
- 2009-18-01 TRF Inspection

Service Bulletins:

• 72-0620

ENGINE LIFE LIMITED COMPONENT RECORD

Γ			71						Г	Γ					Г	픘										Γ		1
CASE	REAR LPT FRAME	LPT SHAFT	ROTOR SUPPORT LPT	LPT DISK STG 4	LPT DISK STG 3	LPT DISK STG 2	LPT DISK STG 1	LPT MODULE		HPT REAR SHAFT	HPT DISK	HPT AIR SEAL	HPT FWD SHAFT	HPT MODULE		HPC REAR CDP AIR SEAL	HPC SPOOL STG 4-9	HPC DISK STG 3	HPC SPOOL STG 1-2	HPC FRONT SHAFT	HPC MODULE		SHAFT, FAN	BOOSTER SPOOL	FAN DISK STG 1	LPC MODULE		
338-117-455-0	#338-171-705-0	338-010-005-0	340-301-702-0	336-002-105-0	336-002-006-0	336-001-909-0	336-001-804-0			1864M90P04	1498M43P07	2116M20P02	2048M21P03			2116M25P01	2048M20G04	2116M23P01	1558M31G07	1386M56P03		The second secon	338-010-601-0	338-001-906-0	338-001-504-0		NUMBER	
DC883787	LA134548	PA979562	DK098816	PC069968	PC097030	PC094326	PC074628			TMTA6995	GWN0T8MM	TMT3T355	XAECJ746			GFF5HF9W	GWN0T9J9	XAECP670	GWN0T9R3	GWN0TA4T			DC902591	DC095150	BC408583		NUMBER	
41,240.48	41,240.48	17,582.48	17,562,48	17,562.48	17,562.48	17,562.48	17.562.48			17,582.48	17,562.48	17,582.48	17,562.48			17.582.48	17.562.48	17,562.48	17.562.48	17.562.48			33,296.56	32,159.56	41,243,58		TOTAL	
32,661	32,661	13,509	13.509	13,509	13,509	13,509	13,509			13,509	13,509	13,509	13,509			13,509	13,509	13,509	13,509	13,509			22,738	22,202	22,954		CYCLES	
1,829	1,829	1,829	1.829	1,829	1,829	1,829	1.829			1,829	1.829	1,829	1,829			1,829	1.829	1,829	1.829	1,829			1,829	1,829	1,829		583/P	
0	U	0	0	0	0	0	0			0	0	0	0			0	0	0	0	0		75	0	0	19,951		584/P	
0	0	0	0	0	0	0	0			0	0	0	0			0	0	0	0	0			19,733	19,199	0		585/P	CYCLES USED IN
30,832	30,832	11,680	11,680	11,680	11,680	11,680	11,680			11,680	11.680	11,680	11,680			11,680	11,680	11,680	11,680	11,680			1,174	1.174	1.174		586/P	SED IN
0	C	0	0	0	0	0	0			0	0	0	0			0	0	0	0	0			0	0	0		587/P	
N/L	33,524	25,000	25,000	25.000	25,000	25,000	25,000			20,000	20,000	20,000	20,000			20,000	20.000	20,000	20,000	20,000			30,000	30,000	30,000		SB3/P	
NA	4,700	11,491	11,491	11,491	11,491	11,491	11,491			6,491	6.491	6,491	6.491			6,491	6.491	6.491	6,491	6.491			7,284	7,798	7.046		SB3/P	
N/L	33,524	25,000	25.000	25,000	25,000	25,000	25,000			20,000	20.000	20,000	20,000			20,000	20,000	20,000	20,000	20,000			30,000	30,000	30.000		SB4/P	
N/A	4,700	11,491	11,491	11,491	11,491	11,491	11,491			6,491	6.491	6,491	6.491			6,491	6,491	6,491	6,491	6.491		00	7.264	7,798	7.046		SB4/P	
N/L	33,524	25,000	25.000	25,000	25,000	25,000	25.000			20,000	20,000	20,000	20,000			20,000	20,000	20,000	20.000	20,000			30,000	30,000	000,00		SBS/P	
N/A	4,/00	11,491	11,491	11,491	11,491	11,491	11,491		22	6,491	6.491	6,491	6.491			6,491	6,491	6,491	6,491	6.491			7,264	7.798	7.046		SBS/P	
NA	33,524	25,000	25.000	25,000	25,000	25,000	25,000		3.5	20,000	20,000	20,000	20,000			20,000	20,000	20,000	20,000	20,000			30,000	30,000	30,000		SB&IP	
NA	4,700	11,491	11,491	11,491	11,491	11,491	11,491			6,491	6.491	6,491	6,491			6,491	6.491	6,491	6.491	6.491			7,284	7,798	7.048		SBG/P	

The above data was obtained from engine records supplied by the previous owners, repair agencies and operators of the engine.
Rear LPT Frame inspected IAW AD 2009-18-01 per SB 72-0620 and has a re-inspection interval of 4,700 cycles.

Suendys Rodriguez - Records Analyst