

OWNER: LLC AVIASERVICE	OPERATOR: LLC AVIASERVICE
ADDRESS: 12409, AIRPORT, LAISHEVO DISTRICT RUSSIAN FEDERATION 420017	ADDRESS: 12409, AIRPORT, LAISHEVO DISTRICT RUSSIAN FEDERATION 420017
PHONE:	PHONE:
FAX:	FAX:
ANALYST: ALIX FOSSE	+33-1.55.93.47.78 (OFFICE)
EMAIL: ALIX.FOSSE@CAMPSYSTEMS.EU	+33 (0) 1.55.93.45.80 (OFFICE)
	WWW.CAMPSYSTEMS.COM

PROJECTED : 6 MOS. to 11-JUL-2021

AIRCRAFT	SERIAL/REGNO: 5613/RA-67228	MODEL: CL-604	MANUFACTURER: BOMBARDIER INCORPORATED		
DATES		LAST ACTUALS		PROJECTED	
CERTIFICATION DATE: 07-MAR-2005		4650:45 A/C HRS	as of 10-JAN-2021	4770:45	
INSERVICE DATE: 28-APR-2006		2986 AFL	as of 10-JAN-2021	3066	
		6973 APH	as of 10-JAN-2021	7113	
		0 APS	as of 03-DEC-2020	90	

APU	SERIAL/PART: P-820/3800050-5-1	MODEL: GTCP36-100(E) (604-CIMMS)	MANUFACTURER: HONEYWELL		
INSTALLED ON 07-MAR-2005		LAST ACTUALS		PROJECTED	
0 APU HRS		6973 APU HRS	as of 10-JAN-2021	7113	
0 APUS		0 APUS	as of 03-DEC-2020	90	

ENGINE NO. 1	SERIAL/PART: 950335/6089T11G01	MODEL: CF-34-3B (CIMMS)	MANUFACTURER: GENERAL ELECTRIC		
INSTALLED ON 07-MAR-2005		LAST ACTUALS		PROJECTED	
0 ENG. HRS	0 A/C HRS	4650:45 ENG. HRS	as of 10-JAN-2021	4770:45	
0 ENC		3002 ENC	as of 10-JAN-2021	3082	

ENGINE NO. 2	SERIAL/PART: 950336/6089T11G01	MODEL: CF-34-3B (CIMMS)	MANUFACTURER: GENERAL ELECTRIC		
INSTALLED ON 07-MAR-2005		LAST ACTUALS		PROJECTED	
0 ENG. HRS	0 A/C HRS	4650:45 ENG. HRS	as of 10-JAN-2021	4770:45	
0 ENC		3002 ENC	as of 10-JAN-2021	3082	

INSUFFICIENT ITEMS

Operator Review And Action Required

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

These tasks have insufficient information for calculating next due. Please provide the missing information (marked by ?) so that they can be setup properly. It is important to note that any task that has insufficient information, will not come due correctly unless the necessary information is provided by you.

TASK NO	TASK DESCRIPTION	EFFECTIVE DATE	UNIT	INTERVAL	COMPLIANCE	NEXT DUE	DISPOSITION
050014	APU - 400 HOUR CHECK		MOS HRS/MSC 400 APUS	+40/-40	12-DEC-2020 ?		
	REF: ENTER MISSING C/W HRS _____						
26-20-00-205	FUNCTIONAL TEST (WEIGHT CHECK) COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE		MOS HRS/MSC AFL	24 +1m/-1m	?		MRB
	REF: AMM 26 23 01 720 802 ENTER MISSING C/W DATE _____						
26-20-00-208	DETAILED INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE (MRB)		MOS HRS/MSC AFL	96 +2m/-2m	?		
	REF: AMM 26 20 00 220 804 ENTER MISSING DATE OF HYDROSTATIC CHECK _____						
262301-001C	MAINTENANCE COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE PER NFPA-10 (CMM PARAGRAPH 5.D)		MOS HRS/MSC AFL	72	?		
	REF: ENTER MISSING C/W DATE _____						

AUTHORIZED BY _____

CERT.# _____

DATE _____

?-Insufficient Information

(s) Suppressed Requirement

*-Estimated Due (New Requirement)

(EBT)-Estimated Base Time

11-JAN-2021

© CAMP SYSTEMS

NEW REQUIREMENT/FLAGGED ITEMS

Operator Review And Action Required

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

TASK NO	TASK DESCRIPTION	EFFECTIVE DATE	UNIT	INTERVAL	BASE TIME		NEXT DUE	DISPOSITION	
					Current	Change To			
TCCA CF-2020-54 R01 PART I LH	LUBRICATION OF LEFT HAND (LH) MLG SHOCK STRUT LOWER PIN								
		05-JAN-2021	DUE AT	MOS	12	05-JAN-2021	_____	05-JAN-2022 ^M	MANDATORY
			DUE AT	HRS/MSC	200	4638:14 (EBT)	_____	4838:14 ^M	
	REF: AD		AFL			_____			
	NEW REQUIREMENT ADDED ON 29-DEC-2020. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
TCCA CF-2020-54 R01 PART I RH	LUBRICATION OF RIGHT HAND (RH) MLG SHOCK STRUT LOWER PIN								
		05-JAN-2021	DUE AT	MOS	12	05-JAN-2021	_____	05-JAN-2022 ^M	MANDATORY
			DUE AT	HRS/MSC	200	4638:14 (EBT)	_____	4838:14 ^M	
	REF: AD		AFL			_____			
	NEW REQUIREMENT ADDED ON 29-DEC-2020. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
TCCA CF-2020-54 R01 PART II LH	DVI OF THE LH MLG SHOCK STRUT LOWER PIN								
		05-JAN-2021		MOS		05-JAN-2021	_____		MANDATORY
				HRS/MSC		4638:14 (EBT)	_____		
	REF: AD		DUE NEXT	AFL	150	2987 (EBT)	_____	3137*	
	NEW REQUIREMENT ADDED ON 06-JAN-2021. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								
TCCA CF-2020-54 R01 PART II RH	DVI OF THE RH MLG SHOCK STRUT LOWER PIN								
		05-JAN-2021		MOS		05-JAN-2021	_____		MANDATORY
				HRS/MSC		4638:14 (EBT)	_____		
	REF: AD		DUE NEXT	AFL	150	2987 (EBT)	_____	3137*	
	NEW REQUIREMENT ADDED ON 06-JAN-2021. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.								

AUTHORIZED BY _____

CERT.# _____

DATE _____

?-Insufficient Information

(s) Suppressed Requirement

*-Estimated Due (New Requirement)

(EBT)-Estimated Base Time

11-JAN-2021

© CAMP SYSTEMS

NEW REQUIREMENT/FLAGGED ITEMS

Operator Review And Action Required

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

These tasks or requirements have been added newly to your aircraft status. Please review them and approve or modify as appropriate. Please pay particular attention to the Base and Next Due Times for these tasks. It is important to note that any task that has insufficient information (marked by ?), will never come due unless the necessary information is provided by you.

TASK NO	TASK DESCRIPTION	EFFECTIVE DATE	UNIT	INTERVAL	BASE TIME		NEXT DUE	DISPOSITION
					Current	Change To		
TCCA CF-2020-54 R01 PART III LH	NDT INSPECTION OF THE LH MLG SHOCK STRUT LOWER PIN	05-JAN-2021	MOS		05-JAN-2021	_____		MANDATORY

	REF: AD		DUE AT	AFL	200	2987 (EBT)		3187 ^M
	NEW REQUIREMENT ADDED ON 29-DEC-2020. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.							
TCCA CF-2020-54 R01 PART III RH	NDT INSPECTION OF THE RH MLG SHOCK STRUT LOWER PIN	05-JAN-2021	MOS		05-JAN-2021	_____		MANDATORY

	REF: AD		DUE AT	AFL	200	2987 (EBT)		3187 ^M
	NEW REQUIREMENT ADDED ON 29-DEC-2020. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.							
SB 604-27-039 PART A	ACCOMPLISH, SERVICE BULLETIN SPECIAL CHECK - TEMPORARY PERIODIC TESTING OF THE RUDDER PCU LOAD LIMITERS	07-DEC-2020	MOS		07-DEC-2020	_____		RECOMMENDED

			DUE NEXT	HRS/MSC	1000	4615:09 (EBT)		5615:09*
	REF: See Workcard		AFL			_____		
	NEW REQUIREMENT ADDED ON 08-DEC-2020. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.							
SB 604-27-039 PART B	ACCOMPLISH, SERVICE BULLETIN SPECIAL CHECK - ONE-TIME VISUAL INSPECTION OF THE RUDDER PCU LOAD LIMITERS AND REPLACE THE LOAD LIMITER (IF THE NUT AND END CAP OF THE RUDDER PCU LOAD LIMITER IS NOT CRIMPED PROPERLY)	07-DEC-2020	MOS		07-DEC-2020	_____		RECOMMENDED

			DUE NEXT	HRS/MSC	3400	4615:09 (EBT)		8015:09*
	REF: See Workcard		AFL			_____		
	NEW REQUIREMENT ADDED ON 08-DEC-2020. REVIEW BASE TIMES TO ENSURE CORRECT DUE TIMES.							

AUTHORIZED BY _____

?-Insufficient Information

11-JAN-2021

(s) Suppressed Requirement

CERT.# _____

*-Estimated Due (New Requirement)

DATE _____

(EBT)-Estimated Base Time

© CAMP SYSTEMS

Due List

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021
Operator: LLC AVIASERVICE
Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
273504-001A	FUNCTIONAL TEST NO. 1 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY LINEARITY (27-35-04-101) (CMR*)								
27.330	P/N: 600-59154-3 S/N: GST05979 REF: AMM 27 35 04 720 801	MOS HRS/MSC 300 AFL			08-MAY-2020 4328:45 2835	4628:45		OVD	
WO: 5613_NOV2020									
273504-002A	FUNCTIONAL TEST NO. 2 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY LINEARITY (27-35-04-101) (CMR*)								
27.335	P/N: 600-59154-3 S/N: GST05253 REF: AMM 27 35 04 720 801	MOS HRS/MSC 300 AFL			08-MAY-2020 4328:45 2835	4628:45		OVD	
WO: 5613_NOV2020									
34-61-00-970-801	LOAD THE NAVIGATION DATABASE TO FLIGHT MANAGEMENT COMPUTER (FMC) VIA DBU								
	REF:	DAYS 28 HRS/MSC AFL			23-DEC-2020 4630:25 2981	27-JAN-2021 M		16d	27-JAN-2021
050042	12 MONTH CHECK								
	REF: MPD SECTION 2.2.2	MOS 12 HRS/MSC AFL	+1m/-1m		08-MAY-2020 4328:45 2835	23-MAR-2021	23-APR-2021	71d (+31)	23-MAR-2021
237121-001B	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING DEVICE (ULD)								
23.065	P/N: 068-E5542-00 S/N: ULB004405 REF: AMM 23 71 03 710 801	MOS 36 HRS/MSC AFL	+1m/-1m		23-MAR-2018 3512:30 2441	23-MAR-2021	23-APR-2021	71d (+31)	23-MAR-2021
WO: 5613_NOV2020									
313109-001B	OPERATIONAL TEST FDR (ULB) (ULD) UNDERWATER LOCATOR BEACON (31-31-00-202)								
31.055	P/N: 068-E5542-00 S/N: ULB004479 REF: AMM 31 31 07 710 801	MOS 36 HRS/MSC AFL	+1m/-1m		23-MAR-2018 3512:30 2441	23-MAR-2021	23-APR-2021	71d (+31)	23-MAR-2021
WO: 5613_NOV2020									

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)

Due List

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021
Operator: LLC AVIASERVICE
Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
351012-701	WARDROBE PBE								
	P/N: DP3113(A)	MOS	120	TSN:0	30-MAR-2011	30-MAR-2021		78d	30-MAR-2021
	S/N: E1002274	HRS/MSC		TSN:0	1551:30				
	REF:	AFL		TSN:0	1194				
WO: 5613_NOV2020									
256089-701	FIRST AID KIT								
	P/N: IFAK	MOS			08-MAY-2020	01-APR-2021 M		80d	01-APR-2021
	S/N: 081705020	HRS/MSC	O/C		4328:45				
	REF:	AFL			2835				
WO: 5613_NOV2020									
11-31-62-601	DISCARD SELF-ILLUMINATED EXIT SIGN							STLMC	
		MOS	60		08-APR-2016	08-APR-2021		87d	08-APR-2021
		HRS/MSC			2660:45				
	REF:	AFL			1999				
261401-701A	RESTORE AFT LAVATORY SMOKE DETECTOR SMOKE DETECTOR (26-10-60-601)							STLMC	
	P/N: 473597-2	MOS	60		08-APR-2016	08-APR-2021		87d	08-APR-2021
	S/N: 1131	HRS/MSC			2660:45				
	REF:	AFL			1999				
261401-702A	RESTORE BAGGAGE SMOKE DETECTOR SMOKE DETECTOR (26-10-60-601)							STLMC	
	P/N: 473597-2	MOS	60		08-APR-2016	08-APR-2021		87d	08-APR-2021
	S/N: 1132	HRS/MSC			2660:45				
	REF:	AFL			1999				
050012	100 HOUR CHECK								
		MOS			14-DEC-2020				20-APR-2021
		HRS/MSC	100		4616	4716		65:15	
	REF: See Workcard	AFL			2974				
TCCA CF-2018-06	FLOODLIGHT PANEL - COCKPIT FLOODLIGHT WATER PENETRATION							MANDATORY	
		MOS	38		(EFF)	05-MAY-2021		114d	05-MAY-2021
		HRS/MSC							
	REF: AD	AFL							

(xEXT) - Extension incorporated in the next due (s) - Suppressed Requirement + - FAA manual flag is set (EBT) - Estimated Base Time (EFF) - Effective C/W (#) - RTS-Update Pending (!) - RTS-Update Overdue
 * - Estimated Due (applies to New Requirement)

Due List

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021
Operator: LLC AVIASERVICE
Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	TIME SINCE	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	DISPOSITION TIME REMAINING	EST. DUE
050040	6 MONTH CHECK								
		MOS	6	+1m/-1m					
		HRS/MSC			12-DEC-2020	08-MAY-2021	08-JUN-2021	117d (+31)	08-MAY-2021
		AFL			4614				
	REF: MPD SECTION 2.2.2				2973				
25-60-60-605	GENERAL VISUAL INSPECTION OF THE FIRST AID / MEDICAL KITS (DO NOT OPEN IF SEALED)							STLMC	
		MOS	12						
		HRS/MSC			08-MAY-2020	08-MAY-2021		117d	08-MAY-2021
		AFL			4328:45				
	REF:				2835				
	WO: 5613_NOV2020								
256205-701A	TEST ARTEX ME406, PORTABLE EMERGENCY LOCATOR TRANSMITTER FOR THE INTEGRITY OF THE ELT AND ANTENNA SYSTEM.							CUSTOMER CODE	
	P/N: 453-6603	MOS	12						
	S/N: 00906	HRS/MSC			08-MAY-2020	08-MAY-2021		117d	08-MAY-2021
	REF:	AFL			4328:45				
					2835				
30-40-00-301	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL. NOTE: WHICHEVER INTERVAL COMES FIRST							OPTIONAL	
		MOS	12	+1m/-1m					
		HRS/MSC	600	+40/-40	08-MAY-2020	08-MAY-2021	08-JUN-2021	117d (+31)	08-MAY-2021
		AFL			4328:45	4928:45	4968:45	278 (+40)	
	REF: AMM 56 10 01 220 804				2835				
FAA 2020-10-05	NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS							MANDATORY	
		MOS	12						
		HRS/MSC			(EFF)	24-JUN-2021		164d	24-JUN-2021
	REF: AD	AFL							

Discrepancy Due List Report
MODEL: CL-604 SERIAL: 5613 RegNo: RA-67228

Report Date: 11-JAN-2021

DISCR # DATE LOGGED PART/SERIAL	CATEGORY	ATA	DESCRIPTION	UNIT	INTERVAL	LOGBOOK TIMES	LOGBOOK Ref.	NEXT DUE (x Ext)	TIME REMAINING	EST. DATE
---------------------------------------	----------	-----	-------------	------	----------	------------------	-----------------	---------------------	-------------------	-----------

NO DATA FOUND

Discrepancy Type: