

**OWNER:** LLC AVIASERVICE  
**ADDRESS:** 12409, AIRPORT, LAISHEVO DISTRICT  
 RUSSIAN FEDERATION 420017  
**PHONE:**  
**FAX:**

**OPERATOR:** LLC AVIASERVICE  
**ADDRESS:** 12409, AIRPORT, LAISHEVO DISTRICT  
 RUSSIAN FEDERATION 420017  
**PHONE:**  
**FAX:**

**ANALYST:** ALIX FOSSE  
**EMAIL:** ALIX.FOSSE@CAMPSYSTEMS.EU

+33-1.55.93.47.78 (DIRECT)  
 +33 (0) 1.55.93.45.80 (OFFICE)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Special Requirement: INCLUDE SPECIAL REQUIREMENTS; With: WARRANTY;

**AIRCRAFT SERIAL/REGNO:** 5613/RA-67228      **MODEL:** CL-604      **MANUFACTURER:** BOMBARDIER INCORPORATED

DATES	LAST ACTUALS		CURRENT ACTUAL	
CERTIFICATION DATE: 07-MAR-2005	4650:45 A/C HRS	as of 10-JAN-2021	_____ A/C HRS	as of ____/____/____
INSERVICE DATE: 28-APR-2006	2986 AFL	as of 10-JAN-2021	_____ AFL	as of ____/____/____
	6973 APH	as of 10-JAN-2021	_____ APH	as of ____/____/____
	0 APS	as of 03-DEC-2020	_____ APS	as of ____/____/____

**APU SERIAL/PART:** P-820/3800050-5-1      **MODEL:** GTCP36-100(E) (604-CIMMS)      **MANUFACTURER:** HONEYWELL

INSTALLED ON 07-MAR-2005	LAST ACTUALS		CURRENT ACTUAL	
0 APU HRS	6973 APU HRS	as of 10-JAN-2021	_____ APU HRS	as of ____/____/____
0 APUS	0 APUS	as of 03-DEC-2020	_____ APUS	as of ____/____/____

**ENGINE NO. 1 SERIAL/PART:** 950335/6089T11G01      **MODEL:** CF-34-3B (CIMMS)      **MANUFACTURER:** GENERAL ELECTRIC

INSTALLED ON 07-MAR-2005		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	4650:45 ENG. HRS	as of 10-JAN-2021	_____ ENG. HRS	as of ____/____/____
0 ENC		3002 ENC	as of 10-JAN-2021	_____ ENC	as of ____/____/____

**ENGINE NO. 2 SERIAL/PART:** 950336/6089T11G01      **MODEL:** CF-34-3B (CIMMS)      **MANUFACTURER:** GENERAL ELECTRIC

INSTALLED ON 07-MAR-2005		LAST ACTUALS		CURRENT ACTUAL	
0 ENG. HRS	0 A/C HRS	4650:45 ENG. HRS	as of 10-JAN-2021	_____ ENG. HRS	as of ____/____/____
0 ENC		3002 ENC	as of 10-JAN-2021	_____ ENC	as of ____/____/____

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 05</b>	<b>TIME LIMITS/MAINTENANCE CHECKS</b>							
050012	100 HOUR CHECK							
	PKG 0	MOS				14-DEC-2020		
		HRS/MSC	100			4616		<b>4716</b>
	REF: See Workcard	AFL				2974		
050013	400 HOUR CHECK							
	PKG 400	MOS				12-DEC-2020		
		HRS/MSC	400	+40/-40		4614		<b>5014</b>
	REF: See Workcard	AFL				2973		5054
050015	600 HOUR CHECK							
	PKG 600	MOS				08-MAY-2020		
		HRS/MSC	600	+40/-40		4328:45		<b>4928:45</b>
	REF: See Workcard	AFL				2835		4968:45
050017	800 HOUR CHECK							
	PKG 800	MOS				08-MAY-2020		
		HRS/MSC	800	+40/-40		4328:45		<b>5128:45</b>
	REF: See Workcard	AFL				2835		5168:45
050019	1200 HOUR CHECK							
	PKG 1200	MOS				08-MAY-2020		
		HRS/MSC	1200	+40/-40		4328:45		<b>5528:45</b>
	REF: See Workcard	AFL				2835		5568:45

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050023	1600 HOUR CHECK							
	PKG 1600	MOS				08-MAY-2020		
	REF: See Workcard	HRS/MSC AFL	1600	+40/-40		4328:45 2835	<b>5928:45</b>	5968:45
050024	2400 HOUR CHECK							
	PKG 2400	MOS				08-MAY-2020		
	REF: See Workcard	HRS/MSC AFL	2400	+40/-40		4328:45 2835	<b>6728:45</b>	6768:45
050029	3200 HOUR CHECK							
	PKG 3200	MOS				03-APR-2017		
	REF: See Workcard	HRS/MSC AFL	3200	+40/-40		3041:45 2185	<b>6241:45</b>	6281:45
050029-1	4800 HOUR CHECK							
	PKG 4800	MOS				08-MAY-2020		
	REF: See Workcard	HRS/MSC AFL	4800	+40/-40		4328:45 2835	<b>9128:45</b>	9168:45
050029-2	6400 HOUR CHECK							
	PKG 6400	MOS				07-MAR-2005		
	REF: See Workcard	HRS/MSC AFL	6400	+40/-40		0 0	<b>6400</b>	6440

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050040	6 MONTH CHECK							
	PKG 0	MOS	6	+1m/-1m	-35	12-DEC-2020	<b>08-MAY-2021</b>	08-JUN-2021
	REF: MPD SECTION 2.2.2	HRS/MSC AFL				4614 2973		
050042	12 MONTH CHECK							
	PKG 12	MOS	12	+1m/-1m	-46	08-MAY-2020	<b>23-MAR-2021</b>	23-APR-2021
	REF: MPD SECTION 2.2.2	HRS/MSC AFL				4328:45 2835		
050044	24 MONTH CHECK							
	PKG 24	MOS	24	+1m/-1m	-46	08-MAY-2020	<b>23-MAR-2022</b>	23-APR-2022
	REF: MPD SECTION 2.2.2	HRS/MSC AFL				4328:45 2835		
050046	36 MONTH CHECK							
	PKG 36	MOS	36	+1m/-1m		26-MAR-2019	<b>26-MAR-2022</b>	26-APR-2022
	REF: MPD SECTION 2.2.2	HRS/MSC AFL				3702:35 2541		
050048	48 MONTH CHECK							
	PKG 48	MOS	48	+1m/-1m	22	23-MAR-2018	<b>14-APR-2022</b>	14-MAY-2022
	REF: See Workcard	HRS/MSC AFL				3512:30 2441		

**Status Report**

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

Owner/Operator: LLC AVIASERVICE

Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050096	96 MONTH CHECK							
	PKG 96	MOS	96			16-JUN-2014	<b>28-APR-2022</b>	28-MAY-2022
	REF: See Workcard	HRS/MSC APL				2304:15 1731		
APU Model : GTCP36-100(E) (604-CIMMS) Serial # P-820 Part # 3800050-5-1								
050014	APU - 400 HOUR CHECK							
	PKG 400	MOS				12-DEC-2020		
	REF:	HRS/MSC APUS	400				?	?
050016	APU - 600 HOUR CHECK							
	PKG 600	MOS				08-MAY-2020		
	REF:	HRS/MSC APUS	600			6583	<b>7183</b>	7223
050018	APU - 800 HOUR CHECK							
	PKG 800	MOS				08-MAY-2020		
	REF:	HRS/MSC APUS	800			6583	<b>7383</b>	7423
050020	APU - 1200 HOUR CHECK							
	PKG 1200	MOS				08-MAY-2020		
	REF:	HRS/MSC APUS	1200			6583	<b>7783</b>	7823



**BOMBARDIER**

### Status Report

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

Owner/Operator: LLC AVIASERVICE

Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION	UNIT	INTERVAL	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
050026	APU - 2400 HOUR CHECK							
	PKG 2400	MOS				08-MAY-2020		
	REF:	HRS/MSC APUS	2400	+40/-40		6583	8983	9023

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>CHAPTER 00</b>	<b>INFORMATION</b>								
CI64-120213	REVIEW BOMBARDIER TLMC TR 5-2-57 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	MOS HRS/MSC - AFL					(EBT)		
CI64-120712	REVIEW TLMC REVISION 18 / MPD REVISION 18 / TLMC TR 5-2-58, 5-2-59 AND 5-2-60 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	MOS HRS/MSC - AFL					(EBT)		
CI64-130121	REVIEW CL604 CHANGE NOTICE FORM TLMC - MPD REVISION 19 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	MOS HRS/MSC - AFL					(EBT)		
CI64-130724	REVIEW BOMBARDIER TLMC / MPD REVISION 20 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	MOS HRS/MSC - AFL					(EBT)		
CI64-140123	REVIEW TLMC / MPD REVISION 21 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	MOS HRS/MSC - AFL					(EBT)		
CI64-140218	REVIEW CL-604 MPD TR-343 & TR-344 DATED 31 JAN 2014 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	MOS HRS/MSC - AFL					16-JUL-2014		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI64-140808	REVIEW CL-604 - TLMC REVISION 22 / MPD REVISION 22 DATED 11 JUL. 2014 - SUMMARY CHANGE FORM	MOS						10-SEP-2014	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							
CI64-141030	REVIEW CL604 -TEMPORARY REVISION MPD 348 TO 355 TLMC 5-2-62 TO 5-2-64 DATED 02 OCT 2014 CAMP CHANGE FORM	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							
CI64-150121	REVIEW BOMBARDIER CHALLENGER 604 TLMC REV 23 (MPD REV 23)	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							
CI64-150127	REVIEW BOMBARDIER CHALLENGER 604 TLMC TR 5-2-65 (MPD TR-356, -357, -358)	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							
CI64-150611	REVIEW BOMBARDIER CL604 REVISION 24 (MPD REV 24)	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							
CI64-151201	REVIEW BOMBARDIER CHALLENGER 604 TLMC REV 25 (MPD REV 25)	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI64-160609	REVIEW BOMBARDIER CHALLENGER 604 - TLMC REV. 26 DATED JUNE 09/2016	MOS						06-FEB-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
+ CI64-160609-MPD	REVIEW MAINTENANCE PLANING DOCUMENT (MPD) - REV 26 - DATED 09-JUN-2016	MOS						06-FEB-2017	
	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-160805	REVIEW BOMBARDIER CHALLENGER 604 TIME LIMITS/MAINTENANCE CHECKS (TLMC) - TR 5-2-67, DATED AUG 05/2016	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-161128	REVIEW BOMBARDIER CHALLENGER 604 TLMC REV 27 (MPD REV 27) DATED NOV 28/2016.	MOS						06-FEB-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-170223	REVIEW TLMC REV 28 DATED 23-FEB-17	MOS							
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-170616-MPD	REVIEW BOMBARDIER CHALLENGER CL-604 MAINTENANCE PLANNING DOCUMENT (MPD) REVISION 29 DATED 16-JUN-2017.	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
CI64-170616-TLMC	REVIEW BOMBARDIER CHALLENGER CL-604 TIME LIMITS / MAINTENANCE CHECKS REVISION 29 DATED 16-JUN-2017.	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
+ CI64-171204-TLMC	REVIEW BOMBARDIER CHALLENGER CL-604 TIME LIMITS / MAINTENANCE CHECKS REVISION 30 DATED DEC 04/2017.	MOS					11-JAN-2018		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-181119-TLMC-REV 31	TLMC REVISION 31 - DATED NOV 19/2018	MOS					(EBT)		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-190327	REVIEW TLMC SECTION 5-10-10 (TR 5-2-68) AND SECTION 5-10-11 (TR 5-2-69) - DATED MAR 27/2019	MOS					20-MAY-2019		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							
CI64-191218-TLMC	REVIEW CHALLENGER 604 TLMC REV 32 - DATED DEC 18/2019	MOS					19-FEB-2020		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF CI64</b>	HRS/MSC - AFL							
CI64-200319 TR 5-2-70	REVIEW CHALLENGER 604 TLMC TR 5-2-70 - DATED MARCH 19/2020	MOS					10-APR-2020		
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF 00</b>	HRS/MSC - AFL							

**APU Model : GTCP36-100(E) (604-CIMMS) Serial # P-820 Part # 3800050-5-1**

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
AC12-161102	APU - REVIEW GTCP36-100E SIL APU-56 REV 2	MOS						06-FEB-2017	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF AC12</b>	HRS/MSC - APUS							
AC12-180112	APU - REVIEW HONEYWELL GTCP 36-100(E) (604-CIMMS) APU-49 SIL REV 10	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF APU-SIL-49</b>	HRS/MSC - APUS							
AC12-201020	APU - REVIEW GTCP36-100(E) MM REV 14	MOS						12-NOV-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF AC12</b>	HRS/MSC - APUS							
AC12-990430	APU - REVIEW GTCP36-100(E) MM REV 13	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF AC12-990430</b>	HRS/MSC - APUS							
<b>ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01</b>									
EC46-140507	NO. 1 ENGINE - REVIEW EC46 - SEI-780 SERVICE MANUAL REVISION NO. 53 DATED MAR 31, 2014 CAMP REQUIREMENT CHANGE FORM	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	HRS/MSC - ENC							
EC46-150304	NO. 1 ENGINE - REVIEW EC46 - EMM SEI-780 SERVICE MANUAL REVISION NO. 54 DATED 19-DEC-2014 - CAMP CHANGE FORM	MOS						(EBT)	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	HRS/MSC - ENC							

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC46-150305	NO. 1 ENGINE - REVIEW EC46 - EMM SEI-780 SERVICE MANUAL REVISION NO. 55 DATED 20-FEB-2015 - CAMP REQUIREMENT CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC							
EC46-160303	NO. 1 ENGINE - REVIEW GE, SEI-780 SERVICE MANUAL REV NO. 56, DATED 01-FEB-2016								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-170201	NO. 1 ENGINE - REVIEW CF34-3B SERVICE MANUAL REV 57								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-170627	NO. 1 ENGINE - REVIEW CF34-3B EMM TR 05-0089								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC76-170627</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-180201	NO. 1 ENGINE - REVIEW CF34-3B EMM REV 58								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-180907	NO. 1 ENGINE - REVIEW SEI-780 MM TR 05-0095								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC46-190201	NO. 1 ENGINE - REVIEW CF34-3B EM SEI-780 REV 59								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-200114	NO. 1 ENGINE - REVIEW CF34-3B (CIMMS) TR 05-0097								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					19-FEB-2020		
EC46-200201	NO. 1 ENGINE - REVIEW CF34-3B SM SEI-780 REV 60								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					19-FEB-2020		
<b>ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01</b>									
EC46-140507	NO. 2 ENGINE - REVIEW EC46 - SEI-780 SERVICE MANUAL REVISION NO. 53 DATED MAR 31, 2014 CAMP REQUIREMENT CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-150304	NO. 2 ENGINE - REVIEW EC46 - EMM SEI-780 SERVICE MANUAL REVISION NO. 54 DATED 19-DEC-2014 - CAMP CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-150305	NO. 2 ENGINE - REVIEW EC46 - EMM SEI-780 SERVICE MANUAL REVISION NO. 55 DATED 20-FEB-2015 - CAMP REQUIREMENT CHANGE FORM								
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC							

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC46-160303	NO. 2 ENGINE - REVIEW	GE, SEI-780	SERVICE MANUAL	REV NO. 56, DATED 01-FEB-2016					
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-170201	NO. 2 ENGINE - REVIEW	CF34-3B	SERVICE MANUAL	REV 57					
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-170627	NO. 2 ENGINE - REVIEW	CF34-3B	EMM TR 05-0089						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC76-170627</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-180201	NO. 2 ENGINE - REVIEW	CF34-3B	EMM REV 58						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-180907	NO. 2 ENGINE - REVIEW	SEI-780	MM TR 05-0095						
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		
EC46-190201	NO. 2 ENGINE - REVIEW	CF34-3B	EM SEI-780	REV 59					
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	MOS HRS/MSC - ENC					(EBT)		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
EC46-200114	NO. 2 ENGINE - REVIEW CF34-3B (CIMMS) TR 05-0097	MOS						19-FEB-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	HRS/MSC - ENC							
EC46-200201	NO. 2 ENGINE - REVIEW CF34-3B SM SEI-780 REV 60	MOS						19-FEB-2020	
<b>REQUIREMENT CHANGE FORMS</b>	<b>REF: RCF EC46</b>	HRS/MSC - ENC							
<b>CHAPTER 08 LEVELING AND WEIGHING</b>									
089010	WEIGHT AND BALANCE	MOS	48				23-MAR-2018	<b>23-MAR-2022</b>	
	<b>REF:</b>	HRS/MSC AFL					3512:30 2441		
<b>CHAPTER 11 PLACARDS AND MARKINGS</b>									
11-30-60-601 (s)	GENERAL VISUAL INSPECTION OF THE CABIN PLACARDS - INTERNAL						PKG		
	PKG 12	MOS	12				08-MAY-2020		
<b>STLMC</b>	<b>REF:</b>	HRS/MSC AFL					4328:45 2835		
11-31-62-601	DISCARD SELF-ILLUMINATED EXIT SIGN	MOS	60				08-APR-2016	<b>08-APR-2021</b>	
<b>STLMC</b>	<b>REF:</b>	HRS/MSC AFL					2660:45 1999		
<b>CHAPTER 21 AIR CONDITIONING</b>									
21-20-00-201 (s)	OPERATIONAL TEST OF THE PRESSURE BULKHEAD CHECK VALVES						PKG		
	PKG 800	MOS					08-MAY-2020		
21.005	<b>REF: AMM 21 21 04 710 801</b>	HRS/MSC 800 AFL	800	+40/-40			4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-20-00-202 (s)	OPERATIONAL TEST AVIONICS EXHAUST FAN LOW SPEED DETECTOR (MRB)						PKG		
21.010	604-96001-1 PKG 800 C04470395 REF: AMM 21 24 22 710 801	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
21-24-34-301 (s)	OPERATIONAL TEST DATA CONCENTRATOR UNIT (DCU) FAN						PKG		
21.015	PKG 1600 REF: AMM 21 24 34 710 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
21-30-00-201 (s)	RESTORATION (CLEANING) OF THE OUTFLOW VALVE POPPET AREA						PKG		
21.020 RESTORE	PKG 1600 REF: AMM 21 32 01 160 802	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
21-30-00-202 (s)	DISCARD OF THE PRIMARY OUTFLOW VALVE AIR FILTER.						PKG		
21.025	PKG 1600 REF: AMM 21 32 07 960 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
21-30-00-203 (s)	OPERATIONAL TEST OF THE PRESSURIZATION CONTROL SYSTEM (MANUAL MODE)						PKG		
21.030	PKG 600 REF: AMM 21 31 00 710 802	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
21-30-00-205 (s)	OPERATIONAL TEST OF THE EMERGENCY DEPRESS SWITCH/LIGHT						PKG		
21.035	PKG 2400 REF: AMM 21 31 00 710 803	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
21-31-00-101	FUNCTIONAL TEST OF THE OUTFLOW VALVES (CMR**)								
21.040	PKG 1600 REF: AMM 21 31 00 720 801	MOS HRS/MSC AFL	1600				08-MAY-2020 4328:45 2835	5928:45	



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
21-50-00-201 (s) 21.045	OPERATIONAL TEST EMERGENCY RAM AIR SHUTOFF VALVE 398724-1-1 PKG 2400 1898 REF: AMM 21 52 10 710 801	MOS HRS/MSC AFL	2400 +40/-40				PKG 08-MAY-2020 4328:45 2835		
21-51-00-301 (s) 21.050	CLEAN WATER SEPARATOR PKG 800 REF: AMM 21 51 13 160 801	MOS HRS/MSC AFL	800 +40/-40				PKG 08-MAY-2020 4328:45 2835		
212104-001 21.055	NO. 1 2 INCH CHECK VALVE 3202062-1-1 1875 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212104-002 21.055	NO. 2 2 INCH CHECK VALVE 3202062-1-1 1893 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212104-003 21.060	CHECK VALVE 123790-1-1 1146 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212104-004 21.065	3 INCH BACKUP VALVE 3202076-1-1 984 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212113-001 21.070	CONTROL CABLE 601A95120-3 375 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212119-001	FOOTWARMER/DEMIST FAN								
21.075	601R96380-3 C04470393 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212122-001	CLASS C COMPARTMENT HEATER								
21.080	601R96381-1 1146 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212125-001	TEMPERATURE SWITCH								
21.085	601R96384-4 1151 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212210-001	ASSY - AIR CONDITIONING DUCT								
21.090	601-95014-1 L-98884 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212210-002	ASSY - AIR CONDITIONING DUCT								
	14306-1 L-98105 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212210-003	ASSY - AIR CONDITIONING DUCT								
	14307-1 L-99260 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212210-004	ASSY - AIR CONDITIONING DUCT								
	14316-1 L-99511 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
212307-001	NO. 1 AIR-CONDITIONING CONTROL UNIT ECU								
21.095	2201600-6 1455 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212307-002	NO. 2 AIR-CONDITIONING UNIT ECU								
21.095	2201600-6 1454 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
212422-001	AVIONICS EXHAUST FAN								
21.010	604-96001-1 C04470395 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213101-001	FORWARD CHECK VALVE								
21.100	2770080-102 3748 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213101-002	AFT CHECK VALVE								
21.105	2770080-102 3743 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213104-001	AIR JET PUMP								
21.110	131428-1 124-A1786 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213107-001	MANUAL SYSTEM REGULATOR								
21.115	131402-2 1290D REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213110-001	MANUAL SYSTEM VALVE								
21.120	131400-2 15-796 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213110-002	CABIN PRESSURE SELECTOR PANEL								
21.125	2117598-8 15-C0264 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213113-001	CABIN PRESSURE CONTROLLER								
21.130	604-59010-1 94-A0264 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213113-002	CABIN PRESSURE CONTROLLER								
21.135	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213201-001	PRESSURE REGULATING PRIMARY VALVE								
21.140	103632-3 90-644 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
213201-002	PRESSURE REGULATING SECONDARY VALVE								
21.025	103664-2 124-162 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
213301-001	CABIN PRESSURE ACQUISITION UNIT								
21.145	10275B04C03 1748A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
213304-001	CABIN ALTITUDE INDICATOR								
21.150	46045-1103 416636 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
213313-001	CABIN PRESSURE CONTROL								
21.155	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
215101-701	LH WATER SEPARATOR								
	85020-6 2658 REF:	MOS HRS/MSC AFL	O/C				30-MAR-2011 1551:30 1194		
215101-702	RH WATER SEPARATOR								
	85020-6 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C				07-MAR-2005 0 0		
215134-001	NO. 1 PRESSURE REGULATING SHUTOFF VALVE								
21.160	3213876-12 1812 REF: See Workcard	MOS HRS/MSC AFL	O/C				12-DEC-2020 4614 2973		
215134-002	NO. 2 PRESSURE REGULATING SHUTOFF VALVE								
21.160	3213876-12 2896 REF: See Workcard	MOS HRS/MSC AFL	O/C				03-NOV-2020 4564:55 2944		
215210-001	EMERGENCY RAM AIR SHUTOFF VALVE								
21.045	398724-1-1 1898 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216000-701	DUCT BWT-14915-1 1065 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
216000-702	DUCT BWT-14915-1 1062 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
216000-703	DUCT BWT-14915-1 1090 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
216000-704	DUCT BWT-14915-1 1097 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
216000-705	DUCT BWT-14915-1 1088 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
216101-001	COCKPIT CABIN TEMPERATURE SELECTOR 627964-1 627964-01802 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
21.165									
216101-002	CABIN TEMPERATURE CONTROL PANEL 627964-1 627964-01807 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
21.170									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216102-001	COCKPIT TEMPERATURE MODE SELECTOR								
21.175	625638-1 625638-01992 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216102-002	CABIN TEMPERATURE MODE SELECTOR								
21.180	625638-1 625638-01994 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216113-001	COCKPIT TEMPERATURE CONTROL								
21.185	625514-2-1 625514-01500 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216113-002	CABIN TEMPERATURE CONTROL								
21.190	625514-2-1 625514-01503 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216115-001	NO. 1 LOW LIMIT TEMPERATURE CONTROL								
21.195	625520-2 625520-01466 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216115-002	NO. 2 LOW LIMIT TEMPERATURE CONTROL								
21.195	625520-2 625520-01475 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216116-001	DUCT TEMPERATURE SENSOR								
21.200	627962-2 627962-18431 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216116-002	DUCT TEMPERATURE SENSOR								
21.200	627962-2 627962-18419 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216116-003	DUCT TEMPERATURE SENSOR								
21.200	627962-2 627962-18500 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216116-004	DUCT TEMPERATURE SENSOR								
21.200	627962-2 627962-18163 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216119-001	COCKPIT FAN SENSOR								
21.205	625692-2-1 625692-01571 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216119-002	CABIN FAN SENSOR								
21.210	625692-2-1 625692-01554 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216125-001	LH TORQUE MOTOR								
21.215	124904-1-1 5955 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216125-002	RH TORQUE MOTOR								
21.215	124904-1-1 5957 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
216128-001	NO. 1 MODULATING/SHUTOFF VALVE								
21.220	979558-8 1626 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216128-002	NO. 2 MODULATING/SHUTOFF VALVE								
21.220	979558-8 1628 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216131-001	NO. 1 TEMPERATURE LIMITER								
21.225	129580-6 6792 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216131-002	NO. 2 TEMPERATURE LIMITER								
21.225	129580-6 6794 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216134-001	NO. 1 PRESSURE REGULATING VALVE								
21.230	3214066-1 2498 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
216134-002	NO. 2 PRESSURE REGULATING VALVE								
21.230	3214066-1 2508 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
259529-701	GALLEY AIR HEATER								
	2831-46 676 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

**CHAPTER 22 AUTO FLIGHT**

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-11-00-201 (s)	OPERATIONAL TEST OF THE SVL-4000 RUDDER ACTUATOR BRAKE						PKG		
22.005	PKG 1600 <b>REF:</b> AMM 22 22 01 710 803	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
22-11-00-202 (s)	LUBRICATION OF THE ELEVATOR SERVO						PKG		
22.010	PKG 48 <b>REF:</b> AMM 12 20 04 640 835	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
22-12-00-201 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE FLIGHT COMPARTMENT						PKG		
L/HIRF	PKG 96 <b>REF:</b> AMM 22 12 22 220 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
22-12-00-202 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE FUSELAGE / STABILIZER - INTERNAL						PKG		
L/HIRF	PKG 48 <b>REF:</b> AMM 22 12 22 220 802	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
22-12-00-203 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION OF THE VERTICAL STABILIZER - INTERNAL						PKG		
L/HIRF	PKG 96 <b>REF:</b> AMM 22 12 22 220 803	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
22-12-00-204 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE AFT EQUIPMENT COMPARTMENT						PKG		
L/HIRF	PKG 48 <b>REF:</b> AMM 22 12 22 220 804	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-12-00-205 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE FUSELAGE BETWEEN FS409.00 AND FS621.00, BELOW WL73.5 - INTERNAL						PKG		
	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 805</b>	HRS/MSC AFL					2304:15 1731		
22-12-00-206 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE AVIONICS RACKS						PKG		
	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 806</b>	HRS/MSC AFL					2304:15 1731		
22-12-00-207 (s)	SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE #2 VHF ANTENNA						PKG		
	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 280 801</b>	HRS/MSC AFL					2304:15 1731		
22-12-00-208 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE AVIONICS COMPARTMENTS						PKG		
	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 808</b>	HRS/MSC AFL					3512:30 2441		
22-12-00-209 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE UPPER FS621 BULKHEAD						PKG		
	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 809</b>	HRS/MSC AFL					2304:15 1731		
22-12-00-210 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE WING DISCONNECTS - EXTERNAL						PKG		
	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 810</b>	HRS/MSC AFL					2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-12-00-211 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION ON THE WING DISCONNECTS - INTERNAL						PKG		
	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 811</b>	HRS/MSC AFL					2304:15 1731		
22-12-00-212 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE MAIN WHEEL WELLS						PKG		
	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 812</b>	HRS/MSC AFL					3512:30 2441		
22-12-00-213 (s)	DETAILED INSPECTION OF THE LIGHTNING / HIGH INTENSITY RADIATED FIELD (L/HIRF) PROTECTION IN THE NOSE WHEEL WELL AND LANDING GEAR ASSEMBLY						PKG		
	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
<b>L/HIRF</b>	<b>REF: AMM 22 12 22 220 813</b>	HRS/MSC AFL					3512:30 2441		
22-12-16-301	DISCARD NO. 1 FLIGHT MANAGEMENT (FMC6000) COMPUTER BATTERY								
	822-0868-089	MOS	24	+1m/-1m			11-MAR-2020	<b>09-FEB-2022</b>	09-MAR-2022
<b>LIFE LIMIT</b>	<b>REF: AMM 22 12 16 960 801</b>	HRS/MSC AFL			-30				
22-12-16-301	DISCARD NO. 2 FLIGHT MANAGEMENT (FMC6000) COMPUTER BATTERY								
	822-0868-089	MOS	24	+1m/-1m			01-MAR-2020	<b>30-JAN-2022</b>	28-FEB-2022
<b>LIFE LIMIT</b>	<b>REF: AMM 22 12 16 960 801</b>	HRS/MSC AFL			-30				
22-12-25-301	DISCARD MAINTENANCE DIAGNOSTIC MDC4000 COMPUTER BATTERY								
	622-9818-405	MOS	48	+1m/-1m			21-MAR-2018	<b>16-APR-2022</b>	16-MAY-2022
<b>LIFE LIMIT</b>	<b>REF: AMM 22 12 25 960 801</b>	HRS/MSC AFL			26		3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
22-22-00-101	OPERATIONAL TEST OF THE YAW DAMPER LINEAR ACTUATORS (SVL-4000 RELAYS) (CMR**)								
22.015	PKG 4800 REF: AMM 22 22 01 710 802	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	9128:45	
22-30-BCC-9001 (s)	DIODE TEST PERFORME DIODE TEST PROCEDURE PER TE-22305001-SMM P.601						PKG		
STLMC	PKG 800 REF:	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835		
221101-701	FLIGHT CONTROL (FCP4003) PANEL								
	822-0182-001 20C3Y REF:	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			16-JUN-2014 2304:15 1731		
221104-001	AILERON SERVO (SMT-87A) MOUNT								
22.020	601R92614-9 1MDXB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221110-001	SERVO AILERON ACTUATOR								
22.025	601R92614-13 1LY8F REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221113-001	ELEVATOR SERVO (SMT-87B) MOUNT								
22.030	601R92614-11 1NMGN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221113-002	SERVO ELEVATOR ACTUATOR								
22.035	601R92614-15 1N3VW REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221204-001	I/O (IOC4000) CONCENTRATOR								
22.040	622-9814-731 1VVFB REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
221204-002	I/O (IOC4000) CONCENTRATOR								
22.045	622-9814-731 1RXKT REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
221204-003	I/O (IOC4000) CONCENTRATOR								
22.050	622-9814-731 1RXKR REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-MAY-2020 4328:45 2835		
221204-004	I/O (IOC4000) CONCENTRATOR								
22.055	622-9814-731 1VVDX REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-MAY-2020 4328:45 2835		
221207-001	1A POWER SUPPLY (PWR4000) MODULE								
22.060	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221207-002	1B POWER SUPPLY (PWR4000) MODULE								
22.065	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221207-003	2A POWER SUPPLY (PWR4000) MODULE								
22.070	622-9945-021 1RXRD REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221207-004	2B POWER SUPPLY (PWR4000) MODULE								
22.075	622-9945-021 1RXPT REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221210-001	1A FLIGHT CONTROL (FCC4006) COMPUTER								
22.080	822-0809-710 101W REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-APR-2009 987:33 782		
221210-002	1B FLIGHT CONTROL (FCC4006) COMPUTER								
22.085	822-0809-510 57UD REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-APR-2009 987:33 782		
221210-003	2A FLIGHT CONTROL (FCC4006) COMPUTER								
22.090	822-0809-710 48JX REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			24-APR-2009 987:33 782		
221210-004	2B FLIGHT CONTROL (FCC4006) COMPUTER								
22.095	822-0809-710 351VP REF: See Workcard	MOS HRS/MSC AFL	O/C				09-SEP-2012 1893 1430		
221216-001	NO. 1 FLIGHT MANAGEMENT (FMC6000) COMPUTER								
22.100	822-0868-089 1408 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-MAY-2020 4328:45 2835		
221216-002	NO. 2 FLIGHT MANAGEMENT (FMC6000) COMPUTER								
22.100	822-0868-089 1GDWM REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-MAY-2020 4328:45 2835		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221219-001	NO. 1 IAPS ENVIRONMENTAL (IEC4000) CONTROLLER								
22.105	822-0288-001 1RXTF REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221219-002	NO. 2 IAPS ENVIRONMENTAL (IEC4000) CONTROLLER								
22.105	822-0288-001 1RXTG REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221222-001	LIGHTNING/HIRF (LPH4001) PROTECTOR								
22.110	822-0332-702 1TOFN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221222-002	LPH4000 PROTECTOR								
22.115	822-0287-702 1W2BK REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221225-001	MAINTENANCE DIAGNOSTIC MDC4000 COMPUTER								
22.120	622-9818-405 F8YT REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			21-MAR-2018 3512:30 2441		
221228-001	NO. 1 SWITCHING MOD (SSM4000) SERVO								
22.125	822-0782-001 1VV1R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221228-002	NO. 2 SWITCHING MOD (SSM4000) SERVO								
22.125	822-0782-001 1VXHD REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
221233-001	AVIONICS BAY (CSU-4100) UNIT								
22.130	822-1364-002 1VWTC REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221233-002	AVIONICS BAY (CSU-4100) UNIT								
22.130	822-1364-002 1VWTD REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221234-001	AVIONICS BAY (OCM-4100) MODULE								
22.135	822-1463-210 1VRTF REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
221234-002	AVIONICS BAY (OCM-4100) MODULE								
22.135	822-1463-210 1VRTG REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
222201-001	NO. 1 LINEAR (SVL4000) ACTUATOR								
22.140	622-9968-002 4364 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
222201-002	NO. 2 LINEAR (SVL4000) ACTUATOR								
22.140	622-9968-002 4204 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

**CHAPTER 23 COMMUNICATIONS**

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
23-10-AWL-9001	SATCOM ANTENNA - REMOVAL OF THE SATCOM ANTENNA AND ADAPTER AT FS589 AND DETAILED VISUAL INSPECTION OF THE AIRCRAFT SKIN AROUND ANTENNA CUTOUTS AND DOUBLER ATATCH RIVETS.								
<b>STLMC</b>	<b>REF:</b>	MOS HRS/MSC AFL	7800				18-APR-2006 0 0	<b>7800</b>	
23-60-00-201 (s)	FUNCTIONAL TEST OF THE STATIC DISCHARGERS						PKG		
23.005	PKG 96 <b>REF:</b> AMM 23 61 01 720 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
23-60-00-202 (s)	FUNCTIONAL TEST (BONDING CHECK) OF THE STATIC DISCHARGER BASE						PKG		
<b>MRB</b>	PKG 48 <b>REF:</b> AMM 23 61 04 720 801	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
23-60-00-203 (s)	FUNCTIONAL TEST (BONDING CHECK) OF THE NOSE-RADOME LIGHTNING STRIPS						PKG		
<b>MRB</b>	PKG 48 <b>REF:</b> AMM 53 61 01 720 801	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
23-71-00-202 (s)	OPERATIONAL TEST CVR SYSTEM						PKG		
23.010	PKG 1200 <b>REF:</b> AMM 23 71 00 710 801	MOS HRS/MSC AFL	1200	+40/-40			08-MAY-2020 4328:45 2835		
230018-701	COCKPIT SIGMA 7 HANDSET								
	500040-11-12 1005-1856 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231003-701	SATCOM ANTENNA 10101-00 0P00183 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
231006-701	SATCOM ANTENNA MOUNTING PLATE 10102-135 05461 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
231101-001 23.015	NO. 1 VHF TRANSCEIVER 822-1115-001 1NW1C <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231101-002 23.015	NO. 2 VHF TRANSCEIVER 822-1115-001 1NW1D <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231104-001 23.020	UPPER VHF ANTENNA S65-8280-10 310-12971 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231104-002 23.020	LOWER VHF ANTENNA S65-8280-10 310-13096 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231201-001 23.025	NO. 1 HF (HF-9031A) TRANSCEIVER 822-0101-002 1915 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231201-002	NO. 2 HF (HF-9031A) TRANSCEIVER								
23.025	822-0101-002 1925 REF: See Workcard	MOS HRS/MSC AFL	O/C				17-FEB-2007 222:18 184		
231203-001	NO. 1 HF ANTENNA COUPLER								
23.030	685-0350-002 5555 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231203-002	NO. 2 HF ANTENNA COUPLER								
23.035	685-0350-002 5556 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231304-001	CABIN ALTITUDE INDICATOR								
23.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
231715-701	WIRELESS W/BASE UNIT (LH FWD CABIN DADO) HANDSET								
	500092-200 2409179 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
231715-702	WIRELESS W/BASE UNIT (LH AFT CABIN DADO) HANDSET								
	500092-200 2512031 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
231716-701	IRIDIUM ANTENNA								
	500644-1 5044347 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
231717-701	TRANSCEIVER IRRIDIUM UNIT 500617 5275 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
231720-701	FILTER BAND PASS IRIDIUM UNIT 500918 133 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
232000-701	SATCOM AMPLIFIER 403010H 05733479 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
232001-701	SATCOM (SATELLITE DATA UNIT) SDU 403068-UAT 646 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
232101-001 23.045	SELCAL DECODER 1200008-001 4300 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
233006-701	(AVIONIC BAY F/S 275) PREAMPLIFIER 990-3393-001 05040018168 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233008-701	FWD WARDROBE SWITCH PANEL 990-6103-177 05050019218 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		



**BOMBARDIER**

### Status Report

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

Owner/Operator: LLC AVIASERVICE

Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233107-701	ENTERTAINMENT HI/MID (LH PSU)FS366.00 SPEAKERS 990-4019-003 05070020317 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233107-702	ENTERTAINMENT HI/MID (LH PSU)FS477.00 SPEAKERS 990-4019-003 05030017441 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233107-703	ENTERTAINMENT HI/MID (LH PSU)FS549.00 SPEAKERS 990-4019-003 05030017442 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233107-704	ENTERTAINMENT HI/MID (RH PSU)FS366.00 SPEAKERS 990-4019-003 05030017445 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233107-705	ENTERTAINMENT HI/MID (RH PSU)FS447.00 SPEAKERS 990-4019-003 05040018145 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233107-706	ENTERTAINMENT HI/MID (RH PSU)FS551.00 SPEAKERS 990-4019-003 05070020320 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
233121-701	AUDIO/VIDEO MONITORING - IR REMOTE CONTROL 990-2016-088 05050019372 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
233121-702	AUDIO/VIDEO MONITORING - IR REMOTE CONTROL 990-2016-088 05050019373 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
235101-701	AUDIO ELECTRONIC CONTROL UNIT 5630-1-4 1992 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
235104-001	NO. 1 AUDIO CONTROL (DUAL VHF) PANEL 856-0073-020 4605 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
235104-001-01	AUDIO CONTROL (VHF) PANEL 856-0073-020 5298 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
235104-002	NO. 2 AUDIO CONTROL (DUAL VHF) PANEL 856-0073-020 4993 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
237101-001	COCKPIT VOICE RECORDER 2100-1020-00 000306247 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				24-APR-2009 987:33 782		
237110-001	CVR INERTIAL SWITCH 3LO-453-2 L13433 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
237121-001	CVR ULB (ULD) UNDERWATER LOCATOR BEACON								
23.065	068-E5542-00 ULB004405 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2018 3512:30 2441		
237121-001A	DISCARD OF THE COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING DEVICE (ULD) BATTERY.								
23.065 <b>LIFE LIMIT</b>	068-E5542-00 ULB004405 REF: AMM 23 71 03 960 801	MOS HRS/MSC AFL	DUE				23-MAR-2018 3512:30 2441	<b>01-JUN-2023 M</b>	
237121-001B	OPERATIONAL TEST OF THE COCKPIT VOICE RECORDER (CVR) UNDERWATER LOCATING DEVICE (ULD)								
23.065	068-E5542-00 ULB004405 REF: AMM 23 71 03 710 801	MOS HRS/MSC AFL	36	+1m/-1m			23-MAR-2018 3512:30 2441	<b>23-MAR-2021</b>	23-APR-2021
238101-001	NO. 1 RADIO TUNING UNIT (RTU4000) RTU								
23.070	622-9852-224 1VXTB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
238101-002	NO. 2 RADIO TUNING UNIT (RTU4000) RTU								
23.070	622-9852-224 1VXTC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 24</b>	<b>ELECTRICAL POWER</b>								
24-00-00-301 (s)	OPERATIONAL TEST (CYCLING) OF THE THERMAL CIRCUIT BREAKERS						PKG		
<b>OPTIONAL</b>	PKG 12 REF: AMM 24 00 00 710 801	MOS HRS/MSC AFL	12	+1m/-1m			08-MAY-2020 4328:45 2835		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-20-00-201 (s)	DISCARD NO. 1 IDG CHARGE (OIL-IN) FILTER ELEMENT PKG 2400	MOS					PKG 08-MAY-2020 4328:45 2835		
24.005 <b>LIFE LIMIT</b>	<b>REF:</b> See Workcard	HRS/MSC AFL	2400	+40/-40					
24-20-00-201	DISCARD NO. 2 IDG CHARGE (OIL-IN) FILTER ELEMENT	MOS					08-MAY-2020 4328:45 2835	<b>6728:45</b>	6768:45
<b>LIFE LIMIT</b>	<b>REF:</b>	HRS/MSC AFL	2400	+40/-40					
24-20-00-207	FUNCTIONAL TEST OF THE AIR DRIVEN GENERATOR (ADG) HEATER (A/C 5574, 5595 TO 5665, 5701 AND SUBS)	MOS	24	+1m/-1m		-63	08-MAY-2020 4328:45 2835	<b>06-MAR-2022</b> <b>5928:45</b>	06-APR-2022 5968:45
<b>MRB</b>	<b>REF:</b> AMM 24 23 01 720 801	HRS/MSC AFL	1600	+40/-40					
24-21-00-101	FUNCTIONAL TEST GCU OVERVOLTAGE PROTECTION CIRCUITS (CMR*) PKG 1600	MOS					08-MAY-2020 4328:45 2835	<b>5928:45</b>	
24.010	<b>REF:</b> AMM 24 20 00 720 801	HRS/MSC AFL	1600						
24-23-00-101	OPERATIONAL TEST AIR DRIVEN GENERATOR (ADG). (CMR*)	MOS	24				15-AUG-2019 3958 2666	<b>15-AUG-2021</b> <b>5558</b>	
24.015	<b>REF:</b> AMM 24 23 01 710 801	HRS/MSC AFL	1600						
24-26-60-602 (s)	OPERATIONAL TEST OF THE RESIDUAL CURRENT DEVICE PKG 12	MOS	12				08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	HRS/MSC AFL							
24-30-00-201 (s)	OPERATIONAL TEST TRANSFORMER RECTIFIER UNIT (TRU) FAN PKG 600	MOS					08-MAY-2020 4328:45 2835		
24.020	<b>REF:</b> AMM 24 31 01 710 802	HRS/MSC AFL	600	+40/-40					

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
24-30-00-202 (s)	FUNCTIONAL TEST MAIN BATTERY (CAPACITY CHECK) (MRB)						PKG		
24.140	024637-000 PKG 0 095020010A19F REF: AMM 24 32 01 720 801	MOS HRS/MSC AFL	6	+1m/-1m			12-DEC-2020 4614 2973		
24-30-00-203 (s)	FUNCTIONAL TEST APU BATTERY (CAPACITY CHECK) (MRB)						PKG		
24.145	024453-000 PKG 0 0905200229D95 REF: AMM 24 32 04 720 801	MOS HRS/MSC AFL	6	+1m/-1m			12-DEC-2020 4614 2973		
24-30-00-204 (s)	OPERATIONAL TEST DC ESSENTIAL BUS (MRB)						PKG		
24.025	PKG 800 REF: AMM 24 61 00 710 803	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
24-30-00-205 (s)	OPERATIONAL TEST LEFT AND RIGHT BATTERY BUSES						PKG		
24.030	PKG 1600 REF: AMM 24 61 00 710 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
24-30-00-206 (s)	OPERATIONAL TEST DC EMERGENCY BUS (MRB)						PKG		
24.035	PKG 800 REF: AMM 24 61 00 710 802	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
240004-001	AFT FUSE - ENGINE PYLON HARNESS								
	1697M51G03 LMD90051 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-MAR-2005 0 0		
240004-002	AFT FUSE - ENGINE PYLON HARNESS								
	1697M51G03 LMDW6412 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
240014-701	FREQUENCY CONVERTER 1-002-0102-1968 HT002498 <b>REF:</b>	MOS HRS/MSC AFL	O/C					13-JAN-2013 1974:30 1486	
240103-001	LH JB10 JUNCTION BOX 604-51423-1 05010325 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
240104-001	RH JB11 JUNCTION BOX 604-51423-3 05010328 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
240118-001	FREQUENCY/VOLTAGE SENSOR 600-59181-3 12348 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				04-JUL-2012 1854:30 1403		
241011-001	NO. 1 CONSTANT SPEED UNIT PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
241011-002	NO. 2 CONSTANT SPEED UNIT PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
241101-001	NO. 1 IDG GENERATOR 731579C 1291GEN5576 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
241101-001A (s)	DISCARD OF THE NO. 1 IDG SCAVENGE (OIL&#8722;OUT) FILTER ELEMENT						PKG		
24.055	731579C PKG 2400	MOS					08-MAY-2020		
<b>LIFE LIMIT</b>	1291GEN5576	HRS/MSC	2400	+40/-40			4328:45		
	<b>REF:</b> AMM 24 12 16 960 801	AFL					2835		
241101-002	NO. 2 IDG GENERATOR								
24.060	731579C	MOS		N:0			07-MAR-2005		
	1292GEN5577	HRS/MSC	O/C	N:0			0		
	<b>REF:</b> See Workcard	AFL		N:0			0		
241101-002A (s)	DISCARD OF NO. 2 THE IDG SCAVENGE (OIL&#8722;OUT) FILTER ELEMENT						PKG		
24.060	731579C PKG 2400	MOS					08-MAY-2020		
<b>LIFE LIMIT</b>	1292GEN5577	HRS/MSC	2400	+40/-40			4328:45		
	<b>REF:</b> AMM 24 12 16 960 801	AFL					2835		
241204-001	NO. 1 IDG OIL COOLER								
24.065	63E79-2	MOS		N:0			07-MAR-2005		
	1572	HRS/MSC	O/C	N:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		N:0			0		
241204-002	NO. 2 IDG OIL COOLER								
24.065	63E79-2	MOS		N:0			07-MAR-2005		
	1573	HRS/MSC	O/C	N:0			0		
	<b>REF:</b> GENERIC NO REF	AFL		N:0			0		
242104-001	NO. 1 GENERATOR CONTROL UNIT GCU								
24.070	720846D	MOS		N:0			07-MAR-2005		
	5371	HRS/MSC	O/C	N:0			0		
	<b>REF:</b> See Workcard	AFL		N:0			0		
242104-002	NO. 2 GENERATOR CONTROL UNIT GCU								
24.070	720846D	MOS		N:0			07-MAR-2005		
	5367	HRS/MSC	O/C	N:0			0		
	<b>REF:</b> See Workcard	AFL		N:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242104-003	APU GENERATOR CONTROL UNIT GCU								
24.070	720846D 5365 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242201-001	APU DRIVEN GENERATOR								
24.075	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242301-001	AIR DRIVEN GENERATOR								
24.080	604-90800-19 1568 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242301-002	ADG EJECTION JACK								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242301-003	AIR DRIVEN TURBINE ASSY								
24.085	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242310-001	AIR DRIVEN GENERATOR CONTROL								
24.015	604-90800-7 1540 REF: See Workcard	MOS HRS/MSC AFL	O/C				02-APR-2012 1770:30 1364		
242316-001	ADG, MANUAL DEPLOY CABLE								
24.095	601R90830-23 0467 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
242322-001	HAND AIR DRIVEN GENERATOR PUMP								
24.100	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242323-001	GENERATOR AIR DRIVEN RESTOW PUMP								
24.105	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242328-001	AIR DRIVEN GENERATOR UPLOCK								
24.110	604-90800-3 761345B REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
242334-001	AIR DRIVEN GENERATOR AUTO DEPLOY CONTROLLER								
24.115	600-59143-5 82046-5 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
243101-001	TRANSFORMER RECTIFIER (TRU) AC CONVERTER								
24.120	MS17976-2 04068677 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
243101-002	TRANSFORMER RECTIFIER (TRU) AC CONVERTER								
24.125	MS17976-2 04073386 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
243101-003	TRANSFORMER RECTIFIER (TRU) AC CONVERTER								
24.130	MS17976-2 04073387 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
243101-004	TRANSFORMER RECTIFIER (TRU) AC CONVERTER								
24.135	MS17976-2 04073393 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
243201-001	MAIN BATTERY								
24.140	024637-000 095020010A19F REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			23-MAR-2018 3512:30 2441		
243204-001	APU BATTERY								
24.145	024453-000 0905200229D95 REF: See Workcard	MOS HRS/MSC AFL	O/C				22-MAR-2019		
243204-701	SPARE MAIN BATTERY								
	024637-000 09052000E660A REF:	MOS HRS/MSC AFL	O/C						
243204-702	SPARE APU BATTERY								
	600-59151-11 121244 REF:	MOS HRS/MSC AFL	O/C				14-OCT-2011 1682:42 1282		
243207-001	MAIN BATTERY CHARGER								
24.150	N534-1802/100-0211-03 3598 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			27-OCT-2006 151:30 132		
243207-002	APU BATTERY CHARGER								
24.155	100-1084-01 1139130 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			04-APR-2019 3728:50 2552		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258065-706	SINGLE (RH#1) SEAT 6042520360-003 1672087 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
APU Model : GTCP36-100(E) (604-CIMMS) Serial # P-820 Part # 3800050-5-1									
24-20-00-203 (s)	APU - DISCARD APU GENERATOR ADAPTOR FILTER ELEMENT PKG 2400	MOS HRS/MSC	2400	+40/-40			08-MAY-2020 6583		
<b>LIFE LIMIT</b>	REF: AMM 24 22 04 960 801	APUS							
24-20-00-205 (s)	APU - DETAILED INSPECTION APU GENERATOR/ADAPTOR DRY CAVITY PKG 600	MOS HRS/MSC	600	+40/-40			08-MAY-2020 6583		
	REF: AMM 24 22 02 220 801	APUS							
<b>CHAPTER 25 EQUIPMENT/FURNISHINGS</b>									
233001-701	DIGITAL INTERFACE UNIT 920055 C02360796 REF:	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			05-OCT-2017 3307:10 2325		
233004-701	LAVATORY ORDINANCE SIGN 990-6104-280 05050019333 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
25-11-00-201 (s)	OPERATIONAL TEST OF THE INERTIAL REEL CONTROL AND INERTIAL REEL PKG 36	MOS HRS/MSC	36	+1m/-1m			26-MAR-2019 3702:35 2541		
25.005	REF: AMM 25 11 04 710 801	AFL							



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-11-00-202 (s)  25.010	INSPECT GENERAL VISUAL INSPECTION GENERAL VISUAL OF PILOT/COPILOT SEAT RESTRAINTS  PKG 36  <b>REF:</b> AMM 25 11 01 210 801	MOS HRS/MSC AFL	36	+1m/-1m			PKG  26-MAR-2019 3702:35 2541		
25-18-60-601 (s)  <b>STLMC</b>	GENERAL VISUAL INSPECTION OF THE JUMPSEAT RESTRAINTS  PKG 400  <b>REF:</b>	MOS HRS/MSC AFL	400				PKG  12-DEC-2020 4614 2973		
25-18-60-602 (s)  <b>STLMC</b>	OPERATIONAL TEST OF THE JUMPSEAT INERTIA REELS  PKG 400  <b>REF:</b>	MOS HRS/MSC AFL	400				PKG  12-DEC-2020 4614 2973		
25-18-60-603 (s)  <b>STLMC</b>	OPERATIONAL TEST OF THE JUMPSEAT TRACKING AND LOCKING MECHANISMS  PKG 400  <b>REF:</b>	MOS HRS/MSC AFL	400				PKG  12-DEC-2020 4614 2973		
25-21-60-601 (s)  <b>STLMC</b>	GENERAL VISUAL INSPECTION OF THE PASSENGER SEAT RESTRAINTS  PKG 800  <b>REF:</b>	MOS HRS/MSC AFL	800				PKG  08-MAY-2020 4328:45 2835		
25-21-60-602 (s)  <b>STLMC</b>	OPERATIONAL TEST OF THE PASSENGER SEAT INERTIA REELS  PKG 800  <b>REF:</b>	MOS HRS/MSC AFL	800				PKG  08-MAY-2020 4328:45 2835		
25-21-60-603 (s)  <b>STLMC</b>	OPERATIONAL TEST OF THE PASSENGER SEAT TRACKING AND LOCKING MECHANISMS  PKG 800  <b>REF:</b>	MOS HRS/MSC AFL	800				PKG  08-MAY-2020 4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-35-60-601 (s)	GENERAL VISUAL INSPECTION OF GALLEY WASTE CONTAINER PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
25-49-60-601 (s)	GENERAL VISUAL INSPECTION OF LAVATORY WASTE CONTAINER PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
25-60-00-202	DISCARD OF THE EMERGENCY LOCATOR TRANSMITTER UNIT (ELT) BATTERY 452-0133 375887-037	MOS					17-MAR-2018 3512:30 2441	<b>01-FEB-2023 M</b>	
25.060 <b>LIFE LIMIT</b>	<b>REF:</b> AMM 25 62 01 960 801	HRS/MSC AFL	DUE						
25-60-00-203 (s)	DETAILED INSPECTION EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY 452-0133 PKG 24 375887-037	MOS	24	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
<b>REF:</b> AMM 25 62 01 220 801	AFL								
25-60-60-601 (s)	GENERAL VISUAL INSPECTION OF THE LIFE VEST PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
25-60-60-603 (s)	GENERAL VISUAL INSPECTION OF THE SMOKE HOOD PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
25-60-60-605	GENERAL VISUAL INSPECTION OF THE FIRST AID / MEDICAL KITS (DO NOT OPEN IF SEALED) PKG 12	MOS	12				08-MAY-2020 4328:45 2835	<b>08-MAY-2021</b>	
<b>STLMC</b>	<b>REF:</b>	AFL							

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
25-60-60-606 (s)	GENERAL VISUAL INSPECTION OF THE EMERGENCY EXIT LIFE LINE PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
25-61-60-601 (s)	GENERAL VISUAL INSPECTION OF THE LIFE RAFT PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
25-62-AWL-9002	ELT ANTENNA -REMOVAL OF THE ELT ANTENNA AT FS710, RBL9 AND DETAILED VISUAL INSPECTION OF THE AIRCRAFT SKIN AROUND ANTENNA CUT-OUTS AND DOUBLER ATTACH RIVETS.	MOS					18-APR-2006 0 0	<b>7800</b>	
<b>STLMC</b>	<b>REF:</b>	AFL	7800						
25-63-60-601 (s)	GENERAL VISUAL INSPECTION OF THE PBE PKG 12	MOS	12				PKG 08-MAY-2020 4328:45 2835		
<b>STLMC</b>	<b>REF:</b>	AFL							
250001-701	FLIGHT DECK GREY CONTROLLER 922000-2 G02056116 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
250072-701	COCKPIT SUNVISOR RCL-600-601 M013799 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
251001-701	GALLEY JUMPSEAT J2000-1 (S) 28755 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
251101-001	PILOT SEAT								
25.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
251101-002	COPILOT SEAT								
25.055	604-40022-4 385-1406 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
251407-701	STORAGE BOX								
	TM432513-02-3 025 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
252026-701	CABIN TEMPERATURE CONTROLLER								
	990-8000-002 05010016593 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
253029-701	OVEN TIA HOR-MDL 1575 CONTROLLER								
	400-1377-01 05-03-36728 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
256037-701	LIFE (#3 DIVAN) VEST								
	63600-101 L2244905 REF:	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		
256037-701A	RESTORATION LIFE (#3 DIVAN) VEST (25-60-60-602)								
STLMC	63600-101 L2244905 REF:	MOS HRS/MSC AFL	120				01-AUG-2013	01-AUG-2023	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256037-702	LIFE (RH#1) VEST 63600-101 L2247404 REF:	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		
256037-702A	RESTORATION LIFE (RH#1) VEST (25-60-60-602) 63600-101 L2247404 REF:	MOS HRS/MSC AFL	120				01-AUG-2013	<b>01-AUG-2023</b>	
	<b>STLMC</b>								
256037-703	LIFE (RH#2) VEST 63600-101 L2244902 REF:	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		
256037-703A	RESTORATION LIFE (RH#2) VEST (25-60-60-602) 63600-101 L2244902 REF:	MOS HRS/MSC AFL	120				01-AUG-2013	<b>01-AUG-2023</b>	
	<b>STLMC</b>								
256037-704	LIFE (DIVAN FWD) VEST 63600-101 L2244906 REF:	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		
256037-704A	RESTORATION LIFE (DIVAN FWD) VEST (25-60-60-602) 63600-101 L2244906 REF:	MOS HRS/MSC AFL	120				01-AUG-2013	<b>01-AUG-2023</b>	
	<b>STLMC</b>								
256037-705	LIFE (DIVAN MID) VEST 63600-101 L2244900 REF:	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256037-705A	RESTORATION LIFE (DIVAN MID) VEST (25-60-60-602)								
	63600-101	MOS	120				01-AUG-2013	<b>01-AUG-2023</b>	
	L2244900	HRS/MSC							
<b>STLMC</b>	<b>REF:</b>	AFL							
256037-706	LIFE (DIVAN AFT) VEST								
	63600-101	MOS		N:10			20-APR-2015		
	L2571845	HRS/MSC	O/C	N:0			2495:55		
	<b>REF:</b>	AFL		N:0			1885		
256037-706A	RESTORATION LIFE (DIVAN AFT) VEST (25-60-60-602)								
	63600-101	MOS	120				01-JUN-2014	<b>01-JUN-2024</b>	
	L2571845	HRS/MSC							
<b>STLMC</b>	<b>REF:</b>	AFL							
256037-707	LIFE (LH#1) VEST								
	63600-101	MOS		N:20			20-APR-2015		
	L2244901	HRS/MSC	O/C	N:0			2495:55		
	<b>REF:</b>	AFL		N:0			1885		
256037-707A	RESTORATION LIFE (LH#1) VEST (25-60-60-602)								
	63600-101	MOS	120				01-AUG-2013	<b>01-AUG-2023</b>	
	L2244901	HRS/MSC							
<b>STLMC</b>	<b>REF:</b>	AFL							
256037-708	LIFE (LH#2) VEST								
	63600-101	MOS		N:20			20-APR-2015		
	L2247402	HRS/MSC	O/C	N:0			2495:55		
	<b>REF:</b>	AFL		N:0			1885		
256037-708A	RESTORATION LIFE (LH#2) VEST (25-60-60-602)								
	63600-101	MOS	120				01-AUG-2013	<b>01-AUG-2023</b>	
	L2247402	HRS/MSC							
<b>STLMC</b>	<b>REF:</b>	AFL							

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256037-709	LIFE (LH#3) VEST 63600-101 L2247406 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		
256037-709A	RESTORATION LIFE (LH#3) VEST (25-60-60-602) 63600-101 L2247406 <b>REF:</b>	MOS HRS/MSC AFL	120				01-AUG-2013	<b>01-AUG-2023</b>	
<b>STLMC</b>									
256037-710	LIFE (LH#4) VEST 63600-101 L2247403 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			20-APR-2015 2495:55 1885		
256037-710A	RESTORATION LIFE (LH#4) VEST (25-60-60-602) 63600-101 L2247403 <b>REF:</b>	MOS HRS/MSC AFL	120				01-AUG-2013	<b>01-AUG-2023</b>	
<b>STLMC</b>									
256089-701	FIRST AID KIT IFAK 081705020 <b>REF:</b>	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835	<b>01-APR-2021 M</b>	
256108-701	ELT NAV INTERFACE 455-6500 05212 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
256201-001	(ELT) EMERGENCY LOCATOR TRANSMITTER 453-5000-273 07312 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	O:1 O:0 O:0			17-MAR-2018 3512:30 2441		
25.060									

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256201-001B (s)  25.060	OPERATIONAL TEST OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM  453-5000-273 PKG 24 07312 <b>REF:</b> AMM 25 62 00 710 801	MOS HRS/MSC AFL	24	+1m/-1m			PKG  08-MAY-2020 4328:45 2835		
256201-001C (s)  <b>STLMC</b>	INSPECT (ELT) EMERGENCY LOCATOR TRANSMITTER THE ELT UNIT  453-5000-273 PKG 12 07312 <b>REF:</b>	MOS HRS/MSC AFL	12				PKG  08-MAY-2020 4328:45 2835		
256201-002  25.065	EMERGENCY LOCATOR TRANSMITTER (ELT) BATTERY  452-0133 375887-037 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	A/R	N:5 N:0 N:0			17-MAR-2018 3512:30 2441	<b>01-FEB-2023 M</b>	
256204-001  25.070	ELT ANTENNA  110-337 341027 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:36 N:0 N:0			17-MAR-2018 3512:30 2441		
256205-701	ARTEX ME406, PORTABLE EMERGENCY LOCATOR TRANSMITTER  453-6603 00906 <b>REF:</b>	MOS HRS/MSC AFL	O/C	O:26 O:816:15 O:394			08-MAY-2020 4328:45 2835		
256205-701A  <b>CUSTOMER CODE</b>	TEST ARTEX ME406, PORTABLE EMERGENCY LOCATOR TRANSMITTER FOR THE INTEGRITY OF THE ELT AND ANTENNA SYSTEM.  453-6603 00906 <b>REF:</b>	MOS HRS/MSC AFL	12				08-MAY-2020 4328:45 2835	<b>08-MAY-2021</b>	



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
256205-701B (s)	INSPECT ARTEX ME406, PORTABLE EMERGENCY LOCATOR TRANSMITTER FOR THE FOLLOWING; (1) PROPER INSTALLATION; (2) BATTERY CORROSION; (3) OPERATION OF THE CONTROLS AND CRASH SENSOR; AND (4) THE PRESENCE OF A SUFFICIENT SIGNAL RADIATED FROM ITS ANTENNA.						PKG		
	453-6603 PKG 12	MOS	12				08-MAY-2020		
<b>CUSTOMER CODE</b>	00906	HRS/MSC					4328:45		
	<b>REF:</b>	AFL					2835		
256206-701	ARTEX M406, PORTABLE EMERGENCY LOCATOR TRANSMITTER BATTERY PACK								
	455-0012	MOS	60	N:0			22-OCT-2016	<b>01-OCT-2023 M</b>	
	371258-046	HRS/MSC		N:0			2885:11		
<b>CUSTOMER CODE</b>	<b>REF:</b>	AFL		N:0			2100		
258065-701	SINGLE (LH#1) SEAT								
	6042520360-003	MOS		N:0			19-APR-2006		
	1672088-1	HRS/MSC	O/C	N:0			23:48		
	<b>REF:</b>	AFL		N:0			15		
258065-702	SINGLE (LH#2) SEAT								
	6042520360-001	MOS		N:0			19-APR-2006		
	1672085-0	HRS/MSC	O/C	N:0			23:48		
	<b>REF:</b>	AFL		N:0			15		
258065-703	SINGLE (LH#3) SEAT								
	6042520360-003	MOS		N:0			19-APR-2006		
	1672088-0	HRS/MSC	O/C	N:0			23:48		
	<b>REF:</b>	AFL		N:0			15		
258065-704	SINGLE (LH#4) SEAT								
	6042520360-001	MOS		N:0			19-APR-2006		
	1672085-1	HRS/MSC	O/C	N:0			23:48		
	<b>REF:</b>	AFL		N:0			15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258065-705	SINGLE (RH#1) SEAT 6042520360-002 1672169 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
258065-707	RH SIDE DIVAN 6042520362-103/01/5613 1888320 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
258082-701	PILOT (25-60-60-604) SMOKE HOOD MR-10008N P1500018 REF:	MOS HRS/MSC AFL	120	N:5 N:0 N:0			17-FEB-2016 2648:25 1991	<b>17-SEP-2025</b>	
258082-702	COPILOT (25-60-60-604) SMOKE HOOD MR-10008N P1500020 REF:	MOS HRS/MSC AFL	120	N:5 N:0 N:0			17-FEB-2016 2648:25 1991	<b>17-SEP-2025</b>	
258084-701	BREWER COFFEE MACHINE 400-1794-06 03-9-34305 REF:	MOS HRS/MSC AFL	O/C	R:9 R:0 R:0			14-NOV-2014 2408:05 1805		
258090-701	CD CHANGER 996-4712-001 05050019290 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
258289-701	AUDIO CVR MIXER 5020-1 3503 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
258413-701	SIDE WALL LH FWD TABLE 54900-28 22794 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
258413-702	SIDE WALL LH AFT TABLE 54900-28 22785 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
258413-703	SIDE WALL RH FWD TABLE 54900-28 22787 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
258609-701	MONITOR REMOTE BOX 990-4166-102 05120024124 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259000-701	LDC 18" (LH FWD BULKHEAD 350) MONITOR- 990-1810-112 05080020625 REF:	MOS HRS/MSC AFL	O/C	N:53 N:1392:42 N:1059			17-SEP-2010 1416:30 1074		
259000-702	LDC 18" (AFT BULKHEAD) MONITOR- 990-4156-101 03010000381 REF:	MOS HRS/MSC AFL	O/C	N:53 N:1392:42 N:1059			17-SEP-2010 1416:30 1074		
259106-701	VCR (DIVAN END) PLAYER 990-4719-001 05050019291 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259174-701	ANNUNCIATOR SWITCH (FS280.00) PANEL 990-4157-153 05050019201 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259175-701	LAVATORY CALL SWITCH PANEL 990-6101-522 05050019215 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259176-701	LAVATORY FLUSH SWITCH PANEL 990-6101-524 05050019217 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259177-701	JUMPSEAT SWITCH PANEL 990-6101-523 05050019216 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259178-701	LAVATORY BAGGAGE SWITCH PANEL 990-6104-200 05050019220 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259179-701	MASTER SEAT PANEL 990-6306-076 05050019235 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259180-701	GALLEY SWITCH PANEL 990-6404-051 05050019241 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259183-701	AIRSTAIR SWITCH PANEL 990-6101-521 05050019199 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259184-701	ENTERTAINMENT CABINET SWITCH PANEL 990-6206-106 05050019234 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259184-702	SWITCH (FS408.00 LH) PANEL 990-6109-247 05050019227 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259184-703	SWITCH (FS513.00 LH) PANEL 990-6109-247 05050019228 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259185-701	SWITCH (FS392.00 RH) PANEL 990-6109-247 05050019226 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259185-702	SWITCH (FS408.00 RH) PANEL 990-6109-248 05050019230 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259185-703	SWITCH (FS484.00 LH) PANEL 990-6109-248 05050019231 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259185-704	SWITCH (FS392.00 LH) PANEL 990-6109-248 05050019229 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259186-701	SWITCH PANEL 990-6108-203 05050019225 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259186-702	SWITCH (FS480.00 RH) PANEL 990-6108-202 05050019221 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259186-703	SWITCH (FS499.00 RH) PANEL 990-6108-202 05050019222 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259188-701	LH FS513 SUBWOOFER EN-602W-8P 050500257 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259188-702	RH FS370 SUBWOOFER EN-602W-8P 050500252 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259262-701	HEAD TOW BAR WY602 3365 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259263-701	TOW BAR WY501-2 3364 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259273-701	DVD (DIVAN END) PLAYER 996-4720-001 08080051795 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			09-OCT-2008 796:15 627		
259304-701	PASSENGER ADDRESS/ENTERTAINMENT (CABIN) CONTROLLER 990-6812-001 05050019262 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259304-702	AUDIO/VIDEO MONITORING (LOWER GALLEY) CONTROLLER 990-6812-001 05050019261 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259306-701	INFRARED RECEIVER (LH DADO STA 361) MODULE 990-6913-001 05050018949 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259319-701	AUDIO/VIDEO MONITORING (LOWER GALLEY) INTERFACE UNIT 990-6820-001 05050018754 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259506-701	MHR SENSOR FWD BULKHEAD - IR SENSOR 990-4131-001 05030017942 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259506-702	MHR SENSOR AFT BULKHEAD - IR SENSOR 990-4131-001 05030017941 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259641-701	AUDIO/ VIDEO AMPLIFIER 990-3063-005 05030017326 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259715-701	TIA MODEL 1545-5 OVEN 400-1398-01-LN 05-03-36706 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:59 R:0 N:1527:42 R:0 N:1179 R:0			30-MAR-2011 1551:30 1194		
259722-701	MICROWAVE OVEN R-242DC-W 040912275 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259782-701	ENTERTAINMENT CONTROLLER 990-6800-004 05050019259 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-701	WINDOW (BEHIND GALLEY) SHADE CH-01-010-D2 2405 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-702	WINDOW LH#1 SHADE CH-01-015 2397 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259800-703	WINDOW LH#2 SHADE CH-01-015 2395 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-704	WINDOW LH#3 SHADE CH-01-015 2400 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-705	WINDOW LH#4 SHADE CH-01-015 2401 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-706	WINDOW LH#5 SHADE CH-01-015 2399 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-707	WINDOW LH#6 SHADE CH-01-015 2391 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-708	WINDOW LH#7 SHADE CH-01-015 2398 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-709	WINDOW RH#1 SHADE CH-01-015 2396 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259800-710	WINDOW RH#2 SHADE CH-01-015 2403 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-711	WINDOW RH#3 SHADE CH-01-015 2402 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-712	WINDOW RH#5 SHADE CH-01-015 2392 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-713	WINDOW RH#6 SHADE CH-01-015 2394 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-714	WINDOW RH#7 SHADE CH-01-015 2393 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259800-715	WINDOW (EMERGENCY EXIT DOOR) SHADE CH-01-015E 2404 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
259956-701	LIFE RAFT 1320FASA-6J2-1-127 13UL-00533 REF:	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			08-MAY-2020 4328:45 2835		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259956-701A	RESTORATION LIFE RAFT (25-61-60-602) 1320FASA-6J2-1-127 13UL-00533 <b>REF:</b>	MOS HRS/MSC AFL	36				08-MAY-2020 4328:45 2835	<b>31-JAN-2023 M</b>	
<b>STLMC</b>									
259956-701B	REPLACEMENT LIFE RAFT ELT BATTERY 1320FASA-6J2-1-127 13UL-00533 <b>REF:</b>	MOS HRS/MSC AFL	DUE				03-APR-2017 3041:45 2185	<b>31-JAN-2023 M</b>	
259956-702	LIFE RAFT 1320FASA-6J2-1-127 13UL-00535 <b>REF:</b>	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			08-MAY-2020 4328:45 2835		
259956-702A	RESTORATION LIFE RAFT (25-61-60-602) 1320FASA-6J2-1-127 13UL-00535 <b>REF:</b>	MOS HRS/MSC AFL	36				08-MAY-2020 4328:45 2835	<b>31-JAN-2023 M</b>	
<b>STLMC</b>									
259956-702B	REPLACEMENT LIFE RAFT ELT BATTERY 1320FASA-6J2-1-127 13UL-00535 <b>REF:</b>	MOS HRS/MSC AFL	DUE				03-APR-2017 3041:45 2185	<b>31-JAN-2023 M</b>	
259964-701	PILOT LIFE (CREW) VEST 63600-501 L667323 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:7 N:0 N:0			20-APR-2015 2495:55 1885		
259964-701A	RESTORATION PILOT LIFE (CREW) VEST (25-60-60-602) 63600-501 L667323 <b>REF:</b>	MOS HRS/MSC AFL	120				01-SEP-2014	<b>01-SEP-2024</b>	
<b>STLMC</b>									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
259964-702	COPILOT LIFE (CREW) VEST 63600-501 L2667328 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:7 N:0 N:0			20-APR-2015 2495:55 1885		
259964-702A	RESTORATION COPILOT LIFE (CREW) VEST (25-60-60-602) 63600-501 L2667328 <b>REF:</b>	MOS HRS/MSC AFL	120				01-SEP-2014	<b>01-SEP-2024</b>	
<b>STLMC</b>									
259964-703	JUMPSEAT LIFE (CREW) VEST 63600-501 L2667329 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:7 N:0 N:0			20-APR-2015 2495:55 1885		
259964-703A	RESTORATION JUMPSEAT LIFE (CREW) VEST (25-60-60-602) 63600-501 L2667329 <b>REF:</b>	MOS HRS/MSC AFL	120				01-SEP-2014	<b>01-SEP-2024</b>	
<b>STLMC</b>									
383000-701	TOILET 4620-108-1 0027 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
<b>CHAPTER 26 FIRE PROTECTION</b>									
26-13-04-201 (s)	VISUAL CHECK MAIN LANDING GEAR SENSING ELEMENT PKG 1200	MOS					PKG 08-MAY-2020		
26.005	<b>REF:</b> AMM 26 13 04 210 801	HRS/MSC AFL	1200	+40/-40			4328:45 2835		
26-13-04-202 (s)	FUNCTIONAL TEST MAIN LANDING GEAR SENSING ELEMENT PKG 3200	MOS					PKG 03-APR-2017		
26.010	<b>REF:</b> AMM 26 13 04 720 801	HRS/MSC AFL	3200	+40/-40			3041:45 2185		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-20-00-204 (s) 26.015	FUNCTIONAL TEST ENGINE FIRE SHUTOFF-RELAY CIRCUITRY PKG 2400 <b>REF:</b> AMM 26 20 00 720 801	MOS HRS/MSC AFL	2400	+40/-40			PKG 08-MAY-2020 4328:45 2835		
26-20-00-205  <b>MRB</b>	FUNCTIONAL TEST (WEIGHT CHECK) COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE 30H673 PKG 24 G-04698942 <b>REF:</b> AMM 26 23 01 720 802	MOS HRS/MSC AFL	24	+1m/-1m		-46	PKG	? ?	
26-20-00-207 26.065	DETAILED INSPECTION OF THE NO. 1 ENGINE FIRE EXTINGUISHER CONTAINERS (MRB) 601-65910-13 65544 <b>REF:</b> AMM 26 20 00 220 803	MOS HRS/MSC AFL	60	+1m/-1m			18-MAR-2019 3702:35 2541	<b>18-MAR-2024</b>	18-APR-2024
26-20-00-207 26.070	DETAILED INSPECTION OF THE NO. 2 ENGINE FIRE EXTINGUISHER CONTAINERS (MRB) 601-65910-13 ACX9740 <b>REF:</b> AMM 26 20 00 220 803	MOS HRS/MSC AFL	60	+1m/-1m			18-MAR-2019 3702:35 2541	<b>18-MAR-2024</b>	18-APR-2024
26-20-00-208 26.095	DETAILED INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE (MRB) 30H673 G-04698942 <b>REF:</b> AMM 26 20 00 220 804	MOS HRS/MSC AFL	96	+2m/-2m				? ?	
26-20-00-209 26.075	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) FIRE-EXTINGUISHER CONTAINER (MRB) 897889-2 2435T <b>REF:</b> AMM 26 20 00 220 805	MOS HRS/MSC AFL	60	+1m/-1m			18-MAR-2019 3702:35 2541	<b>18-MAR-2024</b>	18-APR-2024
26-21-00-201 (s) 26.020	FUNCTIONAL TEST OF THE BOTTLE 1 AND BOTTLE 2 ARMED PUSH TO DISCH SWITCH/LIGHTS PKG 4800 <b>REF:</b> AMM 26 21 00 720 802	MOS HRS/MSC AFL	4800	+40/-40			PKG 08-MAY-2020 4328:45 2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
26-21-16-201 (s)	DETAILED INSPECTION OF THE FIRE-EXTINGUISHING SYSTEM LINES						PKG		
26.030	PKG 48 REF: AMM 26 20 00 220 802	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
26-22-00-201 (s)	FUNCTIONAL TEST APU FIRE EXTINGUISHING SYSTEM						PKG		
26.035	PKG 4800 REF: AMM 26 22 00 720 801	MOS HRS/MSC AFL	4800	+40/-40			08-MAY-2020 4328:45 2835		
261113-001	EXHAUST FIRE DETECTION CONTROL								
26.040	377-02836 0450-252 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
261113-002	EXHAUST FIRE DETECTION CONTROL								
26.045	377-02836 0426-143 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
261119-001	NO. 1 ENGINE FIRE DETECTION CONTROL								
26.050	377-02836 0450-272 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
261119-002	NO. 2 ENGINE FIRE DETECTION CONTROL								
26.050	377-02836 0450-261 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
261204-001	APU FIRE DETECTION CONTROL								
26.055	377-02836 0450-282 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
261301-001	MAIN LANDING GEAR FIRE DETECTION CONTROL								
26.060	377-02836 5401U REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
261401-701	AFT LAVATORY SMOKE DETECTOR								
	473597-2 1131 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-MAR-2011 1551:30 1194		
261401-701A	RESTORE AFT LAVATORY SMOKE DETECTOR SMOKE DETECTOR (26-10-60-601)								
STLMC	473597-2 1131 REF:	MOS HRS/MSC AFL	60				08-APR-2016 2660:45 1999	<b>08-APR-2021</b>	
261401-702	BAGGAGE SMOKE DETECTOR								
	473597-2 1132 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			30-MAR-2011 1551:30 1194		
261401-702A	RESTORE BAGGAGE SMOKE DETECTOR SMOKE DETECTOR (26-10-60-601)								
STLMC	473597-2 1132 REF:	MOS HRS/MSC AFL	60				08-APR-2016 2660:45 1999	<b>08-APR-2021</b>	
262104-001	NO. 1 FIRE EXTINGUISHER ENGINE BOTTLE								
26.065	601-65910-13 65544 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-MAR-2019 3702:35 2541		
262104-001B (s)	DETAILED INSPECTION OF THE NO. 1 ENGINE FIRE EXTINGUISHER-BOTTLE PRESSURE GAUGE								
26.065	601-65910-13 PKG 24 65544 REF: AMM 26 21 04 220 802	MOS HRS/MSC AFL	24	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262104-002	NO. 2 FIRE EXTINGUISHER ENGINE BOTTLE								
26.070	601-65910-13 ACX9740 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-MAR-2019 3702:35 2541		
262104-002B (s)	DETAILED INSPECTION OF THE NO. 2 ENGINE FIRE-EXTINGUISHER-BOTTLE PRESSURE GAUGE						PKG		
26.070	601-65910-13 PKG 24 ACX9740 REF: AMM 26 21 04 220 802	MOS HRS/MSC AFL	24	+1m/-1m			08-MAY-2020 4328:45 2835		
262204-001	APU FIRE EXTINGUISHER BOTTLE								
26.075	897889-2 2435T REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				18-MAR-2019 3702:35 2541		
262204-001B (s)	DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU)FIRE-EXTINGUISHER-BOTTLE PRESSURE GAUGE.						PKG		
26.075	897889-2 PKG 24 2435T REF: AMM 26 22 04 220 802	MOS HRS/MSC AFL	24	+1m/-1m			08-MAY-2020 4328:45 2835		
262207-001	LEFT NO.1 FIRE EXTINGUISHER CARTRIDGE								
26.080	897776-01 36197 REF: AMM 26 20 00 000 801	MOS HRS/MSC AFL	120		N:5 N:0 N:0		20-APR-2015 2495:55 1885	<b>20-NOV-2024</b>	
<b>LIFE LIMIT</b>									
262207-002	LEFT NO.2 FIRE EXTINGUISHER CARTRIDGE								
26.085	897776-01 36245 REF: AMM 26 20 00 000 801	MOS HRS/MSC AFL	120		N:5 N:0 N:0		20-APR-2015 2495:55 1885	<b>20-NOV-2024</b>	
<b>LIFE LIMIT</b>									
262207-003	RIGHT NO.1 FIRE EXTINGUISHER CARTRIDGE								
26.080	897776-01 38965 REF: AMM 26 20 00 000 801	MOS HRS/MSC AFL	120				18-MAR-2019 3702:35 2541	<b>28-MAR-2028 M</b>	
<b>LIFE LIMIT</b>									



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262207-004	RIGHT NO.2 FIRE EXTINGUISHER CARTRIDGE 897776-01 26.085 LIFE LIMIT	MOS HRS/MSC AFL	120				18-MAR-2019 3702:35 2541	28-MAR-2028 M	
262207-005	APU FIRE EXTINGUISHER CARTRIDGE 897776-01 26.090 LIFE LIMIT	MOS HRS/MSC AFL	120				18-MAR-2019 3702:35 2541	28-MAR-2028 M	
262301-001	COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE 30H673 26.095 G-04698942 REF: See Workcard	MOS HRS/MSC AFL	O/C				12-DEC-2020 4614 2973		
262301-001B (s)	WEIGHT CHECK COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE (26-20-60-603) 30H673 PKG 12 G-04698942 STLMC REF:	MOS HRS/MSC AFL	12					PKG	
262301-001C	MAINTENANCE COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE PER NFPA-10 (CMM PARAGRAPH 5.D) 30H673 G-04698942 REF:	MOS HRS/MSC AFL	72					? ?	
262301-001D (s)	VISUAL INSPECTION COCKPIT PORTABLE FIRE EXTINGUISHER BOTTLE PER CMM PARAGRAPH 5.B 30H673 PKG 0 G-04698942 REF:	MOS HRS/MSC AFL	6					PKG	
262301-002	LH WARDROBE FIRE EXTINGUISHER PROTABLE BOTTLE 100-9750N 001227C REF:	MOS HRS/MSC AFL	O/C	N:188 O:0 O:0 O:0			05-OCT-2017 3307:10 2325		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262301-002A	FUNCTIONAL TEST (HYDROSTATIC TEST) LH WARDROBE FIRE EXTINGUISHER PROTABLE BOTTLE (26-20-60-604) 100-9750N 001227C <b>REF:</b>	MOS HRS/MSC AFL	144				01-JUL-2013	<b>01-JUL-2025</b>	
<b>STLMC</b>									
262301-002B (s)	WEIGHT CHECK LH WARDROBE FIRE EXTINGUISHER PROTABLE BOTTLE (26-20-60-603) 100-9750N PKG 12 001227C <b>REF:</b>	MOS HRS/MSC AFL	12				08-MAY-2020 4328:45 2835		
<b>STLMC</b>									
262301-002C	MAINTENANCE LH WARDROBE FIRE EXTINGUISHER PROTABLE BOTTLE PER NFPA-10 (CMM PARAGRAPH 5. D) 100-9750N 001227C <b>REF:</b>	MOS HRS/MSC AFL	72				05-OCT-2017 3307:10 2325	<b>05-OCT-2023</b>	
262301-002D (s)	VISUAL INSPECTION LH WARDROBE FIRE EXTINGUISHER PROTABLE BOTTLE PER CMM PARAGRAPH 5.B 100-9750N PKG 0 001227C <b>REF:</b>	MOS HRS/MSC AFL	6				12-DEC-2020 4614 2973		
262301-003	SMALL CABINET FIRE EXTINGUISHER PROTABLE BOTTLE 466090A B71138353 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-OCT-2016 2885:11 2100		
262301-003A	FUNCTIONAL TEST (HYDROSTATIC TEST) SMALL CABINET FIRE EXTINGUISHER PROTABLE BOTTLE (26-20-60-604) 466090A B71138353 <b>REF:</b>	MOS HRS/MSC AFL	144				22-OCT-2016 2885:11 2100	<b>01-APR-2028 M</b>	
<b>STLMC</b>									
262301-003B (s)	WEIGHT CHECK SMALL CABINET FIRE EXTINGUISHER PROTABLE BOTTLE (26-20-60-603) 466090A PKG 12 B71138353 <b>REF:</b>	MOS HRS/MSC AFL	12				08-MAY-2020 4328:45 2835		
<b>STLMC</b>									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
262301-004	SMALL CABINET PORTABLE FIRE EXTINGUISHER BOTTLE 466090A B711383346 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-OCT-2016 2885:11 2100		
262301-004A	FUNCTIONAL TEST (HYDROSTATIC TEST) SMALL CABINET PORTABLE FIRE EXTINGUISHER BOTTLE (26-20-60-604) 466090A B711383346 <b>REF:</b>	MOS HRS/MSC AFL	144				22-OCT-2016 2885:11 2100	<b>01-APR-2028 M</b>	
262301-004B (s)	WEIGHT CHECK SMALL CABINET PORTABLE FIRE EXTINGUISHER BOTTLE (26-20-60-603) 466090A PKG 12 B711383346 <b>REF:</b>	MOS HRS/MSC AFL	12				08-MAY-2020 4328:45 2835		
262301-005	BULKHEAD 350 PORTABLE WATER FIRE EXTINGUISHER BOTTLE 892480 16707 <b>REF:</b>	MOS HRS/MSC AFL	O/C				17-SEP-2010 1416:30 1074		
262301-005B (s)	WEIGHT CHECK BULKHEAD 350 PORTABLE WATER FIRE EXTINGUISHER BOTTLE 892480 PKG 12 16707 <b>REF:</b>	MOS HRS/MSC AFL	12				08-MAY-2020 4328:45 2835		
<b>CHAPTER 27 FLIGHT CONTROLS</b>									
27-00-00-201 (s)	DETAILED INSPECTION OF THE AILERON, RUDDER, ELEVATOR AND SPOILER CONTROL CABLES IN THE LOWER FORWARD FUSELAGE PKG 48	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27.005	<b>REF:</b> AMM 27 00 00 220 801								

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-202 (s)	DETAILED INSPECTION OF THE AILERON, RUDDER, ELEVATOR AND SPOILER CONTROL CABLES IN THE MAIN AVIONICS COMPARTMENT						PKG		
27.010	PKG 48 <b>REF:</b> AMM 27 00 00 220 802	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27-00-00-203 (s)	DETAILED INSPECTION OF THE AILERON AND SPOILER CONTROL CABLES IN THE MAIN LANDING GEAR (MLG) WHEEL WELL						PKG		
27.015	PKG 48 <b>REF:</b> AMM 27 00 00 220 803	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27-00-00-204 (s)	DETAILED INSPECTION OF THE AILERON, RUDDER, ELEVATOR AND SPOILER CONTROL CABLES IN THE MID-LOWER FUSELAGE						PKG		
27.020	PKG 96 <b>REF:</b> AMM 27 00 00 220 804	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
27-00-00-205 (s)	DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE LOWER MID-FUSELAGE COMPARTMENT						PKG		
27.025	PKG 96 <b>REF:</b> AMM 27 00 00 220 805	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
27-00-00-206 (s)	DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE AFT EQUIPMENT COMPARTMENT						PKG		
27.030	PKG 24 <b>REF:</b> AMM 27 00 00 220 806	MOS HRS/MSC AFL	24	+1m/-1m			08-MAY-2020 4328:45 2835		
27-00-00-207 (s)	DETAILED INSPECTION OF THE ELEVATOR CONTROL CABLES IN THE VERTICAL STAB						PKG		
27.035	PKG 96 <b>REF:</b> AMM 27 00 00 220 807	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-00-00-208 (s)	DETAILED INSPECTION OF THE RUDDER AND ELEVATOR CONTROL CABLES IN THE FUSELAGE/STABILIZER SECTION.						PKG		
27.040	PKG 48 REF: AMM 27 00 00 220 808	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27-00-00-209 (s)	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE OUTBOARD WING BOX						PKG		
27.045	PKG 48 REF: AMM 27 11 00 220 811	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27-00-00-210 (s)	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE INBOARD TRAILING EDGE						PKG		
27.050	PKG 36 REF: AMM 27 11 00 220 812	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
27-00-00-211 (s)	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN THE OUTBOARD TRAILING EDGE						PKG		
27.055	PKG 36 REF: AMM 27 11 00 220 813	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
27-00-00-212 (s)	DETAILED INSPECTION OF THE AILERON CONTROL CABLES IN CONTROL COLUMN						PKG		
27.060	PKG 48 REF: AMM 27 11 00 220 814	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27-10-00-204 (s)	OPERATIONAL TEST AILERON ANTIFLOAT MECHANISM						PKG		
27.065	PKG 800 REF: AMM 27 15 04 710 801	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
27-13-04-101	OPERATIONAL TEST ROLL DISCONNECT SYSTEM (CMR*)								
27.070	PKG 800 REF: AMM 27 13 04 710 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	<b>5128:45</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-14-01-101  27.075	FUNCTIONAL TEST AILERON POWER CONTROL UNITS (PCUS) (CMR**) PKG 800 REF: AMM 27 14 01 720 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	
27-20-00-201 (s)  27.080	GENERAL VISUAL INSPECTION OF THE SINGLE RUDDER CONTROL PATH PKG 4800 REF: AMM 27 21 00 210 801	MOS HRS/MSC AFL	4800	+40/-40			08-MAY-2020 4328:45 2835		
27-20-00-204 (s)  27.085	FUNCTIONAL TEST LOAD LIMITER (IN VERT/STAB) TRAVELS PKG 4800 REF: AMM 27 21 25 720 801	MOS HRS/MSC AFL	4800	+40/-40			08-MAY-2020 4328:45 2835		
27-21-00-101  27.090	FUNCTIONAL TEST RUDDER BACKLASH (CMR**) PKG 800 REF: AMM 27 21 00 720 805	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	
27-21-25-201 (s)  27.095	GENERAL VISUAL INSPECTION OF THE RUDDER BALANCE SPRING PKG 1600 REF: AMM 27 21 00 210 804	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
27-23-00-101  27.095	OPERATIONAL TEST PCU LOAD LIMITERS (CMR**) PKG 3200 REF: AMM 27 21 25 710 801	MOS HRS/MSC AFL	3200				03-APR-2017 3041:45 2185	6241:45	
27-30-00-202 (s)  27.100	GENERAL VISUAL INSPECTION ELEVATOR POWER-CONTROL-UNIT (PCU) CENTERING SPRING PKG 1200 REF: AMM 27 33 01 210 801	MOS HRS/MSC AFL	1200	+40/-40			08-MAY-2020 4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-30-00-209 (s) 27.105	OPERATIONAL TEST ELEVATOR JAM-TOLERANT MECHANISM PKG 3200 <b>REF:</b> AMM 27 31 19 710 801	MOS HRS/MSC AFL	3200	+40/-40			PKG 03-APR-2017 3041:45 2185		
27-30-00-210 (s) 27.110	OPERATIONAL TEST LOAD LIMITER (VERTICAL STABILIZER) PKG 3200 <b>REF:</b> AMM 27 31 16 710 801	MOS HRS/MSC AFL	3200	+40/-40			PKG 03-APR-2017 3041:45 2185		
27-32-00-101 27.115	OPERATIONAL TEST ELEVATOR DISCONNECT SYSTEM (CMR*) PKG 800 <b>REF:</b> AMM 27 32 00 710 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	<b>5128:45</b>	
27-33-01-101 27.120	FUNCTIONAL TEST ELEVATOR BACKLASH (CMR*) PKG 800 <b>REF:</b> AMM 27 31 00 720 805	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	<b>5128:45</b>	
27-33-01-201 (s)	GENERAL VISUAL INSPECTION OF THE ELEVATOR BALANCE SPRINGS PKG 4800 <b>REF:</b> AMM 27 31 00 210 801	MOS HRS/MSC AFL	4800	+40/-40			PKG 08-MAY-2020 4328:45 2835		
27-35-00-201 (s) 27.125	OPERATIONAL TEST STALL WARNING COMPUTER FOR SINGLE CHANNEL OF STALL PROTECTION COMPUTER 600-59152-35 PKG 800 M3903 <b>REF:</b> AMM 27 35 01 710 801	MOS HRS/MSC AFL	800	+40/-40			PKG 08-MAY-2020 4328:45 2835		
27-35-00-202 (s) 27.125	OPERATIONAL TEST STALL WARNING COMPUTER FOR DUAL CHANNEL OF STALL PROTECTION COMPUTER 600-59152-35 PKG 800 M3903 <b>REF:</b> AMM 27 35 01 710 802	MOS HRS/MSC AFL	800	+40/-40			PKG 08-MAY-2020 4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-35-01-103	FUNCTIONAL TEST STALL PROTECTION SYSTEM (SPS) FLAP INPUT (A/C 5301 TO 5560 PRE SB 604-27-005) - (CMR*)								
27.130	REF: AMM 27 35 01 720 801	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
27-35-01-104	FUNCTIONAL TEST PHASE ADVANCE AND SIDESLIP COMPENSATION (A/C 5301 TO 5560 PRE SB 604-27-005) - (CMR*)								
27.135	REF: AMM 27 35 01 720 802	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
27-35-01-105	FUNCTIONAL TEST FLAP AND SIDESLIP COMPENSATION MONITOR OF THE STALL PROTECTION COMPUTER (A/C 5561 AND SUBS AND 5301 TO 5560 POST SB 604-27-005) (CMR**)								
27.140	PKG 4800 REF: AMM 27 35 01 720 803	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	9128:45	
27-35-10-101	FUNCTIONAL TEST FOR THE STALL PROTECTION SYSTEM (SPS) STICK PUSHER CAPSTAN SHAFT, PART NO. 600-59156-7 (VENDOR PART NO. 501-1258-01). (CMR**)								
CMR	REF: AMM 27 35 13 720 801	MOS HRS/MSC AFL	1600	+40			08-MAY-2020 4328:45 2835	5928:45	5968:45
27-40-00-202 (s)	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER TRIM-ACTUATOR ASSY								
27.145	PKG 48 REF: AMM 27 42 01 220 801	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
27-40-00-204 (s)	LUBRICATION OF THE HORIZONTAL STABILIZER PITCH TRIM ACTUATOR								
27.155	PKG 48 REF: AMM 12 20 04 640 817	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-40-00-205 (s)	OPERATIONAL TEST PITCH TRIM SWITCH						PKG		
27.160	PKG 800 REF: AMM 27 41 04 710 801	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
27-40-00-206 (s)	OPERATIONAL TEST HORIZONTAL STABILIZER TRIM SYSTEM						PKG		
27.165	PKG 800 REF: AMM 27 40 00 710 801	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
27-41-00-101 (s)	OPERATIONAL TEST (BITE) OF THE HORIZONTAL-STABILIZER TRIM-CONTROL SYSTEM (HSTCS) (CMR**)						PKG		
	PKG 600 REF: AMM 27 41 00 740 801	MOS HRS/MSC AFL	640				08-MAY-2020 4328:45 2835		
27-42-01-102	SPECIAL DETAILED INSPECTION OF THE UPPER AND LOWER HORIZONTAL STABILIZER TRIM ACTUATOR PINS								
<b>AIRWORTHINESS</b>	REF:	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	<b>7800</b>	
+ 27-42-01-108	DISCARD OF THE L/H LOWER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT; PART NO. 601R92386-1/-3								
	601R92386-1 12-5613-A REF: AMM 27 42 01 961 801	MOS HRS/MSC AFL	20000	I:2304:15 I:1731			16-JUN-2014 2304:15 1731	<b>20000</b>	
<b>LIFE LIMIT</b>									
+ 27-42-01-108	DISCARD OF THE L/H UPPER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT; PART NO. 601R92386-1/-3								
	601R92386-1 11-5613-A REF: AMM 27 42 01 961 801	MOS HRS/MSC AFL	20000	I:2304:15 I:1731			16-JUN-2014 2304:15 1731	<b>20000</b>	
<b>LIFE LIMIT</b>									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 27-42-01-108	DISCARD OF THE R/H LOWER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT; PART NO. 601R92386-1/-3  601R92386-1 22-5613-A <b>REF:</b> AMM 27 42 01 961 801	MOS HRS/MSC AFL		I:2304:15 I:1731			16-JUN-2014 2304:15 1731		<b>20000</b>
<b>LIFE LIMIT</b>			20000						
+ 27-42-01-108	DISCARD OF THE R/H UPPER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT; PART NO. 601R92386-1/-3  601R92386-1 21-5613-A <b>REF:</b> AMM 27 42 01 961 801	MOS HRS/MSC AFL		I:2304:15 I:1731			16-JUN-2014 2304:15 1731		<b>20000</b>
<b>LIFE LIMIT</b>			20000						
27-42-01-109	RESTORATION HORIZONTAL STABILIZER TRIM ACTUATOR (OVERHAUL) OF THE HORIZONTAL STABILIZER TRIM ACTUATOR, PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS)  604-92305-7 633 <b>REF:</b>	MOS HRS/MSC AFL	9600 8420	I:1919 I:751			16-JUN-2014 2304:15 1731	<b>9985:15</b> <b>9400</b>	
<b>OVERHAUL</b>									
27-42-01-110	SPECIAL DETAILED INSPECTION HORIZONTAL STABILIZER TRIM ACTUATOR OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA), PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS)  604-92305-7 633 <b>REF:</b>	MOS HRS/MSC AFL	120				16-JUN-2014	<b>16-JUN-2024</b>	
<b>LIFE LIMIT</b>									
27-42-01-111	DETAILED INSPECTION HORIZONTAL STABILIZER TRIM ACTUATOR OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) SECONDARY LOAD PATH INDICATOR, PART NO. 604-92305-7 AND SUBS (VENDOR PART NO. 8454-3 AND SUBS)  604-92305-7 633 <b>REF:</b>	MOS HRS/MSC AFL	5000				16-JUN-2014 2304:15 1731	<b>7304:15</b>	
<b>LIFE LIMIT</b>									
27-42-01-113	RESTORATION OF THE HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA), PART NO. 604-92305-9 (CMR*)  604-92305-7 633 <b>REF:</b> AMM 27 42 01 840 801	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
<b>LIFE LIMIT</b>									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-50-00-201 (s) 27.175	FUNCTIONAL TEST ASYMMETRY/OVERSPEED DETECTOR AND BRAKE UNIT (MRB) PKG 800 REF: AMM 27 51 07 720 801	MOS HRS/MSC AFL	800	+40/-40			PKG 08-MAY-2020 4328:45 2835		
27-50-00-203 (s) 27.180	LUBRICATION OF THE BALL NUT OF THE FLAP ACTUATORS PKG 12 REF: AMM 12 20 04 640 813	MOS HRS/MSC AFL	12	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
27-50-00-205 (s) 27.185	LUBRICATION OF THE FLAP VANE ACTUATOR RODS PKG 12 REF: AMM 12 20 04 640 809	MOS HRS/MSC AFL	12	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
27-50-00-206 (s) 27.190	LUBRICATION OF THE BENT-UP TRAILING EDGE (BUTE) DOOR HINGE PKG 12 REF: AMM 12 20 04 640 810	MOS HRS/MSC AFL	12	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
27-50-00-207 (s) 27.195	VISUAL CHECK OF THE INBOARD AND OUTBOARD FLAP ACTUATORS PKG 800 REF: AMM 27 53 00 210 801	MOS HRS/MSC AFL	800	+40/-40			PKG 08-MAY-2020 4328:45 2835		
27-50-00-208 (s) 27.200	FUNCTIONAL TEST INBOARD AND OUTBOARD FLAP ACTUATORS PKG 2400 REF: AMM 27 53 00 720 801	MOS HRS/MSC AFL	2400	+40/-40			PKG 08-MAY-2020 4328:45 2835		
27-51-04-101 27.205	FUNCTIONAL TEST OF FLAP CONTROL UNIT (ALL-DRIVERS-ON CIRCUIT) (CMR*) PKG 4800 REF: AMM 27 51 04 720 801	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	<b>9128:45</b>	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
27-53-00-101-1	RESTORATION OF THE LH WING - OUTBOARD FLAP - OUTER ACTUATOR (WS 264) (CMR**) 600-93000-113 1352 <b>REF:</b> AMM 27 53 04 610 801	MOS HRS/MSC AFL	9600				07-MAR-2005 0 0	9600	
27-53-00-101-2	RESTORATION OF THE LH WING - OUTBOARD FLAP - INNER ACTUATOR (WS 178) (CMR**) 600-93000-115 1345 <b>REF:</b> AMM 27 53 04 610 801	MOS HRS/MSC AFL	9600				07-MAR-2005 0 0	9600	
27-53-00-101-7	RESTORATION OF THE RH WING - OUTBOARD FLAP - INNER ACTUATOR (WS 178) (CMR**) 600-93000-116 1081 <b>REF:</b> AMM 27 53 04 610 801	MOS HRS/MSC AFL	9600				07-MAR-2005 0 0	9600	
27-53-00-101-8	RESTORATION OF THE RH WING - OUTBOARD FLAP - OUTER ACTUATOR (WS 264) (CMR**) 600-93000-114 1086 <b>REF:</b> AMM 27 53 04 610 801	MOS HRS/MSC AFL	9600				07-MAR-2005 0 0	9600	
27-60-00-201 (s)	LUBRICATION OF THE FLIGHT SPOILER FLEXSHAFT & CONTROL CABLE ENDS PKG 400 27.210 <b>REF:</b> AMM 12 20 04 640 818	MOS HRS/MSC AFL	400	+40/-40			PKG 12-DEC-2020 4614 2973		
271101-001	NO. 1 SHAKER 600-59155-7 218 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				07-MAR-2005 0 0		
271101-002	NO. 2 SHAKER 600-59155-7 189 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271113-001	NO. 1 TENSION REGULATOR								
27.220	604-91301-1 FR255 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271113-002	NO. 2 TENSION REGULATOR								
27.220	604-91301-2 FR254 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271201-001	ROLL/YAW AILERON TRIM ACTUATOR								
27.225	600-91100-3 G5957 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271301-001	ROLL DISCONNECT HANDLE ASSY								
	600-90625-27 0353 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271401-001	NO. 1 AILERON PCU								
27.230	600-75100-17 1391D REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271401-002	NO. 2 AILERON PCU								
27.230	600-75100-17 1819D REF: See Workcard	MOS HRS/MSC AFL	O/C	R:3 N:1835 R:0 N:686 R:0			16-JUN-2014 2304:15 1731		
271402-001	L/H OUTBD AILERON (PCU) PRESSURE SWITCH								
	3941008-101 2282 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JUL-2009 1085:48 846		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271402-002	L/H INBD AILERON (PCU) PRESSURE SWITCH 3941008-101 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271402-003	R/H INBD AILERON (PCU) PRESSURE SWITCH 3941008-101 1875 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-JUN-2007 319:24 255		
271402-004	R/H OUTBD AILERON (PCU) PRESSURE SWITCH 3941008-101 2813 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-OCT-2012 1913:55 1444		
271501-001	LEFT AILERON 600-13000-1003 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271501-002	RIGHT AILERON 600-13000-1004 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
271504-001	NO. 1 LH AILERON ANTI-FLOAT TORSION (SPRING) BAR 600-10057-5 CLA0168 REF: See Workcard	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>10000</b>
271504-002	NO. 2 RH AILERON ANTI-FLOAT TORSION (SPRING) BAR 600-10057-6 CLA0177 REF: See Workcard	MOS HRS/MSC AFL	10000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>10000</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271507-001	NO. 1 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER								
27.405	1018100-7 HAI 4285 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-MAY-2020 4328:45 2835		
271507-001A (s)	FUNCTIONAL TEST NO. 1 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-10-00-207)						PKG		
27.405	1018100-7 PKG 4800 HAI 4285 REF: AMM 27 15 07 720 801	MOS HRS/MSC AFL	4800	+40/-40			08-MAY-2020 4328:45 2835		
271507-001B	DETAILED INSPECTION NO. 1 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-15-07-101) (CMR**)								
27.405	1018100-7 PKG 800 HAI 4285 REF: AMM 27 15 07 220 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	
271507-002	NO. 2 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER								
27.410	1018100-7 HAI4600 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			08-MAY-2020 4328:45 2835		
271507-002A (s)	FUNCTIONAL TEST NO. 2 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-10-00-207)						PKG		
27.410	1018100-7 PKG 4800 HAI4600 REF: AMM 27 15 07 720 801	MOS HRS/MSC AFL	4800	+40/-40			08-MAY-2020 4328:45 2835		
271507-002B	DETAILED INSPECTION NO. 2 AILERON FLUTTER (FLIGHT CONTROLS) DAMPER (27-15-07-101) (CMR**)								
27.410	1018100-7 PKG 800 HAI4600 REF: AMM 27 15 07 220 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	
271510-001	NO. 1 POSITION - AILERON TRANSMITTER								
27.245	600-59132-1 F2129 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
271510-002	NO. 2 POSITION - AILERON TRANSMITTER								
27.245	600-59132-1 F2117 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272116-001	RUDDER LOAD LIMITER								
27.250	600-91302-33 1726 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272125-001	RUDDER TRIM (ROLL & YAW) ACTUATOR								
27.255	600-91100-3 10368 REF: See Workcard	MOS HRS/MSC AFL	O/C				17-SEP-2010 1416:30 1074		
272125-002	RUDDER CONTROL LOAD LIMITER								
27.260	600-91302-31 1716 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272134-001	NO. 1 LOAD LIMITER								
27.265	600-91302-53 824 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272134-002	NO. 2 LOAD LIMITER								
27.265	600-91302-53 826 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272134-003	NO. 3 LOAD LIMITER								
27.265	600-91302-43 670 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272301-001	POWER CONTROL UNIT RUDDER PCU								
27.270	600-75101-29 8077 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272301-002	POWER CONTROL UNIT RUDDER PCU								
27.270	600-75101-29 8068 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272301-003	POWER CONTROL UNIT RUDDER PCU								
27.270	600-75101-29 8087 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272302-001	UPPER CONTROL ROD								
	600-92602-37 TY-33042 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272302-002	MID CONTROL ROD								
	600-92602-37 TY-33046 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272302-003	LOWER CONTROL ROD								
	600-92602-37 TY-28521 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
272401-001	RUDDER ASSY RUDDER								
27.275	604-22001-1 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
272404-001	RUDDER POSITION TRANSDUCER								
27.280	600-59191-5 F0850 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273102-001	NO. 1 LOAD - ELEVATOR CONTROLS LIMITER								
27.285	600-91302-29 3401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273102-002	NO. 2 LOAD - ELEVATOR CONTROLS LIMITER								
27.285	600-91302-29 3405 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273113-001	NO. 1 PITCH FEEL SIMULATOR								
27.290 <b>LIFE LIMIT</b>	600-92300-61 20023 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273113-001A	FUNCTIONAL TEST OF THE NO. 1 PITCH FEEL SIMULATOR. (CMR**)								
	600-92300-61 PKG 1600 20023 REF: AMM 27 31 13 720 801	MOS HRS/MSC AFL	1600				08-MAY-2020 4328:45 2835	<b>5928:45</b>	
273113-002	NO. 2 PITCH FEEL SIMULATOR								
27.290 <b>LIFE LIMIT</b>	600-92300-61 20026 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273113-002A	FUNCTIONAL TEST OF THE NO. 2 PITCH FEEL SIMULATOR. (CMR**)								
	600-92300-61 PKG 1600 20026 REF: AMM 27 31 13 720 801	MOS HRS/MSC AFL	1600				08-MAY-2020 4328:45 2835	<b>5928:45</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273204-001	PITCH DISCONNECT HANDLE ASSY 600-90625-25 0306 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273301-001 27.295	POWER CONTROL UNIT ELEVATOR PCU 600-75102-23 2740 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273301-002 27.295	POWER CONTROL UNIT ELEVATOR PCU 600-75102-23 2739 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273301-003 27.295	POWER CONTROL UNIT ELEVATOR PCU 600-75102-23 2737 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273301-004 27.295	POWER CONTROL UNIT ELEVATOR PCU 600-75102-23 2738 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273404-001 27.300	LEFT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER 600-75142-9 HAI 4283 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273404-001A 27.300	FUNCTIONAL TEST LEFT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-101) (CMR*) 600-75142-9 PKG 4800 HAI 4283 REF: AMM 27 34 04 720 801	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	<b>9128:45</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273404-001B	DETAILED INSPECTION LEFT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR*)								
27.300	600-75142-9 PKG 800 HAI 4283 REF: AMM 27 34 04 220 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	
273404-002	LEFT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER								
27.305	600-75142-9 HAI 4276 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273404-002A	FUNCTIONAL TEST LEFT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-101) (CMR*)								
27.305	600-75142-9 PKG 4800 HAI 4276 REF: AMM 27 34 04 720 801	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	9128:45	
273404-002B	DETAILED INSPECTION LEFT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR*)								
27.305	600-75142-9 PKG 800 HAI 4276 REF: AMM 27 34 04 220 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	
273404-003	RIGHT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER								
27.310	600-75142-9 HAI 4274 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273404-003A	FUNCTIONAL TEST RIGHT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-101) (CMR*)								
27.310	600-75142-9 PKG 4800 HAI 4274 REF: AMM 27 34 04 720 801	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	9128:45	
273404-003B	DETAILED INSPECTION RIGHT INBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR*)								
27.310	600-75142-9 PKG 800 HAI 4274 REF: AMM 27 34 04 220 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	5128:45	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273404-004	RIGHT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER								
27.315	600-75142-9 HAI2111 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:3915:12 N:3355			09-OCT-2008 796:15 627		
273404-004A	FUNCTIONAL TEST RIGHT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-101) (CMR*)								
27.315	600-75142-9 PKG 4800 HAI2111 REF: AMM 27 34 04 720 801	MOS HRS/MSC AFL	4800				08-MAY-2020 4328:45 2835	<b>9128:45</b>	
273404-004B	DETAILED INSPECTION RIGHT OUTBOARD ELEVATOR FLUTTER (FLIGHT CONTROLS) DAMPER (27-34-04-102) (CMR*)								
27.315	600-75142-9 PKG 800 HAI2111 REF: AMM 27 34 04 220 801	MOS HRS/MSC AFL	800				08-MAY-2020 4328:45 2835	<b>5128:45</b>	
273407-001	ELEVATOR POSITION TRANSDUCER								
27.320	600-59191-5 F0887 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273500-001	ASSY STICK PUSHER CABLE								
27.325	600-90525-807 5360517-003 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273504-001	NO. 1 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY								
27.330	600-59154-3 GST05979 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:11 R:0 R:0			08-MAY-2020 4328:45 2835		
273504-001A	FUNCTIONAL TEST NO. 1 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY LINEARITY (27-35-04-101) (CMR*)								
27.330	600-59154-3 GST05979 REF: AMM 27 35 04 720 801	MOS HRS/MSC AFL	300				08-MAY-2020 4328:45 2835	<b>4628:45</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273504-001B	RESTORATION NO. 1 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY (27-35-04-102) (CMR)								
27.330	600-59154-3 GST05979 <b>REF:</b> AMM 27 35 04 160 801	MOS HRS/MSC AFL	N/A						
273504-002	NO. 2 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY								
27.335	600-59154-3 GST05253 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:6 R:0 R:0			08-MAY-2020 4328:45 2835		
273504-002A	FUNCTIONAL TEST NO. 2 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY LINEARITY (27-35-04-101) (CMR*)								
27.335	600-59154-3 GST05253 <b>REF:</b> AMM 27 35 04 720 801	MOS HRS/MSC AFL	300				08-MAY-2020 4328:45 2835	<b>4628:45</b>	
273504-002B	RESTORATION NO. 2 ANGLE OF ATTACK TRANSDUCER/SENSOR ASSY (27-35-04-102) (CMR)								
27.335	600-59154-3 GST05253 <b>REF:</b> AMM 27 35 04 160 801	MOS HRS/MSC AFL	N/A						
273510-001	NO. 1 LATERAL STALL WARNING SYSTEM ACCELEROMETER								
27.340	600-59199-9 3004 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273510-002	NO. 2 LATERAL STALL WARNING SYSTEM ACCELEROMETER								
27.340	600-59199-9 3003 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273510-003	ACCELERATION SWITCH								
27.345	PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
273511-001	STALL WARNING COMPUTER								
27.125	600-59152-35 M3903 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 N:1055 R:0 N:479 R:0			05-OCT-2017 3307:10 2325		
273513-001	STICK PUSHER CAPSTAN								
27.350	600-59156-7 80036 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273514-001	STICK PUSHER ACTUATOR								
27.355	600-59156-15 80057 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273534-001	NO. 1 STALL MARGIN INDICATOR								
27.360	600-59217-1 1554 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
273534-002	NO. 2 STALL MARGIN INDICATOR								
27.360	600-59217-1 1572 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
274101-001	HORIZONTAL STABILIZER TRIM ACTUATOR (HSTA) CONTROL UNIT								
27.365	601R92301-15 1658 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			06-JUN-2007 306 248		
274107-001	PILOT CONTROL COLUMN WHEEL								
27.370	601R90101-1 3948 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274107-002	COPILOT CONTROL COLUMN WHEEL								
27.375	601R90101-2 3906 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
274201-001	HORIZONTAL STABILIZER TRIM ACTUATOR								
27.380 LIFE LIMIT	604-92305-7 633 REF: See Workcard	MOS HRS/MSC AFL	19200 20000	R:3 N:1919 R:0 N:751 R:0			16-JUN-2014 2304:15 1731	19585:15 20980	
274201-002	L/H UPPER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT								
	601R92386-1 11-5613-A REF: See Workcard	MOS HRS/MSC AFL	H/T 20000	N:2304:15 N:1731			16-JUN-2014 2304:15 1731	20000	
274201-003	R/H UPPER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT								
	601R92386-1 21-5613-A REF: See Workcard	MOS HRS/MSC AFL	H/T 20000	N:2304:15 N:1731			16-JUN-2014 2304:15 1731	20000	
274201-004	L/H LOWER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT								
	601R92386-1 12-5613-A REF: See Workcard	MOS HRS/MSC AFL	H/T 20000	N:2304:15 N:1731			16-JUN-2014 2304:15 1731	20000	
274201-005	R/H LOWER HORIZONTAL-STABILIZER TRIM-ACTUATOR (HSTA) TRUNNION SUPPORT								
	601R92386-1 22-5613-A REF: See Workcard	MOS HRS/MSC AFL	H/T 20000	N:2304:15 N:1731			16-JUN-2014 2304:15 1731	20000	
274201-701	L/H LOWER PIN, HORIZONTAL TAIL TRIM ACTUATOR								
	601R92309-3 0761 REF:	MOS HRS/MSC AFL	O/C	N:3 N:0 N:0			16-JUN-2014 2304:15 1731		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
274201-702	R/H LOWER PIN, HORIZONTAL TAIL TRIM ACTUATOR 600-92383-7 22-5613-A <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:2304:15 N:1731			16-JUN-2014 2304:15 1731		
274201-703	L/H UPPER PIN, HORIZONTAL TAIL TRIM ACTUATOR 600-92384-7 11-5613-A <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:2304:15 N:1731			16-JUN-2014 2304:15 1731		
274201-704	R/H UPPER PIN, HORIZONTAL TAIL TRIM ACTUATOR 600-92384-7 21-5613-A <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:2304:15 N:1731			16-JUN-2014 2304:15 1731		
274204-001 27.385	MOTOR CONTROL UNIT 604-92306-3 433 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275100-001 27.390	NO. 1 FLAP BRAKE DETECTOR UNIT 600-93000-123 1727 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275100-002 27.390	NO. 2 FLAP BRAKE DETECTOR UNIT 600-93000-123 1726 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275101-001 27.395	FLAP CONTROL UNIT 600-93000-121 D616 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			18-AUG-2006 82:48 84		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275103-001	NO. 4 FLAP CONTROL POSITION LEVER								
27.400	601R93003-3 0520 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275110-001	UNIT FLAP CONTROL								
27.415	PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275200-001	POWER DRIVE UNIT								
27.425	600-93000-71 0691 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			07-FEB-2007 218:25 182		
275300-001	LH WING - INBOARD FLAP - INNER ACTUATOR (WS 76.50)								
27.430	600-93000-95 2456 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275300-002	RH WING - INBOARD FLAP - INNER ACTUATOR (WS 76.50)								
27.430	600-93000-95 2454 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275301-001	LH WING - INBOARD FLAP - OUTER ACTUATOR (WS 127.25)								
27.435	600-93000-93 2437 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275301-002	RH WING - INBOARD FLAP - OUTER ACTUATOR (WS 127.25)								
27.435	600-93000-93 2436 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275302-001	LH WING - OUTBOARD FLAP - OUTER ACTUATOR (WS 264)								
	600-93000-113	MOS		N:0			07-MAR-2005		
	1352	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
275302-002	RH WING - OUTBOARD FLAP - OUTER ACTUATOR (WS 264)								
	600-93000-114	MOS		N:0			07-MAR-2005		
	1086	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
275303-001	LH WING - OUTBOARD FLAP - INNER ACTUATOR (WS 178)								
27.440	600-93000-115	MOS		N:0			07-MAR-2005		
	1345	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
275303-002	RH WING - OUTBOARD FLAP - INNER ACTUATOR (WS 178)								
27.440	600-93000-116	MOS		N:0			07-MAR-2005		
	1081	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
275304-001	LEFT NO.1 FLEXIBLE DRIVE SHAFT								
27.445	600-93000-61	MOS		N:3			16-JUN-2014		
	3296	HRS/MSC	O/C	N:0			2304:15		
	REF: See Workcard	AFL		N:0			1731		
275304-001A (s)	DETAILED INSPECTION LEFT NO.1 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.445	600-93000-61 PKG 2400	MOS					08-MAY-2020		
	3296	HRS/MSC	2400	+40/-40			4328:45		
	REF: AMM 27 53 07 220 801	AFL					2835		
275304-002	RIGHT NO. 1 FLEXIBLE DRIVE SHAFT								
27.450	600-93000-61	MOS		N:0			07-MAR-2005		
	2333	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275304-002A (s)	DETAILED INSPECTION RIGHT NO. 1 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.450	600-93000-61 PKG 2400 2333 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275305-001	LEFT NO.2 FLEXIBLE DRIVE SHAFT								
27.455	600-93000-63 1886 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275305-001A (s)	DETAILED INSPECTION LEFT NO.2 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.455	600-93000-63 PKG 2400 1886 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275305-002	RIGHT NO. 2 FLEXIBLE DRIVE SHAFT								
27.460	600-93000-63 1887 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275305-002A (s)	DETAILED INSPECTION RIGHT NO. 2 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.460	600-93000-63 PKG 2400 1887 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275306-001	LEFT NO.3 FLEXIBLE DRIVE SHAFT								
27.465	600-93000-65 2212 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275306-001A (s)	DETAILED INSPECTION LEFT NO.3 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.465	600-93000-65 PKG 2400 2212 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275306-002	RIGHT NO. 3 FLEXIBLE DRIVE SHAFT								
27.470	600-93000-65 2233 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275306-002A (s)	DETAILED INSPECTION RIGHT NO. 3 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.470	600-93000-65 PKG 2400 2233 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275307-001	LEFT NO.4 FLEXIBLE DRIVE SHAFT								
27.475	600-93000-67 2282 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275307-001A (s)	DETAILED INSPECTION LEFT NO.4 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.475	600-93000-67 PKG 2400 2282 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275307-002	RIGHT NO. 4 FLEXIBLE DRIVE SHAFT								
27.480	600-93000-67 2285 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275307-002A (s)	DETAILED INSPECTION RIGHT NO. 4 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.480	600-93000-67 PKG 2400 2285 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275308-001	LEFT NO.5 FLEXIBLE DRIVE SHAFT								
27.485	600-93000-69 2253 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275308-001A (s)	DETAILED INSPECTION LEFT NO.5 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.485	600-93000-69 PKG 2400 2253 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275308-002	RIGHT NO. 5 FLEXIBLE DRIVE SHAFT								
27.490	600-93000-69 2252 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275308-002A (s)	DETAILED INSPECTION RIGHT NO. 5 FLEXIBLE DRIVE SHAFT (27-50-00-202)						PKG		
27.490	600-93000-69 PKG 2400 2252 REF: AMM 27 53 07 220 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
275404-001	LEFT OUTBOARD FLAP ASSEMBLY								
27.495	600-14500-805 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275404-002	RIGHT OUTBOARD FLAP ASSEMBLY								
27.495	600-14500-806 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275404-003	INBOARD FLAP LH ASSY								
	600-14002-1001 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275404-004	INBOARD FLAP RH ASSY								
	600-14002-1002 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275410-001	FLAP VANE ACTUATOR								
27.500	600-14202-15 CLA0339 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275410-002	FLAP VANE ACTUATOR								
27.505	600-14202-15 CLA0335 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275410-003	FLAP VANE ACTUATOR								
27.510	600-14202-15 CLA0341 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275410-004	FLAP VANE ACTUATOR								
27.515	600-14202-15 CLA0337 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275410-005	FLAP VANE ACTUATOR								
27.520	600-14202-15 CLA0333 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275410-006	FLAP VANE ACTUATOR								
27.525	600-14202-15 CLA0298 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275500-001	NO. 1 FLAP POSITION TRANSMITTER								
27.530	600-93030-9 0115160 REF: See Workcard	MOS HRS/MSC AFL	O/C				16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
275500-002	NO. 2 FLAP POSITION TRANSMITTER								
27.530	600-93030-11 6590473 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
275500-701	NO. 1 CONTROL ROD FLAP POSITION TRANSMITTER								
	600-92602-97 TY-54375 REF:	MOS HRS/MSC AFL	O/C	N:20 N:0 N:0			16-JUN-2014 2304:15 1731		
276100-001	NO. 1 POSITION - SPOILER TRANSMITTER								
27.535	600-59132-1 F2108 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276100-002	NO. 2 POSITION - SPOILER TRANSMITTER								
27.535	600-59132-1 F0758 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276100-003	NO. 1 LOAD LIMITER								
27.540	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276100-004	NO. 2 LOAD LIMITER								
27.540	600-91302-49 659 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276102-001	NO. 1 LOAD LIMITER								
27.545	600-91302-47 622 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
276103-001	SPOILER LEVER								
27.550	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276103-003	NO. 1 SPOILER PUSH/PULL CONTROL								
27.555	600-91303-11 660 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276103-004	NO. 2 SPOILER PUSH/PULL CONTROL								
27.555	600-91303-13 670 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276104-001	POWER CONTROL FLIGHT SPOILER UNIT								
27.560	600-75103-15 2711A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276104-002	POWER CONTROL FLIGHT SPOILER UNIT								
27.565	600-75103-15 2694A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276104-003	POWER CONTROL FLIGHT SPOILER UNIT								
27.570	600-75103-15 2712A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
276104-004	POWER CONTROL FLIGHT SPOILER UNIT								
27.575	600-75103-15 2713A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT	
276105-001	SPOILER CONTROL LEVER									
27.580	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0			
276304-001	GROUND SPOILER SELECT MANIFOLD									
27.585	600-75124-7 922A REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			15-FEB-2020 4308:05 2823			
276500-001	LH POWER CONTROL GROUND SPOILER PCU									
27.590	600-75106-7 1373 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0			
276500-002	RH POWER CONTROL GROUND SPOILER PCU									
27.590	600-75106-7 1375 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0			
<b>CHAPTER 28 FUEL</b>										
28-10-00-201 (s)	GENERAL VISUAL INSPECTION OF THE FUEL TANK ACCESS PANELS						PKG			
28.005	PKG 600 REF: AMM 28 11 01 210 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835			
28-10-00-202 (s)	GENERAL VISUAL INSPECTION OF THE FUEL DRAIN VALVES						PKG			
28.010	PKG 600 REF: AMM 28 11 07 210 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835			
28-10-00-203 (s)	GENERAL VISUAL INSPECTION OF THE WATER DRAIN VALVES						PKG			
28.015	PKG 600 REF: AMM 28 11 04 210 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835			

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10-00-204 (s)	GENERAL VISUAL INSPECTION FUEL TANK EXTERIOR						PKG		
28.020	PKG 600 REF: AMM 28 10 00 210 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
28-10-00-205 (s)	GENERAL VISUAL INSPECTION SADDLE TANK DRAIN						PKG		
28.025	PKG 600 REF: AMM 28 13 10 210 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
28-10-00-206 (s)	GENERAL VISUAL INSPECTION GRAVITY FILLER CAP						PKG		
28.030	PKG 600 REF: AMM 28 10 00 210 802	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
28-10-00-207 (s)	FUNCTIONAL TEST VENT LINE SHROUDS						PKG		
28.035	PKG 96 REF: AMM 28 14 22 720 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
28-10-00-208 (s)	FUNCTIONAL TEST MOTIVE FLOW LINES SHROUDS						PKG		
28.040	PKG 96 REF: AMM 28 22 10 720 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
28-10-00-209 (s)	FUNCTIONAL TEST FUEL FEED LINE SHROUDS						PKG		
28.045	PKG 96 REF: AMM 28 21 16 720 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
28-10-00-210 (s)	FUNCTIONAL TEST OF THE FORWARD AND AFT AUXILIARY TANKS - INTERSPACE AND FUEL TRANSFER LINE SHROUDS						PKG		
28.050	PKG 96 REF: AMM 28 12 10 720 802	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-10-00-213 (s)	VISUAL CHECK VENT/DISTRIBUTION SHROUD DRAINS BLOCKAGE/LEAKAGE						PKG		
28.055	PKG 600 REF: AMM 28 00 00 210 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
28-15-00-202 (s)	OPERATIONAL TEST OF THE TAIL-TANK TRANSFER SHUTOFF-VALVE						PKG		
28.060	PKG 1600 REF: AMM 28 15 22 710 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
28-15-00-203 (s)	OPERATIONAL TEST TAIL TANK SECONDARY TRANSFER-PUMP						PKG		
28.065	PKG 1600 REF: AMM 28 15 28 710 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
28-15-43-101	FUNCTIONAL TEST OF THE TAIL TANK RESTRICTOR (CMR**)								
	REF: AMM 28 15 43 720 801	MOS HRS/MSC AFL	15000				07-MAR-2005 0 0	15000	
28-20-00-202 (s)	OPERATIONAL TEST COLLECTOR TANK CHECK VALVE						PKG		
28.075	PKG 96 REF: AMM 28 11 19 710 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
28-21-13-201 (s)	OPERATIONAL TEST NO. 1 ENGINE FIREWALL FUEL SHUTOFF VALVE (MRB)						PKG		
28.270	601-62900-7 PKG 400 AA54801 REF: AMM 28 21 13 710 801	MOS HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
28-21-13-201 (s)	OPERATIONAL TEST NO. 2 ENGINE FIREWALL FUEL SHUTOFF VALVE (MRB)						PKG		
28.275	601-62900-7 PKG 400 AA35164 REF: AMM 28 21 13 710 801	MOS HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
28-24-00-101	OPERATIONAL TEST APU FUEL FEED AND SOV & NEGATIVE-G SOV FOR LEAKS (CMR*)								
28.070	PKG 2400 REF: AMM 28 24 00 710 801	MOS HRS/MSC AFL	2400				08-MAY-2020 4328:45 2835	6728:45	
28-31-00-201 (s)	OPERATIONAL TEST DUMP VALVE (MRB)								
28.080	AV16B2178-2 PKG 400 AA30237 REF: AMM 28 31 01 710 801	MOS HRS/MSC AFL	400				PKG 12-DEC-2020 4614 2973		
281107-001	LEFT OUTBOARD FUEL DRAIN VALVE								
28.085	2770086-103 5200 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281107-002	LEFT INBOARD FUEL DRAIN VALVE								
28.090	2770086-103 5417 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281107-003	RIGHT FUEL DRAIN VALVE								
28.095	2770086-103 5422 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281201-001	FORWARD TANK								
28.100	604-31900-1 AVFWD0657 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281204-001	AFT AUXILIARY FUEL TANK								
28.105	80022-119 AVAF0658 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281304-001	DRAIN VALVE								
28.110	68C4H 0366 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281401-001	NO. 1 PRESSURE RELIEF VENT VALVE								
28.115	2880022-101 4046 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281401-002	NO. 2 PRESSURE RELIEF VENT VALVE								
28.115	2880022-101 4052 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281404-001	TAIL TANK RELIEF VALVE								
28.120	94-8101 0327 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281410-001	FWD AUXILIARY TANK-LINE FLOAT VALVE								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281419-001	CENTER PRESSURE RELIEF VENT VALVE								
28.125	2880022-102 4065 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281501-001	LH FUEL TRANSFER EJECTOR PUMP								
28.130	2780473-105 1891 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281501-002	RH FUEL TRANSFER EJECTOR PUMP								
28.130	2780473-105 1895 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281504-001	NO. 1 FUEL SCAVENGER EJECTOR PUMP								
28.135	2780472-103 1367 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281504-002	NO. 2 FUEL SCAVENGER EJECTOR PUMP								
28.135	2780472-103 1371 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281510-001	NO. 1 TRANSFER FLOAT VALVE								
28.140	600-62533-3 0707 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281510-002	NO. 2 TRANSFER FLOAT VALVE								
28.140	600-62533-3 0708 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281513-001	(L/H TANK) FUEL SHUTOFF VALVE ASSEMBLY								
28.145	AV16B2082-4 AA35091 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281513-002	(R/H TANK) FUEL SHUT OFF VALVE ASSY								
28.150	AV16B2082-4 AA263672 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			03-APR-2017 3041:45 2185		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
281513-003	(CENTER TANK) FUEL BALANCE LINE SHUT-OFF VALVE								
28.155	AV16B2082-4 AA35104 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281516-001	NO. 1 CHECK, TAIL TANK VALVE								
28.160	601R62296-5 3422 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281516-002	NO. 2 CHECK, TAIL TANK VALVE								
28.160	601R62296-5 3424 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281519-001	TAIL TANK TRANSFER CHECK VALVE								
	601-62900-7 AA35177 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281522-001	TAIL TANK TRANSFER SHUT OFF VALVE								
28.165	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281528-001	NO. 1 PRIMARY T/TANK TRANSFER BOOST PUMP								
28.170	604-62146-1 B67489 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
281528-002	NO. 2 PRIMARY T/TANK TRANSFER BOOST PUMP								
28.170	604-62146-1 B73076 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282101-001	NO. 1 FUEL EJECTOR PUMP								
28.175	2780602-105 1715 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282101-002	NO. 2 FUEL EJECTOR PUMP								
28.175	2780602-105 1717 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282113-001	LH FIREWALL SHUT OFF VALVE								
28.180	601-62900-7 AA35160 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282113-002	RH FIREWALL SHUT OFF VALVE								
28.180	601-62900-8 U29584 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282204-001	NO. 1 CHECK VALVE								
28.185	869A-8TB 04-052789 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282204-002	NO. 2 CHECK VALVE								
28.185	869A-8TB 04-0804165 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282301-001	LH FUEL BOOST PUMP CARTRIDGE								
28.190	601R62181-5 B78911 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282301-002	RH FUEL BOOST PUMP CARTRIDGE								
28.195	226114-3 A01608 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			05-SEP-2019 4057:25 2699		
282301-003	APU FUEL BOOST PUMP CARTRIDGE								
28.200	601R62181-5 A45201 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			03-APR-2017 3041:45 2185		
282304-001	PUMP CANISTER								
28.205	601R62181-1 B78553 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282304-002	PUMP CANISTER								
28.210	601R62181-1 B74561 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282304-003	PUMP CANISTER								
28.215	601R62181-1 B19800 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282419-001	2-WAY APU FUEL VALVE								
28.220	8679409 AA31694 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282425-001	APU PUMP ELECTRIC BOOST CANISTER								
28.225	601R62181-5 F11889 REF: See Workcard	MOS HRS/MSC AFL	O/C				11-MAR-2016 2654:25 1995		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282501-001	FUEL/DEFUEL ADAPTOR VALVE								
28.230	2770082-101 1883 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282504-001	CHECK REFUEL/DEFUEL VALVE								
28.235	2780481-102 2812 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282513-001	REFUEL/DEFUEL SHUTOFF VALVE								
28.240	2880025-101 4107 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282513-002	REFUEL/DEFUEL SHUTOFF VALVE								
28.245	2880025-101 4108 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282513-003	REFUEL/DEFUEL SHUTOFF VALVE								
28.250	2880025-101 4111 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282513-701	REFUEL/DEFUEL PANEL								
	798976-1-1 00251 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
282516-001	FUEL/DEFUEL CONTROL PANEL								
28.255	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
282516-002	FUEL/DEFUEL CONTROL PANEL								
28.260	600-52303-1007/02 6790116 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282516-003	FUEL/DEFUEL CONTROL PANEL								
28.265	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282522-001	NO. 1 ENGINE FIREWALL FUEL SHUTOFF VALVE								
28.270	601-62900-7 AA54801 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			07-FEB-2007 218:25 182		
282522-002	NO. 2 ENGINE FIREWALL FUEL SHUTOFF VALVE								
28.275	601-62900-7 AA35164 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
282525-001	TANK REFUEL EJECTOR								
28.280	2810082-101 0651 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
283101-001	DUMP VALVE								
28.080	AV16B2178-2 AA30237 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
283101-002	APU GATE VALVE								
28.285	AV16B2178-2 AA31289 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284101-001	L/H WING TANK NO.1 PROBE FUEL								
28.290	768-959-1B 1538 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-002	R/H WING TANK NO.1 PROBE FUEL								
28.290	768-959-1B 1539 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-003	L/H WING TANK NO.2 PROBE FUEL								
28.295	768-960-1B 1292 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-004	R/H WING TANK NO.2 PROBE FUEL								
28.295	768-960-1B 1293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-005	L/H WING TANK NO.3 PROBE FUEL								
28.300	768-961-1B 744 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-006	R/H WING TANK NO.3 PROBE FUEL								
28.300	768-961-1B 745 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-007	L/H WING TANK NO.4 PROBE FUEL								
28.305	768-962-2B 747 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284101-008	R/H WING TANK NO.4 PROBE FUEL								
28.305	768-962-2B 749 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-009	L/H WING TANK NO.5 PROBE FUEL								
28.310	768-963-1B 2777 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-010	R/H WING TANK NO.5 PROBE FUEL								
28.310	768-963-1B 2778 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-011	L/H WING TANK NO.6 PROBE FUEL								
28.315	768-964-1 747 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284101-012	R/H WING TANK NO.6 PROBE FUEL								
28.315	768-964-1 748 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284104-001	L/H CENTRE TANK NO.1 PROBE FUEL								
28.320	768-965-1B 1208 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284104-002	L/H CENTRE TANK NO.2 PROBE FUEL								
28.320	768-966-1 417 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284104-003	R/H CENTRE TANK NO.3 PROBE FUEL								
28.320	768-967-1B 694 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284110-001	TAIL TANK PROBE FUEL								
28.325	768-969-1 448 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284113-001	FUEL QUANTITY GAUGING (FQGC) COMPUTER								
28.330	736-847-14 0519 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284116-001	NO.1 CENTER AND MAIN FUEL TANKS LEVEL SENSOR								
28.335	601R62304-5 2784 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284116-002	NO.2 CENTER AND MAIN FUEL TANKS LEVEL SENSOR								
28.340	601R62304-5 2795 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284116-003	NO.3 CENTER AND MAIN FUEL TANKS LEVEL SENSOR								
28.345	601R62304-5 2407 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284116-004	NO.4 CENTER AND MAIN FUEL TANKS LEVEL SENSOR								
28.345	601R62304-5 2524 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284119-001	FORWARD AUXILIARY FUEL TANK LEVEL SENSOR								
28.395	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284122-001	TAIL TANK UPPER FUEL LEVEL SENSOR								
28.350	601R62304-3 1156 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284122-002	TAIL TANK LOWER FUEL LEVEL SENSOR								
28.350	601R62304-3 1162 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284122-003	TAIL TANK HIGH LEVEL SENSOR								
28.350	601R62304-5 2664 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284201-001	ELECTRIC BOOST-PUMP PRESSURE SWITCH								
28.355	601R62291-3/21SN41-112 R101 REF: See Workcard	MOS HRS/MSC AFL	O/C				28-OCT-2019 4179:40 2752		
284201-002	ELECTRIC BOOST-PUMP PRESSURE SWITCH								
28.370	601R62291-3 E013221 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:156 N:3512:30 N:2441			24-MAR-2018 3512:30 2441		
284204-001	NO. 1 PRIMARY EJECTOR PRESSURE SWITCH								
28.365	601R62291-1 F000548 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284204-002	NO. 2 PRIMARY EJECTOR PRESSURE SWITCH								
28.365	601R62291-1 F000551 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284207-001	NO. 1 DIFFERENTIAL PRESSURE SWITCH								
28.380	601R92292-7 625 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284207-002	NO. 2 DIFFERENTIAL PRESSURE SWITCH								
28.380	601R62292-7 624 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284210-001	APU FUEL PUMP PRESSURE SWITCH								
	600-59180-1 1096 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284213-001	ROTOR-BURST PROTECTION PRESSURE SWITCH								
28.385	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284213-001A (s)	FUNCTIONAL TEST ROTOR-BURST PROTECTION PRESSURE SWITCH (28-15-00-201)						PKG		
<b>MRB</b>	PN PKG 1600 SN-UNKNOWN REF: AMM 28 42 13 720 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
284216-001	LH TAIL TANK FUEL PRESSURE SWITCH								
28.390	GP422-1306-3 1494 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
284216-002	RH TAIL TANK FUEL PRESSURE SWITCH								
28.390	GP422-1306-3 1509 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
284219-001	FUEL TEMPERATURE SENSOR								
28.405	601R62452-1 L0167 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>APU Model : GTCP36-100(E) (604-CIMMS) Serial # P-820 Part # 3800050-5-1</b>									
28-20-00-201 (s)	APU - DISCARD FUEL-FEED LINE FILTER OF THE APU								
	PKG 800	MOS					08-MAY-2020		
<b>LIFE LIMIT</b>	REF: AMM 28 24 16 960 801	HRS/MSC APUS	800	+40/-40			6583		
<b>ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01</b>									
28-21-13-202 (s)	NO. 1 ENGINE - OPERATIONAL TEST ENGINE FIREWALL FUEL SHUTOFF-VALVE FOR LEAKS								
28.005	PKG 800	MOS					08-MAY-2020		
	REF: See Workcard	HRS/MSC ENC	800	+40/-40			4328:45 2850		
<b>ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01</b>									
28-21-13-202 (s)	NO. 2 ENGINE - OPERATIONAL TEST ENGINE FIREWALL FUEL SHUTOFF-VALVE FOR LEAKS								
28.005	PKG 800	MOS					08-MAY-2020		
	REF: See Workcard	HRS/MSC ENC	800	+40/-40			4328:45 2850		
<b>CHAPTER 29 HYDRAULIC POWER</b>									
29-10-00-201 (s)	VISUAL CHECK FILTER DIFFERENTIAL PRESSURE INDICATOR								
29.005	PKG 600	MOS					08-MAY-2020		
	REF: AMM 29 10 00 210 801	HRS/MSC AFL	600	+40/-40			4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
29-11-00-301 (s) 29.010	FUNCTIONAL TEST (ACIDITY INSP) OF HYDRAULIC FLUID (SYST #1 & #2) PKG 24 <b>REF:</b> AMM 29 11 00 281 801	MOS HRS/MSC AFL	24	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
29-12-00-301 (s) 29.015	FUNCTIONAL TEST (ACIDITY INSP) OF HYDRAULIC FLUID (SYST #3) PKG 24 <b>REF:</b> AMM 29 12 00 281 801	MOS HRS/MSC AFL	24	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
291101-001 29.020	NO. 1 ENGINE DRIVEN PUMP 601R75113-5 MX623732 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				31-JAN-2014 2268 1707		
291101-002 29.020	NO. 2 ENGINE DRIVEN PUMP 601R75113-5 MX-554511 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				30-MAR-2011 1551:30 1194		
291103-001 29.025	NO. 1 ATTENUATOR BALL 601R75155-1 MX680465 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291103-002 29.025	NO. 2 ATTENUATOR BALL 601R75155-1 MX680440 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291104-001 29.030	NO. 1 ELECTRIC MOTOR DRIVEN PUMP 601R75154-7 MX683225 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291104-002	NO. 2 ELECTRIC MOTOR DRIVEN PUMP								
29.030	601R75154-7 MX684224 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291107-001	NO. 1 PRESSURE - HYDRAULIC SYSTEM MANIFOLD								
29.035	601R75118-3 4087 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291107-002	NO. 2 PRESSURE - HYDRAULIC SYSTEM MANIFOLD								
29.035	601R75118-3 4088 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291108-001	1A HYDRAULIC PRESSURE SWITCH								
29.040	600-59134-1 4742 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291108-002	2A HYDRAULIC PRESSURE SWITCH								
29.045	600-59134-1 4751 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291108-003	1B HYDRAULIC PRESSURE SWITCH								
29.050	600-59134-1 4743 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291108-004	2B HYDRAULIC PRESSURE SWITCH								
29.055	600-59134-1 4740 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291109-001	NO.1 PRESSURE - HYDRAULIC SYSTEM TRANSDUCER								
29.060	600-59174-17 7116-10-203 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-APR-2006 23:48 15		
291109-002	NO.2 PRESSURE - HYDRAULIC SYSTEM TRANSDUCER								
29.060	600-59174-17 7052-5-100 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291113-001	NO. 1 PRESSURE RELIEF VALVE								
29.065	601R75158-1 4252 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291113-002	NO. 2 PRESSURE RELIEF VALVE								
29.065	601R75158-1 4253 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291119-001	NO. 1 RETURN FILTER MANIFOLD								
29.070	600-75117-1 5471 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291119-002	NO. 2 RETURN FILTER MANIFOLD								
29.070	600-75117-1 4831R REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291119-003	NO. 3 RETURN FILTER MANIFOLD								
29.070	600-75117-1 5476 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291122-001	NO. 1 EDP CASE DRAIN FILTER								
29.075	600-75114-3 8212 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291122-002	NO. 2 EDP CASE DRAIN FILTER								
29.075	600-75114-3 8218 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291123-001	NO. 1EP CASE DRAIN FILTER								
29.080	600-75114-3 8217 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291123-002	NO. 2EP CASE DRAIN FILTER								
29.080	600-75114-3 8233 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291128-001	NO. 1 HYDRAULIC ACCUMULATOR								
29.085 LIFE LIMIT	601R75138-1 60163-5099 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291128-002	NO. 2 HYDRAULIC ACCUMULATOR								
29.085 LIFE LIMIT	601R75138-1 60163-5142 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291131-001	NO. 1 AIR PRESSURE INDICATING GAUGE								
29.090	600-75125-3 04-1208271 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291131-002	NO. 2 AIR PRESSURE INDICATING GAUGE								
29.090	600-75125-3 04-1208268 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291140-001	NO. 1 TEMPERATURE TRANSDUCER								
29.095	601R75127-1 K8437 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291140-002	NO.2 TEMPERATURE TRANSDUCER								
29.095	601R75127-1 K9046 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291140-003	NO. 3 TEMPERATURE TRANSDUCER								
29.180	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291143-001	NO. 1 HYDRAULIC RESERVOIR								
29.100	600-75112-21 321 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291143-002	NO. 2 HYDRAULIC RESERVOIR								
29.100	601R75120-3 1401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291143-003	NO. 3 HYDRAULIC RESERVOIR								
29.175	601R75111-3 1427A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291149-001	NO. 1 CASE DRAIN VALVE								
29.105	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291149-002	NO. 2 CASE DRAIN VALVE								
29.105	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291152-001	NO. 1 HYDRAULIC SHUTOFF VALVE								
29.110	601R75151-9 D67687 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-MAR-2011 1551:30 1194		
291152-001A (s)	OPERATIONAL TEST NO. 1 HYDRAULIC SHUTOFF VALVE (29-11-52-201)						PKG		
29.110	601R75151-9 PKG 1600 D67687 REF: AMM 29 11 52 710 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
291152-002	NO. 2 HYDRAULIC SHUTOFF VALVE								
29.115	601R75151-9 C83569 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			30-MAR-2011 1551:30 1194		
291152-002A (s)	OPERATIONAL TEST NO. 2 HYDRAULIC SHUTOFF VALVE (29-11-52-201)						PKG		
29.115	601R75151-9 PKG 1600 C83569 REF: AMM 29 11 52 710 801	MOS HRS/MSC AFL	1600	+40/-40			08-MAY-2020 4328:45 2835		
291155-001	LH ELECTRICAL ACTUATOR								
29.120	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291155-002	RH ELECTRICAL ACTUATOR								
29.120	PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291201-001	NO. 3A ATTENUATOR BALL								
29.125	601R75155-1 MX683875 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291201-002	NO. 3B ATTENUATOR BALL								
29.125	601R75155-1 MX683829 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291203-001	NO. 3A ELECTRIC MOTOR DRIVEN PUMP								
29.130	601R75154-7 MX686120 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291203-002	NO. 3B ELECTRIC MOTOR DRIVEN PUMP								
29.130	601R75154-7 MX685008 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291204-001	NO. 3A HYDRAULIC PRESSURE SWITCH								
29.135	600-59134-1 4665 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291204-002	NO. 3B HYDRAULIC PRESSURE SWITCH								
29.135	1206P0169 4663 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291204-003	NO. 3 PRESSURE - HYDRAULIC SYSTEM MANIFOLD								
29.140	601R75118-3 4104 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291205-003	NO. 3 PRESSURE - HYDRAULIC SYSTEM TRANSDUCER								
29.145	600-59174-17 7952-2-128 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291210-001	NO. 3 PRESSURE RELIEF VALVE								
29.150	601R75158-1 4207 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291219-001	NO. 3A CASE DRAIN FILTER								
29.155	600-75114-3 8108 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291219-002	NO. 3B CASE DRAIN FILTER								
29.160	600-75114-3 8112 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291225-001	NO. 3 HYDRAULIC SYSTEM ACCUMULATOR								
<b>LIFE LIMIT</b>	601R75138-3 60164-1265 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291228-001	NO. 3 AIR PRESSURE INDICATING GAUGE								
29.170	600-75125-3 04-0916547 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
291240-001	NO. 1 CASE DRAIN FILTER								
29.185	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291240-002	NO. 2 CASE DRAIN FILTER								
29.185	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
291241-001	NO. 3 PRESSURE RELIEF VALVE								
29.190	601R75119-1 4215 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 30 ICE AND RAIN PROTECTION</b>									
30-10-00-201 (s)	FUNCTIONAL TEST SENSOR DETECTION CIRCUIT						PKG		
30.005	PKG 2400 REF: AMM 30 12 19 720 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
30-11-00-101	DETAILED INSPECTION OF THE WING ANTI-ICE DUCT PICCOLO-TUBE. (CMR**)								
	REF: AMM 30 11 07 220 801	MOS HRS/MSC AFL	6400	+40/-40			07-MAR-2005 0 0	6400	6440
+ 30-12-00-102	FUNCTIONAL TEST OF THE LOW TEMPERATURE GROUND WING ANTI-ICE (LTGWAI) OVERHEAT CIRCUIT (POST SB 604-30-004) (CMR**)								
MPD SECTION 7	REF: AMM 30 12 25 720 801	MOS HRS/MSC AFL	2400				08-MAY-2020 4328:45 2835	6728:45	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 30-12-00-103	DISCARD OF NO.1 MODULATING AND SHUT-OFF VALVE, PART NO. 3214442-4 (POST SB 604-30-004)								
	3214442-4	MOS							
	3451	HRS/MSC	13500				0		13500
<b>MPD SECTION 7</b>	<b>REF: AMM 30 12 04 960 801</b>	AFL							
+ 30-12-00-103	DISCARD OF NO.2 MODULATING AND SHUT-OFF VALVE, PART NO. 3214442-4 (POST SB 604-30-004)								
	3214442-4	MOS							
	3468	HRS/MSC	13500				0		13500
<b>MPD SECTION 7</b>	<b>REF: AMM 30 12 04 960 801</b>	AFL							
+ 30-22-00-101	OPERATIONAL TEST OF THE COWL ANTI-ICE FAILURE INDICATION (POST SB 604-30-004) (CMR*)								
		MOS					08-MAY-2020		
		HRS/MSC	600				4328:45		4928:45
<b>MPD SECTION 7</b>	<b>REF: AMM 30 22 00 710 801</b>	AFL					2835		
30-40-00-201	FUNCTIONAL TEST NO. 1 RAIN REPELLENT LAYER								
	600-33030-25	MOS					14-OCT-2013		
	11949	HRS/MSC	N/A				2169:25		
<b>MRB</b>	<b>REF: AMM 30 40 00 720 801</b>	AFL					1641		
30-40-00-201	FUNCTIONAL TEST NO. 2 RAIN REPELLENT LAYER								
	600-33030-26	MOS					30-DEC-2013		
	11844	HRS/MSC	N/A				2233:55		
<b>MRB</b>	<b>REF: AMM 30 40 00 720 801</b>	AFL					1688		
30-40-00-301	DETAILED INSPECTION OF THE WINDSHIELD/SIDE WINDOW AERODYNAMIC SEAL. NOTE: WHICHEVER INTERVAL COMES FIRST								
		MOS	12	+1m/-1m			08-MAY-2020	<b>08-MAY-2021</b>	08-JUN-2021
		HRS/MSC	600	+40/-40			4328:45	<b>4928:45</b>	4968:45
<b>OPTIONAL</b>	<b>REF: AMM 56 10 01 220 804</b>	AFL					2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
30-81-00-201 (s)	OPERATIONAL TEST ICE DETECTION SYSTEM (MRB)						PKG		
30.010	PKG 800 REF: AMM 30 81 00 710 801	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
301104-001	NO. 1 ASSY, ANTI-ICING COUPLING								
30.015	601-80026-5 L-98197 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301104-002	NO. 2 ASSY, ANTI-ICING COUPLING								
30.015	601-80026-5 L-96886 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301107-001	NO. 1 WING ANTI-ICE COUPLING								
30.020	601-80033-1 L-96348 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301107-002	NO. 2 WING ANTI-ICE COUPLING								
30.020	601-80033-2 L-77483 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301200-001	TEMPERATURE CTRL/OVERHEAT SENSOR								
30.025	624384-2 124C-3033 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301200-002	TEMPERATURE CTRL/OVERHEAT SENSOR								
30.030	624384-2 124C-3036 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
301200-003	TEMPERATURE CTRL/OVERHEAT SENSOR								
30.035	624384-2 094C-2963 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301200-004	TEMPERATURE CTRL/OVERHEAT SENSOR								
30.040	624384-2 124C-3020 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301200-006	ANTI-ICE CONTROLLER								
30.045	624382-2 624382-00734 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301201-001	NO. 1 THERMAL SWITCH								
30.050	600-59122-21 4344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301201-002	NO. 2 THERMAL SWITCH								
30.050	600-59122-21 4344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301202-001	LH PRESSURE SWITCH								
30.055	642000-2 3877 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
301202-002	RH PRESSURE SWITCH								
30.055	642000-2 3863 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
302101-001	NO. 1 ASSY DUCT								
30.060	228-56041-101 SB/RJ/2710 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
302101-002	NO. 2 ASSY DUCT								
30.060	228-56041-101 SB/RJ/2709 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
302200-001	NO. 1 COWL ANTI-ICE VALVE								
30.065	601-97097-9 1290 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:74 R:0 N:630:30 R:0 N:4386 R:0			14-OCT-2011 1682:42 1282		
302200-002	NO. 2 COWL ANTI-ICE VALVE								
30.065	601-97097-9 1351 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			09-OCT-2008 796:15 627		
302201-001	LH COWL ANTI-ICE PRESSURE SWITCH								
	12681 4259 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
302201-002	RH COWL ANTI-ICE PRESSURE SWITCH								
	12681 4284 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
303116-001	NO. 1 AIR DATA SENSOR CONTROLLER								
30.070	604-59007-1 673 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
303116-002	NO. 2 AIR DATA SENSOR CONTROLLER								
30.070	604-59007-1 674 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
304100-001	NO. 1 DUAL THERMAL CONTROL								
30.075	600-59100-9 1453B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
304100-002	NO. 2 DUAL THERMAL CONTROL								
30.075	600-59100-9 1456B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
304100-701	NO. 1 SIDE WINDOW TEMPERATURE CONTROLLER								
	600-59100-13 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C						
304100-702	NO. 2 SIDE WINDOW TEMPERATURE CONTROLLER								
	600-59100-13 437B REF:	MOS HRS/MSC AFL	O/C				01-JUN-2016 2708:55 2019		
308101-001	NO. 1 ICE DETECTOR								
30.080	604-51262-1 1934 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
308101-002	NO. 2 ICE DETECTOR								
30.080	604-51262-1 1952 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

**CHAPTER 31 INDICATING/RECORDING SYSTEMS**



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
31-31-00-203 (s)	FUNCTIONAL TEST FLIGHT DATA RECORDER (FDR) DEDICATED SENSORS (A/C 5463 AND SUBS, POST SB 604-31-010)						PKG		
31.005	PKG 96 <b>REF:</b> AMM 31 31 01 720 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
31-31-00-204	FUNCTIONAL TEST FLIGHT DATA RECORDER (FDR) FORCE SENSORS (A/C 5551 AND SUBS, POST SB 604-31-014)								
31.010	<b>REF:</b> AMM 31 31 01 720 804	MOS HRS/MSC AFL	N/A				28-APR-2006 0 0		
31-41-00-201 (s)	OPERATIONAL TEST OF THE DATA CONCENTRATOR UNIT (DCU) (MASTER WARNING/MASTER CAUTION SIGNALS)						PKG		
31.015	PKG 600 <b>REF:</b> AMM 31 41 04 710 802	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
31-41-04-201 (s)	OPERATIONAL TEST DATA CONCENTRATOR UNIT OUTPUT BUS						PKG		
31.020	PKG 4800 <b>REF:</b> AMM 31 41 04 710 803	MOS HRS/MSC AFL	4800	+40/-40			08-MAY-2020 4328:45 2835		
31-41-04-202 (s)	FUNCTIONAL TEST DCU AURAL WARNING						PKG		
31.025	PKG 2400 <b>REF:</b> AMM 31 41 04 720 801	MOS HRS/MSC AFL	2400	+40/-40			08-MAY-2020 4328:45 2835		
31-61-01-201 (s)	CLEAN/RESTORE ELECTRONIC FLIGHT DISPLAY INLET COOLING SCREEN						PKG		
31.030 <b>RESTORE</b>	PKG 400 <b>REF:</b> AMM 31 61 01 160 803	MOS HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
311101-001	FLIGHT DISPLAY MOUNT								
31.035	822-0826-001 1NTFH <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C				07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
311101-002	FLIGHT DISPLAY MOUNT								
31.040	822-0826-001 1NFTG <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
311101-003	FLIGHT DISPLAY MOUNT								
31.045	822-0826-001 1NHWD <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
312101-001	NO. 1 DIGITAL CLOCK								
31.050	M877-5 15719 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
312101-002	NO. 2 DIGITAL CLOCK								
31.050	M877-5 21969 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:12 N:0 N:0			16-JUN-2014 2304:15 1731		
313000-001	FLIGHT DATA RECORDER								
31.055	2100-4043-00 000335844 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
313102-701	FDR SYSTEM ACCELEROMETER								
	3001-01-111 0705-8147 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
313103-701	FDR SYSTEM HARNESS								
	604-57591-1 P-S75868-02 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
313106-701	FDR SYSTEM PANEL 604-59024-1 335 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
313109-001 31.055	FDR (ULB) (ULD) UNDERWATER LOCATOR BEACON 068-E5542-00 ULB004479 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:21 N:0 N:0				23-MAR-2018 3512:30 2441	
313109-001A 31.055 LIFE LIMIT	DISCARD FDR (ULB) (ULD) UNDERWATER LOCATOR BEACON BATTERY (31-31-00-201) 068-E5542-00 ULB004479 REF: AMM 31 31 07 960 801	MOS HRS/MSC AFL	DUE					23-MAR-2018 3512:30 2441	<b>01-JUN-2023 M</b>
313109-001B 31.055	OPERATIONAL TEST FDR (ULB) (ULD) UNDERWATER LOCATOR BEACON (31-31-00-202) 068-E5542-00 ULB004479 REF: AMM 31 31 07 710 801	MOS HRS/MSC AFL	36	+1m/-1m				23-MAR-2018 3512:30 2441	<b>23-MAR-2021</b> 23-APR-2021
314101-001 31.060	CENTER EICAS CONTROL (ECP4003) PANEL 822-0180-102 1KLCG REF: See Workcard	MOS HRS/MSC AFL	O/C					18-APR-2006 23:48 15	
314101-004 31.065	NO. 1 DATA CONCENTRATOR UNIT (4002) DCU PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2005 0 0	
314101-005 31.065	NO. 2 DATA CONCENTRATOR UNIT (4002) DCU PN SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2005 0 0	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
314104-001	NO. 1 DATA CONCENTRATOR UNIT DCU								
31.070	822-0179-014 1RY YF REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
314104-002	NO. 2 DATA CONCENTRATOR UNIT DCU								
31.070	822-0179-014 1WKDH REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
315201-001	LAMP DRIVER UNIT								
	622-9822-001 1NLCN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
316101-001	NO. 1 ELECTRONIC FLIGHT DISPLAY								
31.075	622-9978-314 IXWIL REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
316101-002	NO. 2 ELECTRONIC FLIGHT DISPLAY								
31.080	622-9978-314 2078B REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
316101-003	NO. 3 ELECTRONIC FLIGHT DISPLAY								
31.085	622-9978-314 508M REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
316101-004	NO. 4 ELECTRONIC FLIGHT DISPLAY								
31.090	622-9978-314 NKXB REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
316101-005	NO. 5 ELECTRONIC FLIGHT DISPLAY 622-9978-314	MOS					08-MAY-2020		
31.095	IRWJB REF: See Workcard	HRS/MSC AFL	O/C				4328:45 2835		
316101-006	NO. 6 ELECTRONIC FLIGHT DISPLAY 622-9978-314	MOS					08-MAY-2020		
31.100	2155 REF: See Workcard	HRS/MSC AFL	O/C				4328:45 2835		
319002-701	ANNUNCIATOR DIMMING TEST UNIT 92-7001-03	MOS		N:0			19-APR-2006		
	989 REF:	HRS/MSC AFL	O/C	N:0 N:0			23:48 15		
<b>CHAPTER 32 LANDING GEAR</b>									
32-00-00-301	CLEANING OF THE LANDING GEAR AND UNDERCARRIAGE AREA	MOS							
	REF: AMM 32 00 00 140 801	HRS/MSC AFL	-						
32-00-01-201 (s)	FUNCTIONAL TEST LANDING GEAR EMERGENCY-EXTENSION SYST PKG 800	MOS					PKG 08-MAY-2020		
32.005	REF: AMM 32 34 00 720 801	HRS/MSC AFL	800	+40/-40			4328:45 2835		
32-00-01-202 (s)	FUNCTIONAL TEST MLG SHOCK STRUT ASSEMBLY PKG 1200	MOS					PKG 08-MAY-2020		
32.010	REF: AMM 32 11 07 720 801	HRS/MSC AFL	1200	+40/-40			4328:45 2835		
32-00-01-203 (s)	FUNCTIONAL TEST NLG SHOCK STRUT ASSEMBLY PKG 1200	MOS					PKG 08-MAY-2020		
32.015	REF: AMM 32 21 16 720 801	HRS/MSC AFL	1200	+40/-40			4328:45 2835		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-01-204 (s)	LUBRICATION OF MAIN LANDING GEAR PKG 400	MOS					PKG		
32.020	REF: AMM 12 20 04 640 802	HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
32-00-01-205 (s)	LUBRICATION OF THE NOSE LANDING GEAR PKG 400	MOS					PKG		
32.025	REF: AMM 12 20 04 640 801	HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
32-00-01-206 (s)	LUBRICATION MAIN LANDING GEAR (MLG) DOORS PKG 400	MOS					PKG		
32.030	REF: AMM 12 20 04 640 833	HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
32-00-01-207 (s)	LUBRICATION NOSE LANDING GEAR (NLG) DOORS PKG 400	MOS					PKG		
32.035	REF: AMM 12 20 04 640 832	HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
32-00-01-208 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION CABLE IN THE NLG WHEEL WELL PKG 48	MOS	48	+1m/-1m			PKG		
32.040	REF: AMM 32 34 28 220 802	HRS/MSC AFL					23-MAR-2018 3512:30 2441		
32-00-01-209 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION CABLE IN FORWARD AVIONICS COMPARTMENT PKG 48	MOS	48	+1m/-1m			PKG		
32.045	REF: AMM 32 34 28 220 803	HRS/MSC AFL					23-MAR-2018 3512:30 2441		
32-00-01-210 (s)	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION CABLE IN MAIN AVIONICS COMPARTMENT PKG 48	MOS	48	+1m/-1m			PKG		
32.050	REF: AMM 32 34 28 220 804	HRS/MSC AFL					23-MAR-2018 3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-00-01-211 (s)  32.055	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION CABLE IN MID-LWR FUSELAGE COMPARTMENT PKG 96  <b>REF:</b> AMM 32 34 28 220 805	MOS HRS/MSC AFL	96	+1m/-1m			PKG  16-JUN-2014 2304:15 1731		
32-00-01-212 (s)  32.060	DETAILED INSPECTION LANDING GEAR EMERGENCY EXTENSION CABLE IN THE MLG WHEEL WELL PKG 48  <b>REF:</b> AMM 32 34 28 220 806	MOS HRS/MSC AFL	48	+1m/-1m			PKG  23-MAR-2018 3512:30 2441		
32-00-01-213 (s)  32.065	GENERAL VISUAL INSPECTION MAIN LANDING GEAR ASSEMBLY PKG 600  <b>REF:</b> AMM 32 11 00 210 801	MOS HRS/MSC AFL	600	+40/-40			PKG  08-MAY-2020 4328:45 2835		
32-00-01-214 (s)  32.070	GENERAL VISUAL INSPECTION NOSE LANDING GEAR ASSEMBLY PKG 600  <b>REF:</b> AMM 32 21 01 210 801	MOS HRS/MSC AFL	600	+40/-40			PKG  08-MAY-2020 4328:45 2835		
32-00-01-215 (s)  32.075	DETAILED INSPECTION MAIN LANDING GEAR ASSEMBLY PKG 96  <b>REF:</b> AMM 32 11 00 220 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG  16-JUN-2014 2304:15 1731		
32-00-01-216 (s)  32.080	DETAILED INSPECTION NOSE LANDING GEAR ASSEMBLY PKG 96  <b>REF:</b> AMM 32 21 01 220 802	MOS HRS/MSC AFL	96	+1m/-1m			PKG  16-JUN-2014 2304:15 1731		
32-10-00-201  <b>MRB</b>	SPECIAL DETAILED INSPECTION LH MLG SIDE BRACE FITTING SHAFT PART NO. 601R10237-1 ONLY. 601R10237-3 HD0761 <b>REF:</b> NDT MT-32-10-001	MOS HRS/MSC AFL	N/A				16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-10-00-201	SPECIAL DETAILED INSPECTION RH MLG SIDE BRACE FITTING SHAFT PART NO. 601R10237-1 ONLY. 601R10237-3 HD0753	MOS HRS/MSC AFL	N/A				16-JUN-2014 2304:15 1731		
<b>MRB</b>	<b>REF: NDT MT-32-10-001</b>								
+ 32-11-00-102	DISCARD OF THE NO. 1 LH MAIN LANDING GEAR (MLG) FITTING, PART NO. 19062-1/-2 (NHA 19064-103/-104/-105/-106). 19064-105 07MDT0437	MOS HRS/MSC AFL	9625	I:2431			16-JUN-2014 2304:15 1731	<b>8925</b>	
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 00 961 802</b>								
+ 32-11-00-102	DISCARD OF THE NO. 2 RH MAIN LANDING GEAR (MLG) FITTING, PART NO. 19062-1/-2 (NHA 19064-103/-104/-105/-106). 19064-104 DCL338	MOS HRS/MSC AFL	9625	I:1731			16-JUN-2014 2304:15 1731	<b>9625</b>	
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 00 961 802</b>								
+ 32-11-00-103	DISCARD OF THE NO. 1 MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO. 19038-3. 19038-3 DCL676	MOS HRS/MSC AFL	9625				07-MAR-2005 0 0	<b>9625</b>	
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 00 961 801</b>								
+ 32-11-00-103	DISCARD OF THE NO. 2 MAIN LANDING GEAR (MLG) PINTLE PIN, PART NO. 19038-3. 19038-3 DCL675	MOS HRS/MSC AFL	9625				07-MAR-2005 0 0	<b>9625</b>	
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 00 961 801</b>								
+ 32-11-07-101	DISCARD OF THE NO. 1 MLG SHOCK STRUT UPPER PIN, PART NO. 19134-3 19134-3 12EXC1471	MOS HRS/MSC AFL	9625				16-JUN-2014 2304:15 1731	<b>11356</b>	
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 801</b>								



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-07-101	DISCARD OF THE NO. 2 MLG SHOCK STRUT UPPER PIN, PART NO. 19134-3								
	19134-3	MOS					07-MAR-2005		
	EXC-0654	HRS/MSC					0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 801</b>	<b>AFL</b>	<b>9625</b>				<b>0</b>	<b>9625</b>	
+ 32-11-07-102	DISCARD NO. 1 MLG SHOCK STRUT LOWER PIN (PART NO.19146-3)								
	19146-3	MOS					07-MAR-2005		
	MIL-0831	HRS/MSC					0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 802</b>	<b>AFL</b>	<b>9625</b>				<b>0</b>	<b>9625</b>	
+ 32-11-07-102	DISCARD NO. 2 MLG SHOCK STRUT LOWER PIN (PART NO.19146-3)								
	19146-3	MOS					07-MAR-2005		
	MIL-0832	HRS/MSC					0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 802</b>	<b>AFL</b>	<b>9625</b>				<b>0</b>	<b>9625</b>	
+ 32-11-07-103	DISCARD OF THE NO. 1 MLG SHOCK STRUT PISTON, PART NO. 19114-1/-3 (NHA 19115-101/-103).								
	19114-3	MOS					15-DEC-2011		
	DCL713	HRS/MSC					1700:40		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 803</b>	<b>AFL</b>	<b>9625</b>	<b>l:1282</b>			<b>1296</b>	<b>9639</b>	
+ 32-11-07-103	DISCARD OF THE NO. 2 MLG SHOCK STRUT PISTON, PART NO. 19114-1/-3 (NHA 19115-101/-103).								
	19115-103	MOS					07-MAR-2005		
	DCL752	HRS/MSC					0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 803</b>	<b>AFL</b>	<b>9625</b>				<b>0</b>	<b>9625</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-07-104	DISCARD NO. 1 SHOCK STRUT CYLINDER PART NO.19104-1/-3 (NHA 19105-101/-103). 19105-103 DCL813	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 804</b>	AFL	9625				0	<b>9625</b>	
+ 32-11-07-104	DISCARD NO. 2 SHOCK STRUT CYLINDER PART NO.19104-1/-3 (NHA 19105-101/-103). 19105-103 DCL812	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 07 961 804</b>	AFL	9625				0	<b>9625</b>	
+ 32-11-10-101	DISCARD NO.1 MAIN LANDING GEAR TRAILING ARM PART NO. 19083-3 (NHA 19084-103). 19084-103 DCL695	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 10 961 802</b>	AFL	18215				0	<b>18215</b>	
+ 32-11-10-101	DISCARD NO.2 MAIN LANDING GEAR TRAILING ARM PART NO. 19083-3 (NHA 19084-103). 19084-103 DCL687	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 10 961 802</b>	AFL	18215				0	<b>18215</b>	
+ 32-11-10-102	DISCARD NO. 1 MLG MAIN FITTING/TRAILING ARM PIVOT PIN (PART NO. 19039-1) 19039-1 MBM-0450	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 10 961 803</b>	AFL	9625				0	<b>9625</b>	
+ 32-11-10-102	DISCARD NO. 2 MLG MAIN FITTING/TRAILING ARM PIVOT PIN (PART NO. 19039-1) 19039-1 MBM-0458	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 10 961 803</b>	AFL	9625				0	<b>9625</b>	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-11-13-101	DISCARD NO. 1 MLG AXLE (PART NO.19050-3) 19050-3 DCL721	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 13 961 801</b>	AFL	9625				0	<b>9625</b>	
+ 32-11-13-101	DISCARD NO. 2 MLG AXLE (PART NO.19050-3) 19050-3 DCL723	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 11 13 961 801</b>	AFL	9625				0	<b>9625</b>	
32-12-00-201 32.095	DETAILED INSPECTION HINGE AND FASTENERS OF THE MLG DOOR  <b>REF: AMM 32 12 01 220 801</b>	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022
+ 32-21-00-102	DISCARD OF THE NLG MAIN FITTING, PART NO. 200811316 OR 20091-1 (NHA 200811269 OR 20090-101). 20090-101 MDS-0794	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 00 961 801</b>	AFL	9740				0	<b>9740</b>	
+ 32-21-00-103	DISCARD NO. 1 NLG PIVOT (TRUNNION) PIN (MAIN FITTING TO AIRCRAFT), (PART NO. 200811601) 200811601 13EXC1970	MOS HRS/MSC					16-JUN-2014 2304:15		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 00 961 802</b>	AFL	9740				1731	<b>11471</b>	
+ 32-21-00-103	DISCARD NO. 2 NLG PIVOT (TRUNNION) PIN (MAIN FITTING TO AIRCRAFT), (PART NO. 200811601) 200811601 13EXC1971	MOS HRS/MSC					16-JUN-2014 2304:15		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 00 961 802</b>	AFL	9740				1731	<b>11471</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-00-104	DISCARD NLG SHOCK STRUT SLIDING TUBE (PART NO.200811707) 200811707 MBM0365	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 16 961 801</b>	AFL	9740				0	<b>9740</b>	
+ 32-21-00-105	DISCARD NLG DRAG BRACE LOWER LINK PART NO.200814311 (NHA 200814213). 200814213 MIL1209	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 07 961 801</b>	AFL	9740				0	<b>9740</b>	
+ 32-21-00-106	DISCARD NLG DRAG BRACE UPPER LINK PART NO.20049-1/-3 (NHA 20050-101). 20050-101 DCL274	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 07 961 802</b>	AFL	9740				0	<b>9740</b>	
+ 32-21-00-107	DISCARD NLG DRAG BRACE HINGE PIN (PART NO.200814624) 200814624 MIL1495	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 07 961 803</b>	AFL	9740				0	<b>9740</b>	
+ 32-21-07-102	DISCARD NOSE LANDING GEAR ATTACHMENT PIN (MAIN FITTING TO DRAG BRACE), PART NO. 200811721 200811721 MIL0121	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 07 961 804</b>	AFL	9740				0	<b>9740</b>	
+ 32-21-07-103	DISCARD NO. 1 NOSE LANDING GEAR DRAG BRACE UPPER PIVOT PIN (PART NO.200814601) 200814601 RTC-1406	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 07 961 805</b>	AFL	9740				0	<b>9740</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-21-07-103	DISCARD NO. 2 NOSE LANDING GEAR DRAG BRACE UPPER PIVOT PIN (PART NO.200814601) 200814601 RTC-1421	MOS HRS/MSC AFL					07-MAR-2005 0 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 07 961 805</b>		9740					<b>9740</b>	
+ 32-21-13-101	DISCARD NLG AXLE FITTING PART NO. 200811308 (NHA 200811218) 200811218 SAM-1019	MOS HRS/MSC AFL					07-MAR-2005 0 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 13 961 801</b>		9740					<b>9740</b>	
+ 32-21-13-102	DISCARD NOSE LANDING GEAR (SLIDING TUBE TO END FITTING) PIN (PART NO. 200811602) 200811602 MY0138	MOS HRS/MSC AFL					07-MAR-2005 0 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 21 13 961 802</b>		9740					<b>9740</b>	
+ 32-32-01-102	DISCARD NO. 1 MAIN LANDING GEAR SIDESTAY PIN PART NO. 6318-1/-3 (NHA 6350-1/-3) 6350-3 12SPP00324	MOS HRS/MSC AFL					16-JUN-2014 2304:15 1731		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 802</b>		9625					<b>11356</b>	
+ 32-32-01-102	DISCARD NO. 2 MAIN LANDING GEAR SIDESTAY PIN PART NO. 6318-1/-3 (NHA 6350-1/-3) 6350-3 12SPP00375	MOS HRS/MSC AFL					16-JUN-2014 2304:15 1731		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 802</b>		9625					<b>11356</b>	
+ 32-32-01-103	DISCARD NO. 1 MAIN LANDING GEAR SIDE STAY ACTUATOR EYE BOLT (ROD-END), PART NO.19400-2 (NHA 19400-1). 19400-1 0705	MOS HRS/MSC AFL					16-JUN-2014 2304:15 1731		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 801</b>		21945					<b>23676</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 32-32-01-103	DISCARD NO. 2 MAIN LANDING GEAR SIDE STAY ACTUATOR EYE BOLT (ROD-END), PART NO.19400-2 (NHA 19400-1). 19400-1 0863	MOS HRS/MSC					16-JUN-2014 2304:15		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 801</b>	AFL	21945				1731	<b>23676</b>	
+ 32-32-01-104	DISCARD NO. 1 MLG SIDE STAY ACTUATOR CYLINDER PART NO. 17027-8 (NHA 17027-9). 17027-8 938C	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 803</b>	AFL	21945				0	<b>21945</b>	
+ 32-32-01-104	DISCARD NO. 2 MLG SIDE STAY ACTUATOR CYLINDER PART NO. 17027-8 (NHA 17027-9). 17027-8 933C	MOS HRS/MSC					07-MAR-2005 0		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 803</b>	AFL	21945				0	<b>21945</b>	
+ 32-32-01-105	DISCARD NO. 1 MAIN LANDING GEAR SIDE STAY ACTUATOR PISTON (PART NO. 17014-6/-8) 17014-8 3973	MOS HRS/MSC					16-JUN-2014 2304:15		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 804</b>	AFL	21945				1731	<b>23676</b>	
+ 32-32-01-105	DISCARD NO. 2 MAIN LANDING GEAR SIDE STAY ACTUATOR PISTON (PART NO. 17014-6/-8) 17014-8 3978	MOS HRS/MSC					16-JUN-2014 2304:15		
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>	<b>REF: AMM 32 32 01 961 804</b>	AFL	21945				1731	<b>23676</b>	
32-40-00-201 (s)	FUNCTIONAL TEST BRAKE ACCUMULATORS PKG 800	MOS HRS/MSC	800	+40/-40			PKG 08-MAY-2020 4328:45		
32.100	<b>REF: AMM 32 43 07 720 801</b>	AFL					2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-40-00-204 (s)	LUBRICATION MLG BRAKE CONTROL VALVE ASSEMBLY						PKG		
32.105	PKG 800 REF: AMM 12 20 04 640 825	MOS HRS/MSC AFL	800	+40/-40			08-MAY-2020 4328:45 2835		
32-40-00-205 (s)	DETAILED INSPECTION BRAKE WEAR PINS						PKG		
32.110	PKG 600 REF: AMM 32 43 19 220 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
32-50-00-201 (s)	OPERATIONAL TEST NOSEWHEEL STEERING SELECTOR/ARMING VALVE						PKG		
32.115	PKG 400 REF: AMM 32 51 00 710 803	MOS HRS/MSC AFL	400	+40/-40			12-DEC-2020 4614 2973		
32-50-00-202	OPERATIONAL TEST NOSE WHEEL STEERING ELECTRONIC CONTROL MODULE (ECM) P/N 601-86100-13, VENDOR P/N 7040-13/15								
32.120	601-86100-23 04-133 REF: AMM 32 51 31 710 801	MOS HRS/MSC AFL	N/A				22-MAR-2011 1551:30 1194		
32-ZL-00-204 (s)	GENERAL VISUAL INSPECTION LEFT NOSE LANDING GEAR DOOR						PKG		
32.125	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
32-ZL-00-205 (s)	GENERAL VISUAL INSPECTION RIGHT NOSE LANDING GEAR DOOR						PKG		
32.125	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
32-ZL-00-206 (s)	GENERAL VISUAL INSPECTION AFT NOSE LANDING GEAR DOOR						PKG		
32.125	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
32-ZL-00-207 (s) 32.130	GENERAL VISUAL INSPECTION LEFT MLG DOOR PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
32-ZL-00-208 (s) 32.130	GENERAL VISUAL INSPECTION RIGHT MLG DOOR PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
320002-001 32.135	NO. 1 MLG LH MAIN FITTING 19064-105 07MDT0437 <b>REF:</b> AMM 32 11 00 961 802	MOS HRS/MSC AFL	H/T	N:2936:34 O:0 N:2431 O:0			16-JUN-2014 2304:15 1731		
320002-002 32.135	NO. 2 MLG RH MAIN FITTING 19064-104 DCL338 <b>REF:</b> AMM 32 11 00 961 802	MOS HRS/MSC AFL	H/T	N:111 N:2304:15 N:1731			16-JUN-2014 2304:15 1731	<b>11029 M</b>	
320004-001 32.140	NO. 1 SHOCK STRUT CYLINDER 19105-103 DCL813 <b>REF:</b> AMM 32 11 07 961 804	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
320004-002 32.140	NO. 2 SHOCK STRUT CYLINDER 19105-103 DCL812 <b>REF:</b> AMM 32 11 07 961 804	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
320005-001 32.145	NO. 1 SHOCK STRUT PISTON 19114-3 DCL713 <b>REF:</b> AMM 32 11 07 961 803	MOS HRS/MSC AFL	H/T	R:0 N:1682:42 R:0 N:1282 R:0			15-DEC-2011 1700:40 1296		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320005-002	NO. 2 SHOCK STRUT PISTON								
32.145	19115-103 DCL752 REF: AMM 32 11 07 961 803	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
320007-001	NO. 1 MAIN LANDING GEAR SIDESTAY PIN								
32.150	6350-3 12SPP00324 REF: AMM 32 32 01 961 802	MOS HRS/MSC AFL	H/T	N:0 N:0			16-JUN-2014 2304:15 1731		
320007-002	NO. 2 MAIN LANDING GEAR SIDESTAY PIN								
32.150	6350-3 12SPP00375 REF: AMM 32 32 01 961 802	MOS HRS/MSC AFL	H/T	N:0 N:0			16-JUN-2014 2304:15 1731		
320008-001	NO. 1 MAIN LANDING GEAR SIDE STAY ACTUATOR PISTON								
32.155	17014-8 3973 REF: AMM 32 32 01 961 804	MOS HRS/MSC AFL	H/T	N:0 N:0			16-JUN-2014 2304:15 1731		
320008-002	NO. 2 MAIN LANDING GEAR SIDE STAY ACTUATOR PISTON								
32.155	17014-8 3978 REF: AMM 32 32 01 961 804	MOS HRS/MSC AFL	H/T	N:0 N:0			16-JUN-2014 2304:15 1731		
320009-001	NO. 1 MAIN LANDING GEAR SIDE STAY ACTUATOR EYE BOLT								
32.160	19400-1 0705 REF: AMM 32 32 01 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0			16-JUN-2014 2304:15 1731		
320009-002	NO. 2 MAIN LANDING GEAR SIDE STAY ACTUATOR EYE BOLT								
32.160	19400-1 0863 REF: AMM 32 32 01 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0			16-JUN-2014 2304:15 1731		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
320011-001	NO. 1 MLG SIDE STAY ACTUATOR CYLINDER								
32.165	17027-8 938C REF: AMM 32 32 01 961 803	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
320011-002	NO. 2 MLG SIDE STAY ACTUATOR CYLINDER								
32.165	17027-8 933C REF: AMM 32 32 01 961 803	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
320012-001	NO. 1 PINTLE MLG PIN								
32.170	19038-3 DCL676 REF: AMM 32 11 00 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
320012-002	NO. 2 PINTLE MLG PIN								
32.170	19038-3 DCL675 REF: AMM 32 11 00 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321100-001	LH MLG DOWNLOCK SENSOR #1 HARNESS								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
321100-002	RH MLG DOWNLOCK SENSOR #1 HARNESS								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
321101-001	LH MLG DOWNLOCK SENSOR #2 HARNESS								
	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321101-002	RH MLG DOWNLOCK SENSOR #2 HARNESS PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
321102-001	MLG WOW SENSOR #2 (LH OUTBD) HARNESS 19300-123 14-141 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			16-JUN-2014 2304:15 1731		
321102-002	MLG WOW SENSOR #1 (LH INBD) HARNESS 19300-103 12-501 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:3 N:2684:30 R:0 N:1270 R:0			16-JUN-2014 2304:15 1731		
321102-003	MLG WOW SENSOR #1 (RH INBD) HARNESS 19300-104 13-083 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:10 N:7875:24 R:0 N:4845 R:0			16-JUN-2014 2304:15 1731		
321102-004	MLG WOW SENSOR #2 (RH OUTBD) HARNESS 19300-124 15-009 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:9 N:3700 R:0 N:2564 R:0			16-JUN-2014 2304:15 1731		
321106-001	NO. 1 MLG AXLE 19050-3 DCL721 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321106-002	NO. 2 MLG AXLE 19050-3 DCL723 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321107-001	NO. 1 MLG SHOCK ABSORBER								
32.180	604-85001-5 DCL651/05 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
321107-002	NO. 2 MLG SHOCK ABSORBER								
32.180	604-85001-5 DCL650/05 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
321108-001	NO. 1 MLG SHOCK STRUT LOWER PIN								
32.185	19146-3 MIL-0831 REF: AMM 32 11 07 961 802	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321108-002	NO. 2 MLG SHOCK STRUT LOWER PIN								
32.185	19146-3 MIL-0832 REF: AMM 32 11 07 961 802	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321108-003	NO. 1 MLG SHOCK STRUT UPPER PIN								
32.190	19134-3 12EXC1471 REF: AMM 32 11 07 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			16-JUN-2014 2304:15 1731		
321108-004	NO. 2 MLG SHOCK STRUT UPPER PIN								
32.190	19134-3 EXC-0654 REF: AMM 32 11 07 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321109-001	NO. 1 MLG MAIN FITTING/TRAILING ARM PIVOT PIN								
32.195	19039-1 MBM-0450 REF: AMM 32 11 10 961 803	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321109-002	NO. 2 MLG MAIN FITTING/TRAILING ARM PIVOT PIN								
32.195	19039-1 MBM-0458 <b>REF:</b> AMM 32 11 10 961 803	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321110-001	NO.1 MAIN LANDING GEAR TRAILING ARM								
32.200	19084-103 DCL695 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321110-002	NO.2 MAIN LANDING GEAR TRAILING ARM								
32.200	19084-103 DCL687 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
321111-001	LEFT MAIN GEAR ASSEMBLY								
32.205	604-85001-25 DCL319/05 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:1682:42 N:1282			15-DEC-2011 1700:40 1296		
321111-001A	RESTORATION (OVERHAUL) LEFT MAIN GEAR ASSEMBLY (32-00-01-217)								
32.085 <b>OVERHAUL</b>	604-85001-25 DCL319/05 <b>REF:</b> AMM 32 11 00 280 801	MOS HRS/MSC AFL	192	+1m/-1m			28-APR-2006	<b>28-APR-2022</b>	28-MAY-2022
321111-002	RIGHT MAIN GEAR ASSEMBLY								
32.205	604-85001-26 DCL318/05 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:1682:42 N:1282			15-DEC-2011 1700:40 1296		
321111-002A	RESTORATION (OVERHAUL) RIGHT MAIN GEAR ASSEMBLY (32-00-01-217)								
<b>OVERHAUL</b>	604-85001-26 DCL318/05 <b>REF:</b> AMM 32 11 00 280 801	MOS HRS/MSC AFL	192	+1m/-1m			28-APR-2006	<b>28-APR-2022</b>	28-MAY-2022

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
321201-001	MLG LH DOOR								
32.210	604-31178-5 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
321201-002	MLG RH DOOR								
32.210	604-31178-6 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322100-001	NOSE LANDING GEAR ASSY								
32.215	604-85002-41 DCL320/05 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322100-001A	RESTORATION (OVERHAUL) NOSE LANDING GEAR ASSY (32-00-01-218)								
32.090 <b>OVERHAUL</b>	604-85002-41 DCL320/05 REF: AMM 32 21 01 280 801	MOS HRS/MSC AFL	192	+1m/-1m			28-APR-2006 0 0	<b>28-APR-2022</b>	28-MAY-2022
322101-001	SHOCK STRUT ASSY								
32.220	20030-103 DCL320/05 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322102-001	NOSE WHEEL POSITION FEEDBACK ASSY STEERING CONTR.								
32.225	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322104-001	STEERING AND FEEDBACK CONTROL								
32.230	7102-7 DCL714/05 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322105-001	NLG MAIN FITTING								
32.235	20090-101 MDS-0794 REF: AMM 32 21 00 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322106-001	NO. 1 NLG PIVOT (TRUNNION) PIN								
32.240	200811601 13EXC1970 REF: AMM 32 21 00 961 802	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			16-JUN-2014 2304:15 1731		
322106-002	NO. 2 NLG PIVOT (TRUNNION) PIN								
32.240	200811601 13EXC1971 REF: AMM 32 21 00 961 802	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			16-JUN-2014 2304:15 1731		
322107-001	NLG DRAG BRACE ASSY								
32.245	20045-103 DCL329/05 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322108-001	NLG SHOCK STRUT SLIDING TUBE								
32.250	200811707 MBM0365 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322109-001	NLG DRAG BRACE LOWER LINK								
32.255	200814213 MIL1209 REF: AMM 32 21 07 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322110-001	NLG DRAG BRACE UPPER LINK								
32.260	20050-101 DCL274 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322111-002	NLG DRAG BRACE HINGE PIN								
32.265	200814624 MIL1495 REF: AMM 32 21 07 961 803	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322113-001	NO. 1 NOSE LANDING GEAR DRAG BRACE UPPER PIVOT PIN								
32.270	200814601 RTC-1406 REF: AMM 32 21 07 961 805	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322113-002	NO. 2 NOSE LANDING GEAR DRAG BRACE UPPER PIVOT PIN								
32.270	200814601 RTC-1421 REF: AMM 32 21 07 961 805	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322114-001	NLG RETRACTION ACTUATOR								
32.275	104471003 FAH0633 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322115-001	NOSE LANDING GEAR ATTACHMENT PIN								
32.280	200811721 MIL0121 REF: AMM 32 21 07 961 804	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322116-001	NLG AXLE FITTING								
32.285	200811218 SAM-1019 REF: AMM 32 21 13 961 801	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		
322117-001	NLG DOWNLOCK (LH) SENSOR #1 DRAG BRACE ASSY HARNESS								
	19300-251 10-344 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
322118-001	NLG DOWNLOCK (LH) SENSOR #2 DRAG BRACE ASSY HARNESS 19300-261 11-343 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322201-001	L/H NLG FORWARD DOOR ASSEMBLY 600-33043-961 6652921 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322201-002	R/H NLG FORWARD DOOR ASSEMBLY 600-33043-962 6652934 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322204-001	NLG AFT DOOR 600-33044-1005/01 4197129 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322207-001	NOSE LANDING GEAR DOOR MECHANISM ACTUATOR 600-75136-5 HAI1405 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
322213-001	NOSE LANDING GEAR DOOR SELECTOR VALVE 601R75146-1 0946T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			18-APR-2006 23:48 15		
322216-003	NOSE LANDING GEAR (SLIDING TUBE TO END FITTING) PIN 200811602 MY0138 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323101-001	LANDING GEAR CONTROL HANDLE ASSY								
32.315	601R50967-11 1581 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323101-001A	RESTORATION LANDING GEAR CONTROL HANDLE ASSY (32-31-01-101) (CMR)								
32.315	601R50967-11 1581 REF: AMM 32 31 03 160 801	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
323101-001B	RESTORATION LANDING GEAR CONTROL HANDLE ASSY (32-31-01-102) (CMR)								
32.315	601R50967-11 1581 REF: AMM 32 31 03 160 801	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
323101-001C	DETAILED INSPECTION LANDING GEAR CONTROL HANDLE ASSY (32-31-01-103) (CMR)								
32.315	601R50967-11 1581 REF: AMM 32 31 02 220 801	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
323202-001	NO. 1 MLG SIDE STAY ACTUATOR								
32.320	604-85001-9 00664 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323202-002	NO. 2 MLG SIDE STAY ACTUATOR								
32.320	604-85001-9 00661 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323204-001	NOSE LANDING GEAR UPLOCK ASSEMBLY								
32.325	601R85002-91 DH-0152-04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323205-001	NO. 1 MLG UPLOCK ASSEMBLY								
32.330	601R85001-11 DH-0296-04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323205-002	NO. 2 MLG UPLOCK ASSEMBLY								
32.330	601R85001-11 DH-0403-04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323207-001	MLG SELECTOR VALVE								
32.335	601R75145-1 0379T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323210-001	MLG PRIORITY VALVE								
32.340	4619-3 1792B REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323213-001	MLG RUNAROUND & BYPASS VALVE								
32.345	601R75160-5 0288T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323305-001	NLG RETRACTION ACTUATOR (LOWER) PIN								
32.350	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323307-001	NOSE LANDING GEAR SELECTOR VALVE								
32.355	601R75146-1 0751T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
323310-001	NLG PRIORITY VALVE								
32.360	4622 1877A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323404-001	NO. 1 DOWNLOCK ASSIST ACTUATOR								
32.365	600-85001-87 DCL1155/05 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323404-002	NO. 2 DOWNLOCK ASSIST ACTUATOR								
32.365	600-85001-87 DCL1150/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323422-001	NO. 1 HYDRAULIC BYPASS VALVE								
32.370	600-75120-3 1361 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
323425-001	NO. 2 HYDRAULIC BYPASS VALVE								
32.370	600-75120-3 1359 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324101-001	LOB MLG WHEEL ASSEMBLY								
32.375	5012373 DEC11-3594 REF: See Workcard	MOS HRS/MSC AFL	O/C				05-DEC-2019 4227:15 2780		
324101-001A	SPECIAL DETAILED INSPECTION LOB MLG WHEEL ASSEMBLY (32-40-00-202)								
32.375	5012373 DEC11-3594 REF: AMM 32 41 01 280 801	MOS HRS/MSC AFL	A/R				05-DEC-2019 4227:15 2780		
MRB									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324101-001B	DETAILED INSPECTION LOB MLG WHEEL ASSEMBLY (32-40-00-206)								
	5012373	MOS					05-DEC-2019		
	DEC11-3594	HRS/MSC	T/C				4227:15		
<b>MRB</b>	<b>REF: AMM 32 41 01 220 802</b>	AFL					2780		
324101-001C	RESTORE/OVERHAUL LOB MLG WHEEL ASSEMBLY (32-40-00-207)								
	5012373	MOS							
	DEC11-3594	HRS/MSC	A/R						
<b>OVERHAUL</b>	<b>REF: AMM 32 41 01 615 801</b>	AFL							
324101-002	LIB MLG WHEEL ASSEMBLY								
	5012373	MOS		R:7			12-DEC-2020		
32.380	JAN09-3011	HRS/MSC	O/C	R:285:15			4614		
	<b>REF: See Workcard</b>	AFL		R:138			2973		
324101-002A	SPECIAL DETAILED INSPECTION LIB MLG WHEEL ASSEMBLY (32-40-00-202)								
	5012373	MOS					08-MAY-2020		
32.380	JAN09-3011	HRS/MSC	A/R				4328:45		
<b>OVERHAUL</b>	<b>REF: AMM 32 41 01 280 801</b>	AFL					2835		
324101-002B	DETAILED INSPECTION LIB MLG WHEEL ASSEMBLY (32-40-00-206)								
	5012373	MOS					08-MAY-2020		
	JAN09-3011	HRS/MSC	T/C				4328:45		
<b>MRB</b>	<b>REF: AMM 32 41 01 220 802</b>	AFL					2835		
324101-002C	RESTORE/OVERHAUL LIB MLG WHEEL ASSEMBLY (32-40-00-207)								
	5012373	MOS					24-OCT-2019		
	JAN09-3011	HRS/MSC	A/R				4170:15		
<b>OVERHAUL</b>	<b>REF: AMM 32 41 01 615 801</b>	AFL					2746		
324101-003	RIB MLG WHEEL ASSEMBLY								
	5012373	MOS					12-DEC-2020		
32.385	NOV08-2960	HRS/MSC	O/C				4614		
	<b>REF: See Workcard</b>	AFL					2973		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324101-003A	SPECIAL DETAILED INSPECTION RIB MLG WHEEL ASSEMBLY (32-40-00-202)								
32.385	5012373 NOV08-2960 <b>REF:</b> AMM 32 41 01 280 801	MOS HRS/MSC AFL	A/R				05-DEC-2019 4227:15 2780		
<b>MRB</b>									
324101-003B	DETAILED INSPECTION RIB MLG WHEEL ASSEMBLY (32-40-00-206)								
	5012373 NOV08-2960 <b>REF:</b> AMM 32 41 01 220 802	MOS HRS/MSC AFL	T/C				05-DEC-2019 4227:15 2780		
<b>MRB</b>									
324101-003C	RESTORE/OVERHAUL RIB MLG WHEEL ASSEMBLY (32-40-00-207)								
	5012373 NOV08-2960 <b>REF:</b> AMM 32 41 01 615 801	MOS HRS/MSC AFL	A/R						
<b>OVERHAUL</b>									
324101-004	ROB MLG WHEEL ASSEMBLY								
32.390	5012373 SEP12-3761 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:3 R:0 R:0			14-JUL-2017 3188:48 2263		
324101-004A	SPECIAL DETAILED INSPECTION ROB MLG WHEEL ASSEMBLY (32-40-00-202)								
32.390	5012373 SEP12-3761 <b>REF:</b> AMM 32 41 01 280 801	MOS HRS/MSC AFL	A/R	I:772			14-JUL-2017 3188:48 2263		
<b>MRB</b>									
324101-004B	DETAILED INSPECTION ROB MLG WHEEL ASSEMBLY (32-40-00-206)								
	5012373 SEP12-3761 <b>REF:</b> AMM 32 41 01 220 802	MOS HRS/MSC AFL	T/C	I:772			14-JUL-2017 3188:48 2263		
<b>MRB</b>									
324101-004C	RESTORE/OVERHAUL ROB MLG WHEEL ASSEMBLY (32-40-00-207)								
	5012373 SEP12-3761 <b>REF:</b> AMM 32 41 01 615 801	MOS HRS/MSC AFL	A/R	I:772			14-JUL-2017 3188:48 2263		
<b>OVERHAUL</b>									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324102-001	LOB MLG TIRE								
32.395	027-697-0 9002R00255 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			05-DEC-2019 4227:15 2780		
324102-002	LIB MLG TIRE								
32.400	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-DEC-2020 4614 2973		
324102-003	RIB MLG TIRE								
32.400	PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C				12-DEC-2020 4614 2973		
324102-004	ROB MLG TIRE								
32.395	027-697-0 5100S00381 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:26 N:0 N:0			14-JUL-2017 3188:48 2263		
324201-001	NO. 1 NLG WHEEL ASSEMBLY								
32.405	5010598 APR14-8327 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				02-NOV-2020 4564:55 2944		
324201-001A	SPECIAL DETAILED INSPECTION NO. 1 NLG WHEEL ASSEMBLY (32-40-00-203)								
32.405	5010598 APR14-8327 <b>REF:</b> AMM 32 42 01 280 801	MOS HRS/MSC AFL	A/R						
<b>MRB</b>									
324201-001B	DETAILED INSPECTION NO. 1 NLG WHEEL ASSEMBLY (32-40-00-208)								
32.405	5010598 APR14-8327 <b>REF:</b> AMM 32 42 01 220 801	MOS HRS/MSC AFL	T/C						
<b>MRB</b>									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324201-001C	RESTORE/OVERHAUL NO. 1 NLG WHEEL ASSEMBLY (32-40-00-209)								
<b>OVERHAUL</b>	5010598 APR14-8327 <b>REF:</b> AMM 32 42 01 615 801	MOS HRS/MSC AFL	A/R						
324201-002	NO. 2 NLG WHEEL ASSEMBLY								
32.410	5010598 JAN05-5885 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	R:5 R:312:30 R:135			16-OCT-2019 4160 2739		
324201-002A	SPECIAL DETAILED INSPECTION NO. 2 NLG WHEEL ASSEMBLY (32-40-00-203)								
32.410 <b>MRB</b>	5010598 JAN05-5885 <b>REF:</b> AMM 32 42 01 280 801	MOS HRS/MSC AFL	A/R				24-MAY-2019 3847:30 2604		
324201-002B	DETAILED INSPECTION NO. 2 NLG WHEEL ASSEMBLY (32-40-00-208)								
<b>MRB</b>	5010598 JAN05-5885 <b>REF:</b> AMM 32 42 01 220 801	MOS HRS/MSC AFL	T/C				24-MAY-2019 3847:30 2604		
324201-002C	RESTORE/OVERHAUL NO. 2 NLG WHEEL ASSEMBLY (32-40-00-209)								
<b>OVERHAUL</b>	5010598 JAN05-5885 <b>REF:</b> AMM 32 42 01 615 801	MOS HRS/MSC AFL	A/R				24-MAY-2019 3847:30 2604		
324202-001	NO. 1 NLG TIRE								
32.415	031-614-0 7059S00473 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			02-NOV-2020 4564:55 2944		
324202-002	NO. 2 NLG TIRE								
32.415	031-614-0 6184S00303 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				16-OCT-2019 4160 2739		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324304-001	NO. 2 OUTBOARD BRAKE CONTROL VALVE 604-75115-5 0100T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324304-002	BOTTOM (NO. 2) HYDRAULIC BRAKE CONTROL VALVE PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324304-003	TOP (NO. 3) HYDRAULIC BRAKE CONTROL VALVE 604-75115-5 0097T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324307-001	#2 OUTBOARD HYDRAULIC / BRAKE SYSTEM ACCUMULATOR 601R75138-1 60163-4892 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324307-002	#3 INBOARD HYDRAULIC / BRAKE SYSTEM ACCUMULATOR 601R75138-1 60163-4887 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324313-002	NO. 2 BRAKE ACCUMULATOR INDICATING GAUGE 600-75125-3 04-111571 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324313-003	NO. 3 BRAKE ACCUMULATOR INDICATING GAUGE 600-75125-3 04-1208274 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324316-001	NO. 1 BRAKE VOLUMETRIC HYDR FUSE								
32.435	601R75150-1 5623 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324316-002	NO. 2 BRAKE VOLUMETRIC HYDR FUSE								
32.440	601R75150-1 7262 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:12 N:0 N:0			16-JUN-2014 2304:15 1731		
324316-003	NO. 3 BRAKE VOLUMETRIC HYDR FUSE								
32.445	601R75150-1 5661 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324316-004	NO. 4 BRAKE VOLUMETRIC HYDR FUSE								
32.450	601R75150-1 5630 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324316-005	LANDING GEAR SELECTOR VALVE								
32.455	601R75149-1 0343T REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324319-001	LOB ASSY BRAKE								
32.460	604-85123-101 MAY03-1231 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			08-MAY-2020 4328:45 2835		
324319-002	LIB ASSY BRAKE								
32.465	604-85123-101 JUL12-2557 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-AUG-2017 3225:35 2281		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324319-003	RIB ASSY BRAKE 604-85123-101 JUN98-0395 REF: See Workcard	MOS HRS/MSC AFL	O/C				09-APR-2019 3744:03 2558		
324319-004	ROB ASSY BRAKE 604-85123-101 MAY02-1154 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
324320-001	RELIEF VALVE P44-771 04-0903105 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324401-001	NO. 1 WHEEL SPEED TRANSDUCER 604-87000-1 1392 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324401-002	NO. 2 WHEEL SPEED TRANSDUCER 604-87000-1 1402 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324401-003	NO. 3 WHEEL SPEED TRANSDUCER 604-87000-1 1399 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324401-004	NO. 4 WHEEL SPEED TRANSDUCER 604-87000-1 1401 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324404-001	ANTI-SKID CONTROL UNIT								
32.495	604-87000-9 439 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324407-001	NO. 1 BRAKE ANTI-SKID VALVE								
32.500	604-87000-5 767 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324407-002	NO. 2 BRAKE ANTI-SKID VALVE								
32.505	604-87000-5 749 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324501-001	PARKING BRAKE CABLE CONTROL								
32.510	601R88005-1 1571 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			07-FEB-2007 218:25 182		
324504-001	LH BRAKE CONTROL - PILOT CABLE								
	600-88003-9 2743 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324504-002	RH BRAKE CONTROL - PILOT CABLE								
	600-88003-9 2627 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324507-001	LH BRAKE CONTROL - COPILOT CABLE								
	600-88004-35 1496 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
324507-002	RH BRAKE CONTROL - COPILOT CABLE 600-88004-33 1455 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324513-001 32.515	PARKING BRAKE SHUTOFF VALVE 604-75401-5 327 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324701-001 32.520	INBOARD HYDRAULIC PRESSURE TRANSDUCER 600-59174-17 7052-2-137 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
324701-002 32.520	OUTBOARD HYDRAULIC PRESSURE TRANSDUCER 600-59174-17 7052-5-95 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
325100-001 32.525	NLG STEERING COMPENSATOR 600-85002-13 CEP-0013 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
325101-001 32.530	NOSE WHEEL STEERING HANDWHEEL 601-86100-21 DCL671/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
325104-001 32.535	NOSE WHEEL (RUDDER) STEERING COMMAND POTENTIOMETER 601-86100-17 051-12 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
325113-001	NOSE WHEEL STEERING ELECTRONIC CONTROL								
32.120	601-86100-23 04-133 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
325116-001	AFT NLG STEERING SELECTOR VALVE								
32.540	600-85002-11 DH-0106-04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
325116-002	FWD NLG STEERING SELECTOR VALVE								
32.540	600-85002-11 DH-0110-04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
326005-001	NLG STEERING HARNESS								
	19300-231 9-264 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
326101-001	PROXIMITY SENSOR CONTROL UNIT								
32.545	604-50969-7 F188 REF: See Workcard	MOS HRS/MSC AFL	O/C				06-OCT-2015 2597:30 1956		
326107-001	LH NOSE GEAR BAY HARNESS SUB ASSY								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
326107-002	RH NOSE GEAR BAY HARNESS SUB ASSY								
	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
326108-001	LH N/W DISC HARNESS SUB ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
326108-002	RH N/W DISC HARNESS SUB ASSY PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
335002-701	EXIT (SELF POWERED) SIGN AC/31-BA A11-2434 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			08-APR-2016 2660:45 1999		
<b>CHAPTER 33 LIGHTS</b>									
33-24-60-601 (s)	OPERATIONAL TEST OF THE ORDINANCE SIGNS PKG 12 REF:	MOS HRS/MSC AFL	12				PKG 08-MAY-2020 4328:45 2835		
33-50-00-202 (s)	OPERATIONAL TEST OF THE EMERGENCY LIGHTS PKG 12 REF: AMM 33 51 00 710 801	MOS HRS/MSC AFL	12	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
33-51-60-601 (s)	OPERATIONAL TEST OF THE INTERIOR EMERGENCY LIGHTS PKG 12 REF:	MOS HRS/MSC AFL	12				PKG 08-MAY-2020 4328:45 2835		
33-51-60-602 (s)	OPERATIONAL TEST OF THE INTERIOR EMERGENCY LIGHTS BATTERY PACKS PKG 12 REF:	MOS HRS/MSC AFL	12				PKG 08-MAY-2020 4328:45 2835		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
330023-701	CABIN FLUORESCENT LAMP AL123ST-1168B N/A <b>REF:</b>	MOS HRS/MSC AFL	O/C				26-JUN-2008 700:18 574		
330024-701	DIMMING INTERFACE (LOWER GALLEY) MODULE AL-2502 1863 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
330024-702	DIMMING INTERFACE (LOWER GALLEY) MODULE AL-2502 1850 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
331006-701	DIMMER CONTROL LH TOP FS280 ASSEMBLY 70-0180-3 5489 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
331007-701	DIMMER CONTROL RH TOP FS280 ASSEMBLY 70-0180-3 5518 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
331204-001 33.015	POWER SUPPLY PS643 A109567 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
331210-001 33.020	OVERHEAD POWER SUPPLY PS643 A105944 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
331307-001	NO. 1 READING LIGHT 2LA005163-25	MOS		N:0			07-MAR-2005		
33.025	1035151 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
331307-002	NO. 2 READING LIGHT 2LA005163-25	MOS		N:0			07-MAR-2005		
33.025	1035156 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
332001-701	GALLEY POWER SUPPLY UNIT AL-2000	MOS		N:0			19-APR-2006		
	47171 REF:	HRS/MSC AFL	O/C	N:0 N:0			23:48 15		
332001-702	GALLEY POWER SUPPLY UNIT AL-2000	MOS		N:0			19-APR-2006		
	47557 REF:	HRS/MSC AFL	O/C	N:0 N:0			23:48 15		
332001-703	GALLEY POWER SUPPLY UNIT AL-2000	MOS		N:0			22-OCT-2016		
	60025 REF:	HRS/MSC AFL	O/C	N:0 N:0			2885:11 2100		
332001-704	GALLEY POWER SUPPLY UNIT AL-2000	MOS					29-NOV-2012		
	29432 REF:	HRS/MSC AFL	O/C				1939:36 1466		
332001-705	POWER SUPPLY (AFT LAVATORY) UNIT AL-2000	MOS		N:0			19-APR-2006		
	47175 REF:	HRS/MSC AFL	O/C	N:0 N:0			23:48 15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332019-701	DIMMER (LH WARDROBE) MODULE 990-8990-003 05030017368 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332020-701	GALLEY DIMMING INTERFACE MODULE AL-2010 4123 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-701	POWER SUPPLY (LH PSU) FS356.00 UNIT AL-2116 13494 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-702	POWER SUPPLY (LH PSU) FS372.00 UNIT AL-2116 13265 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-703	POWER SUPPLY (LH PSU) FS406.00 UNIT AL-2116 16631 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2017 3041:45 2185		
332056-704	POWER SUPPLY (LH PSU) FS432.00 UNIT AL-2116 12732 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-705	POWER SUPPLY (LH PSU) FS432-00 UNIT AL-2116 12731 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332056-706	POWER SUPPLY (LH PSU) FS439.00 UNIT AL-2116 12739 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-707	POWER SUPPLY (LH PSU) FS439.00 UNIT AL-2116 12747 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-708	POWER SUPPLY (LH PSU) FS467.00 UNIT AL-2116 12748 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-709	POWER SUPPLY (LH PSU) FS539.00 UNIT AL-2116 12749 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-710	POWER SUPPLY (LH PSU) FS539.00 UNIT AL-2116 12740 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-711	POWER SUPPLY (RH PSU) FS356.00 UNIT AL-2116 16630 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			03-APR-2017 3041:45 2185		
332056-712	POWER SUPPLY (RH PSU) FS433.00 UNIT AL-2116 13112 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			25-OCT-2007 410:30 368		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332056-713	POWER SUPPLY (RH PSU) FS433.00 UNIT AL-2116 12741 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-714	POWER SUPPLY (RH PSU) FS440.00 UNIT AL-2116 13266 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-715	POWER SUPPLY (RH PSU) FS440.00 UNIT AL-2116 12742 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-716	POWER SUPPLY (RH PSU) FS468.00 UNIT AL-2116 12744 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-717	POWER SUPPLY (RH PSU) FS494.00 UNIT AL-2116 16143 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:47 N:0 N:0			17-MAY-2018 3572:45 2476		
332056-718	POWER SUPPLY (RH PSU) FS530.00 UNIT AL-2116 12751 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
332056-719	POWER SUPPLY (RH PSU) FS530.00 UNIT AL-2116 13268 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
332056-720	POWER SUPPLY (RH PSU) FS559.00 UNIT AL-2116 13274 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
334001-701	STROBE (FS566 BOTTOM) LIGHT 2LA002760-39 1057948 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
334001-702	STROBE (FS431 TOP) LIGHT 2LA002760-39 1057943 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
334113-001 33.030	PULSELITE CONTROL UNIT PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2005 0 0	
334113-701	PULSE LIGHT CONTROL UNIT 600-50491-3 BW00352 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
334202-001 33.035	TAIL NAVIGATION LIGHT 2LA006181-01 3535 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C					12-DEC-2020 4614 2973	
334402-001 33.040	LH WING ANTI-COLLISION STROBE LIGHT 2LA006178-03 1038838 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				07-MAR-2005 0 0	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
334402-002	RH WING ANTI-COLLISION STROBE LIGHT								
33.040	2LA006178-03 1038828 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
334404-701	STA 615 LH UNDER FLOOR POWER SUPPLY								
	8ES002769-03 1066091 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
334407-001	NO. 1 POWER STROBE SUPPLY								
33.045	8ES005421-09 1034416 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
334407-002	NO. 2 POWER STROBE SUPPLY								
33.045	8ES005421-09 1029953 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
334407-003	TAIL POWER STROBE SUPPLY								
33.050	8ES005421-09 1029969 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
335101-001	FORWARD EMERGENCY POWER SUPPLY								
33.055	61-0478-9 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-JUN-2014 2304:15 1731		
335101-001A (s)	FUNCTIONAL TEST FORWARD EMERGENCY POWER SUPPLY (33-50-00-201)						PKG		
33.055	61-0478-9 PKG 12 NSN REF: AMM 33 51 01 720 801	MOS HRS/MSC AFL	12	+1m/-1m			08-MAY-2020 4328:45 2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
335101-002	AFT EMERGENCY POWER SUPPLY								
33.060	61-0478-9 NSN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C				16-JUN-2014 2304:15 1731		
335101-002A (s)	FUNCTIONAL TEST AFT EMERGENCY POWER SUPPLY (33-50-00-201)						PKG		
33.060	61-0478-9 PKG 12 NSN REF: AMM 33 51 01 720 801	MOS HRS/MSC AFL	12	+1m/-1m			08-MAY-2020 4328:45 2835		
335104-701	BATTERY PACK ASSY								
	55-2198-1 SN-UNKNOWN REF:	MOS HRS/MSC AFL	O/C	N:7 N:0 N:0			23-APR-2019 3786:12 2576		
<b>CHAPTER 34 NAVIGATION</b>									
34-11-00-201 (s)	FUNCTIONAL TEST OF THE PITOT-STATIC SYSTEM						PKG		
34.005	PKG 36 REF: AMM 34 11 00 720 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
34-11-00-202 (s)	DETAILED INSPECTION OF THE PITOT-STATIC PROBES						PKG		
34.010	PKG 36 REF: AMM 34 11 01 220 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
34-11-00-203 (s)	SERVICING OF THE VISUAL DRAIN						PKG		
34.015	PKG 24 REF: AMM 34 11 09 616 801	MOS HRS/MSC AFL	24	+1m/-1m			08-MAY-2020 4328:45 2835		
34-12-00-201 (s)	FUNCTIONAL TEST STANDBY ALTIMETER INDICATOR						PKG		
34.020	1611AM8 PKG 36 AG667 REF: AMM 34 12 01 720 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
34-12-00-202 (s)	FUNCTIONAL TEST STANDBY AIRSPEED INDICATOR (ASI)						PKG		
34.025	PKG 36 REF: AMM 34 12 04 720 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
34-54-00-201 (s)	OPERATIONAL TEST ATC TRANSPONDER SELECT SWITCH						PKG		
34.035	PKG 36 REF: AMM 34 54 00 710 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
34-61-00-201 (s)	OPERATIONAL TEST FMS INHIBIT SWITCH						PKG		
34.040	PKG 3200 REF: AMM 23 81 02 710 802	MOS HRS/MSC AFL	3200	+40/-40			03-APR-2017 3041:45 2185		
34-61-00-970-801	LOAD THE NAVIGATION DATABASE TO FLIGHT MANAGEMENT COMPUTER (FMC) VIA DBU								
	REF:	DAYS HRS/MSC AFL	28				23-DEC-2020 4630:25 2981	<b>27-JAN-2021 M</b>	
34-61-04-970-801	LOAD THE NAVIGATION DATA BASE TO THE FMC.								
<b>CUSTOMER CODE</b>	REF:	MOS HRS/MSC AFL	A/R				10-MAR-2009 954:54 750		
340004-701	LDS PROCESSOR								
	78-8060-6086-5 80252 REF:	MOS HRS/MSC AFL	O/C				18-SEP-2009 1139:33 881		
340005-701	LDS ANTENNA								
	856-0072-020 X81179 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
340016-701	RDC-4002, REMOTE DATA CONCENTRATOR 822-1533-001 H78J <b>REF:</b>	MOS HRS/MSC AFL	O/C				17-SEP-2010 1416:30 1074		
341101-001	NO. 1 PITOT STATIC PROBE 0856KV9 228920 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	<b>9600</b>	
341101-002	NO. 2 PITOT STATIC PROBE 0856KV10 229014 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	<b>9600</b>	
341104-001	NO. 3 PITOT STATIC PROBE 0851HF 236455 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
341107-001	NO. 1 STATIC PRESSURE PORT ST315-3L 1930219 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:24 N:0 N:0			16-JUN-2014 2304:15 1731		
341107-002	NO. 2 STATIC PRESSURE PORT ST315-3R 1860708 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:28 N:0 N:0			16-JUN-2014 2304:15 1731		
341113-001	TOTAL TEMPERATURE SENSOR 102AH2AG A56637 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341201-001	STANDBY ALTIMETER INDICATOR								
34.020	1611AM8 AG667 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:4 O:0 O:0			18-MAR-2018 3512:30 2441		
341201-001B (s)	RECERTIFY STANDBY ALTIMETER INDICATOR PER 14 CFR 91.411 PART 43, APP. E						PKG		
FAR	1611AM8 PKG 24 AG667 REF: AMM 34 12 01 720 801	MOS HRS/MSC AFL	24				08-MAY-2020 4328:45 2835		
341204-001	STANDBY AIRSPEED INDICATOR								
34.065	273AS5 AM008 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
341301-001	NO. 1 AIR DATA COMPUTER								
34.070	822-0842-421 1VTOB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
341301-001A	FUNCTIONAL TEST NO. 1 AIR DATA COMPUTER (34-13-00-102)								
34.070	822-0842-421 PKG 24 1VTOB REF: AMM 34 13 00 720 809	MOS HRS/MSC AFL	24		-46		08-MAY-2020 4328:45 2835	23-MAR-2022	
341301-001B (s)	RECERTIFY NO. 1 AIR DATA COMPUTER PER 14 CFR 91.411						PKG		
FAR	822-0842-421 PKG 24 1VTOB REF: AMM 34 13 00 720 809	MOS HRS/MSC AFL	24				08-MAY-2020 4328:45 2835		
341301-002	NO. 2 AIR DATA COMPUTER								
34.075	822-0842-421 1VTOC REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
341301-002A	FUNCTIONAL TEST NO. 2 AIR DATA COMPUTER (34-13-00-102)								
34.075	822-0842-421 PKG 24	MOS	24				08-MAY-2020	<b>23-MAR-2022</b>	
<b>RVSM</b>	1VTOC	HRS/MSC					4328:45		
	<b>REF:</b> AMM 34 13 00 720 809	AFL					2835		
341301-002B (s)	RECERTIFY NO. 2 AIR DATA COMPUTER PER 14 CFR 91.411						PKG		
	822-0842-421 PKG 24	MOS	24				08-MAY-2020		
<b>FAR</b>	1VTOC	HRS/MSC					4328:45		
	<b>REF:</b> AMM 34 13 00 720 809	AFL					2835		
341304-001	NO.1 AIR DATA REF (ARP4000) PANEL								
34.080	622-9819-016	MOS					18-AUG-2009		
	6N1T	HRS/MSC	O/C				1119		
	<b>REF:</b> See Workcard	AFL					870		
341304-002	NO. 2 AIR DATA REF. (ARP4000) PANEL								
34.080	622-9819-106	MOS		R:0			14-JUL-2011		
	1MR1J	HRS/MSC	O/C	R:0			1632:36		
	<b>REF:</b> See Workcard	AFL		R:0			1248		
342201-001	STANDBY COMPASS								
34.085	PAI700-5V	MOS		N:0			07-MAR-2005		
	54846	HRS/MSC	O/C	N:0			0		
	<b>REF:</b> See Workcard	AFL		N:0			0		
342301-001	STANDBY HORIZON INDICATOR								
34.090	501-1197-23	MOS		O:0			28-MAR-2013		
	9538	HRS/MSC	O/C	O:0			2026:25		
	<b>REF:</b> See Workcard	AFL		O:0			1520		
342407-001	NO. 3 AOA VANE TRANSDUCER								
34.095	856-0077-010	MOS					18-APR-2006		
	FK1377	HRS/MSC	O/C				23:48		
	<b>REF:</b> GENERIC NO REF	AFL					15		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344101-001	WEATHER RADAR (RTA-854) ANTENNA								
34.100	622-8440-004 27BGX REF: See Workcard	MOS HRS/MSC AFL	O/C				06-AUG-2015 2567:35 1937		
344104-001	NO. 1 WX CONTROL (WXP4220) PANEL								
34.105	622-9932-002 1RY3N REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344104-002	NO. 2 WX CONTROL (WXP4220) PANEL								
34.110	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344104-701	NO.2 WEATHER RADAR CONTROL PANEL								
	622-9932-002 25NDN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344204-701	#1 DISPLAY CONTROL (DCP-4000) PANEL								
	622-9812-206 204PN REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344204-702	#2 DISPLAY CONTROL (DCP-4000) PANEL								
	622-9812-206 20C5P REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344302-701	TCAS (FS325 BOTTOM FUSELAGE) ANTENNA								
	S65-5366-7L 261-69187 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344302-702	TCAS (FS302 TOP FUSELAGE) ANTENNA 622-8973-001 1X23Y <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344304-701	TCAS (AVIONIC BAY) PROCESSOR 822-1293-033 163879 <b>REF:</b>	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			20-APR-2015 2495:55 1885		
344307-001	LOWER ANTENNA PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344401-001	NO. 1 RADIO ALTIMETER 622-2855-011 1WGBG <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344401-002	NO. 2 RADIO ALTIMETER 622-2855-011 11396 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C				07-DEC-2010 1475:24 1130		
344403-701	2ND RADIO ALTIMETER MOUNTING TRAY 653-9015-001 1LKFG <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344407-001	FORWARD RADIO ALTIMETER ANTENNA S67-2002 543-31320 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344407-002	AFT RADIO ALTIMETER ANTENNA								
34.125	S67-2002 543-31310 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344407-701	NO.2 RADIO ALTIMETER (FS633.00) ANTENNA								
	S67-2002 543-34455 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344407-702	NO.2 RADIO ALTIMETER (FS667.00) ANTENNA								
	S67-2002 543-34491 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344410-001	NO. 1 RADIO ALTIMETER CONVERTER								
34.130	622-7209-002 1RVGB REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344410-701	#2 RADIO ALTIMETER CONVERTER								
	622-7209-002 1YN3Y REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
344412-701	EGPWS COMPUTER								
	965-0976-003-216-216 22224 REF:	MOS HRS/MSC AFL	O/C	N:10 R:0 N:194:37 R:0 N:167 R:0			07-FEB-2007 218:25 182		
344501-001	NO. 1 LASER INERTIAL REFERENCE IRU								
34.135	856-0075-010 4992 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
344501-002	NO. 2 LASER INERTIAL REFERENCE IRU								
34.135	856-0075-010 5028 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344501-003	NO. 3 LASER INERTIAL REFERENCE IRU								
34.135	856-0075-010 5534 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:5 R:0 R:0			14-NOV-2014 2408:05 1805		
344504-001	NO. 1 NO. 2 DUAL IRS MODE SELECTOR PANEL								
34.140	856-0075-020 0645 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
344507-001	IRS MODE SELECTOR NO.3 PANEL								
	856-0075-050 0236 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345101-001	VHF NAV (VIR-432) RECEIVER								
34.145	622-7194-201 G5FF REF: See Workcard	MOS HRS/MSC AFL	O/C	R:4 R:0 R:0			05-OCT-2017 3307:10 2325		
345101-002	VHF NAV (VIR-432) RECEIVER								
34.150	622-7194-201 1NKVK REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345104-001	VOR/LOC COUPLER								
34.155	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345107-001	NO. 1 VOR/LOC ANTENNA								
34.160	S65-247170-7 180-2337 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345107-002	NO. 2 VOR/LOC ANTENNA								
34.160	S65-247170-7 180-2335 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345110-001	GLIDESLOPE ANTENNA								
34.165	S41422-2 111-5077 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345113-001	MARKER BEACON ANTENNA								
34.170	S35-1000-2 102-5442 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345201-001	NO. 1 ADF RECEIVER								
34.175	622-7382-101 1NRCP REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345201-002	NO. 2 ADF RECEIVER								
34.175	622-7382-101 1NMJL REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345204-001	ADF (ANT-462B) ANTENNA								
34.180	622-7384-001 1N2MN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345301-001	NO. 1 DME TRANSCEIVER								
34.185	622-7309-101 1N43H REF: See Workcard	MOS HRS/MSC AFL	O/C				14-NOV-2014 2408:05 1805		
345301-002	NO. 2 DME TRANSCEIVER								
34.185	622-7309-101 59 REF: See Workcard	MOS HRS/MSC AFL	O/C				24-NOV-2014 2415:35 1812		
345304-001	NO. 1 ANTENNA								
34.190	S65-5366-7L 261-67064 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345304-002	NO. 2 ANTENNA								
34.190	S65-5366-7L 261-67473 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345401-001	NO. 1 ATC TRANSPONDER								
34.195	622-9210-501 1W24V REF: See Workcard	MOS HRS/MSC AFL	O/C				03-NOV-2020 4564:55 2944		
345401-001A (s)	RECERTIFY NO. 1 ATC TRANSPONDER PER 14 CFR 91.413 PART 43, APP. F						PKG		
FAR	622-9210-501 PKG 24 1W24V REF: GENERIC NO REF	MOS HRS/MSC AFL	24				08-MAY-2020 4328:45 2835		
345401-002	NO. 2 ATC TRANSPONDER								
34.195	622-9210-501 12F3T REF: See Workcard	MOS HRS/MSC AFL	O/C				12-DEC-2020 4614 2973		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345401-002A (s)	RECERTIFY NO. 2 ATC TRANSPONDER PER 14 CFR 91.413 PART 43, APP. F						PKG		
<b>FAR</b>	622-9210-501 PKG 24 12F3T <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	24						
345404-001	NO.1 LOWER TRANSPONDER ANTENNA								
34.200	S65-5366-7L 261-67120 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345404-002	NO.2 LOWER TRANSPONDER ANTENNA								
34.200	S65-5366-7L 261-67075 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345404-003	NO.1 UPPER TRANSPONDER ANTENNA								
	S65-5366-7L 261-67324 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345404-004	NO.2 UPPER TRANSPONDER ANTENNA								
34.205	S65-5366-7L 261-67339 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
345501-001	#1 GPS RECEIVER								
	822-2189-100 HHFC <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			27-MAR-2020 4328:45 2835		
345501-002	#2 GPS RECEIVER								
	822-2189-100 2X1XX <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	O:3 O:0 O:0			27-MAR-2020 4328:45 2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
345504-001	#1 GPS ANTENNA S67-1575-135 818-15904 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
345504-002	#2 GPS ANTENNA S67-1575-135 818-15891 REF: See Workcard	MOS HRS/MSC AFL	O/C				08-MAY-2020 4328:45 2835		
346101-001	NO. 1 DISPLAY CONTROL (CDU) UNIT 822-0867-008 335 REF: See Workcard	MOS HRS/MSC AFL	O/C	R:2 R:0 R:0			21-APR-2018 3529:25 2456		
346101-002	NO. 2 DISPLAY CONTROL (CDU) UNIT 822-0867-008 1VYRJ REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
346101-003	NO. 3 DISPLAY CONTROL (CDU) UNIT PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
346105-001	DBU 4100 PANEL 822-2215-002 4587B REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-DEC-2010 1475:24 1130		
346200-701	AFIS ANTENNA S65-8280-10 310-13628 REF:	MOS HRS/MSC AFL	O/C				19-APR-2006 23:48 15		

**CHAPTER 35 OXYGEN**

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-00-00-202 (s)	OPERATIONAL TEST PASSENGER OXYGEN SYSTEM (EFFECTIVITY: 5301-5304, 5306, 5310, 5316, 5331 AND SUBS)						PKG		
35.005	PKG 36 REF: AMM 35 20 00 710 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
35-00-00-204 (s)	OPERATIONAL TEST CREW OXYGEN MASK						PKG		
35.010 MRB	PKG 36 REF: AMM 35 11 07 710 801	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
35-00-00-210	RESTORATION LOWER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE REGULATOR (MRB)								
OVERHAUL	895-25015 C06110797 REF: AMM 35 11 01 280 801	MOS HRS/MSC AFL	60				09-AUG-2019 3958 2666	09-AUG-2024	
35-00-00-210	RESTORATION UPPER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE REGULATOR (MRB)								
OVERHAUL	895-25015 ALT282-40590 REF: AMM 35 11 01 280 801	MOS HRS/MSC AFL	60				09-AUG-2019 3958 2666	09-AUG-2024	
35-20-60-601 (s)	OPERATIONAL TEST OF THE PASSENGER OXYGEN SYSTEM						PKG		
STLMC	PKG 12 REF:	MOS HRS/MSC AFL	12				08-MAY-2020 4328:45 2835		
35-20-60-602 (s)	FUNCTIONAL TEST OF THE PASSENGER OXYGEN SYSTEM						PKG		
STLMC	PKG 36 REF:	MOS HRS/MSC AFL	36				26-MAR-2019 3702:35 2541		
35-20-60-603	RESTORE PASSENGER OXYGEN CONTROLLER								
STLMC	604-44101-3 400 REF:	MOS HRS/MSC AFL	72				03-APR-2017 3041:45 2185	03-APR-2023	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
35-30-60-602 (s)	GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE MASK PKG 36	MOS	36				PKG 26-MAR-2019 3702:35 2541		
<b>STLMC</b>	<b>REF:</b>	AFL							
350010-701	PASSENGER OXYGEN CONTROLLER 604-44101-3 400	MOS		O:0			03-APR-2017 3041:45 2185		
	<b>REF:</b>	AFL	O/C	N:4130 O:0 N:605 O:0					
350015-701	SOLENOID VALVE P21046 3177	MOS		N:0			19-APR-2006 23:48 15		
	<b>REF:</b>	AFL	O/C	N:0 N:0					
350021-701	OXYGEN (JUMPSEAT) BOX 833-325-1 2297	MOS		N:0			19-APR-2006 23:48 15		
	<b>REF:</b>	AFL	O/C	N:0 N:0					
351000-001	PILOT OXYGEN REGULATOR MASK ASSEMBLY MC10-13-03	MOS		O:0			05-OCT-2017 3307:10 2325		
35.015	SE56154I <b>REF:</b> See Workcard	HRS/MSC	O/C	N:3309 O:0 O:0					
351000-001A	RESTORATION OF THE PILOT OXYGEN MASK REGULATOR ASSEMBLY (35-00-00-206) MC10-13-03	MOS	72				17-OCT-2016	<b>17-OCT-2022</b>	
35.015	SE56154I <b>REF:</b> AMM 35 11 07 615 801	HRS/MSC							
<b>RESTORE</b>		AFL							
351000-002	COPILOT OXYGEN REGULATOR MASK ASSEMBLY MC10-13-03	MOS		N:175 O:0			05-OCT-2017 3307:10 2325		
35.020	106809I <b>REF:</b> See Workcard	HRS/MSC	O/C	O:0 O:0					
		AFL							

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351000-002A	RESTORATION OF THE COPILOT OXYGEN MASK REGULATOR ASSEMBLY (35-00-00-206)								
35.020	MC10-13-03	MOS	72				11-APR-2017	<b>11-APR-2023</b>	
<b>RESTORE</b>	106809I REF: AMM 35 11 07 615 801	HRS/MSC AFL							
351000-003	JUMP SEAT OXYGEN REGULATOR MASK ASSEMBLY								
35.025	MC10-13-03	MOS		N:158 O:0			05-OCT-2017		
	111376I	HRS/MSC	O/C	N:3747 O:0			3307:10		
	REF: See Workcard	AFL		O:0			2325		
351000-003A	RESTORATION OF THE JUMP SEAT OXYGEN REGULATOR MASK ASSEMBLY (35-00-00-206)								
35.025	MC10-13-03	MOS	72				30-JUN-2017	<b>30-JUN-2023</b>	
<b>RESTORE</b>	111376I REF: AMM 35 11 07 615 801	HRS/MSC AFL							
351000-003B (s)	TEST JUMP SEAT OXYGEN REGULATOR MASK ASSEMBLY THIRD CREW MEMBER OXYGEN SYSTEM - IN ACCORDANCE WITH EROS OPERATING INSTRUCTIONS AND MAINTENANCE MANUAL 4NUT0045A - COMPLETE SYSTEM TEST						PKG		
	MC10-13-03 PKG 12	MOS	12				08-MAY-2020		
<b>STLMC</b>	111376I REF:	HRS/MSC AFL					4328:45 2835		
351012-701	WARDROBE PBE								
	DP3113(A)	MOS	120	N:0			30-MAR-2011	<b>30-MAR-2021</b>	
	E1002274	HRS/MSC		N:0			1551:30		
	REF:	AFL		N:0			1194		
351101-001	UPPER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE								
35.030	895-25015	MOS	180	N:0			09-AUG-2019	<b>09-AUG-2034</b>	
<b>LIFE LIMIT</b>	ALT282-40590 REF: See Workcard	HRS/MSC AFL		N:0			3958 2666		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351101-001A	FUNCTIONAL (HYDROSTATIC) TEST UPPER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE CYLINDER (35-00-00-201)								
35.030	895-25015	MOS	60					01-MAY-2033	M
<b>OVERHAUL</b>	ALT282-40590 REF:	HRS/MSC AFL							
351101-002	LOWER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE								
35.035	895-25015	MOS	180	N:0			09-AUG-2019	09-AUG-2034	
<b>LIFE LIMIT</b>	C06110797 REF: See Workcard	HRS/MSC AFL		N:0			3958 2666		
351101-002A	FUNCTIONAL (HYDROSTATIC) TEST LOWER OXYGEN CYLINDER/REGULATOR ASSEMBLY BOTTLE CYLINDER (35-00-00-201)								
35.035	895-25015	MOS	60					01-MAY-2033	M
<b>OVERHAUL</b>	C06110797 REF:	HRS/MSC AFL							
351101-003	OXYGEN CYLINDER/REGULATOR ASSEMBLY (PART NO.802895-X)								
<b>SYSTEM</b>	PN NOT INSTALLED REF: See Workcard	MOS HRS/MSC AFL							
351101-003A	FUNCTIONAL (HYDROSTATIC) TEST ONLY (35-00-00-203) OXYGEN CYLINDER CYLINDER (35-00-00-201)								
<b>SYSTEM</b>	PN NOT INSTALLED REF:	MOS HRS/MSC AFL							
351110-001	NO. 1 STOWAGE BOX								
35.040	MXP335-3	MOS		N:2			13-MAY-2019		
	SE97852	HRS/MSC	O/C	N:0			3831:12		
	REF: See Workcard	AFL		N:0			2591		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
351110-002	NO. 2 STOWAGE BOX								
35.040	MXP335-2 SE79440 REF: See Workcard	MOS HRS/MSC AFL	O/C				14-AUG-2019 3958 2666		
352001-701	PASSENGER OXYGEN CONTROLLER								
	604-44101-3 223 REF:	MOS HRS/MSC AFL	O/C	R:0 R:0 R:0			07-FEB-2007 218:25 182		
352003-701	OXYGEN (LH #1) BOX								
	833-626-1 2570 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-702	OXYGEN (LH #2) BOX								
	833-626-1 2581 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-703	OXYGEN (LH #3) BOX								
	833-626-1 2562 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-704	OXYGEN (LH #4) BOX								
	833-626-1 2593 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-705	OXYGEN (RH #1) BOX								
	833-626-1 2576 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
352003-706	OXYGEN (RH #2) BOX 833-626-1 5269 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-707	OXYGEN (RH #3) BOX 833-626-1 2596 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-708	OXYGEN (RH #4) BOX 833-626-1 2578 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352003-709	OXYGEN (LAVATORY) BOX 833-626-1 2568 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
352011-701	OXYGEN PRESSURE SWITCH P24028 3360 REF:	MOS HRS/MSC AFL	O/C	N:143 N:0 N:0			25-MAR-2018 3512:30 2441		
352011-702	OXYGEN PRESSURE SWITCH 8012 0801 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
353016-701	OXYGEN PORTABLE BOTTLE 5600-9CIA-YON P13022535 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			14-AUG-2019 3958 2666		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
353016-701A	HYDROSTATIC TEST OXYGEN PORTABLE BOTTLE (35-30-60-601)								
	5600-9CIA-YON	MOS	60				14-AUG-2019	<b>14-AUG-2024</b>	
	P13022535	HRS/MSC					3958		
<b>STLMC</b>	<b>REF:</b>	AFL					2666		
<b>CHAPTER 36 PNEUMATIC</b>									
36-11-00-301 (s)	RESTORATION (CLEANING) OF THE 10TH STAGE BLEED AIR SHUTOFF VALVE FILTER						PKG		
	PKG 3200	MOS					03-APR-2017		
		HRS/MSC	3200				3041:45		
<b>OPTIONAL</b>	<b>REF: AMM 36 11 01 130 801</b>	AFL					2185		
36-12-00-301 (s)	RESTORATION (CLEANING) OF THE 14TH STAGE BLEED AIR SHUTOFF VALVE FILTER						PKG		
	PKG 3200	MOS					03-APR-2017		
		HRS/MSC	3200				3041:45		
<b>OPTIONAL</b>	<b>REF: AMM 36 12 01 130 801</b>	AFL					2185		
36-21-00-101	FUNCTIONAL TEST OF THE LEADING EDGE THERMAL SWITCHES. (CMR*)								
		MOS					07-MAR-2005		
		HRS/MSC	6400	+40/-40			0	<b>6400</b>	6440
	<b>REF: AMM 36 21 07 720 801</b>	AFL					0		
361100-001	10TH STAGE BLEED AIR ISOLATION VALVE SHUTOFF								
	PN	MOS					07-MAR-2005		
36.005	SN-UNKNOWN	HRS/MSC	O/C				0		
	<b>REF: See Workcard</b>	AFL					0		
361100-002	LH 10TH STAGE BLEED AIR VALVE SHUTOFF								
	979998-2	MOS					07-MAR-2005		
36.010	5105	HRS/MSC	O/C				0		
	<b>REF: See Workcard</b>	AFL					0		
361100-003	RH 10TH STAGE BLEED AIR VALVE SHUTOFF								
	604-97601-1	MOS					22-OCT-2016		
36.010	2213	HRS/MSC	O/C				2885:11		
	<b>REF: See Workcard</b>	AFL					2100		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361100-004	10TH STAGE BLEED AIR VALVE CHECK								
36.015	600-97006-7 2977 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361101-001	BLEED AIR (L/H) CLEANER								
36.025	600-97196-1 A377 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361101-002	BLEED AIR (R/H) CLEANER								
36.025	600-97196-2 A376 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361102-001	APU BLEED AIR CHECK VALVE								
36.030	PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361113-001	NO. 1 14TH STAGE BLEED AIR CHECK VALVE								
36.035	62490-7B 3724 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361113-002	NO. 2 14TH STAGE BLEED AIR CHECK VALVE								
36.035	62490-7B 3727 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361113-003	NO. 1 ASSY LOW PRESSURE DUCT								
36.040	13850-105 05307184-001 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361113-004	NO. 2 ASSY LOW PRESSURE DUCT								
36.040	13850-105 05307184-003 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361113-005	ASSY DUCT								
36.045	13854-103 05307790-003 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361113-006	ASSY - HIGH PRESSURE DUCT								
	13852-101 05304825-002 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361114-001	NO. 1 ASSY DUCT								
36.050	13861-101 L-98257 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361114-002	NO. 2 ASSY DUCT								
36.050	13865-101 05306345-002 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361200-001	NO. 1 14TH STAGE MODULATING/SHUTOFF VALVE								
36.055	3214442-4 3451 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
361200-002	NO. 2 14TH STAGE MODULATING/SHUTOFF VALVE								
36.055	3214442-4 3468 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
361200-003	NO. 1 14TH STAGE BLEED AIR SHUTOFF VALVE 604-97603-1	MOS		N:0				07-MAR-2005	
36.060	3443 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
361200-004	NO. 2 14TH STAGE BLEED AIR SHUTOFF VALVE 604-97603-1	MOS		N:0				07-MAR-2005	
36.060	3446 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
361200-005	14TH STAGE ISOLATION SHUTOFF VALVE 979626-5	MOS		R:4				19-FEB-2011	
36.065	3043C REF: See Workcard	HRS/MSC AFL	O/C						
361204-001	NO. 1 ASSY DUCT 13863-101	MOS		N:0				07-MAR-2005	
36.070	05305458-001 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
361204-002	NO. 2 ASSY DUCT 13866-101	MOS		N:0				07-MAR-2005	
36.070	05303437-004 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
362104-001	NO. 1 10TH STAGE BLEED AIR PRESSURE TRANSDUCER 600-59174-9	MOS		N:0				07-MAR-2005	
36.075	7055-8-64 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		
362104-002	NO. 2 10TH STAGE BLEED AIR PRESSURE TRANSDUCER IPTE2F1000-200G	MOS		N:0				07-MAR-2005	
36.075	7055-8-75 REF: See Workcard	HRS/MSC AFL	O/C	N:0 N:0			0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
362113-001	NO. 1 BLEED AIR LEAK CONTROL UNIT								
36.080	20-035008-067 A2885 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
362113-002	NO. 2 BLEED AIR LEAK CONTROL UNIT								
36.080	20-035008-067 A2883 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

APU Model : GTCP36-100(E) (604-CIMMS) Serial # P-820 Part # 3800050-5-1

361022-001	APU - BLEED AIR CHECK APU VALVE								
	3202896-1 1884 REF: AMM 36 11 07 960 801	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

**CHAPTER 38 WATER/WASTE**

38-10-60-601 (s)	RESTORE THE PORTABLE WATER FILTER CARTRIDGE						PKG		
STLMC	PKG 0 REF:	MOS HRS/MSC AFL	6				12-DEC-2020 4614 2973		
38-10-60-602 (s)	RESTORE THE PORTABLE WATER SYSTEM						PKG		
STLMC	PKG 0 REF:	MOS HRS/MSC AFL	6				12-DEC-2020 4614 2973		
38-10-60-603 (s)	FUNCTIONAL TEST OF THE WATER HEATER PRESSURE RELIEF VALVE						PKG		
STLMC	PKG 36 REF:	MOS HRS/MSC AFL	36				26-MAR-2019 3702:35 2541		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
38-40-60-601 (s)	GENERAL VISUAL INSPECTION OF THE AIR PRESSURE REGULATOR GAUGE PKG 0	MOS	6				PKG	12-DEC-2020	
<b>STLMC</b>	<b>REF:</b>	HRS/MSC AFL						4614 2973	
38-40-60-602 (s)	REPLACE THE BLEED AIR FILTER PKG 0	MOS	6				PKG	12-DEC-2020	
<b>STLMC</b>	<b>REF:</b>	HRS/MSC AFL						4614 2973	
380002-701	AFT LAVATORY WATER HEATER 8921082G5 N0525318 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
380002-702	GALLEY WATER HEATER 8921082G5 N0525320 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
380003-701	WATER LEVEL CONTROLLER 016264-02 0251 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				20-APR-2007 282:27 234	
380004-701	WATER LEVEL PROBE 016263-01 0253 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	
380006-701	AFT LAVATORY WATER FILTER ASSEMBLY 770011 010247 <b>REF:</b>	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0				19-APR-2006 23:48 15	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
380009-701	WATER TANK HEATER BLANKET 4E3156-03 0220 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
380009-702	WATER TANK HEATER BLANKET 4E3156-04 0236 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
380024-701	INSTA-HOT WATER (GALLEY) HEATER MRX1000-103 1003-274 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
381001-701	AFT WATER TANK TM433811-16-1 05015-1 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
383001-701	TOILET DRAIN VALVE ASSY 4650-8 NA REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			22-JUL-2011 1641 1252		
<b>CHAPTER 49 AIRBORNE AUXILIARY POWER</b>									
491002-001	APU INLET DUCT PN 49.015 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
491404-001	APU INLET BELLOWS 600-97212-1 724 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494313-001	APU FAULT INDICATOR								
49.025	604-53201-1 B0913 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
495301-001	PNEU SHUTOFF LOAD CONTROL VALVE								
49.035	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
495302-001	PNEUMATIC SHUTOFF VALVE								
49.040	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
496040-001	MOTIONAL PICKUP TRANSDUCER								
49.045	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
496044-001	APU LOW OIL PRESSURE SWITCH								
49.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
496101-001	ELECTRIC CONTROL UNIT APU ECU								
49.055	2117406-6 15-A0552 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
496101-002	SPARE ELECTRIC CONTROL UNIT APU ECU								
49.060	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
498001-001	APU EXHAUST ISOLATOR								
49.065	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
498101-001	APU EXHAUST NOZZLE ASSY								
49.070	601-97028-3 242 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
49APU1	APU								
49.APU1	3800050-5-1 P-820 REF: See Workcard	MOS HRS/MSC AFL	E/C						
APU Model : GTCP36-100(E) (604-CIMMS) Serial # P-820 Part # 3800050-5-1									
49-10-00-201 (s)	APU - DETAILED INSPECTION OF THE AUXILIARY POWER UNIT (APU) ENCLOSURE ASSEMBLY.						PKG		
	PKG 600	MOS					08-MAY-2020		
<b>MRB</b>	REF: AMM 49 11 01 220 801	HRS/MSC APUS	600	+40/-40			6583		
49-12-01-201 (s)	APU - VISUAL CHECK APU SUPPORT SKID ASSEMBLY (PRE SB 604-49-006)						PKG		
	PKG 2400	MOS					08-MAY-2020		
	REF: AMM 49 12 01 210 801	HRS/MSC APUS	2400	+40/-40			6583		
49-20-00-201 (s)	APU - INSPECT DETAILED OF THE APU COMBUSTION CHAMBER (PRE SB 604-49-006)						PKG		
	PKG 600	MOS					08-MAY-2020		
	REF: AMM 49 24 00 220 801	HRS/MSC APUS	600	+40/-40			6583		
49-20-00-205 (s)	APU - VISUAL CHECK APU CONTAINMENT RING (PRE SB 604-49-006)						PKG		
	PKG 2400	MOS					08-MAY-2020		
	REF: AMM 49 22 07 210 802	HRS/MSC APUS	2400	+40/-40			6583		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
49-21-00-201 (s)	APU - DETAILED INSPECTION APU OIL DRAIN PLUG MAGNETIC ELEMENT (PRE SB 604-49-006) PKG 600	MOS HRS/MSC	600	+40/-40			PKG 08-MAY-2020 6583		
	REF: AMM 49 91 22 220 801	APUS							
49-30-00-201 (s)	APU - DISCARD APU FUEL FILTER ELEMENT (PRE SB 604-49-006) PKG 400	MOS HRS/MSC	400	+40/-40			PKG 12-DEC-2020		
<b>LIFE LIMIT</b>	REF: AMM 49 31 01 960 801	APUS							
49-40-00-201	APU - RESTORATION (OVERHAUL) OF THE AUXILIARY POWER UNIT (APU) STARTER MOTOR ASSEMBLY. (PRE SB 604-49-006) (MRB)	MOS HRS/MSC	2100	+40/-40			26-MAR-2019 5884	<b>7984</b>	8024
<b>OVERHAUL</b>	REF: AMM 49 44 01 280 801	APUS							
49-80-00-201 (s)	APU - DETAILED INSPECTION APU EXHAUST NOZZLE (PRE SB 604-49-006) PKG 1200	MOS HRS/MSC	1200	+40/-40			PKG 08-MAY-2020 6583		
	REF: AMM 49 81 01 220 801	APUS							
49-80-00-202 (s)	APU - DETAILED INSPECTION APU EXHAUST DUCT (PRE SB 604-49-006) PKG 1200	MOS HRS/MSC	1200	+40/-40			PKG 08-MAY-2020 6583		
	REF: AMM 49 81 04 220 801	APUS							
49-80-00-203 (s)	APU - VISUAL CHECK APU EXHAUST SHIELD AND VISOR ASSEMBLY (PRE SB 604-49-006) PKG 1200	MOS HRS/MSC	1200	+40/-40			PKG 08-MAY-2020 6583		
	REF: AMM 49 81 07 210 801	APUS							
49-90-00-201 (s)	APU - DISCARD APU OIL FILTER ELEMENT (PRE SB 604-49-006) PKG 400	MOS HRS/MSC	400	+40/-40			PKG 12-DEC-2020		
<b>LIFE LIMIT</b>	REF: AMM 49 91 07 960 804	APUS							

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
490060	APU - COMPRESSOR ROTOR - VISUALLY CHECK THROUGH INLET DUCTS FOR COMPRESSOR ROTOR DAMAGE. NO DAMAGE IS ALLOWED	MOS					05-MAY-2020		
	REF:	HRS/MSC	1500				6582		8082
		APUS							
490070	APU - PERFORM DETAILED HOT SECTION INSPECTION	MOS					05-MAY-2020		
	REF:	HRS/MSC	1500				6582		8082
		APUS							
491000-001	APU - APU IMPELLER - (TLMC 49-20-00-204) - (PRE SB 604-49-006) TURBINE	MOS					07-MAR-2005		
	3615880-1			N:0			0		10000
	050134500080	HRS/MSC	10000	N:0			0		10000
<b>LIFE LIMIT</b>	REF: AMM 49 22 04 961 801	APUS	10000	N:0			0		10000
491010-001	APU - APU IMPELLER - (TLMC 49-20-00-203) - (PRE SB 604-49-006) COMPRESSOR	MOS					07-MAR-2005		
	3822101-1			N:0			0		100000
	040350109023	HRS/MSC		N:0			0		100000
<b>LIFE LIMIT</b>	REF: AMM 49 20 03 961 801	APUS	100000	N:0			0		100000
492004	APU - TURBINE PLENUM ASSEMBLY, TURBINE HOUSING SCROLL, DEFLECTOR, TURBINE NOZZLE, TURBINE ROTOR AND LABYRINTH SEAL - CHECK THESE COMPONENTS USING A FIBERSCOPE, AT TIME OF COMBUSTION UNIT INSPECTION BY OBSERVATION THROUGH COMBUSTION CHAMBER AND EXHAUST OPENINGS IN THE TURBINE PLENUM ASSEMBLY	MOS					07-MAR-2005		
	REF:	HRS/MSC	O/C				0		
		APUS					0		
493008-001	APU - FUEL CONTROL UNIT APU FCU	MOS					07-MAR-2005		
	3882600-8			N:0			0		
	28991	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	APUS		N:0			0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
494000-001	APU - PLUG IGNITOR 369964-6 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
494010-001	APU - MOTOR APU STARTER 519892-6-2 6321 REF: See Workcard	MOS HRS/MSC APUS	O/C	O:0 O:0			16-JUN-2014 4086		
494034-001	APU - UNIT APU IGNITION 3603281-3 040218051865 REF: See Workcard	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
494035	APU - STARTER MOTOR - REMOVE, INSPECT AND REINSTALL 519892-6-2 6321 REF:	MOS HRS/MSC APUS	600				05-MAY-2020 6582	7182	
495010-001	APU - APU PNEU SURGE VALVE 978668-3-1 4155 REF: See Workcard	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
495014-001	APU - PNEUMATIC SHUTOFF VALVE 109776-5 1130 REF:	MOS HRS/MSC APUS	O/C				20-JUL-2009 2052:30		
496100-001	APU - ELECTRIC CONTROL UNIT APU ECU 2117406-6 94-A0535 REF:	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
497000-001	APU - APU HOURMETER 3888033-4 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC APUS	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 52 DOORS</b>									
52-10-00-201 (s)	FUNCTIONAL TEST PASSENGER DOOR LATCH MECHANISM PKG 2400	MOS HRS/MSC	2400	+40/-40			08-MAY-2020 4328:45 2835		
52.005	REF: AMM 52 11 04 720 801	AFL							
52-10-00-202 (s)	LUBRICATION THE PASSENGER DOOR (EXTERNAL) PKG 400	MOS HRS/MSC	400	+40/-40			12-DEC-2020 4614 2973		
52.010	REF: AMM 12 20 04 640 807	AFL							
52-10-00-204	LUBRICATION PASSENGER DOOR (INTERNAL) (A/C 5301 TO 5315 PRE SB 604-52-002)	MOS HRS/MSC	N/A				07-MAR-2005 0 0		
52.015	REF: AMM 12 20 04 640 834	AFL							
52-10-00-205 (s)	LUBRICATION OF THE PASSENGER DOOR (INTERNAL) (A/C 5301 TO 5315 POST SB 604-52-002 AND A/C 5316 AND SUBS) PKG 1600	MOS HRS/MSC	1600	+40/-40			08-MAY-2020 4328:45 2835		
52.020	REF: AMM 12 20 04 640 834	AFL							
52-11-00-101	SPECIAL DETAILED INSPECTION PASSENGER DOOR HINGE	MOS HRS/MSC	5315					5315	
52.025	REF: NDT ET-52-10-001	AFL							
<b>AIRWORTHINESS</b>									

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-11-00-102	DETAILED INSPECTION OF THE PASSENGER DOOR FLAP CUTOUT								
52.030		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 52 11 01 220 804</b>	HRS/MSC					0		
		AFL	7800				0	7800	
52-11-00-202 (s)	DETAILED INSPECTION FITTINGS AND ATTACHMENT OF PASSENGER DOOR								
52.035	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
<b>AIRWORTHINESS</b>	<b>REF: AMM 52 11 01 220 802</b>	HRS/MSC					3512:30		
		AFL					2441		
52-11-00-203 (s)	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PASSENGER DOOR								
52.040	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 52 11 01 220 803</b>	HRS/MSC					2304:15		
		AFL					1731		
52-20-00-201 (s)	OPERATIONAL TEST OF LATCH MECHANISM OF O/WING EMERGENCY EXIT DOOR								
52.045	PKG 36	MOS	36	+1m/-1m			26-MAR-2019		
	<b>REF: AMM 52 21 04 710 801</b>	HRS/MSC					3702:35		
		AFL					2541		
52-20-00-202 (s)	FUNCTIONAL TEST EXIT-PULL SIGN								
52.050	PKG 36	MOS	36	+1m/-1m			26-MAR-2019		
	<b>REF: AMM 52 21 07 720 801</b>	HRS/MSC					3702:35		
		AFL					2541		
52-20-00-203 (s)	LUBRICATION OF THE EMERGENCY EXIT DOOR								
52.055	PKG 24	MOS	24	+1m/-1m			08-MAY-2020		
	<b>REF: AMM 12 20 04 640 805</b>	HRS/MSC					4328:45		
		AFL					2835		
52-21-00-202 (s)	DETAILED INSPECTION LATCH FITTINGS AND DOOR STOPS OF O/WING EMERGENCY EXIT DOOR								
52.060	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
	<b>REF: AMM 52 21 01 220 802</b>	HRS/MSC					3512:30		
		AFL					2441		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-21-00-203	DETAILED INSPECTION INTERNAL STRUCTURE OF OVERWING EMERGENCY EXIT DOOR								
52.065	REF: AMM 52 21 01 220 803	MOS HRS/MSC AFL	48	+1m/-1m			07-MAR-2018 3512:30 2441	<b>07-MAR-2022</b>	07-APR-2022
52-31-00-202	DETAILED INSPECTION STOP FITTINGS OF THE CARGO COMPARTMENT DOOR								
52.070	REF: AMM 52 31 01 220 802	MOS HRS/MSC AFL	48	+1m/-1m			07-MAR-2018 3512:30 2441	<b>07-MAR-2022</b>	07-APR-2022
52-31-00-203 (s)	DETAILED INSPECTION INTERNAL STRUCTURE OF THE CARGO COMPARTMENT DOOR						PKG		
52.075	PKG 96 REF: AMM 52 31 01 220 803	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
52-40-00-201 (s)	OPERATIONAL TEST ADG DOOR OPERATING MECHANISM						PKG		
52.080	PKG 1200 REF: AMM 52 44 01 710 801	MOS HRS/MSC AFL	1200	+40/-40			08-MAY-2020 4328:45 2835		
52-45-00-301 (s)	LUBRICATION OF THE SERVICE DOOR LOCKS						PKG		
<b>OPTIONAL</b>	PKG 0 REF: AMM 12 20 04 640 837	MOS HRS/MSC AFL	6				12-DEC-2020 4614 2973		
52-ZL-00-206 (s)	GENERAL VISUAL INSPECTION PASSENGER DOOR - EXTERNAL						PKG		
52.085	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
52-ZL-00-207 (s)	GENERAL VISUAL INSPECTION PASSENGER DOOR - INTERNAL						PKG		
52.090	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
52-ZL-00-208 (s)	GENERAL VISUAL INSPECTION OVERWING EMERGENCY EXIT DOOR - EXTERNAL						PKG		
52.095	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
52-ZL-00-209 (s)	GENERAL VISUAL INSPECTION OVERWING EMERGENCY EXIT DOOR - INTERNAL						PKG		
52.100	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
52-ZL-00-210 (s)	GENERAL VISUAL INSPECTION CARGO COMPARTMENT DOOR - EXTERNAL						PKG		
52.105	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
52-ZL-00-211 (s)	GENERAL VISUAL INSPECTION CARGO COMPARTMENT DOOR - INTERNAL						PKG		
52.110	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
521100-001	PASSENGER DOOR								
52.115	600-31901-1003 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
521107-001	PASSENGER DOOR OUTER ASSY								
52.120	604-38110-7 0316 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
521119-001	MAIN ENTRY DOOR MOTOR ASSEMBLY								
52.125	444-2435-2 1482 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
522104-001	OVERWING EMERGENCY DOOR								
52.130	600-31051-3 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
523100-001	BAGGAGE BAY DOOR								
52.135	600-35027-159 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
523107-001	BAGGAGE BAY DOOR HANDLE								
52.140	600-35060-13 1989 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
523113-001	FORWARD CARGO COMPARTMENT DOOR, BALANCE SPRING DRIVEN MOTOR								
52.145	ML3844-11A 13823 REF: See Workcard	MOS HRS/MSC AFL	O/C				30-JUL-2014 2332:15 1750		
523113-002	AFT CARGO COMPARTMENT DOOR, BALANCE SPRING DRIVEN MOTOR								
52.145	ML3844-12A 11979 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
524100-001	EQUIPMENT BAY DOOR								
52.150	600-35128-65 5613 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
524107-001	EXTERNAL HANDLE								
52.155	601R35034-3 1365 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



**BOMBARDIER**

# Status Report

CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021

Owner/Operator: LLC AVIASERVICE

Report Date: 11-JAN-2021

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
524410-001	LH DOOR ACCESS ASSEMBLY								
52.160	601R33028-1 6925073 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
524410-002	RH DOOR ACCESS ASSEMBLY								
52.160	601R33028-2 3828812 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
524525-001	DOOR ASSEMBLY								
52.165	600-33040-1 2750304 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 53 FUSELAGE</b>									
53-10-00-101	DETAILED INSPECTION OF THE FUSELAGE SKIN AT THE NLG CUTOUT - FS235.00								
53.005		MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	REF: AMM 53 10 01 220 814	AFL	7800				0		<b>7800</b>
53-10-00-102	DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD WEB - FS202								
53.010		MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	REF: AMM 53 10 01 220 815	AFL	6900				0		<b>6900</b>
53-10-00-103	DETAILED INSPECTION OF THE FRAME - FS220.00								
53.015		MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	REF: AMM 53 10 01 220 816	AFL	7800				0		<b>7800</b>
53-10-00-104	DETAILED INSPECTION WINDOW LOWER SILL - FS235, FS249 AND FS264								
53.020		MOS HRS/MSC					03-APR-2017 3041:45		
<b>AIRWORTHINESS</b>	REF: AMM 53 10 01 220 817	AFL	1545				2185		<b>3730</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-105	DETAILED INSPECTION OF THE WINDOW LOWER SILL- FS 209								
53.025		MOS					03-APR-2017		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 818</b>	HRS/MSC					3041:45		
		AFL	1933				2185		<b>4118</b>
53-10-00-106	DETAILED INSPECTION WINDSHIELD UPPER SILL - FS 234, BL2.5								
53.030		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 819</b>	HRS/MSC					0		
		AFL	3747				0		<b>3747</b>
53-10-00-107	DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD - VERTICAL STIFFENER BL22								
53.035		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 820</b>	HRS/MSC					0		
		AFL	5545				0		<b>5545</b>
53-10-00-110	DETAILED INSPECTION OF THE FORWARD PRESSURE BULKHEAD VERTICAL MEMBER - WL79.5 AND WL93, BL22								
53.040		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 823</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-10-00-111	SPECIAL DETAILED INSPECTION FUSELAGE FRAME FS235 UPPER CAP ANGLE BL. 8								
53.045		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-10-002</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-10-00-112	DETAILED INSPECTION OF FLOOR CONNECTION CLIPS FS202.75.								
53.050		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 833</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-10-00-113	SPECIAL DETAILED INSPECTION OF THE FWD PRESSURE BULKHEAD WEB WL 79.5 TO WL 91.7								
53.055		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-114	DETAILED INSPECTION OF THE NLG BEAM, WEB BELOW DRAG BEAM - FS210 TO FS215, UPPER CAP - FS210 AND LOWER CAP - FS224								
53.060		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 824</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
53-10-00-115	DETAILED INSPECTION OF THE NLG DRAG STRUT - FS213, AND THE NLG BEAM VERTICAL STIFFENER CLIP - FS215								
53.065		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 825</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
53-10-00-119	SPECIAL DETAILED INSPECTION OF THE PILOT FLOOR WEB ADJACENT TO PRESSURE BULKHEAD, FS203, BL 16.								
53.070		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-10-009</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
+ 53-10-00-121	DETAILED INSPECTION OF THE FORWARD PRESSURE-BULKHEAD CAP-ANGLE AFT-SIDE - FS202.75								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 10 01 220 834</b>	HRS/MSC AFL	6941				0 0		<b>6941</b>
53-10-00-201	DETAILED INSPECTION OF THE INTERNAL FUSELAGE, FRAMES AND FORWARD BULKHEAD - FS169.00 TO FS202.75.								
53.075		MOS	48	+1m/-1m			12-MAR-2018	<b>12-MAR-2022</b>	12-APR-2022
	<b>REF: AMM 53 10 01 220 801</b>	HRS/MSC AFL					3512:30 2441		
53-10-00-203	DETAILED INSPECTION OF THE INTERNAL FUSELAGE (SKINS AND STRUCTURE ) - FS202.75 TO FS280.00 BELOW THE FLOOR.								
53.085		MOS	48	+1m/-1m			15-MAR-2018	<b>15-MAR-2022</b>	15-APR-2022
	<b>REF: AMM 53 10 01 220 803</b>	HRS/MSC AFL					3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-10-00-204	DETAILED INSPECTION OF THE INTERNAL FUSELAGE, SKIN AND STRUCTURE - FS202.75 TO FS280.00 ABOVE THE FLOOR.								
53.090	REF: AMM 53 10 01 220 804	MOS HRS/MSC AFL	192	+1m/-1m			28-APR-2006 0 0	28-APR-2022	28-MAY-2022
53-10-00-208	DETAILED INSPECTION OF THE BEAMS, CROSSMEMBERS AND PANELS OF THE FLOOR STRUCTURE - FS 169 TO FS280								
53.110	REF: AMM 53 10 01 220 807	MOS HRS/MSC AFL	48	+1m/-1m			12-MAR-2018 3512:30 2441	12-MAR-2022	12-APR-2022
53-10-00-210	DETAILED INSPECTION OF THE FORWARD JACKING POINT - FS 278.00								
53.115	REF: AMM 53 10 01 220 809	MOS HRS/MSC AFL	48	+1m/-1m			12-MAR-2018 3512:30 2441	12-MAR-2022	12-APR-2022
53-10-00-212 (s)	DETAILED INSPECTION OF THE NLG WHEEL WELL STRUCTURE.								
53.125	PKG 48 REF: AMM 53 10 01 220 811	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-10-00-213 (s)	DETAILED INSPECTION OF THE NLG INTERNAL BOX STRUCTURE - FS169 TO FS235								
53.130	PKG 48 REF: AMM 53 10 01 220 812	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-10-00-218	DETAILED INSPECTION OF THE AFT SIDE OF THE PILOT BULKHEAD AND FRAME - FS280.00 ABOVE WL73.50 (FLOOR LEVEL)								
53.155	REF: AMM 53 10 01 220 828	MOS HRS/MSC AFL	240	+1m/-1m			28-APR-2006 0 0	28-APR-2026	28-MAY-2026

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-101	SPECIAL DETAILED INSPECTION OF END POST OF SIDE WINDOW-FS280								
53.160		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-10-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-102	DETAILED INSPECTION OF THE STRUCTURE AROUND THE CABIN WINDOWS								
53.165		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 831</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-103	DETAILED INSPECTION OF THE FOUR CORNERS AND STRUCTURE AROUND THE OVERWING EMERGENCY EXIT.								
53.170		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 832</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-104	SPECIAL DETAILED INSPECTION OF THE CUTOUTS FOR THE CABIN WINDOWS								
53.175		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-105	DETAILED INSPECTION OF THE STRINGER SPLICE - STRINGER 3, FS473								
53.180		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 833</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-106	SPECIAL DETAILED INSPECTION OF THE SKIN CIRCUMFERENTIAL SPLICE AT FS559.00, BETWEEN STRINGERS 10L AND 10R								
53.185		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 834</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-107	DETAILED INSPECTION OF THE SKIN SPLICE - STRINGER 0.0, FS439								
53.190		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 835</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-108	DETAILED INSPECTION OF THE FUSELAGE FRAMES - FS220, FS235, FS250, FS265, FS280, FS295, FS310, FS321.5, FS333, FS349, FS364, FS379, FS394, FS409, FS439, FS450, FS461.5, FS484, FS499, FS529, FS544, FS559, FS574, FS589 AND FS605.								
53.195		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 866</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-109	SPECIAL DETAILED INSPECTION OF THE STRUCTURE AROUND THE PASSENGER DOOR								
53.200		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-110	DETAILED INSPECTION OF THE STRUCTURE AROUND THE OVERWING EMERGENCY EXIT -STRINGER 9, FS450								
53.200		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 837</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-111	SPECIAL DETAILED INSPECTION OF THE STRUCTURE AROUND THE BAGGAGE DOOR								
53.205		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-112	SPECIAL DETAILED INSPECTION OF THE KEEL LONGERON LINKS & BOLTS - FS395.75								
53.210		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-013</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-113	DETAILED INSPECTION OF THE PASSENGER DOOR FRAMES - FS310 AND FS349								
53.215		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 839</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-114	SPECIAL DETAILED INSPECTION OF THE CORNER OF THE PRESSURE SKIN - FS409 TO FS559, WL73								
53.220		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-006</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-115	SPECIAL DETAILED INSPECTION OF THE WING TO FUSELAGE ATTACHMENT FRAME - FS424, WL73								
53.225		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-003</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-116	DETAILED INSPECTION OF THE WING TO FUSELAGE ATTACHMENT FRAME FS513, BL16								
53.230		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 840</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-117	SPECIAL DETAILED INSPECTION OF THE LONGITUDINAL FLOOR BEAMS - FS513								
53.235		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-014</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-118	DETAILED INSPECTION OF THE LONGITUDINAL FLOOR BEAMS - FS484, BL18								
53.240		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 841</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-119	DETAILED INSPECTION OF THE WING TO FUSELAGE ATTACHMENT LUGS AND BOLTS - FS473 AND FS513								
53.245		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 872</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-120	DETAILED INSPECTION OF THE SKIN SPLICE - STRINGER 8, FS424 TO FS439								
53.250		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 843</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-121	DETAILED INSPECTION OF THE LONGERON ASSEMBLY - UNDER FLOOR, FS513,BL45								
53.255		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 875</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-122	DETAILED INSPECTION OF THE TIE BEAM PRESSURE FLOOR-TO-WING, FS460								
53.260		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 823</b>	HRS/MSC					0		
		AFL	5904				0		<b>5904</b>
53-20-00-123	DETAILED INSPECTION OF THE STRINGER SPLICE - STRINGER 13, FS513								
53.265		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 844</b>	HRS/MSC					0		
		AFL	5020				0		<b>5020</b>
53-20-00-125	SPECIAL DETAILED INSPECTION OF THE WING TO FUSELAGE ATTACHMENT FRAME - FS513								
53.270		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-016</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-126	SPECIAL DETAILED INSPECTION OF THE KEEL LONGERON								
53.275		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	5315				0		<b>5315</b>
53-20-00-127	DETAILED INSPECTION OF THE OVERWING FLOOR INTERCOSTAL - FS421, FS527, FS439, FS448.85, FS461.5, FS469.58, FS476.72 AND FS484								
53.280		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 845</b>	HRS/MSC					0		
		AFL	6695				0		<b>6695</b>
53-20-00-128	DETAILED INSPECTION OF THE FRAME TO LONGERON CLEATS - FS439, FS461, FS484, FS499, FS529 AND FS544								
53.285		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 846</b>	HRS/MSC					0		
		AFL	6695				0		<b>6695</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-129	DETAILED INSPECTION OF THE PRESSURE BOX OF THE FORWARD KEEL BEAM - FS409.00 (A/C 5301 TO 5352, PRE SB 604-53-006) NOTE: REF: AD CF-97-16 AND FAA AD-97-24-02								
53.290 <b>AIRWORTHINESS</b>	REF: AMM 53 20 01 220 847	MOS HRS/MSC AFL	N/A				07-MAR-2005 0 0		
53-20-00-130	DETAILED INSPECTION OF THE TENSION CLIP, BULB ANGLE, BEAMS AND THE AFT SKIN PANEL OF THE FORWARD AUXILIARY TANK								
53.295 <b>AIRWORTHINESS</b>	REF: AMM 53 20 01 220 848	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	7800	
53-20-00-134	SPECIAL DETAILED INSPECTION OF THE ACCESS DOORS ON THE FORWARD AUXILIARY TANK								
53.300 <b>AIRWORTHINESS</b>	REF: NDT ET-53-30-013	MOS HRS/MSC AFL	6300				07-MAR-2005 0 0	6300	
53-20-00-135	DETAILED INSPECTION FORWARD PRESSURE SKIN PANEL & FORWARD ATTACH ANGLE OF FORWARD AUXILIARY TANK								
53.305 <b>AIRWORTHINESS</b>	REF: AMM 53 20 01 220 852	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	7800	
53-20-00-136	SPECIAL DETAILED INSPECTION OF THE FORWARD PRESSURE SKIN PANEL OF THE FORWARD AUXILIARY TANK								
53.310 <b>AIRWORTHINESS</b>	REF: NDT ET-53-20-019	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	7800	
53-20-00-140	SPECIAL DETAILED INSPECTION OF THE AREAS AROUND SKIN CUTOUTS : (1) TCAS ANTENNAS AT FS 301.95, BL0.0 AND FS326, BL2.93L,(2) ATC ANTENNA AT FS401.47, BL8.89L AND 8.89R,(3) DUAL GPS ANTENNA AT FS284.1, BL14L & 14R,(4) LOWER BEACON LIGHT AT FS565.5, BL30.67L,(5) DRAIN MAST AT FS611 STRINGER 24R TO 25R,(6) POTABLE WATER FILL ADAPTER AT FS599, STRINGER 19R TO 20R								
53.315 <b>AIRWORTHINESS</b>	REF: NDT ET-53-20-020	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	7800	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-141	SPECIAL DETAILED INSPECTION OF THE AREAS AROUND SKIN CUTOUTS :(1) THIRD VHF COMM ANTENNA AT FS549.29, BL0.0, (2) LIGHTNING SENSOR SYSTEM (LSS) ANTENNA AT FS521.5, BL3.35L,(3) AFIS ANTENNA AT FS478.5, BL3.35R,(4) UPPER BEACON LIGHT AT FS431.5, BL0.0								
53.320		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-009</b>	HRS/MSC					0		
		AFL	5889				0		<b>5889</b>
53-20-00-142	DETAILED INSPECTION OF THE AREA AROUND CUTOUTS : (1) SECOND RADIO ALTIMETER ANTENNA AT FS633.5, BL3R,(2) ELT ANTENNA AT FS723.15, BL12.57,(3) FLIGHT PHONE ANTENNA AT FS FS764, BL0.0								
53.325		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 874</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-143	DETAILED INSPECTION OF THE PRESSURE BULKHEAD - FS409, BL12L TO BL12R (A/C 5353 TO 5431, PRE SB-604-53-006)								
53.330		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 849</b>	HRS/MSC	N/A				0		
		AFL					0		
53-20-00-144	SPECIAL DETAILED INSPECTION OF THE PRESSURE BULKHEAD - FS409.00, LBL9.00 TO RBL9.00								
53.335		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-018</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-145	SPECIAL DETAILED INSPECTION OF THE MACHINED STRAP - FS409.00, LBL6.00 TO RBL6.00								
53.340		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-018</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-146	SPECIAL DETAILED INSPECTION OF THE FUSELAGE FRAME CAP - FS409.00, LBL18.00 TO RBL18.00								
53.345		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-018</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-147	DETAILED INSPECTION OF THE STOPS, FITTINGS AND ATTACHMENTS OF THE OVERWING EMERGENCY EXIT.								
53.350		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 865</b>	HRS/MSC					0		
		AFL	4760				0		<b>4760</b>
53-20-00-148	SPECIAL DETAILED INSPECTION OF THE PRESSURE BULKHEAD - FS409, BL9L TO BL9R (A/C 5353 TO 5431 PRE SB-604-53-006)								
53.355		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC	N/A				0		
		AFL					0		
53-20-00-149	SPECIAL DETAILED INSPECTION OF THE IRIDIUM SATCOM ANTENNA INSTALLATION (IF INSTALLED), FS338.00 STRINGER 0 TO 1R								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-010</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-186	DETAILED INSPECTION OF THE WING-TO-FUSELAGE ATTACHMENT LUGS AND BOLTS - FS424								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 20 01 220 873</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-20-00-188	SPECIAL DETAILED INSPECTION OF THE UPPER LATCH PINS OF THE PASSENGER DOOR								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT MT-53-10-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
+ 53-20-00-192	SPECIAL DETAILED INSPECTION OF THE SKIN CIRCUMFERENTIAL SPLICE AT FS559.00, BETWEEN STRINGERS 10L AND 10R								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-032</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-201	DETAILED INSPECTION OF SILLS, FRAMES & EXTERNAL SKIN AROUND PASSENGER DOOR CUTOUT								
53.360	REF: AMM 53 20 01 220 801	MOS HRS/MSC AFL	48	+1m/-1m			13-MAR-2018 3512:30 2441	<b>13-MAR-2022</b>	13-APR-2022
53-20-00-202 (s)	DETAILED INSPECTION OF FITTINGS & HINGE ON THE FUSELAGE FOR PASSENGER DOOR						PKG		
53.365	PKG 48 REF: AMM 53 20 01 220 802	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
53-20-00-203	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE - FS280.00 TO FS409.00, AS VISIBLE WITH THE FLOOR PANELS INSTALLED								
53.370	REF: AMM 53 20 01 220 803	MOS HRS/MSC AFL	48	+1m/-1m			21-MAR-2018 3512:30 2441	<b>21-MAR-2022</b>	21-APR-2022
53-20-00-204 (s)	DETAILED INSPECTION OF THE FLOOR SUPPORT STRUCTURE - FS280 TO FS409						PKG		
53.375	PKG 96 REF: AMM 53 20 01 220 830	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-205	DETAILED INSPECTION OF THE INTERNAL FUSELAGE (SKINS AND STRUCTURE) - FS280.00 TO FS621.00 ABOVE THE FLOOR								
53.380	REF: AMM 53 20 01 220 862	MOS HRS/MSC AFL	240	+1m/-1m			28-APR-2006 0 0	<b>28-APR-2026</b>	28-MAY-2026
53-20-00-206	DETAILED INSPECTION OF THE LOWER INTERNAL SKIN AND FUSELAGE STRUCTURE - FS280.00 TO FS409.00 AS VISIBLE WITH FLOOR PANELS INSTALLED								
53.385	REF: AMM 53 20 01 220 805	MOS HRS/MSC AFL	48	+1m/-1m			13-MAR-2018 3512:30 2441	<b>13-MAR-2022</b>	13-APR-2022

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-207 (s)	DETAILED INSPECTION OF THE INTERNAL MID-FUSELAGE (SKIN AND STRUCTURE, FS409.00 BULKHEAD FORWARD FACE, AND THE EXTERNAL SURFACES OF THE FORWARD-AUXILIARY FUEL TANK) - FS280.00 TO FS409.00 BELOW THE FLOOR						PKG		
53.390	PKG 96 REF: AMM 53 20 01 220 861	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-210 (s)	DETAILED INSPECTION OF INTERNAL FORWARD KEEL BEAM-FS364 TO FS394						PKG		
53.395	PKG 96 REF: AMM 53 20 01 220 808	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-211 (s)	DETAILED INSPECTION FORWARD KEEL BEAM PRESSURE BOX AND KEEL BEAM LUGS/LINKS-FS394/409						PKG		
53.400	PKG 96 REF: AMM 53 20 01 220 809	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-212 (s)	DETAILED INSPECTION OF AFT KEEL BEAM - FS513 TO FS559						PKG		
53.405	PKG 48 REF: AMM 53 20 01 220 810	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
53-20-00-216 (s)	DETAILED INSPECTION OF AFT FACE OF FRAME BELOW THE FLOOR - FS409						PKG		
53.410	PKG 96 REF: AMM 53 20 01 220 814	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-217 (s)	DETAILED INSPECTION SILLS/FRAMES/EXTERNAL SKIN AROUND EMERGENCY-EXIT DOOR CUTOUT						PKG		
53.415	PKG 96 REF: AMM 53 20 01 220 815	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-218	DETAILED INSPECTION OF FITTING OF EMERGENCY-EXIT DOOR								
53.420	REF: AMM 53 20 01 220 816	MOS HRS/MSC AFL	48	+1m/-1m			07-MAR-2018 3512:30 2441	<b>07-MAR-2022</b>	07-APR-2022
53-20-00-220	DETAILED INSPECTION OF FLOOR SILL AREA OVER THE WING BOX-FS409 TO FS559								
53.425	REF: AMM 53 20 01 220 818	MOS HRS/MSC AFL	48	+1m/-1m			13-MAR-2018 3512:30 2441	<b>13-MAR-2022</b>	13-APR-2022
53-20-00-221 (s)	DETAILED INSPECTION OF WING TO FUSELAGE ATTACHMENT LUG-FS424						PKG		
53.430	PKG 96 REF: AMM 53 20 01 220 819	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-222 (s)	DETAILED INSPECTION OF WING TO FUSELAGE ATTACHMENT LUG - FS473.15						PKG		
53.435	PKG 96 REF: AMM 53 20 01 220 820	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-223 (s)	DETAILED INSPECTION OF FRAME BELOW THE FLOOR - FS513						PKG		
53.440	PKG 96 REF: AMM 53 20 01 220 821	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-224	DETAILED INSPECTION OF WING-TO-FUSELAGE ATTACHMENT LINK - FS513								
53.445	REF: AMM 53 20 01 220 822	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022
53-20-00-225 (s)	DETAILED INSPECTION WING-TO-FLOOR TIE BEAM - FS460						PKG		
53.450	PKG 96 REF: AMM 53 20 01 220 823	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-226	DETAILED INSPECTION OF THE UPPER SURFACE OF THE PRESSURE FLOOR SKIN PANEL - FS409.00 TO FS559.00 AND BL36L TO BL36R								
53.455	REF: AMM 53 20 01 220 824	MOS HRS/MSC AFL	48	+1m/-1m			12-MAR-2018 3512:30 2441	<b>12-MAR-2022</b>	12-APR-2022
53-20-00-227	DETAILED INSPECTION OF THE LOWER SURFACE OF THE PRESSURE FLOOR SKIN PANEL - FS409.00 TO FS559.00 AND BL36L TO BL36R								
53.460	REF: AMM 53 20 01 220 825	MOS HRS/MSC AFL	48	+1m/-1m			13-MAR-2018 3512:30 2441	<b>13-MAR-2022</b>	13-APR-2022
53-20-00-228 (s)	DETAILED INSPECTION OF THE PRESSURE FLOOR SUPPORT BEAMS - FS409 TO FS559 BL0.0, BL9, BL18.6, BL27 AND BL35.4						PKG		
53.465	PKG 96 REF: AMM 53 20 01 220 826	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-229 (s)	DETAILED INSPECTION OF UNDERFLOOR LONGERON ASSEMBLY - FS409 TO FS559						PKG		
53.470	PKG 96 REF: AMM 53 20 01 220 827	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-230 (s)	DETAILED INSPECTION OF MLG UPLOCK STRUCTURE FS513/FS559, BELOW WL73(LH/RH)						PKG		
53.475	PKG 96 REF: AMM 53 20 01 220 828	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-20-00-232 (s)	DETAILED INSPECTION OF THE INTERNAL SURFACES OF THE FORWARD AUXILIARY TANK						PKG		
53.480	PKG 96 REF: AMM 53 20 01 220 863	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-20-00-233 (s)	LUBRICATION OF THE WING -TO-FUSELAGE ATTACHMENT LINKS - FS513.00 PKG 48	MOS	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
<b>MRB</b>	<b>REF: AMM 12 20 04 640 819</b>	HRS/MSC AFL							
53-30-00-101	DETAILED INSPECTION OF THE BULB ANGLE STIFFENER, FORWARD PRESSURE SKIN PANEL AND FORWARD ATTACHMENT ANGLES OF THE AFT AUXILIARY TANK	MOS					07-MAR-2005 0		
53.485 <b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 822</b>	HRS/MSC AFL	7800				0	<b>7800</b>	
53-30-00-102	DETAILED INSPECTION OF THE BEAMS AND THE FUEL SKIN PANELS OF THE AFT AUXILIARY TANK	MOS					07-MAR-2005 0		
53.490 <b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 823</b>	HRS/MSC AFL	7800				0	<b>7800</b>	
53-30-00-104	SPECIAL DETAILED INSPECTION OF THE ACCESS DOORS ON THE AFT AUXILIARY TANK	MOS					07-MAR-2005 0		
53.495 <b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-014</b>	HRS/MSC AFL	6375				0	<b>6375</b>	
53-30-00-106	SPECIAL DETAILED INSPECTION OF THE FORWARD PRESSURE SKIN PANEL OF THE AFT AUXILIARY FUEL TANK	MOS					07-MAR-2005 0		
53.500 <b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-015</b>	HRS/MSC AFL	7800				0	<b>7800</b>	
53-30-00-110	DETAILED INSPECTION OF THE STRINGER SPLICE AT THE REAR PRESSURE BULKHEAD - FS621	MOS					07-MAR-2005 0		
53.505 <b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 829</b>	HRS/MSC AFL	7800				0	<b>7800</b>	
53-30-00-111	DETAILED INSPECTION OF THE FRAME ASSEMBLY PRESSURE BULKHEAD - FS621	MOS					07-MAR-2005 0		
53.510 <b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC AFL	6695				0	<b>6695</b>	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-113	DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB FEED-THROUGH HOLES AND CUTOUTS	MOS					20-APR-2015		
53.520		HRS/MSC					2495:55		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 831</b>	AFL	1548	+48			1885	<b>3433</b>	3481
53-30-00-114	DETAILED INSPECTION OF THE STRINGER SPLICE - FS718, STRINGER 1L AND 1R	MOS					07-MAR-2005		
53.525		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 832</b>	AFL	7800				0	<b>7800</b>	
53-30-00-115	DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD FRAME CAP - FS621	MOS					07-MAR-2005		
53.530		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 833</b>	AFL	7800				0	<b>7800</b>	
53-30-00-116	DETAILED INSPECTION OF THE FUSELAGE FRAME - VS55.625%, STRINGER 5	MOS					07-MAR-2005		
53.535		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 834</b>	AFL	7800				0	<b>7800</b>	
53-30-00-117	SPECIAL DETAILED INSPECTION OF THE CAP ANGLE OF THE FUSELAGE FRAME - FS755	MOS					07-MAR-2005		
53.540		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-017</b>	AFL	7800				0	<b>7800</b>	
53-30-00-118	SPECIAL DETAILED INSPECTION OF THE DRAG ANGLE FUSELAGE OF THE FRAME - FS755	MOS					07-MAR-2005		
53.545		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-009</b>	AFL	7800				0	<b>7800</b>	
53-30-00-119	DETAILED INSPECTION OF THE FUSELAGE FRAME AT FRONT SPAR ATTACHMENT OF THE VERTICAL STABILIZER - FS755	MOS					07-MAR-2005		
53.550		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 835</b>	AFL	7800				0	<b>7800</b>	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-120	SPECIAL DETAILED INSPECTION OF THE VERTICAL STIFFENERS OF THE REAR PRESSURE BULKHEAD	MOS					07-MAR-2005		
53.555		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	7800				0	<b>7800</b>	
53-30-00-121	SPECIAL DETAILED INSPECTION OF THE FLOOR BEAM ATTACHMENT TO THE PRESSURE BULKHEAD - FS621	MOS					07-MAR-2005		
53.560		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-20-022</b>	AFL	7800				0	<b>7800</b>	
53-30-00-122	SPECIAL DETAILED INSPECTION OF THE TRANSVERSE BEAM, AFT OF PRESSURE BULKHEAD - FS621, BL27	MOS					07-MAR-2005		
53.565		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-019</b>	AFL	7800				0	<b>7800</b>	
53-30-00-123	SPECIAL DETAILED INSPECTION OF THE UPPER CAP OF THE PYLON SPAR - FS625.3	MOS					07-MAR-2005		
53.570		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-54-50-001</b>	AFL	7800				0	<b>7800</b>	
53-30-00-124	SPECIAL DETAILED INSPECTION OF THE UPPER CAP OF THE PYLON SPAR AT FUSELAGE FRAME ATTACHMENT - FS672.2	MOS					07-MAR-2005		
53.575		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-020</b>	AFL	7800				0	<b>7800</b>	
53-30-00-125	SPECIAL DETAILED INSPECTION OF THE UPPER CAP OF THE ENGINE SUPPORT BEAM - FS625.3	MOS					07-MAR-2005		
53.580		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	7800				0	<b>7800</b>	
53-30-00-126	DETAILED INSPECTION OF THE FRAME SPLICE - FS672.2, STRINGER 6	MOS					07-MAR-2005		
53.585		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 836</b>	AFL	7800				0	<b>7800</b>	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-129	DETAILED INSPECTION OF THE FUSELAGE STRINGER SPLICE - FS625.3 STRINGER 0.0								
53.590		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 839</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-130	SPECIAL DETAILED INSPECTION OF THE SPLICE ANGLE OF THE OUTER FLANGE CAP - FS625.3								
53.595		MOS					07-MAR-2005		
<b>ALI</b>	<b>REF: NDT ET-53-30-010</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-131	DETAILED INSPECTION OF THE INTERCOSTALS AND CLIPS - FS621 TO FS625.3, PRESSURE BULKHEAD VERTICAL STIFFENERS - FS621, AND THE STIFFENING ANGLES ON THE ENGINE SUPPORT BEAM - FS625.3								
53.600		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 840</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-134	DETAILED INSPECTION OF THE FUSELAGE FRAME WEB - FS755, BL5.5 AND WL131								
53.605		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 843</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-135	DETAILED INSPECTION OF THE STRUCTURE ADJACENT TO THE OVERBOARD LAVATORY SERVICES								
53.610		MOS					30-MAY-2008		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 844</b>	HRS/MSC					668:12		
		AFL	7700				552		<b>7700</b>
53-30-00-137	SPECIAL DETAILED INSPECTION OF DRAG ANGLE - VS67.5								
53.620		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-006</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-138	DETAILED INSPECTION SPLICES/STRINGERS (LEFT & RIGHT) BETWEEN FRAMES-VS55.625/VS67.5								
53.625		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 846</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-139	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB CUTOUT - RBL13.05, WL63.80 (POST SB 604-53-008 PART B)								
53.630		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-011</b>	HRS/MSC	N/A				0		
		AFL					0		
53-30-00-154	SPECIAL DETAILED INSPECTION OF THE REAR PRESSURE BULKHEAD WEB - FS621.00 FWD FACE								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-155	DETAILED INSPECTION OF THE ENGINE SUPPORT BEAM								
		MOS							
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 807</b>	HRS/MSC							
		AFL	7800						<b>7800</b>
53-30-00-157	SPECIAL DETAILED INSPECTION OF THE BONDED DOUBLER ALONG SKIN SPLICE SEALANT AFT OF FS617.00								
		MOS							
<b>ALI</b>	<b>REF:</b>	HRS/MSC							
		AFL	7800						<b>7800</b>
53-30-00-158	DETAILED INSPECTION OF THE FUSELAGE SKIN AROUND THE LDS ANTENNA BETWEEN FS736.00 AND FS755.00, AND STRINGERS 26R AND 26L, (POST SB 604-34-063) OR (POST SB 604-34-066)								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 854</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
53-30-00-159	SPECIAL DETAILED INSPECTION OF THE SPLICE STRAP AND SKIN AT STRINGER 20L AND 20R BETWEEN FS559.00 AND FS621.00								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-53-30-024</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-161	DETAILED INSPECTION OF THE SPLICE ANGLE OF THE OUTER FLANGE CAP - FS625.3.								
<b>AIRWORTHINESS</b>	<b>REF: AMM 53 30 01 220 858</b>	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	<b>7800</b>	
53-30-00-201	DETAILED INSPECTION OF THE AFT FACE OF THE PRESSURE BULKHEAD BELOW FLOOR -FS559								
53.635	<b>REF: AMM 53 30 01 220 801</b>	MOS HRS/MSC AFL	48	+1m/-1m			20-MAR-2018 3512:30 2441	<b>20-MAR-2022</b>	20-APR-2022
53-30-00-202	DETAILED INSPECTION OF FORWARD FACE OF PRESSURE BULKHEAD BELOW FLOOR-FS559								
53.640	<b>REF: AMM 53 30 01 220 802</b>	MOS HRS/MSC AFL	48	+1m/-1m			13-MAR-2018 3512:30 2441	<b>13-MAR-2022</b>	13-APR-2022
53-30-00-203	DETAILED INSPECTION OF AFT FACE OF REAR PRESSURE BULKHEAD - FS621								
53.645	<b>REF: AMM 53 30 01 220 803</b>	MOS HRS/MSC AFL	48	+1m/-1m			07-MAR-2018 3512:30 2441	<b>07-MAR-2022</b>	07-APR-2022
53-30-00-204 (s)	DETAILED INSPECTION OF STABILIZER DRAG ANGLES-FS700 TO FS820, STRINGER 2L AND 2R						PKG		
53.650	<b>REF: AMM 53 30 01 220 804</b>	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-30-00-205	DETAILED INSPECTION OF THE FORWARD FACE OF THE REAR PRESSURE BULKHEAD ABOVE THE FLOOR - FS621								
53.655	<b>REF: AMM 53 30 01 220 805</b>	MOS HRS/MSC AFL	240	+1m/-1m			28-APR-2006 0 0	<b>28-APR-2026</b>	28-MAY-2026
53-30-00-206 (s)	DETAILED INSPECTION OF PROFILE PLATES OF FLOOR SUPPORT STRUCTURE-FS559/FS621						PKG		
53.660	<b>REF: AMM 53 30 01 220 806</b>	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-207 (s) 53.665	DETAILED INSPECTION OF PROFILE PLATES OF FLOOR SUPPORT STRUCTURE - FS621 PKG 48 <b>REF:</b> AMM 53 30 01 220 821	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-30-00-208 (s) 53.670	DETAILED INSPECTION OF ENGINE SUPPORT BEAM STRUCTURE PKG 96 <b>REF:</b> AMM 53 30 01 220 807	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-30-00-209 (s) 53.675	DETAILED INSPECTION OF THE INTERNAL AFT FUSELAGE (SKIN AND STRUCTURE, FS621.00 BULKHEAD FORWARD FACE AND THE EXTERNAL SURFACES OF THE AFT-AUXILIARY FUEL TANK) - FS559.00 TO FS621.00 BELOW THE FLOOR PKG 96 <b>REF:</b> AMM 53 30 01 220 852	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-30-00-211 53.680	DETAILED INSPECTION TRACK SUPPORTS NEAR AND THE SILLS AND FRAMES AROUND THE CARGO COMPARTMENT DOOR CUTOUT <b>REF:</b> AMM 53 30 01 220 810	MOS HRS/MSC AFL	48	+1m/-1m			13-MAR-2018 3512:30 2441	<b>13-MAR-2022</b>	13-APR-2022
53-30-00-213 53.685	DETAILED INSPECTION OF FITTINGS OF CARGO COMPARTMENT DOOR <b>REF:</b> AMM 53 30 01 220 812	MOS HRS/MSC AFL	48	+1m/-1m			07-MAR-2018 3512:30 2441	<b>07-MAR-2022</b>	07-APR-2022
53-30-00-215 (s) 53.690	DETAILED INSPECTION OF INTERNAL SKIN AND FUSELAGE STRUCTURE - FS621 TO FS755 PKG 48 <b>REF:</b> AMM 53 30 01 220 814	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-30-00-216	DETAILED INSPECTION OF THE FORWARD FACE OF FRAME - FS755								
53.695	REF: AMM 53 30 01 220 816	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022
53-30-00-217 (s)	DETAILED INSPECTION OF THE EXTERNAL SKIN AROUND THE APU EXHAUST CUTOUT						PKG		
53.700	PKG 48 REF: AMM 53 30 01 220 817	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
53-30-00-219 (s)	DETAILED INSPECTION OF THE EXTERNAL SIDE SKIN PANELS OF THE FUSELAGE - FS559.00 TO FS755.00 AND STRINGER 6L TO 20L AND 6R TO 20R COVERED BY PYLON						PKG		
53.705	PKG 96 REF: AMM 53 30 01 220 819	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-30-00-222 (s)	DETAILED INSPECTION OF THE INTERNAL SKIN AND STRUCTURE OF THE AFT AUXILIARY TANK						PKG		
53.710	PKG 96 REF: AMM 53 30 01 220 850	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-30-00-223 (s)	SPECIAL DETAILED INSPECTION OF THE SKIN AND FUSELAGE STRUCTURE - FS718 TO FS755						PKG		
53.715	PKG 96 REF: NDT ET-53-30-012	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
53-43-00-202	DETAILED INSPECTION OF AFT FACE OF THE FRAME - VS67.5%								
53.720	REF: AMM 53 43 02 220 801	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022
53-43-00-203	DETAILED INSPECTION OF INTERNAL SKIN & FUSELAGE STRUCTURE - FS755 TO VS67.5%								
53.725	REF: AMM 53 43 02 220 802	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-50-00-201 (s) 53.730	DETAILED INSPECTION OF INTERNAL SKIN AND STRUCTURE OF THE TAIL TANK PKG 96 <b>REF:</b> AMM 53 66 01 220 801	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-50-00-202 (s) 53.735	DETAILED INSPECTION OF THE FLOOR STRUCTURE OF THE TAIL TANK PKG 96 <b>REF:</b> AMM 53 66 01 220 802	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-50-00-203 (s) 53.740	DETAILED INSPECTION OF THE FORWARD FACE OF THE FUEL TAIL TANK FORWARD BULKHEAD. PKG 96 <b>REF:</b> AMM 53 66 01 220 803	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-50-00-204 (s) 53.745	DETAILED INSPECTION OF AFT FACE OF TAIL TANK AFT BULKHEAD PKG 96 <b>REF:</b> AMM 53 66 01 220 804	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-201 (s) 53.750	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - EXTERNAL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-202 (s) 53.755	GENERAL VISUAL INSPECTION OF THE NOSE RADOME - INTERNAL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-203 (s) 53.760	GENERAL VISUAL INSPECTION NOSE COMPARTMENT LOWER EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-204 (s) 53.765	GENERAL VISUAL INSPECTION NOSE COMPARTMENT LOWER INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-205 (s) 53.770	GENERAL VISUAL INSPECTION NOSE COMPARTMENT LOWER INTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-206 (s) 53.775	GENERAL VISUAL INSPECTION OF THE NLG WHEEL WELL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-207 (s) 53.780	GENERAL VISUAL INSPECTION FORWARD AVIONICS & FLIGHT CONTROLS COMPARTMENT-EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-208 (s) 53.785	GENERAL VISUAL INSPECTION FORWARD AVIONICS AND FLIGHT CONTROLS COMPARTMENTS INTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-209 (s) 53.790	GENERAL VISUAL INSPECTION FORWARD AVIONICS AND FLIGHT CONTROLS COMPARTMENT INTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-210 (s) 53.795	GENERAL VISUAL INSPECTION MAIN AVIONICS COMPARTMENT - EXTERNAL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-211 (s) 53.800	GENERAL VISUAL INSPECTION MAIN AVIONICS COMPARTMENT - INTERNAL PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-212 (s) 53.805	GENERAL VISUAL INSPECTION MID-FUSELAGE LOWER - EXTERNAL PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-213 (s) 53.810	GENERAL VISUAL INSPECTION LOWER SURFACE OF THE PRESSURE FLOOR FROM FS409 TO FS559 PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-214 (s) 53.815	GENERAL VISUAL INSPECTION OF THE MLG WHEEL WELL PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-215 (s) 53.820	GENERAL VISUAL INSPECTION MID-FUSELAGE BETWEEN THE PRESSURE FLOOR AND THE CABIN FLOOR - LOWER INTERIOR PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-216 (s) 53.825	GENERAL VISUAL INSPECTION AFT COMPARTMENT & AFT WING TO FUSELAGE FAIRING-EXTERNAL PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-217 (s) 53.830	GENERAL VISUAL INSPECTION MID-FUSELAGE COMPARTMENT - LOWER INTERNAL (FS589.0 TO FS621.0) PKG 24 REF: See Workcard	MOS HRS/MSC AFL	24	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-218 (s) 53.835	GENERAL VISUAL INSPECTION FORWARD EQUIPMENT COMPARTMENT - EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-219 (s) 53.840	GENERAL VISUAL INSPECTION FORWARD EQUIPMENT COMPARTMENT - INTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-220 (s) 53.845 <b>MRB</b>	GENERAL VISUAL INSPECTION FLIGHT COMPARTMENT EXTERNAL PKG 24 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	24	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
53-ZL-00-221 (s) 53.850	GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT - INTERNAL WITHOUT REMOVAL OF THE HEADLINER AND THE GLARESHIELD PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-222 (s) 53.855	GENERAL VISUAL INSPECTION PASSENGER COMPARTMENT EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-223 53.860	GENERAL VISUAL INSPECTION OF THE PASSENGER COMPARTMENT - INTERNAL <b>REF:</b> See Workcard	MOS HRS/MSC AFL	192	+1m/-1m			28-APR-2006 0 0	<b>28-APR-2022</b>	28-MAY-2022
53-ZL-00-224 (s) 53.865	GENERAL VISUAL INSPECTION OF THE CARGO COMPARTMENT-EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-225 (s) 53.870	GENERAL VISUAL INSPECTION CARGO COMPARTMENT - INTERNAL WITHOUT REMOVAL OF THE HEADLINER PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-226 53.875	GENERAL VISUAL INSPECTION CARGO COMPARTMENT - INTERNAL WITH THE HEADLINER REMOVED  <b>REF:</b> See Workcard	MOS HRS/MSC AFL	192	+1m/-1m			28-APR-2006 0 0	<b>28-APR-2022</b>	28-MAY-2022
53-ZL-00-227 (s) 53.880	GENERAL VISUAL INSPECTION AFT EQUIPMENT COMPARTMENT - EXTERNAL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-228 (s) 53.885	GENERAL VISUAL INSPECTION AFT EQUIPMENT COMPARTMENT - INTERNAL PKG 12 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	12	+1m/-1m			PKG 08-MAY-2020 4328:45 2835		
53-ZL-00-229 (s) 53.890	GENERAL VISUAL INSPECTION FUSELAGE/STABILIZER SECTION - EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-00-230 (s) 53.895	GENERAL VISUAL INSPECTION FUSELAGE/STABILIZER SECTION - INTERNAL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-231 (s) 53.900	GENERAL VISUAL INSPECTION OF THE TAIL CONE - EXTERNAL PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
53-ZL-00-232 (s) 53.905	GENERAL VISUAL INSPECTION OF THE TAIL CONE - INTERNAL PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
53-ZL-00-233 (s) 53.910	GENERAL VISUAL INSPECTION MID-FUSELAGE COMPARTMENT - LOWER INTERNAL (FS559.0 TO FS621.0) PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
53-ZL-60-601 (s) STLMC	GENERAL VISUAL INSPECTION OF THE INTERIOR CABIN PKG 36 REF:	MOS HRS/MSC AFL	36				PKG 26-MAR-2019 3702:35 2541		
536101-001 53.915	ASSY RADOME 601R33038-963 2773960 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
<b>CHAPTER 54 NACELLES/PYLONS</b>									
54-50-00-101 54.005 AIRWORTHINESS	DETAILED INSPECTION PYLON UPPER SKIN - FS682 REF: AMM 54 50 01 220 805	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800
54-50-00-102 54.010 AIRWORTHINESS	DETAILED INSPECTION OF UPPER SPLICE OF PYLON CANTED RIB - FS672.2 REF: AMM 54 50 01 220 806	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800
54-50-00-103 AIRWORTHINESS	SPECIAL DETAILED INSPECTION OF THE AFT ENGINE-MOUNT UPPER-CAP FROM FS672.00 TO FS682.00 REF: NDT ET-54-50-002	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-50-00-201 (s)	DETAILED INSPECTION FORWARD ENGINE-MOUNT SPAR ASSEMBLY						PKG		
54.015	PKG 96 REF: AMM 54 50 01 220 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
54-50-00-203 (s)	DETAILED INSPECTION OF THE INTERNAL STRUCTURE OF THE PYLON						PKG		
54.020	PKG 96 REF: AMM 54 50 01 220 803	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
54-50-00-204 (s)	DETAILED INSPECTION OF AFT ENGINE MOUNT SUPPORT STRUCTURE						PKG		
54.025	PKG 96 REF: AMM 54 50 01 220 804	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
54-ZL-00-201 (s)	GENERAL VISUAL INSPECTION OF THE PYLON - EXTERNAL LH						PKG		
54.030	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
54-ZL-00-202 (s)	GENERAL VISUAL INSPECTION OF THE PYLON - EXTERNAL RH						PKG		
54.035	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
54-ZL-00-203 (s)	GENERAL VISUAL INSPECTION PYLON LEADING EDGE INTERNAL LH						PKG		
54.040	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
54-ZL-00-204 (s)	GENERAL VISUAL INSPECTION PYLON LEADING EDGE INTERNAL RH						PKG		
54.045	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
54-ZL-00-205 (s)	GENERAL VISUAL INSPECTION OF PYLON MID SECTION-INTERNAL LH						PKG		
54.050	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
54-ZL-00-206 (s)	GENERAL VISUAL INSPECTION OF PYLON MID SECTION-INTERNAL RH						PKG		
54.055	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
54-ZL-00-207 (s)	GENERAL VISUAL INSPECTION PYLON TRAILING EDGE INTERNAL LH						PKG		
54.060	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
54-ZL-00-208 (s)	GENERAL VISUAL INSPECTION PYLON TRAILING EDGE INTERNAL RH						PKG		
54.065	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

**CHAPTER 55 STABILIZERS**

55-10-00-101	DETAILED INSPECTION OF THE HORIZONTAL-STABILIZER BATHTUB AND SCREW JACK FITTINGS								
55.005		MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	REF: AMM 55 10 01 220 807	AFL	7800				0	<b>7800</b>	
55-10-00-102	SPECIAL DETAILED INSPECTION OF THE UPPER CAP AND SKIN OF THE REAR SPAR OF THE HORIZONTAL STABILIZER - RIB 1								
55.010		MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	REF: NDT ET-55-10-001	AFL	7800				0	<b>7800</b>	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-103	DETAILED INSPECTION OF THE CENTERLINE RIB UPPER CAP OF THE HORIZONTAL STABILIZER - FS886								
55.015		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 10 01 220 808</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-10-00-105	DETAILED INSPECTION OF THE REAR SPAR UPPER CAP AND SPLICE AT BL 0.0 OF THE HORIZONTAL STABILIZER								
55.020		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 10 01 220 810</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-10-00-106	SPECIAL DETAILED INSPECTION OF THE PIVOT FITTING LUGS OF THE HORIZONTAL STABILIZER ON THE HORIZONTAL STABILIZER SIDE								
55.025		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-10-00-107	DETAILED INSPECTION OF THE UPPER CAP SPLICE OF THE FRONT SPAR OF THE HORIZONTAL STABILIZER - BL6								
55.030		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 10 01 220 817</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-10-00-108	DETAILED INSPECTION OF THE UPPER SKIN PANEL AT STRINGER 1 OF THE HORIZONTAL STABILIZER - BL6								
55.035		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 10 01 220 811</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-10-00-109	DETAILED INSPECTION OF HORIZONTAL STABILIZER REAR SPAR WEB SPLICE - BL0								
55.040		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 10 01 220 812</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-10-00-201	DETAILED INSPECTION OF THE UPPER FACE OF THE TOP CANTED RIB AND THE RIB FITTINGS OF THE VERTICAL STABILIZER AND THE ATTACHMENT FITTINGS & SKIN SPLICES OF HORIZONTAL STABILIZER								
55.045		MOS HRS/MSC REF: AMM 55 00 00 220 803 AFL	48	+1m/-1m			10-MAR-2018 3512:30 2441	<b>10-MAR-2022</b>	10-APR-2022
55-10-00-202 (s)	DETAILED INSPECTION OF THE FRONT SPAR OF THE HORIZONTAL STABILIZER						PKG		
55.050	PKG 96	MOS HRS/MSC REF: AMM 55 10 01 220 802 AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
55-10-00-203 (s)	DETAILED INSPECTION OF THE HORIZONTAL STABILIZER (INTERNAL SKINS, STRUCTURE, REAR SPAR AND HINGE FITTINGS) AND THE ELEVATOR (FORWARD FACE OF THE FRONT SPAR, HINGE FITTINGS AND BOLTS)						PKG		
55.055	PKG 96	MOS HRS/MSC REF: AMM 55 00 00 220 801 AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
55-10-00-207 (s)	DETAILED INSPECTION OF INNER PIVOT PIN OF HORIZONTAL STABILIZER						PKG		
55.060	PKG 48	MOS HRS/MSC REF: AMM 55 10 01 220 815 AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
55-20-00-101	SPECIAL DETAILED INSPECTION OF THE PCU FITTINGS AND THE HINGE FITTINGS OF THE ELEVATOR								
55.065		MOS HRS/MSC REF: NDT ET-55-20-001 AFL	3600				07-MAR-2005 0 0	<b>3600</b>	
<b>AIRWORTHINESS</b>									
55-20-00-102	DETAILED INSPECTION OF THE ELEVATOR SKINS AND FRONT SPAR								
55.070		MOS HRS/MSC REF: AMM 55 10 01 220 813 AFL	7800				07-MAR-2005 0 0	<b>7800</b>	
<b>AIRWORTHINESS</b>									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-20-00-103	DETAILED INSPECTION OF THE ELEVATOR HINGE BOLTS	MOS					07-MAR-2005		
55.075		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 10 01 220 814</b>	AFL	4800				0	<b>4800</b>	
55-20-00-202	DETAILED INSPECTION OF EXTERNAL SURFACES OF ELEVATOR	MOS	48	+1m/-1m			05-MAR-2018	<b>05-MAR-2022</b>	05-APR-2022
55.080		HRS/MSC					3512:30		
	<b>REF: AMM 55 20 01 220 802</b>	AFL					2441		
55-30-00-101	SPECIAL DETAILED INSPECTION OF THE HORIZONTAL STABILIZER PIVOT FITTING LUGS ON THE VERTICAL STABILIZER SIDE	MOS					07-MAR-2005		
55.085		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT UT-55-30-001</b>	AFL	7800				0	<b>7800</b>	
55-30-00-102	SPECIAL DETAILED INSPECTION OF THE STRINGER EXTENSION FITTINGS OF THE VERTICAL STABILIZER VS31.875%	MOS					07-MAR-2005		
55.090		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-30-006</b>	AFL	7800				0	<b>7800</b>	
55-30-00-103	SPECIAL DETAILED INSPECTION OF THE PIVOT LUGS OF THE PITCH TRIM ACTUATOR ON THE VERTICAL STABILIZER SIDE	MOS					07-MAR-2005		
55.095		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-30-004</b>	AFL	7800				0	<b>7800</b>	
55-30-00-104	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT SPAR TO THE FUSELAGE ATTACHMENT FITTINGS	MOS					07-MAR-2005		
55.100		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	AFL	7800				0	<b>7800</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-00-105	DETAILED INSPECTION OF THE VERTICAL STABILIZER STRINGER SPLICE - VS55.625% AT RIB3 AND VS31.875% AT RIB 2								
55.105		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 30 01 220 807</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
55-30-00-106	DETAILED INSPECTION OF THE SKIN CUTOUT AT THE ACCESS HOLES BETWEEN RIBS 1 AND 3, VS31.875% AND VS43.75% OF THE VERTICAL STABILIZER								
55.110		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 30 01 220 808</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
55-30-00-107	SPECIAL DETAILED INSPECTION OF REAR SPAR CAPS OF THE VERTICAL STABILIZER								
55.115		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-30-007</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
55-30-00-108	SPECIAL DETAILED INSPECTION OF THE FRONT SPAR CAPS AT RIB 1 AND SPLICE STRAPS LH/RH OF THE VERTICAL STABILIZER								
55.120		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-30-001</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
55-30-00-109	GENERAL VISUAL INSPECTION OF THE REAR-SPAR WEB OF THE VERTICAL STABILIZER - RIB 7								
55.125		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 30 01 210 807</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>
55-30-00-110	SPECIAL DETAILED INSPECTION OF THE MID-SPAR CAPS OF THE VERTICAL STABILIZER								
55.130		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-30-005</b>	HRS/MSC AFL	7800				0 0		<b>7800</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-30-00-111	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER FRONT SPAR TO FRAME ATTACHMENT FITTINGS LOWER LEGS - FS755.00								
55.135		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-30-00-113	SPECIAL DETAILED INSPECTION OF THE SKIN CUTOUT AT THE ACCESS HOLE BETWEEN RIBS 4 AND 5, VS25.9375% AND VS31.875% OF THE VERTICAL STABILIZER								
55.140		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-30-008</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
55-30-00-115	DETAILED INSPECTION OF THE PITCH TRIM ACTUATOR PIVOT LUGS SUPPORT PLATES ON THE VERTICAL STABILIZER SIDE								
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 30 01 220 813</b>	MOS							
		HRS/MSC							
		AFL	7800						<b>7800</b>
55-30-00-201 (s)	DETAILED INSPECTION OF THE VERTICAL STABILIZER (FORWARD SIDE OF THE FRONT SPAR, ATTACHMENT FITTINGS AND THE SPLICE STRAP)						PKG		
55.150	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 55 30 01 220 812</b>	HRS/MSC					2304:15		
		AFL					1731		
55-30-00-206 (s)	DETAILED INSPECTION OF INTERNAL STRUCTURE OF VERTICAL STABILIZER						PKG		
55.160	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 55 30 01 220 806</b>	HRS/MSC					2304:15		
		AFL					1731		
55-40-00-101	DETAILED INSPECTION OF THE HINGES AND PCU BOLTS OF THE RUDDER								
55.165		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 40 01 220 803</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-40-00-102	DETAILED INSPECTION OF THE SKINS AND FRONT SPAR OF THE RUDDER. A/C 5301 TO 5526 AND A/C 5534	MOS						07-MAR-2005	
55.170		HRS/MSC	N/A				0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 40 01 220 804</b>	AFL					0		
55-40-00-103	GENERAL VISUAL INSPECTION OF THE EXTERNAL SKINS AND FRONT SPAR OF THE RUDDER. A/C 5527 TO 5533 AND A/C 5535 & SUBS	MOS						07-MAR-2005	
55.175		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 55 40 01 210 801</b>	AFL	7800				0		<b>7800</b>
55-40-00-104	SPECIAL DETAILED INSPECTION OF THE VERTICAL STABILIZER TO RUDDER HINGE FITTINGS AND PCU ATTACHMENT LUGS	MOS							
		HRS/MSC							
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-55-40-001</b>	AFL	7800						<b>7800</b>
55-40-00-201	DETAILED INSPECTION OF EXTERNAL SURFACES OF THE RUDDER	MOS	48	+1m/-1m				05-MAR-2018	05-MAR-2022 05-APR-2022
55.180		HRS/MSC					3512:30		
	<b>REF: AMM 55 40 01 220 801</b>	AFL					2441		
55-40-00-202 (s)	DETAILED INSPECTION OF THE RUDDER AND THE VERTICAL STABILIZER	MOS	96	+1m/-1m				PKG	
55.185	PKG 96	HRS/MSC					16-JUN-2014		
	<b>REF: AMM 55 00 00 220 802</b>	AFL					2304:15		
							1731		
55-ZL-00-201 (s)	GENERAL VISUAL INSPECTION VERTICAL STABILIZER ASSEMBLY - EXTERNAL	MOS	48	+1m/-1m				PKG	
55.190	PKG 48	HRS/MSC					23-MAR-2018		
	<b>REF: See Workcard</b>	AFL					3512:30		
							2441		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-ZL-00-202 (s) 55.195	GENERAL VISUAL INSPECTION RAM AIR INTAKE & DORSAL FAIRING - INTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
55-ZL-00-203 (s) 55.200	GENERAL VISUAL INSPECTION LEADING EDGE OF THE VERTICAL STABILIZER - INTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
55-ZL-00-204 (s) 55.205	GENERAL VISUAL INSPECTION VERTICAL STABILIZER - INTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
55-ZL-00-205 (s) 55.210	GENERAL VISUAL INSPECTION TIP OF THE VERTICAL STABILIZER - INTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
55-ZL-00-206 (s) 55.215	GENERAL VISUAL INSPECTION HORIZONTAL STABILIZER - EXTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
55-ZL-00-207 (s) 55.220	GENERAL VISUAL INSPECTION HORIZONTAL STABILIZER EXTERNAL RH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
55-ZL-00-208 (s) 55.225	GENERAL VISUAL INSPECTION LEADING EDGE OF THE HORIZONTAL STABILIZER - INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
55-ZL-00-209 (s)	GENERAL VISUAL INSPECTION LEADING EDGE OF THE HORIZONTAL STABILIZER - INTERNAL RH						PKG		
55.230	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
55-ZL-00-210 (s)	GENERAL VISUAL INSPECTION HORIZONTAL STABILIZER - INTERNAL LH						PKG		
55.235	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
55-ZL-00-211 (s)	GENERAL VISUAL INSPECTION HORIZONTAL STABILIZER - INTERNAL RH						PKG		
55.240	PKG 96 REF: See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
551100-001	ASSY LH ELEVATOR								
55.245	600-24025-1011 AVCH1098 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
551100-002	ASSY RH ELEVATOR								
55.250	600-24025-1012 AVCH1098 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
551100-003	HORIZONTAL STABILIZER ASSEMBLY								
55.255	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 56 WINDOWS</b>									
56-10-00-101	DETAILED INSPECTION OF THE WINDSHIELD AND SIDE WINDOW LOWER T-PLATES								
56.005		MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 56 10 01 220 801</b>	<b>AFL</b>	<b>3747</b>				<b>0</b>	<b>3747</b>	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
56-10-00-102	DETAILED INSPECTION OF THE SIDE WINDOW - 4 BUSHING HOLES	MOS					08-MAY-2020		
56.010		HRS/MSC					4328:45		
<b>AIRWORTHINESS</b>	<b>REF: AMM 56 10 01 220 802</b>	AFL	300				2835		<b>3135</b>
56-10-00-103	DETAILED INSPECTION WINDSHIELD AND SIDE WINDOW - BUSHING HOLES	MOS					15-AUG-2019		
56.015		HRS/MSC					3958		
<b>AIRWORTHINESS</b>	<b>REF: AMM 56 10 01 220 803</b>	AFL	600				2666		<b>3266</b>
56-10-00-104	SPECIAL DETAILED INSPECTION OF THE BOLTS AT THE WINDSHIELD AND SIDE WINDOW T-PLATES.	MOS					05-OCT-2017		
56.020		HRS/MSC					3307:10		
<b>AIRWORTHINESS</b>	<b>REF: NDT PT-56-10-001</b>	AFL	1200				2325		<b>3525</b>
56-10-00-105	SPECIAL DETAILED INSPECTION OF THE ATTACHMENT BOLTS FOR THE WINDSHIELD AND SIDE WINDOW	MOS					07-MAR-2005		
56.025		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT PT-56-10-002</b>	AFL	4800				0		<b>4800</b>
561101-001	NO. 1 WINDSHIELD ASSY, (LH)	MOS					14-OCT-2013		
56.030	600-33030-25	HRS/MSC	O/C	N:3			2169:25		
	11949	AFL		N:0			1641		
	<b>REF: See Workcard</b>			N:0					
561101-002	NO. 2 WINDSHIELD ASSY, (RH)	MOS					30-DEC-2013		
56.030	600-33030-26	HRS/MSC	O/C	N:3			2233:55		
	11844	AFL		N:0			1688		
	<b>REF: See Workcard</b>			N:0					
561103-001	PILOT SIDE (L.S) WINDOW	MOS					07-MAR-2005		
56.035	600-33030-27	HRS/MSC	O/C	N:0			0		
	8075	AFL		N:0			0		
	<b>REF: See Workcard</b>			N:0					

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
561104-001	COPILOT SIDE (R.S) WINDOW								
56.035	600-33030-28 8590 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-JUL-2009 1094:15 850		
562101-001	CABIN WINDOW								
56.040	601R31056-17 N488410/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-002	CABIN WINDOW								
56.045	601R31056-17 N494611/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-003	CABIN WINDOW								
56.050	601R31056-17 N489710/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-004	CABIN WINDOW								
56.055	601R31056-17 N468109/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-005	CABIN WINDOW								
56.060	601R31056-17 N493211/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-006	CABIN WINDOW								
56.065	601R31056-17 N475510/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
562101-007	CABIN WINDOW								
56.070	601R31056-17 N492010/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-008	CABIN WINDOW								
56.075	601R31056-17 N474210/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-009	CABIN WINDOW								
56.080	601R31056-17 N492310/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-010	CABIN WINDOW								
56.085	601R31056-17 N491910/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-011	CABIN WINDOW								
56.090	601R31056-17 N472209/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562101-012	CABIN WINDOW								
56.095	601R31056-17 N492210/04 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
562102-001	CABIN EMERGENCY EXIT WINDOW								
56.100	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

**CHAPTER 57 WINGS**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-101	DETAILED INSPECTION OF THE LOWER WING PLANK - CENTERLINE SPLICE, STRINGERS 15 AND 16								
57.005		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 832</b>	HRS/MSC					0		
		AFL	6407				0		<b>6407</b>
57-10-00-102	DETAILED INSPECTION OF THE LOWER WING PLANK - CENTERLINE SPLICE, WS242 AND WS264								
57.010		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 833</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-103	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - SKIN SPLICE STRINGERS 15 AND 16.								
57.015		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-031</b>	HRS/MSC					0		
		AFL	3893				0		<b>3893</b>
57-10-00-104	DETAILED INSPECTION OF THE LOWER WING PLANK - WS45, WS199 AND WS220								
57.020		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 834</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-105	DETAILED INSPECTION OF LOWER WING PLANK FRONT SPAR SPLICE WS29.42								
57.025		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 835</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-106	DETAILED INSPECTION OF THE LOWER WING PLANK - FRONT SPAR WS45								
57.030		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 836</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-107	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS 45.00, STRINGER 10.								
57.035		MOS					08-MAY-2020		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-013</b>	HRS/MSC					4328:45		
		AFL	1416				2835		<b>4251</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-108	DETAILED INSPECTION OF THE LOWER WING PLANK - FUEL DRAIN HOLE WS45.00, STRINGER 17								
57.040		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 837</b>	HRS/MSC					0		
		AFL	4644				0		<b>4644</b>
57-10-00-109	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - REAR SPAR WS45 AND WS47								
57.045		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT RT-57-10-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-110	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - WS 45.00, STRINGERS 14 AND 15								
57.050		MOS					08-MAY-2020		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-009</b>	HRS/MSC					4328:45		
		AFL	1368				2835		<b>4203</b>
57-10-00-111	DETAILED INSPECTION OF THE LOWER WING PLANK - WS65, WS94, WS106.4 AND WS127.5								
57.055		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 838</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-112	SPECIAL DETAILED INSPECTION LOWER WING PLANK AT WS65 , STRINGER 17								
57.060		MOS					14-AUG-2019		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-016</b>	HRS/MSC					3958		
		AFL	1307				2666		<b>3973</b>
57-10-00-114	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK AT THE REAR SPAR - WS59 TO WS65								
57.065		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	5297				0		<b>5297</b>
57-10-00-115	SPECIAL DETAILED INSPECTION OF THE LOWER WING PLANK - NEAR MLG TRUNNION WS65, AND THE AUXILIARY SPAR ACCESS HOLE.								
57.070		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-117	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK WS85.5, STRINGERS 14 TO 17	MOS					14-AUG-2019		
57.075		HRS/MSC					3958		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-017</b>	AFL	883				2666		<b>3549</b>
57-10-00-123	DETAIL INSPECTION OF LOWER WING PLANK AT REAR SPAR - WS148	MOS					07-MAR-2005		
57.085		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 872</b>	AFL	3951				0		<b>3951</b>
57-10-00-124	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK-WS148 STRINGERS 8 TO 10 AND 15	MOS					16-JUN-2014		
57.090		HRS/MSC					2304:15		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-007</b>	AFL	1719	+19	-12		1731		<b>3438 3457</b>
57-10-00-126	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK - WS148, STRINGER 19	MOS					07-MAR-2005		
57.095		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT RT-57-20-001</b>	AFL	7800				0		<b>7800</b>
57-10-00-127	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AT AFT EDGE-WS163 TO WS170.5	MOS					07-MAR-2005		
57.100		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-032</b>	AFL	7800				0		<b>7800</b>
57-10-00-128	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK - WS163 STRINGER 15	MOS					10-MAR-2018		
57.105		HRS/MSC					3512:30		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-018</b>	AFL	1200				2441		<b>3641</b>
57-10-00-129	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AT REAR SPAR-WS178/WS189	MOS					07-MAR-2005		
57.110		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-024</b>	AFL	7800				0		<b>7800</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-132	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AT REAR SPAR - WS166								
57.115		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-023</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-133	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AT REAR SPAR-WS217/WS222								
57.120		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-004</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-134	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AROUND ACCESS HOLE-WS220, STRINGER 10								
57.125		MOS					03-APR-2017		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-010</b>	HRS/MSC					3041:45		
		AFL	1809				2185		<b>3994</b>
57-10-00-135	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AT REAR SPAR - WS219								
57.130		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT RT-57-20-002</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-137	DETAILED INSPECTION OF LOWER WING PLANK - WS238 AND WS242								
57.135		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 848</b>	HRS/MSC					0		
		AFL	5740				0		<b>5740</b>
57-10-00-141	DETAILED INSPECTION OF LOWER WING PLANK AT REAR SPAR - WS242 AND WS260								
57.140		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 852</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-145	SPECIAL DETAILED INSPECTION OF LOWER WING PLANK AROUND ACCESS HOLE-WS112, STRINGER 10								
57.145		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-20-027</b>	HRS/MSC					0		
		AFL	6158				0		<b>6158</b>



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-146	DETAILED INSPECTION OF WING-TO-FUSELAGE ATTACHMENT LUGS-FS424 & FS513								
57.150		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 856</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-147	DETAILED INSPECTION OF WING-TO-FUSELAGE ATTACHMENT LUG-FS473, BL45								
57.155		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 863</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-148	DETAILED INSPECTION OF WING UPPER SURFACE								
57.160		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 857</b>	HRS/MSC					0		
		AFL	4800				0		<b>4800</b>
57-10-00-149	DETAILED INSPECTION INTERNAL STRUCTURE OF THE WING BOX								
57.165		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 858</b>	HRS/MSC					0		
		AFL	4800				0		<b>4800</b>
57-10-00-152	DETAILED INSPECTION LOWER WING PLANK BUTT STRAP AT FRONT & REAR SPAR - WS314.5								
57.170		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 861</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-10-00-153	DETAILED INSPECTION OF THE LOWER WING PLANK - WS88.0.								
		MOS					15-AUG-2019		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 874</b>	HRS/MSC					3958		
		AFL	792				2666		<b>3458</b>
57-10-00-154	DETAILED INSPECTION OF THE LOWER WING PLANK - WS242.0.								
		MOS					08-MAY-2020		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 10 00 220 875</b>	HRS/MSC					4328:45		
		AFL	952				2835		<b>3787</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-201 (s)	DETAILED INSPECTION OF THE EXTERNAL CENTER WING - LWS50 TO RWS50						PKG		
57.175	PKG 96 REF: AMM 57 10 00 220 866	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-10-00-202	DETAILED INSPECTION OF THE INTERNAL CENTER WING - LWS45 TO RWS45								
57.180	REF: AMM 57 10 00 220 864	MOS HRS/MSC AFL	48	+1m/-1m			15-MAR-2018 3512:30 2441	<b>15-MAR-2022</b>	15-APR-2022
57-10-00-204 (s)	DETAILED INSPECTION OF THE EXTERNAL CENTER WING - LWS48 TO RWS48						PKG		
57.185	PKG 96 REF: AMM 57 10 00 220 865	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-10-00-208	DETAILED INSPECTION OF THE FORWARD FACE OF THE FRONT SPAR OF THE WING - WS50 TO WS353								
57.190	REF: AMM 57 10 00 220 808	MOS HRS/MSC AFL	48	+1m/-1m			21-MAR-2018 3512:30 2441	<b>21-MAR-2022</b>	21-APR-2022
57-10-00-209	DETAILED INSPECTION OF THE INTERNAL WING (FRONT SPAR, REAR SPAR, WING PLANKS, STRUCTURE AND THE MLG MOUNTING FITTINGS) - WS45.00 TO CANTED WS314.50								
57.195	REF: AMM 57 10 00 220 867	MOS HRS/MSC AFL	48	+1m/-1m			15-MAR-2018 3512:30 2441	<b>15-MAR-2022</b>	15-APR-2022
57-10-00-211 (s)	DETAILED INSPECTION OF AFT FACE OF REAR SPAR OF WING - WS48 TO WS353						PKG		
57.200	PKG 48 REF: AMM 57 10 00 220 811	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-10-00-213	DETAILED INSPECTION OF INTERNAL SKIN AND WING STRUCTURE-CANTED WS314.5/WS353								
57.205	REF: AMM 57 10 00 220 813	MOS HRS/MSC AFL	48	+1m/-1m			07-MAR-2018 3512:30 2441	<b>07-MAR-2022</b>	07-APR-2022

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-217 (s)	DETAILED INSPECTION OF THE INTERNAL WING (AUXILIARY SPAR, PLANKS, SKINS, STRUCTURE AND THE MLG TRUNNION FITTING) - WS48.00 TO WS139.90						PKG		
57.210	PKG 48 <b>REF:</b> AMM 57 10 00 220 868	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-10-00-224 (s)	DETAILED INSPECTION OF WING-TO-FUSELAGE ATTACHMENT FITTINGS AND BOLTS-FS 424.00, FS 473.15, FS 513.00						PKG		
57.215	PKG 96 <b>REF:</b> AMM 57 10 00 220 869	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-10-00-227 (s)	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS OF THE FLAP HINGE BOX OF THE INBOARD FLAP - WS76.5 AND WS127.25						PKG		
57.220	PKG 96 <b>REF:</b> AMM 57 10 00 220 827	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-10-00-228 (s)	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS OF THE FLAP HINGE BOX OF THE OUTBOARD FLAP - WS178, WS220 AND WS264						PKG		
57.225	PKG 96 <b>REF:</b> AMM 57 10 00 220 828	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-10-00-229 (s)	DETAILED INSPECTION OF THE AILERON (EXTERNAL SURFACES, WING-TO-AILERON HINGE FITTINGS, HINGE BOLTS AND ANTI-FLOAT TORSION BARS)						PKG		
57.230	PKG 96 <b>REF:</b> AMM 57 60 01 220 808	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-10-00-230 (s)	DETAILED INSPECTION OF HINGE FITTINGS FOR GROUND SPOILER						PKG		
57.235	PKG 96 <b>REF:</b> AMM 57 10 00 220 830	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-10-00-231 (s)	DETAILED INSPECTION OF HINGE FITTINGS FOR FLIGHT SPOILER						PKG		
57.240	PKG 96 REF: AMM 57 10 00 220 831	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
+ 57-24-00-101	DISCARD LH MLG SIDE BRACE FITTING SHAFT (PART NO. 601R10237-1, 601R10237-3 AND 601R10247-3)								
	601R10237-3 HD0761 REF: AMM 57 24 00 960 801	MOS HRS/MSC AFL					16-JUN-2014 2304:15 1731		31731
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>			30000						
+ 57-24-00-101	DISCARD RH MLG SIDE BRACE FITTING SHAFT (PART NO. 601R10237-1, 601R10237-3 AND 601R10247-3)								
	601R10237-3 HD0753 REF: AMM 57 24 00 960 801	MOS HRS/MSC AFL					16-JUN-2014 2304:15 1731		31731
<b>LIFE LIMIT -CIS OPERATIONS ONLY</b>			30000						
57-30-00-101	DETAILED INSPECTION EXTERNAL SURFACES OF THE WING TIP								
57.245	REF: AMM 57 30 00 220 802	MOS HRS/MSC AFL					07-MAR-2005 0 0		4800
<b>AIRWORTHINESS</b>			4800						
57-30-00-201 (s)	DETAILED INSPECTION OF SKIN/SPAR/ATTACH FITTINGS AND INTERNAL STRUCTURE OF WINGLET						PKG		
57.250	PKG 96 REF: AMM 57 30 00 220 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-50-00-101	SPECIAL DETAILED INSPECTION OF OUTBOARD FLAP FRONT SPAR								
57.255	REF: NDT ET-57-50-011	MOS HRS/MSC AFL					07-MAR-2005 0 0		7800
<b>AIRWORTHINESS</b>			7800						

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-00-102	SPECIAL DETAILED INSPECTION OF VANE TANGS (END SUPPORT) OUTBOARD FLAP								
57.260		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-010</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-103	SPECIAL DETAILED INSPECTION OF FORWARD LUGS OF THE OUTBOARD FLAP								
57.265		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-013</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-104	SPECIAL DETAILED INSPECTION OF FORWARD UPPER LUGS OF OUTBOARD FLAP ARM - WS220								
57.270		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-005</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-105	SPECIAL DETAILED INSPECTION OF VANE MID-SUPPORT FITTINGS OF OUTBOARD FLAP								
57.275		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-012</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-106	DETAILED INSPECTION OF VANE SUPPORT FITTING OF THE OUTBOARD FLAP								
57.280		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: AMM 57 50 01 220 812</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-107	SPECIAL DETAILED INSPECTION OF FORWARD LUGS OF INBOARD FLAP								
57.285		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-003</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-108	SPECIAL DETAILED INSPECTION OF INBOARD FLAP HINGE BOXES								
57.290		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-001</b>	HRS/MSC					0		
		AFL	5300				0		<b>5300</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-00-109	SPECIAL DETAILED INSPECTION OF THE INBOARD FLAP FRONT SPAR								
57.295 <b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-57-50-018	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800
57-50-00-110	SPECIAL DETAILED INSPECTION OF WING/RIB BACKUP FITTING OF THE INBOARD FLAPS-WS127.25								
57.300 <b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-57-20-037	MOS HRS/MSC AFL	7240				07-MAR-2005 0 0		7240
57-50-00-111	DETAILED INSPECTION OF INBOARD FLAP VANE SUPPORT ATTACHMENT BRACKETS								
57.305 <b>AIRWORTHINESS</b>	<b>REF:</b> AMM 57 50 01 220 814	MOS HRS/MSC AFL	7200				07-MAR-2005 0 0		7200
57-50-00-112	SPECIAL DETAILED INSPECTION OF CARRIAGES OF INBOARD FLAP VANE								
57.310 <b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-57-50-004	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800
57-50-00-113	SPECIAL DETAILED INSPECTION OF INBOARD FLAP ARMS								
57.315 <b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-57-50-002	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800
57-50-00-114	DETAILED INSPECTION OF INBOARD FLAP FASTENERS HINGE-BOX WING FORWARD-FITTING								
57.320 <b>AIRWORTHINESS</b>	<b>REF:</b>	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800
57-50-00-116	SPECIAL DETAILED INSPECTION OF INTERMEDIATE SUPPORT OF OUTBOARD FLAP VANE								
57.325 <b>AIRWORTHINESS</b>	<b>REF:</b> NDT ET-57-50-015	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0		7800

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-00-117	SPECIAL DETAILED INSPECTION OF SUPPORT STRUTS OF OUTBOARD FLAP VANE								
57.330		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-016</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-118	SPECIAL DETAILED INSPECTION OF END RAMPS OF OUTBOARD FLAP VANE								
57.335		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-014</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-119	SPECIAL DETAILED INSPECTION OF THE FLAP HINGE BOLTS								
57.340		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT PT-57-50-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-121	SPECIAL DETAILED INSPECTION OF THE FORWARD LUGS OF THE INBOARD FLAP HINGE BOX								
		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-57-50-008</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
57-50-00-201 (s)	DETAILED INSPECTION OF INBOARD FLAP & INBOARD FLAP VANE						PKG		
57.345	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
	<b>REF: AMM 57 50 01 220 816</b>	HRS/MSC					3512:30		
		AFL					2441		
57-50-00-202 (s)	DETAILED INSPECTION OF THE INBOARD FLAP						PKG		
57.350	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 57 50 01 220 818</b>	HRS/MSC					2304:15		
		AFL					1731		
57-50-00-204	DETAILED INSPECTION VANE ACTUATOR SLIDING BEAMS AND CARRIAGES OF INBOARD FLAP								
57.355		MOS					07-MAR-2005		
	<b>REF: AMM 57 50 01 220 804</b>	HRS/MSC					0		
		AFL	7000	+40/-40			0		<b>7000 7040</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-00-206 (s) 57.360	DETAILED INSPECTION OF OUTBOARD FLAP AND OUTBOARD FLAP VANE PKG 48 REF: AMM 57 50 01 220 817	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-50-00-207 (s) 57.365	DETAILED INSPECTION OF THE OUTBOARD FLAP PKG 96 REF: AMM 57 50 01 220 819	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-50-00-210 57.370	DETAILED INSPECTION OF FLAP HINGE BOXES OF INBOARD FLAP REF: AMM 57 50 01 220 810	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022
57-50-00-211 57.375	DETAILED INSPECTION OF FLAP HINGE BOXES OF OUTBOARD FLAP REF: AMM 57 50 01 220 811	MOS HRS/MSC AFL	48	+1m/-1m			06-MAR-2018 3512:30 2441	<b>06-MAR-2022</b>	06-APR-2022
57-50-00-212 57.380	DETAILED INSPECTION OF ATTACH BOLTS FOR FLAP HINGE BOXES/ARMS OF INBOARD FLAP REF: AMM 57 52 01 220 801	MOS HRS/MSC AFL	7800	+40/-40			07-MAR-2005 0 0	<b>7800</b>	7840
57-50-00-213 57.385	DETAILED INSPECTION OF ATTACH BOLTS FOR FLAP HINGE BOXES AND THE FLAP HINGE ARMS OF THE OUTBOARD FLAP REF: AMM 57 52 01 220 802	MOS HRS/MSC AFL	7800	+40/-40			07-MAR-2005 0 0	<b>7800</b>	7840
57-50-00-214 57.390	DETAILED INSPECTION OF VANE SUPPORT STRAPS OF OUTBOARD FLAP REF: AMM 57 50 01 220 820	MOS HRS/MSC AFL	7800	+40/-40			07-MAR-2005 0 0	<b>7800</b>	7840



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-50-00-215	DETAILED INSPECTION OF THE FRONT SPAR OF OUTBOARD FLAP								
57.395		MOS					07-MAR-2005		
		HRS/MSC					0		
	REF: AMM 57 50 01 220 821	AFL	7800	+40/-40			0	7800	7840
57-52-01-101	SPECIAL DETAILED INSPECTION OF OUTBOARD FLAP WING/HINGE-FORWARD BOX FITTING								
57.400		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	REF: NDT ET-57-50-006	HRS/MSC	7800				0	7800	
		AFL					0		
57-52-01-102	SPECIAL DETAILED INSPECTION OF HINGE-BOX FORWARD LUGS OF OUTBOARD FLAP								
57.405		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	REF: NDT ET-57-50-008	HRS/MSC	7800				0	7800	
		AFL					0		
57-52-01-103	SPECIAL DETAILED INSPECTION OF HINGE-BOX SUPPORTS OF OUTBOARD FLAP								
57.410		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	REF: NDT ET-57-50-007	HRS/MSC	7800				0	7800	
		AFL					0		
57-60-00-101	DETAILED INSPECTION OF THE AILERON								
57.415		MOS					14-NOV-2014		
		HRS/MSC					2408:05		
	REF: AMM 57 60 01 220 801	AFL	1867				1805	3672	
57-60-00-102	DETAILED INSPECTION OF AILERON UPPER AND LOWER SKINS AND FRONT SPAR								
57.420		MOS					07-MAR-2005		
	REF: AMM 57 60 01 220 802	HRS/MSC	7800				0	7800	
		AFL					0		
57-60-00-103	DETAILED INSPECTION OF THE HINGE BOLTS OF THE AILERON								
57.425		MOS					07-MAR-2005		
	REF: AMM 57 60 01 220 807	HRS/MSC	4800				0	4800	
		AFL					0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-00-101	SPECIAL DETAILED INSPECTION OF THE FLIGHT SPOILER								
57.430	REF: NDT ET-57-70-001	MOS HRS/MSC AFL	1200				05-OCT-2017 3307:10 2325	3525	
57-70-00-102	DETAILED INSPECTION OF UPPER AND LOWER SKINS OF FLIGHT SPOILER								
57.435	REF: AMM 57 70 01 220 803	MOS HRS/MSC AFL	7800				07-MAR-2005 0 0	7800	
57-70-00-103	DETAILED INSPECTION OF THE HINGE BOLTS OF FLIGHT SPOILER								
57.440	REF: AMM 57 70 01 220 804	MOS HRS/MSC AFL	4800				07-MAR-2005 0 0	4800	
57-70-00-201 (s)	DETAILED INSPECTION EXTERNAL SURFACES & FORWARD FACE OF FRONT SPAR OF GROUND SPOILER						PKG		
57.445	PKG 48 REF: AMM 57 70 01 220 801	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-70-00-202 (s)	SPECIAL DETAILED INSPECTION OF BONDED SKINS OF GROUND SPOILER						PKG		
57.450	PKG 48 REF: AMM 57 70 01 280 801	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-70-00-203 (s)	DETAILED INSPECTION EXTERNAL SURFACES & FORWARD FACE OF FRONT SPAR OF FLIGHT SPOILER						PKG		
57.455	PKG 48 REF: AMM 57 70 01 220 802	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-70-00-204 (s)	SPECIAL DETAILED INSPECTION OF THE BONDED SKINS OF THE FLIGHT SPOILER						PKG		
57.460	PKG 48 REF: AMM 57 70 01 280 802	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-70-00-205 (s) 57.465	DETAILED INSPECTION OF HINGE BOLTS OF GROUND SPOILER PKG 96 <b>REF:</b> AMM 57 70 01 220 805	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-70-00-206 (s) 57.470	DETAILED INSPECTION OF HINGE BOLTS OF THE FLIGHT SPOILER PKG 96 <b>REF:</b> AMM 57 70 01 220 804	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-201 (s) 57.475	GENERAL VISUAL INSPECTION WING CENTER SECTION - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-202 (s) 57.480	GENERAL VISUAL INSPECTION WING CENTER SECTION - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-203 (s) 57.485	GENERAL VISUAL INSPECTION FRONT SPAR OF THE WING CENTER SECTION - EXTERNAL PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-204 (s) 57.490	GENERAL VISUAL INSPECTION WING CENTER SECTION - INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-205 (s) 57.495	GENERAL VISUAL INSPECTION WING CENTER SECTION - INTERNAL RH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-ZL-00-206 (s) 57.500	GENERAL VISUAL INSPECTION INBOARD LEADING EDGE OF THE WING - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-207 (s) 57.505	GENERAL VISUAL INSPECTION INBOARD LEADING EDGE OF THE WING - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-208 (s) 57.510	GENERAL VISUAL INSPECTION INBOARD LEADING EDGE OF THE WING - INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-209 (s) 57.515	GENERAL VISUAL INSPECTION INBOARD LEADING EDGE OF THE WING - INTERNAL RH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-210 (s) 57.520	GENERAL VISUAL INSPECTION OUTBOARD LEADING EDGE OF THE WING - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-211 (s) 57.525	GENERAL VISUAL INSPECTION OUTBOARD LEADING EDGE OF THE WING - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-212 (s) 57.530	GENERAL VISUAL INSPECTION OUTBOARD LEADING EDGE OF THE WING - INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-ZL-00-213 (s) 57.535	GENERAL VISUAL INSPECTION OUTBOARD LEADING EDGE OF THE WING - INTERNAL RH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-214 (s) 57.540	GENERAL VISUAL INSPECTION WING FROM WS47 TO WS148 - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-215 (s) 57.545	GENERAL VISUAL INSPECTION WING FROM WS47 TO WS148 - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-216 (s) 57.550	GENERAL VISUAL INSPECTION WING FROM WS45 TO WS148 - INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-217 (s) 57.555	GENERAL VISUAL INSPECTION WING FROM WS45 TO WS148 - INTERNAL RH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-218 (s) 57.560	GENERAL VISUAL INSPECTION WING FROM WS148 TO WS353 - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-219 (s) 57.565	GENERAL VISUAL INSPECTION WING FROM WS148 TO WS353 - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-ZL-00-220 (s) 57.570	GENERAL VISUAL INSPECTION WING FROM WS148 TO WS353 - INTERNAL LH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-221 (s) 57.575	GENERAL VISUAL INSPECTION WING FROM WS148 TO WS353 - INTERNAL RH PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			PKG 16-JUN-2014 2304:15 1731		
57-ZL-00-222 (s) 57.580	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-223 (s) 57.585	GENERAL VISUAL INSPECTION OF THE WINGLET - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-226 (s) 57.590	GENERAL VISUAL INSPECTION INBOARD TRAILING EDGE OF THE WING - EXTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-227 (s) 57.595	GENERAL VISUAL INSPECTION INBOARD TRAILING EDGE OF THE WING - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
57-ZL-00-228 (s) 57.600	GENERAL VISUAL INSPECTION WING TRAILING EDGE - INTERNAL LH PKG 36 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	36	+1m/-1m			PKG 26-MAR-2019 3702:35 2541		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
57-ZL-00-229 (s)	GENERAL VISUAL INSPECTION WING TRAILING EDGE - INTERNAL RH						PKG		
57.605	PKG 36 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	36	+1m/-1m			26-MAR-2019 3702:35 2541		
57-ZL-00-230 (s)	GENERAL VISUAL INSPECTION OUTBOARD TRAILING EDGE OF THE WING - EXTERNAL LH						PKG		
57.610	PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-ZL-00-231 (s)	GENERAL VISUAL INSPECTION OUTBOARD TRAILING EDGE OF THE WING - EXTERNAL RH						PKG		
57.615	PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
57-ZL-00-234 (s)	GENERAL VISUAL INSPECTION AILERON SHROUD - INTERNAL LH						PKG		
57.620	PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
57-ZL-00-235 (s)	GENERAL VISUAL INSPECTION AILERON SHROUD - INTERNAL RH						PKG		
57.625	PKG 96 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
572400-001	LH ASSY MLG SIDE BRACE FITTING								
57.630	601R10241-5 5924-45-9 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
572400-002	RH ASSY MLG SIDE BRACE FITTING								
57.635	601R10241-6 5924-45-27 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
572401-001	LH MLG SIDE BRACE FITTING SHAFT								
57.640	601R10237-3 HD0761 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:17 N:0 N:0			16-JUN-2014 2304:15 1731		
572401-002	RH MLG SIDE BRACE FITTING SHAFT								
57.645	601R10237-3 HD0753 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:17 N:0 N:0			16-JUN-2014 2304:15 1731		
573617-001	NO.1 ASSEMBLY FLAP VANE ACTUATOR BEAM								
57.650	600-14250-29 NSN REF: AMM 27 54 11 961 801	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	9600	
<b>LIFE LIMIT</b>									
573617-002	NO.2 ASSEMBLY FLAP VANE ACTUATOR BEAM								
57.655	600-14250-29 NSN REF: AMM 27 54 11 961 801	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	9600	
<b>LIFE LIMIT</b>									
573617-003	NO.3 ASSEMBLY FLAP VANE ACTUATOR BEAM								
57.660	600-14250-29 NSN REF: AMM 27 54 11 961 801	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	9600	
<b>LIFE LIMIT</b>									
573617-004	NO.4 ASSEMBLY FLAP VANE ACTUATOR BEAM								
57.665	600-14250-29 NSN REF: AMM 27 54 11 961 801	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	9600	
<b>LIFE LIMIT</b>									
573617-005	NO.5 ASSEMBLY FLAP VANE ACTUATOR BEAM								
57.670	600-14250-29 NSN REF: AMM 27 54 11 961 801	MOS HRS/MSC AFL	9600	N:0 N:0 N:0			07-MAR-2005 0 0	9600	
<b>LIFE LIMIT</b>									



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
573617-006	NO.6 ASSEMBLY FLAP VANE ACTUATOR BEAM								
	600-14250-29	MOS		N:0			07-MAR-2005		
57.675	NSN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: AMM 27 54 11 961 801</b>	AFL	9600	N:0			0		<b>9600</b>
577101-001	GROUND LH SPOILER								
	600-10502-51	MOS		N:0			07-MAR-2005		
57.690	7744232	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
577101-002	GROUND RH SPOILER								
	600-10502-52	MOS		N:0			07-MAR-2005		
57.695	5807587	HRS/MSC	O/C	N:0			0		
	<b>REF: See Workcard</b>	AFL		N:0			0		
577301-001	FLIGHT LH SPOILER								
	600-10602-77	MOS		N:0			07-MAR-2005		
57.700	5807596	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
577301-002	FLIGHT RH SPOILER								
	600-10602-78	MOS		N:0			07-MAR-2005		
57.705	5807604	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	AFL		N:0			0		
<b>CHAPTER 71 POWER PLANT</b>									
71-10-00-101	SPECIAL DETAILED INSPECTION OF THE ENGINE NACELLE JOINT								
		MOS					07-MAR-2005		
71.005		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-71-10-002</b>	AFL	7800				0		<b>7800</b>
71-10-00-102	SPECIAL DETAILED INSPECTION OF THE SUPPORT FITTING OF THE NOSE COWL ACTUATOR								
		MOS					07-MAR-2005		
71.010		HRS/MSC					0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-71-10-001</b>	AFL	4400				0		<b>4400</b>

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-10-00-103	SPECIAL DETAILED INSPECTION OF TRACK SUPPORT ASSEMBLY & FLANGE OF SERVICE PYLON								
71.015		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-78-30-004</b>	HRS/MSC					0		
		AFL	7800				0	<b>7800</b>	
71-12-00-202 (s)	DETAILED INSPECTION OF THE CORE BLOW-OUT DOORS						PKG		
71.020	PKG 2400	MOS					08-MAY-2020		
	<b>REF: AMM 71 12 01 220 802</b>	HRS/MSC	2400	+40/-40			4328:45		
		AFL					2835		
71-12-00-203 (s)	GENERAL VISUAL INSPECTION DRAINS MAST AND CHANNELS						PKG		
71.025	PKG 600	MOS					08-MAY-2020		
	<b>REF: AMM 71 12 01 210 804</b>	HRS/MSC	600	+40/-40			4328:45		
		AFL					2835		
71-12-00-204 (s)	OPERATIONAL TEST DRAINS MAST & CHANNELS						PKG		
71.030	PKG 600	MOS					08-MAY-2020		
	<b>REF: AMM 71 12 01 710 801</b>	HRS/MSC	600	+40/-40			4328:45		
		AFL					2835		
71-12-00-205 (s)	DETAILED INSPECTION OF HINGE FITTINGS OF CORE COWL DOOR						PKG		
71.035	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 71 12 01 220 801</b>	HRS/MSC					2304:15		
		AFL					1731		
71-13-00-201 (s)	DETAILED INSPECTION OF THRUST REVERSER SLIDER BLOCKS						PKG		
71.040	PKG 2400	MOS					08-MAY-2020		
	<b>REF: AMM 78 34 10 220 801</b>	HRS/MSC	2400	+40/-40			4328:45		
		AFL					2835		
71-13-00-202 (s)	DETAILED INSPECTION OF SERVICE PYLON CASTING & SUPPORT RAILS						PKG		
71.045	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 71 10 00 220 801</b>	HRS/MSC					2304:15		
		AFL					1731		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-20-00-101	SPECIAL DETAILED INSPECTION OF YOKE OF FORWARD ENGINE MOUNT								
71.050		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-71-20-002</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
71-20-00-102	SPECIAL DETAILED INSPECTION OF THRUST FITTING OF AFT ENGINE MOUNT								
71.055		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-71-20-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
71-20-00-103	SPECIAL DETAILED INSPECTION OF THE LINK AND BOLTS OF THE FORWARD ENGINE MOUNT								
71.060		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: See Workcard</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
71-20-00-202 (s)	DETAILED INSPECTION OF FOWARD ENGINE MOUNT YOKE & LINK ASSEMBLY						PKG		
71.065	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 71 21 01 220 803</b>	HRS/MSC					2304:15		
		AFL					1731		
71-20-00-203 (s)	DETAILED INSPECTION OF THE AFT ENGINE MOUNT ASSEMBLY						PKG		
71.070	PKG 96	MOS	96	+1m/-1m			16-JUN-2014		
	<b>REF: AMM 71 22 01 220 801</b>	HRS/MSC					2304:15		
		AFL					1731		
71-21-01-220-801	DETAILED INSPECTION NO. 1 FORWARD ENGINE MOUNTS								
<b>MRB</b>	<b>REF: AMM 71 21 01 220 801</b>	MOS					07-MAR-2005		
		HRS/MSC	A/R				0		
		AFL					0		
71-21-01-220-801	DETAILED INSPECTION NO.2 FORWARD ENGINE MOUNTS								
<b>MRB</b>	<b>REF: AMM 71 21 01 220 801</b>	MOS					07-MAR-2005		
		HRS/MSC	A/R				0		
		AFL					0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-22-01-220-802	DETAILED INSPECTION NO. 1 AFT ENGINE MOUNTS	MOS					07-MAR-2005		
<b>MRB</b>	<b>REF: AMM 71 22 01 220 801</b>	HRS/MSC AFL	A/R				0 0		
71-22-01-220-802	DETAILED INSPECTION NO. 2 AFT ENGINE MOUNTS	MOS					07-MAR-2005		
<b>MRB</b>	<b>REF: AMM 71 22 01 220 801</b>	HRS/MSC AFL	A/R				0 0		
71-30-00-201 (s)	GENERAL VISUAL INSPECTION OF THE ENGINE FIRE SEALS						PKG		
71.075	PKG 3200	MOS					03-APR-2017		
	<b>REF: AMM 71 30 00 210 801</b>	HRS/MSC AFL	3200	+40/-40			3041:45 2185		
71-61-00-202 (s)	LUBRICATION OF THE BALLSCREW ACTUATORS SUPPORT BUSHINGS						PKG		
71.080	PKG 800	MOS					08-MAY-2020		
	<b>REF: AMM 12 20 04 640 827</b>	HRS/MSC AFL	800	+40/-40			4328:45 2835		
71-61-00-203 (s)	DETAILED INSPECTION OF THE BALLSCREW ACTUATOR SUPPORT FITTINGS						PKG		
71.085	PKG 3200	MOS					03-APR-2017		
	<b>REF: AMM 71 61 01 220 801</b>	HRS/MSC AFL	3200	+40/-40			3041:45 2185		
71-61-00-205	DETAILED INSPECTION OF ATTACHMENT RING OF THE NOSE INLET COWL						07-MAR-2005		
71.090		MOS					0		
	<b>REF: AMM 71 61 01 220 802</b>	HRS/MSC AFL	7800	+40/-40			0	<b>7800</b>	7840
71-ZL-00-201 (s)	GENERAL VISUAL INSPECTION OF THE NACELLE - EXTERNAL LH						PKG		
71.095	PKG 48	MOS	48	+1m/-1m			23-MAR-2018		
	<b>REF: See Workcard</b>	HRS/MSC AFL					3512:30 2441		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71-ZL-00-202 (s) 71.100	GENERAL VISUAL INSPECTION OF THE NACELLE - EXTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
71-ZL-00-203 (s) 71.105	GENERAL VISUAL INSPECTION NOSE INLET ACCESS COWL - INSIDE LH PKG 36 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	36	+1m/-1m			PKG 26-MAR-2019 3702:35 2541		
71-ZL-00-204 (s) 71.110	GENERAL VISUAL INSPECTION NOSE INLET ACCESS COWL - INSIDE RH PKG 36 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	36	+1m/-1m			PKG 26-MAR-2019 3702:35 2541		
71-ZL-00-205 (s) 71.115	GENERAL VISUAL INSPECTION TRANSLATING COWL - INTERNAL LH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
71-ZL-00-206 (s) 71.120	GENERAL VISUAL INSPECTION TRANSLATING COWL - INTERNAL RH PKG 48 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			PKG 23-MAR-2018 3512:30 2441		
71-ZL-00-207 (s) 71.125	GENERAL VISUAL INSPECTION OF THE CORE COWL - INTERNAL LH PKG 36 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	36	+1m/-1m			PKG 26-MAR-2019 3702:35 2541		
71-ZL-00-208 (s) 71.130	GENERAL VISUAL INSPECTION OF THE CORE COWL - INTERNAL RH PKG 36 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	36	+1m/-1m			PKG 26-MAR-2019 3702:35 2541		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711101-001	LOWER TRANSLATING LH DOOR								
71.135	228-50208-237 SBRJ1346 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711101-002	LOWER TRANSLATING RH DOOR								
71.135	228-50208-238 SBRJ1342 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711101-003	UPPER TRANSLATING LH DOOR								
71.140	228-50207-259 SBRJ1327 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711101-004	UPPER TRANSLATING RH DOOR								
71.140	228-50207-260 SBRJ1333 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711201-001	LH LOWER CORE COWL DOOR ASSY								
71.145	228-50162-417 SB/RJ/1337 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711201-002	RH LOWER CORE COWL DOOR ASSY								
71.145	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711201-003	LH UPPER CORE COWL DOOR ASSY								
71.150	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711201-004	RH UPPER CORE COWL DOOR ASSY								
71.150	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711301-001	CORE BIFURCATR FIXED LH COWL								
71.155	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711301-002	CORE BIFURCATR FIXED RH COWL								
71.155	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711301-003	CORE PANEL RH COWL								
71.160	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711301-004	CORE PANEL RH COWL								
71.160	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711302-001	SIDE CORE LH PANEL ASSY								
71.165	228-50082-809 SBRJ11293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711302-002	SIDE CORE RH PANEL ASSY								
71.165	228-50082-810 SB/RJ/11293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
711401-003	UPPER ACCESS PANEL LH COWL								
71.170	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711401-004	UPPER ACCESS PANEL RH COWL								
71.170	228-50080-802 SBRJ11295 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711401-005	LOWER ACCESS LH COWL								
71.175	228-50081-141 SBRJ11293 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
711401-006	LOWER ACCESS RH COWL								
71.175	228-50081-142 SBRJ11291 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712101-001	LH LINK ASSY								
	601-37016-5 2071 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712101-002	RH LINK ASSY								
	601-37016-5 2063 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712102-001	LH UPPER BOLT ASSEMBLY								
	601-37040-17PP 1424 REF: GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
712102-002	RH UPPER BOLT ASSEMBLY 601-37040-17PP 1499 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712102-003	LH LOWER BOLT ASSEMBLY 601-37040-17PP 1502 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712102-004	RH LOWER BOLT ASSEMBLY 601-37040-17PP 1504 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712201-001 71.180	NO. 1 THRUST SHAFT 601-37020-7 CLA1071 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
712201-002 71.180	NO. 2 THRUST SHAFT 601-37020-7 CLA1074 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
716101-001	LH INLET - NEUTRAL COWL 228-50020-801 SB/RJ/2869 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
716101-002	RH INLET - NEUTRAL COWL 228-50020-801 SB/RJ/2872 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
71EN1	NO. 1 ENGINE 6089T11G01 950335 REF: See Workcard	MOS HRS/MSC AFL	E/C						
71.EN1									
71EN2	NO. 2 ENGINE 6089T11G01 950336 REF: See Workcard	MOS HRS/MSC AFL	E/C						
71.EN2									
<b>CHAPTER 72 ENGINE</b>									
ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01									
72-20-00-201 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION OF FAN BLADES PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 08-MAY-2020 4328:45 2850		
72.005									
72-20-00-202 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION FAN SPINNER PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			PKG 08-MAY-2020 4328:45 2850		
72.010									
72-20-00-207 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR PKG 0 REF: See Workcard	MOS HRS/MSC ENC	100				PKG 14-DEC-2020 4616 2990		
72.015									
72-20-00-208 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN CASE FORWARD MOUNTS PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			PKG 03-APR-2017 3041:45 2204		
72.020									

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-20-00-210 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION FAN SHROUD CORE MATERIAL						PKG		
72.025	PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
72-20-00-211 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION EXTERIOR OF ENGINE FAN CASE & BLADE-CONTAINMENT CASE						PKG		
72.030	PKG 1200 REF: See Workcard	MOS HRS/MSC ENC	1200	+40/-40			08-MAY-2020 4328:45 2850		
72-30-00-202 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMPRESSOR BLADES						PKG		
72.035	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-30-00-204 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE VARIABLE AND STATIONARY VANES						PKG		
72.040	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-30-00-205 (s)	NO. 1 ENGINE - LUBRICATION VARIABLE GEOMETRY LINKAGE ROD END BEARINGS						PKG		
72.045	PKG 800 REF: See Workcard	MOS HRS/MSC ENC	800	+40/-40			08-MAY-2020 4328:45 2850		
72-40-00-201 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMBUSTOR LINER						PKG		
72.050	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-40-00-202 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE STAGE 1 NOZZLE						PKG		
72.055	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-40-00-205 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION THERMAL BLANKET PKG 600	MOS					PKG		
72.065	REF: See Workcard	HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
72-40-00-207 (s)	NO. 1 ENGINE - GENERAL VISUAL INSPECTION REAR MAIN MOUNT PKG 3200	MOS					PKG		
72.070	REF: See Workcard	HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-50-00-201 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE HIGH-PRESSURE-TURBINE STAGE 1 AND 2 ROTOR BLADES PKG 3200	MOS					PKG		
72.075	REF: See Workcard	HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-50-00-208 (s)	NO. 1 ENGINE - VISUAL CHECK EXHAUST CENTERBODY PKG 2400	MOS					PKG		
72.080	REF: See Workcard	HRS/MSC ENC	2400	+40/-40			08-MAY-2020 4328:45 2850		
720000-001	NO. 1 ENGINE - FAN BLADE 6018T30P06	MOS							
72.155	KGRA6496 REF: GENERIC NO REF	HRS/MSC ENC	O/C		R:0 N:17467:54 R:0 N:16839 R:0		01-OCT-2018 3699 2558		
720000-002	NO. 1 ENGINE - FAN BLADE 6018T30P06	MOS							
72.155	KGAJ3237 REF: GENERIC NO REF	HRS/MSC ENC	O/C		R:0 N:17467:54 R:0 N:16839 R:0		01-OCT-2018 3699 2558		
720000-003	NO. 1 ENGINE - FAN BLADE 6018T30P06	MOS							
72.155	KGAJ2628 REF: GENERIC NO REF	HRS/MSC ENC	O/C		R:0 N:17467:54 R:0 N:16839 R:0		01-OCT-2018 3699 2558		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-004	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ0943 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-005	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2597 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-006	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAR9952 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:18045:54 R:0 N:17299 R:0			01-OCT-2018 3699 2558		
720000-007	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2408 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:24998:55 R:0 N:20621 R:0			01-OCT-2018 3699 2558		
720000-008	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ3127 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	O:0 N:17467:54 O:0 N:16839 O:0			01-OCT-2018 3699 2558		
720000-009	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ3104 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-010	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ3242 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-011	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ3182 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-012	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ1990 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-013	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2785 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-014	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2943 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-015	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAR9062 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-016	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ3238 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-017	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ1998 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-018	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2859 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-019	NO. 1 ENGINE - FAN BLADE 6018T30P06 BA619978-F <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-020	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2243 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-021	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ4118 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:24998:55 R:0 N:20621 R:0			01-OCT-2018 3699 2558		
720000-022	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2977 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-023	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ1925 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-024	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2233 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-025	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2966 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17895:54 R:0 N:17193 R:0			01-OCT-2018 3699 2558		
720000-026	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2848 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-027	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ3089 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:17467:54 R:0 N:16839 R:0			01-OCT-2018 3699 2558		
720000-028	NO. 1 ENGINE - FAN BLADE 6018T30P06 KGAJ2866 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	R:0 N:18045:54 R:0 N:17299 R:0			01-OCT-2018 3699 2558		
720001-001	NO. 1 ENGINE - CARBON SEAL PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722110-001	NO. 1 ENGINE - FAN FWD ASSEMBLY CASE PN SN-UNKNOWN <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722114-001	NO. 1 ENGINE - FAN AFT ASSEMBLY CASE 6052T01G10 GEVKR75D <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722140-001	NO. 1 ENGINE - ROTOR FAN								
72.105	6078T83G06 GGFV4153 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722150-001	NO. 1 ENGINE - FAN DISK								
72.110	6078T57G05 GEE1FRF9 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	N:0 N:0 N:0			07-MAR-2005 0 0	(30000) 29984	
<b>LIFE LIMIT</b>									
722210-001	NO. 1 ENGINE - FAN DRIVE SHAFT								
72.115	6036T78P02 FBKRM238 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			07-MAR-2005 0 0	(20000) 19984	
<b>LIFE LIMIT</b>									
722450-001	NO. 1 ENGINE - NO.2 BALL BEARING								
72.120	5042T11P01 TMKAB9WW REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722490-001	NO. 1 ENGINE - BALL NO.1 BEARING								
72.125	6078T35P03 FCAH4577 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722520-001	NO. 1 ENGINE - FORWARD FAN SHAFT								
72.130	6078T51P02 GATHF1WJ REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			07-MAR-2005 0 0	(20000) 19984	
<b>LIFE LIMIT</b>									
723110-001	NO. 1 ENGINE - FRONT COMPRESSOR FRAME								
72.135	6030T79G16 ABIK3682 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723120-001	NO. 1 ENGINE - FAN SPEED SENSOR								
72.140	4021T56P04 EGNEP145 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
723210-001	NO. 1 ENGINE - CONTAINMENT CASE								
72.145	4150T32G01 3ABED2E2 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
723310-001	NO. 1 ENGINE - STAGE 9 COMPRESSOR ROTOR DISK								
72.150 <b>LIFE LIMIT</b>	6087T01P03 NCE6291Y REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			07-MAR-2005 0 0	(15000) 14984	
723312-001	NO. 1 ENGINE - CASE ASSEMBLY COMPRESSOR								
	5088T55G02 GATHF1P3 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
723314-001	NO. 1 ENGINE - COMPRESSOR DISCHARGE ROTATING SEAL								
72.160 <b>LIFE LIMIT</b>	4019T38P01 TEJ81792 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	N:0 N:0 N:0			07-MAR-2005 0 0	(30000) 29984	
723316-001	NO. 1 ENGINE - BALL NO.3 BEARING								
72.165	5041T42P02 TBCTF246 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
723318-001	NO. 1 ENGINE - COMPRESSOR FORWARD SHAFT								
72.170 <b>LIFE LIMIT</b>	5037T01P04 PAMEJ947 REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	N:0 N:0 N:0			07-MAR-2005 0 0	(30000) 29984	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723322-001	NO. 1 ENGINE - STAGE 2 COMPRESSOR ROTOR DISK								
	6036T91P02	MOS		N:0			07-MAR-2005		
72.175	GATHER4K	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
723328-001	NO. 1 ENGINE - STAGE 3 - 8 COMPRESSOR ROTOR SPOOL								
	6078T56P05	MOS		N:0			07-MAR-2005		
72.180	GATHELA7	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
723330-001	NO. 1 ENGINE - STAGE 10 - 14 COMPRESSOR ROTOR SPOOL								
	5087T46P02	MOS		N:0			07-MAR-2005		
72.185	GWN08R3K	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
723334-001	NO. 1 ENGINE - COMPRESSOR ROTOR REAR SHAFT								
	6087T03P03	MOS		N:0			07-MAR-2005		
72.190	GEE1FREK	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
723336-001	NO. 1 ENGINE - ROLLER NO.4 BEARING								
	5023T47P02	MOS		N:0			07-MAR-2005		
72.195	TBCTL246	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
723340-001	NO. 1 ENGINE - ROTOR COMPRESSOR								
	5123T14G08	MOS		N:0			07-MAR-2005		
72.200	GGFD4268	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
724103-001	NO. 1 ENGINE - COMBUSTION FRAME								
	PN	MOS		N:0			07-MAR-2005		
72.205	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724124-001	NO. 1 ENGINE - ROLLER NO.5 BEARING								
72.210	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724128-001	NO. 1 ENGINE - BALANCE PISTON STATIONARY AIR SEAL								
72.470	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724219-001	NO. 1 ENGINE - COMBUSTION FRAME								
	3063T82G01 SPK943A7 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724220-001	NO. 1 ENGINE - COMBUSTION LINER								
72.225	6078T65G13 FCW12110 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724221-001	NO. 1 ENGINE - COMBUSTION INNER SHELL LINER								
72.230	6078T53G06 FCW10144 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724222-001	NO. 1 ENGINE - COMBUSTION OUTER SHELL LINER								
72.235	6078T54G08 FCW09143 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724223-001	NO. 1 ENGINE - COMBUSTION LINER DOME								
72.240	6087T17G04 FCW11135 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724512-001	NO. 1 ENGINE - HPT INNER CASING								
72.245	5099T00G05 BCM93169 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724514-001	NO. 1 ENGINE - HPT, ASSY STATOR								
72.250	5099T03G06 GGFG4294 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724517-001	NO. 1 ENGINE - HPT OUTER CASING								
72.255	6036T04G06 SPK92CUU REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724606-001	NO. 1 ENGINE - HPT STAGE NO.1 FRONT COOLING PLATE								
72.260 <b>LIFE LIMIT</b>	5079T65P06 BSLH9294 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(20000) 19984</b>
724608-001	NO. 1 ENGINE - STAGE 1 COMPRESSOR ROTOR BLISK								
72.265 <b>LIFE LIMIT</b>	5087T84P01 GLHTHCA1 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(20000) 19984</b>
724609-001	NO. 1 ENGINE - HPT ROTATING AIR SEAL								
72.270	4019T60G03 BJWF1960 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724610-001	NO. 1 ENGINE - HPT STAGE NO.1 DISK								
72.275 <b>LIFE LIMIT</b>	5079T52P09 GATHF60K REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(15000) 14984</b>

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724612-001	NO. 1 ENGINE - HPT STAGE NO.2 DISK								
	5079T73P02	MOS		N:0			07-MAR-2005		
72.280	GATHF3DH	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724614-001	NO. 1 ENGINE - HPT STAGE NO.2 FRONT COOLING PLATE								
	5079T55P04	MOS		N:0			07-MAR-2005		
72.285	BSLJ9908	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724616-001	NO. 1 ENGINE - HPT STAGE NO.2 REAR COOLING PLATE								
	5079T56P02	MOS		N:0			07-MAR-2005		
72.290	BSLG8355	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	
724620-001	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR SHAFT								
	5079T62P02	MOS		N:0			07-MAR-2005		
72.295	GEE1FRGN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	
724628-001	NO. 1 ENGINE - BALANCE PISTON ROTATING AIR SEAL								
	5079T63P02	MOS		N:0			07-MAR-2005		
72.300	BSLP5421	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724638-001	NO. 1 ENGINE - OUTER TORQUE COUPLING								
	5079T64P05	MOS		N:0			07-MAR-2005		
72.305	BSLK1414	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	
724645-001	NO. 1 ENGINE - HPT STAGE NO.1 AFT COOLING PLATE								
	5123T02P01	MOS		N:0			07-MAR-2005		
72.310	BSLN5077	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	14000	N:0			0	<b>(14000) 13984</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724649-001	NO. 1 ENGINE - RUNNER SEAL								
72.315	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724704-001	NO. 1 ENGINE - STAGE NO 1 NOZZLE								
72.320	5099T12G02 JMM1840A REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724710-001	NO. 1 ENGINE - HIGH PRESSURE TURBINE ROTOR								
72.325	5079T61G11 GGFJ4377 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725110-001	NO. 1 ENGINE - LPT TURBINE TRANSITION ASSEMBLY								
72.330	5121T29G05 GGFA4182 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725112-001	NO. 1 ENGINE - LPT TURBINE TRANSITION CASE								
72.335	5099T31G01 GEVKR577 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725114-001	NO. 1 ENGINE - TRANSITION TURBINE SEAL & LINER								
72.340	6047T28G05 GGM93496 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725125-001	NO. 1 ENGINE - LPT ASSEMBLY ROTOR								
72.345	5071T40G04 GGFM4302 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725210-001	NO. 1 ENGINE - LPT, ASSY STATOR								
72.350	5099T10G04 GGFN4183 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725220-001	NO. 1 ENGINE - LEFT ASSEMBLY THERMOCOUPLE								
72.355	6030T41P02 FDT07497 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725220-002	NO. 1 ENGINE - RIGHT ASSEMBLY THERMOCOUPLE								
72.355	6030T40P02 FDT09328 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725314-001	NO. 1 ENGINE - LPT REAR SHAFT								
72.360 <b>LIFE LIMIT</b>	6030T72P02 NCE9001Y REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(15000) 14984</b>
725320-001	NO. 1 ENGINE - LPT STAGE NO.3 DISK								
72.365 <b>LIFE LIMIT</b>	6078T91P02 GATHF0KW REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(15000) 14984</b>
725324-001	NO. 1 ENGINE - LPT STAGE NO.5 DISK								
72.370 <b>LIFE LIMIT</b>	6078T92P02 GATHF2R4 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(15000) 14984</b>
725326-001	NO. 1 ENGINE - LPT STAGE NO.6 DISK								
72.375 <b>LIFE LIMIT</b>	6078T89P03 GATHF2J2 REF: GENERIC NO REF	MOS HRS/MSC ENC	15000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(15000) 14984</b>



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725330-001	NO. 1 ENGINE - LPT STAGE NO.3 / 4 SEAL								
	5023T59P02	MOS		N:0			07-MAR-2005		
72.380	WES24477	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725332-001	NO. 1 ENGINE - LPT STAGE NO.4 / 5 SEAL								
	5023T67P01	MOS		N:0			07-MAR-2005		
72.385	WES11525	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725334-001	NO. 1 ENGINE - LPT STAGE NO.5 / 6 SEAL								
	5023T64P02	MOS		N:0			07-MAR-2005		
72.390	WES37628	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725338-001	NO. 1 ENGINE - LPT TURBINE DRIVE CONE								
	5023T40P03	MOS		N:0			07-MAR-2005		
72.395	NCE6265Y	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725340-001	NO. 1 ENGINE - LPT STAGE NO.4 DISK								
	6078T02P03	MOS		N:0			07-MAR-2005		
72.400	GATHF10F	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725412-001	NO. 1 ENGINE - TURBINE LOW PRESSURE CASING								
	6017T55G09	MOS		N:0			07-MAR-2005		
72.405	GEVKR4FP	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725414-001	NO. 1 ENGINE - ROLLER NO.6 BEARING								
	5042T14P02	MOS		N:0			07-MAR-2005		
72.410	FCAH1873	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725416-001	NO. 1 ENGINE - TURBINE HIGH PRESSURE OUTER BEARING								
72.415	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725417-001	NO. 1 ENGINE - NO.7 BEARING								
72.420	5042T15P02 FCAH4378 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
726210-001	NO. 1 ENGINE - ACCESSORY GEARBOX								
72.425	5154T98G01 SAPT2389 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
726410-001	NO. 1 ENGINE - POWER TAKEOFF ASSEMBLY DRIVE								
72.430	6037T72G19 SAPT0728 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
726419-001	NO. 1 ENGINE - BALL DUPLEX BEARING								
72.435	4054T13P04 TMKABPV6 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
726419-002	NO. 1 ENGINE - PTO DUPLEX BEARING								
72.440	5042T84P05 TMKAA7MY REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01</b>									
72-20-00-201 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION OF FAN BLADES						PKG		
72.005	PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-20-00-202 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION FAN SPINNER PKG 600	MOS					PKG		
72.010	REF: See Workcard	HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
72-20-00-207 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE MASTER CHIP DETECTOR INDICATOR PKG 0	MOS					PKG		
72.015	REF: See Workcard	HRS/MSC ENC	100				14-DEC-2020 4616 2990		
72-20-00-208 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION ENGINE FAN CASE FORWARD MOUNTS PKG 3200	MOS					PKG		
72.020	REF: See Workcard	HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-20-00-210 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION FAN SHROUD CORE MATERIAL PKG 600	MOS					PKG		
72.025	REF: See Workcard	HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
72-20-00-211 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION EXTERIOR OF ENGINE FAN CASE & BLADE-CONTAINMENT CASE PKG 1200	MOS					PKG		
72.030	REF: See Workcard	HRS/MSC ENC	1200	+40/-40			08-MAY-2020 4328:45 2850		
72-30-00-202 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMPRESSOR BLADES PKG 3200	MOS					PKG		
72.035	REF: See Workcard	HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-30-00-204 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE VARIABLE AND STATIONARY VANES PKG 3200	MOS					PKG		
72.040	REF: See Workcard	HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
72-30-00-205 (s)	NO. 2 ENGINE - LUBRICATION VARIABLE GEOMETRY LINKAGE ROD END BEARINGS						PKG		
72.045	PKG 800 REF: See Workcard	MOS HRS/MSC ENC	800	+40/-40			08-MAY-2020 4328:45 2850		
72-40-00-201 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE COMBUSTOR LINER						PKG		
72.050	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-40-00-202 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE STAGE 1 NOZZLE						PKG		
72.055	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-40-00-205 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION THERMAL BLANKET						PKG		
72.065	PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
72-40-00-207 (s)	NO. 2 ENGINE - GENERAL VISUAL INSPECTION REAR MAIN MOUNT						PKG		
72.070	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-50-00-201 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE HIGH-PRESSURE-TURBINE STAGE 1 AND 2 ROTOR BLADES						PKG		
72.075	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
72-50-00-208 (s)	NO. 2 ENGINE - VISUAL CHECK EXHAUST CENTERBODY						PKG		
72.080	PKG 2400 REF: See Workcard	MOS HRS/MSC ENC	2400	+40/-40			08-MAY-2020 4328:45 2850		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-001	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE89450 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-002	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE84954 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-003	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE89420 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-004	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE89152 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-005	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE89378 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-006	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE81534 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-007	NO. 2 ENGINE - FAN BLADE 6018T30P15 MAE86453 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-008	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89389 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-009	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89821 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-010	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89447 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-011	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89796 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-012	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89802 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-013	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89348 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-014	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89782 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-015	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE86443 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-016	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE86311 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-017	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE79661 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-018	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89844 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-019	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89274 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-020	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89368 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-021	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE86483 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720000-022	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89430 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-023	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89672 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-024	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89800 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-025	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE81497 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-026	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89406 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-027	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE89789 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		
720000-028	NO. 2 ENGINE - FAN BLADE								
72.155	6018T30P15 MAE86439 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			14-SEP-2010 1416:30 1074		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
720001-001	NO. 2 ENGINE - CARBON SEAL								
72.090	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722110-001	NO. 2 ENGINE - FAN FWD ASSEMBLY CASE								
72.095	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722114-001	NO. 2 ENGINE - FAN AFT ASSEMBLY CASE								
72.100	6052T01G10 GEVKR6HM REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722140-001	NO. 2 ENGINE - ROTOR FAN								
72.105	6078T83G06 GGFV4155 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
722150-001	NO. 2 ENGINE - FAN DISK								
72.110 <b>LIFE LIMIT</b>	6078T57G05 GEE1FRDW REF: GENERIC NO REF	MOS HRS/MSC ENC	30000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(30000) 29984</b>
722210-001	NO. 2 ENGINE - FAN DRIVE SHAFT								
72.115 <b>LIFE LIMIT</b>	6036T78P02 FBKRM240 REF: GENERIC NO REF	MOS HRS/MSC ENC	20000	N:0 N:0 N:0			07-MAR-2005 0 0		<b>(20000) 19984</b>
722450-001	NO. 2 ENGINE - NO.2 BALL BEARING								
72.120	5042T11P01 TMKAB9WK REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
722490-001	NO. 2 ENGINE - BALL NO.1 BEARING								
	6078T35P03	MOS		N:0			07-MAR-2005		
72.125	FCAH4576	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
722520-001	NO. 2 ENGINE - FORWARD FAN SHAFT								
	6078T51P02	MOS		N:0			07-MAR-2005		
72.130	GATHF06G	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	ENC	20000	N:0			0	<b>(20000) 19984</b>	
723110-001	NO. 2 ENGINE - FRONT COMPRESSOR FRAME								
	6030T79G16	MOS		N:0			07-MAR-2005		
72.135	SPK941FA	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
723120-001	NO. 2 ENGINE - FAN SPEED SENSOR								
	4021T56P04	MOS		N:0			07-MAR-2005		
72.140	EGNEP488	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
723210-001	NO. 2 ENGINE - CONTAINMENT CASE								
	4150T32G01	MOS		N:0			07-MAR-2005		
72.145	3ABEACE7	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
723310-001	NO. 2 ENGINE - STAGE 9 COMPRESSOR ROTOR DISK								
	6087T01P03	MOS		N:0			07-MAR-2005		
72.150	NCE5922Y	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	REF: GENERIC NO REF	ENC	15000	N:0			0	<b>(15000) 14984</b>	
723312-001	NO. 2 ENGINE - CASE ASSEMBLY COMPRESSOR								
	5088T55G02	MOS		N:0			07-MAR-2005		
	GATHF3DN	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723314-001	NO. 2 ENGINE - COMPRESSOR DISCHARGE ROTATING SEAL								
	4019T38P01	MOS		N:0			07-MAR-2005		
72.160	TEJ81757	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	30000	N:0			0		<b>(30000) 29984</b>
723316-001	NO. 2 ENGINE - BALL NO.3 BEARING								
	5041T41P03	MOS		N:0			07-MAR-2005		
72.165	FCAH2383	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
723318-001	NO. 2 ENGINE - COMPRESSOR FORWARD SHAFT								
	5037T01P04	MOS		N:0			07-MAR-2005		
72.170	PAMEJ948	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	30000	N:0			0		<b>(30000) 29984</b>
723322-001	NO. 2 ENGINE - STAGE 2 COMPRESSOR ROTOR DISK								
	6036T91P02	MOS		N:0			07-MAR-2005		
72.175	GATHF2RG	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0		<b>(15000) 14984</b>
723328-001	NO. 2 ENGINE - STAGE 3 - 8 COMPRESSOR ROTOR SPOOL								
	6078T56P05	MOS		N:0			07-MAR-2005		
72.180	GATHEW7H	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0		<b>(15000) 14984</b>
723330-001	NO. 2 ENGINE - STAGE 10 - 14 COMPRESSOR ROTOR SPOOL								
	5087T46P02	MOS		N:0			07-MAR-2005		
72.185	GWNO8M9C	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0		<b>(15000) 14984</b>
723334-001	NO. 2 ENGINE - COMPRESSOR ROTOR REAR SHAFT								
	6087T03P03	MOS		N:0			07-MAR-2005		
72.190	GEE1FRE4	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0		<b>(15000) 14984</b>

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
723336-001	NO. 2 ENGINE - ROLLER NO.4 BEARING								
72.195	5023T47P02 TBCTL248 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
723340-001	NO. 2 ENGINE - ROTOR COMPRESSOR								
72.200	5123T14G08 GGFD4269 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724103-001	NO. 2 ENGINE - COMBUSTION FRAME								
72.205	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724124-001	NO. 2 ENGINE - ROLLER NO.5 BEARING								
72.210	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724128-001	NO. 2 ENGINE - BALANCE PISTON STATIONARY AIR SEAL								
72.470	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724219-001	NO. 2 ENGINE - COMBUSTION FRAME								
	3063T82G01 SPK943JB REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724220-001	NO. 2 ENGINE - COMBUSTION LINER								
72.225	6078T65G13 FCW12036 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724221-001	NO. 2 ENGINE - COMBUSTION INNER SHELL LINER								
72.230	6078T53G06 FCW10035 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724222-001	NO. 2 ENGINE - COMBUSTION OUTER SHELL LINER								
72.235	6078T54G08 FCW09068 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724223-001	NO. 2 ENGINE - COMBUSTION LINER DOME								
72.240	6087T17G04 FCW11052 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724512-001	NO. 2 ENGINE - HPT INNER CASING								
72.245	5099T00G05 BCM93177 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724514-001	NO. 2 ENGINE - HPT, ASSY STATOR								
72.250	5099T03G06 GCFG4295 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724517-001	NO. 2 ENGINE - HPT OUTER CASING								
72.255	6036T04G06 SPK940WL REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
724606-001	NO. 2 ENGINE - HPT STAGE NO.1 FRONT COOLING PLATE								
72.260	5079T65P06 BSLH9292 REF: GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			07-MAR-2005 0 0		
<b>LIFE LIMIT</b>			20000					<b>(20000) 19984</b>	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724608-001	NO. 2 ENGINE - STAGE 1 COMPRESSOR ROTOR BLISK								
	5087T84P01	MOS		N:0			07-MAR-2005		
72.265	GLHTHAAN	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	
724609-001	NO. 2 ENGINE - HPT ROTATING AIR SEAL								
	4019T60G03	MOS		N:0			07-MAR-2005		
72.270	BJWF1968	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
724610-001	NO. 2 ENGINE - HPT STAGE NO.1 DISK								
	5079T52P09	MOS		N:0			07-MAR-2005		
72.275	GATHF60M	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724612-001	NO. 2 ENGINE - HPT STAGE NO.2 DISK								
	5079T73P02	MOS		N:0			07-MAR-2005		
72.280	GATHF46C	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724614-001	NO. 2 ENGINE - HPT STAGE NO.2 FRONT COOLING PLATE								
	5079T55P04	MOS		N:0			07-MAR-2005		
72.285	BSLJ9894	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724616-001	NO. 2 ENGINE - HPT STAGE NO.2 REAR COOLING PLATE								
	5079T56P02	MOS		N:0			07-MAR-2005		
72.290	BSLG8386	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	
724620-001	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR SHAFT								
	5079T62P02	MOS		N:0			07-MAR-2005		
72.295	GEE1FRG5	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
724628-001	NO. 2 ENGINE - BALANCE PISTON ROTATING AIR SEAL								
	5079T63P02	MOS		N:0			07-MAR-2005		
72.300	BSLP5420	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
724638-001	NO. 2 ENGINE - OUTER TORQUE COUPLING								
	5079T64P05	MOS		N:0			07-MAR-2005		
72.305	BSLK1401	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	20000	N:0			0	<b>(20000) 19984</b>	
724645-001	NO. 2 ENGINE - HPT STAGE NO.1 AFT COOLING PLATE								
	5123T02P01	MOS		N:0			07-MAR-2005		
72.310	BSLN5121	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	14000	N:0			0	<b>(14000) 13984</b>	
724649-001	NO. 2 ENGINE - RUNNER SEAL								
	PN	MOS		N:0			07-MAR-2005		
72.315	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
724704-001	NO. 2 ENGINE - STAGE NO 1 NOZZLE								
	5099T12G02	MOS		N:0			07-MAR-2005		
72.320	JMM1839A	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
724710-001	NO. 2 ENGINE - HIGH PRESSURE TURBINE ROTOR								
	5079T61G11	MOS		N:0			07-MAR-2005		
72.325	GGFJ4378	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725110-001	NO. 2 ENGINE - LPT TURBINE TRANSITION ASSEMBLY								
	5121T29G05	MOS		N:0			07-MAR-2005		
72.330	GGFA4183	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725112-001	NO. 2 ENGINE - LPT TURBINE TRANSITION CASE								
72.335	5099T31G01 GEVKR573 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725114-001	NO. 2 ENGINE - TRANSITION TURBINE SEAL & LINER								
72.340	6047T28G05 GGM93497 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725125-001	NO. 2 ENGINE - LPT ASSEMBLY ROTOR								
72.345	5071T40G04 GGFM4303 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725210-001	NO. 2 ENGINE - LPT, ASSY STATOR								
72.350	5099T10G04 GGFN4184 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725220-001	NO. 2 ENGINE - LEFT ASSEMBLY THERMOCOUPLE								
72.355	6030T41P02 FDT08033 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725220-002	NO. 2 ENGINE - RIGHT ASSEMBLY THERMOCOUPLE								
72.355	6030T40P02 FDT09224 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
725314-001	NO. 2 ENGINE - LPT REAR SHAFT								
72.360	6030T72P02 NCE5584Y REF: GENERIC NO REF	MOS HRS/MSC ENC		N:0 N:0 N:0			07-MAR-2005 0 0		
<b>LIFE LIMIT</b>			15000					<b>(15000) 14984</b>	



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725320-001	NO. 2 ENGINE - LPT STAGE NO.3 DISK 6078T91P02	MOS		N:0			07-MAR-2005		
72.365	GATHF3G1	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725324-001	NO. 2 ENGINE - LPT STAGE NO.5 DISK 6078T92P02	MOS		N:0			07-MAR-2005		
72.370	GATHF2LL	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725326-001	NO. 2 ENGINE - LPT STAGE NO.6 DISK 6078T89P03	MOS		N:0			07-MAR-2005		
72.375	GATHF4C9	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725330-001	NO. 2 ENGINE - LPT STAGE NO.3 / 4 SEAL 5023T59P02	MOS		N:0			07-MAR-2005		
72.380	WES24479	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725332-001	NO. 2 ENGINE - LPT STAGE NO.4 / 5 SEAL 5023T67P01	MOS		N:0			07-MAR-2005		
72.385	WES11511	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725334-001	NO. 2 ENGINE - LPT STAGE NO.5 / 6 SEAL 5023T64P02	MOS		N:0			07-MAR-2005		
72.390	WES37620	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725338-001	NO. 2 ENGINE - LPT TURBINE DRIVE CONE 5023T40P03	MOS		N:0			07-MAR-2005		
72.395	NCE6249Y	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
725340-001	NO. 2 ENGINE - LPT STAGE NO.4 DISK								
	6078T02P04	MOS		N:0			07-MAR-2005		
72.400	GATHF1W7	HRS/MSC		N:0			0		
<b>LIFE LIMIT</b>	<b>REF: GENERIC NO REF</b>	ENC	15000	N:0			0	<b>(15000) 14984</b>	
725412-001	NO. 2 ENGINE - TURBINE LOW PRESSURE CASING								
	6017T55G09	MOS		N:0			07-MAR-2005		
72.405	GEVKR5LA	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725414-001	NO. 2 ENGINE - ROLLER NO.6 BEARING								
	5023T50P03	MOS		N:0			07-MAR-2005		
72.410	TBCTA282	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725416-001	NO. 2 ENGINE - TURBINE HIGH PRESSURE OUTER BEARING								
	PN	MOS		N:0			07-MAR-2005		
72.415	SN-UNKNOWN	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
725417-001	NO. 2 ENGINE - NO.7 BEARING								
	5023T51P02	MOS		N:0			07-MAR-2005		
72.420	TBCTT276	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
726210-001	NO. 2 ENGINE - ACCESSORY GEARBOX								
	5154T98G01	MOS		N:0			07-MAR-2005		
72.425	SAPT2388	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		
726410-001	NO. 2 ENGINE - POWER TAKEOFF ASSEMBLY DRIVE								
	6037T72G19	MOS		N:0			07-MAR-2005		
72.430	SAPT1954	HRS/MSC	O/C	N:0			0		
	<b>REF: GENERIC NO REF</b>	ENC		N:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
726419-001	NO. 2 ENGINE - BALL DUPLEX BEARING								
72.435	4054T13P04 TMKABRCV REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
726419-002	NO. 2 ENGINE - PTO DUPLEX BEARING								
72.440	5042T84P05 TMKABKYT REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 73 ENGINE FUEL AND CONTROL</b>									
732000-701	AUTOTHROTTLE TRAY								
	2802-6 273 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
732001-701	ATS POWER COMPUTER								
	C-88635-3 221 REF:	MOS HRS/MSC AFL	O/C	R:8 R:0 R:0			26-JAN-2011 1540:15 1164		
732002-701	N1 SPEED LH DISPLAY								
	C-88604-5 0406207 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			11-APR-2006 16:48 11		
732003-701	N1 SPEED RH DISPLAY								
	C-88604-6 183094-05 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			20-NOV-2020 4585:45 2959		
732004-701	ATS CONTROL PANEL								
	C-88664-3 303 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
732005-701	PACK SERVOMOTOR CLUTCH K-306-1 234 REF:	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			19-APR-2006 23:48 15		
732104-001	NO. 1 CONTROLLER AMPLIFIER 5071T98P05 LMDK3589 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
732104-002	NO. 2 CONTROLLER AMPLIFIER 5071T98P05 LMDK3594 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
733107-001	NO. 1 ENGINE FUEL PUMP - LOW PRESSURE SWITCH 601R60014-5 2089A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
733107-002	NO. 2 ENGINE FUEL PUMP - LOW PRESSURE SWITCH 601R60014-5 2096A REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

**ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01**

73-10-00-201 (s)	NO. 1 ENGINE - DISCARD FUEL FILTER ELEMENT PKG 1600	MOS HRS/MSC ENC	1600	+40/-40			PKG 08-MAY-2020 4328:45 2850		
73.005 LIFE LIMIT	REF: See Workcard								
73-10-00-202 (s)	NO. 1 ENGINE - VISUAL CHECK ENG FUEL FILTER MECH ACTUAL BYPASS INDICATOR PKG 1200	MOS HRS/MSC ENC	1200	+40/-40			PKG 08-MAY-2020 4328:45 2850		
73.010	REF: See Workcard								

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-00-204 (s)	NO. 1 ENGINE - DETAILED INSPECTION ENGINE FUEL MANIFOLD PKG 2400	MOS					PKG		
73.015		HRS/MSC	2400	+40/-40			08-MAY-2020		
<b>MRB</b>	<b>REF: See Workcard</b>	ENC					4328:45		
							2850		
73-10-00-205 (s)	NO. 1 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE FUEL INJECTORS PKG 3200	MOS					PKG		
73.020		HRS/MSC	3200	+40/-40			03-APR-2017		
	<b>REF: See Workcard</b>	ENC					3041:45		
							2204		
73-10-00-301	NO. 1 ENGINE - INSPECT & INSTALL NEW FUEL FILTER ELEMENT	MOS							
73.025		HRS/MSC	O/C				17-AUG-2006		
	<b>REF: See Workcard</b>	ENC					82:48		
73-20-00-201 (s)	NO. 1 ENGINE - DETAILED INSPECTION MAIN FUEL CONTROL PKG 3200	MOS					PKG		
73.030		HRS/MSC	3200	+40/-40			03-APR-2017		
<b>MRB</b>	<b>REF: See Workcard</b>	ENC					3041:45		
							2204		
731011-001	NO. 1 ENGINE - MFC MAIN FUEL CONTROL 4147T70P02	MOS							
73.040	WYGA8535	HRS/MSC	O/C				07-MAR-2005		
	<b>REF: See Workcard</b>	ENC					0		
							0		
							0		
731014-001	NO. 1 ENGINE - FUEL PUMP 6078T39P04	MOS							
73.045	CGWT3116	HRS/MSC	O/C				07-MAR-2005		
	<b>REF: See Workcard</b>	ENC					0		
							0		
							0		
732002-001	NO. 1 ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR 4071T72P01	MOS							
73.055	WYGA8744	HRS/MSC	O/C				07-MAR-2005		
	<b>REF: See Workcard</b>	ENC					0		
							0		
							0		

**ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
73-10-00-201 (s)	NO. 2 ENGINE - DISCARD FUEL FILTER ELEMENT PKG 1600	MOS					PKG	08-MAY-2020	
73.005		HRS/MSC	1600	+40/-40			4328:45		
<b>LIFE LIMIT</b>	<b>REF: See Workcard</b>	ENC					2850		
73-10-00-202 (s)	NO. 2 ENGINE - VISUAL CHECK ENG FUEL FILTER MECH ACTUAL BYPASS INDICATOR PKG 1200	MOS					PKG	08-MAY-2020	
73.010		HRS/MSC	1200	+40/-40			4328:45		
	<b>REF: See Workcard</b>	ENC					2850		
73-10-00-204 (s)	NO. 2 ENGINE - DETAILED INSPECTION ENGINE FUEL MANIFOLD PKG 2400	MOS					PKG	08-MAY-2020	
73.015		HRS/MSC	2400	+40/-40			4328:45		
<b>MRB</b>	<b>REF: See Workcard</b>	ENC					2850		
73-10-00-205 (s)	NO. 2 ENGINE - SPECIAL DETAILED INSPECTION (BORESCOPE) OF THE FUEL INJECTORS PKG 3200	MOS					PKG	03-APR-2017	
73.020		HRS/MSC	3200	+40/-40			3041:45		
	<b>REF: See Workcard</b>	ENC					2204		
73-10-00-301	NO. 2 ENGINE - INSPECT & INSTALL NEW FUEL FILTER ELEMENT	MOS						17-AUG-2006	
73.025		HRS/MSC	O/C				82:48		
	<b>REF: See Workcard</b>	ENC							
73-20-00-201 (s)	NO. 2 ENGINE - DETAILED INSPECTION MAIN FUEL CONTROL PKG 3200	MOS					PKG	03-APR-2017	
73.030		HRS/MSC	3200	+40/-40			3041:45		
<b>MRB</b>	<b>REF: See Workcard</b>	ENC					2204		
731011-001	NO. 2 ENGINE - MFC MAIN FUEL CONTROL	MOS						07-MAR-2005	
73.040	4147T70P02	HRS/MSC	O/C		N:0		0		
	WYGA8619	ENC			N:0		0		
	<b>REF: See Workcard</b>				N:0		0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
731014-001	NO. 2 ENGINE - FUEL PUMP								
73.045	6078T39P04 CGWT3119 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
732002-001	NO. 2 ENGINE - COMPRESSOR INLET TEMPERATURE SENSOR								
73.055	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 74 IGNITION</b>									
741104-001	STATIC IGNITION INVERTER								
74.005	601R59323-1 1655 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01</b>									
74-00-00-201	NO. 1 ENGINE - DETAILED INSPECTION OF THE CERAMIC ON THE HIGH VOLTAGE IGNITERS								
74.005	REF: See Workcard	MOS HRS/MSC ENC	1200	+40/-40			08-MAY-2020 4328:45 2850	(5528:45) 5528:45	5568:45
741002-001	NO. 1 ENGINE - IGNITION EXCITER								
74.010	9238M66P08 UNJW8914 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
741002-002	NO. 1 ENGINE - IGNITION EXCITER								
74.015	9238M66P08 UNJW8966 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741015-001	NO. 1 ENGINE - (A) PLUG IGNITER								
74.020	4096T38P09 LM916 REF: See Workcard	MOS HRS/MSC ENC	O/C				18-SEP-2009 1139:33 898		
741015-002	NO. 1 ENGINE - (B) PLUG IGNITER								
74.030	4096T38P09 HH318 REF: See Workcard	MOS HRS/MSC ENC	O/C				18-SEP-2009 1139:33 898		
743014-001	NO. 1 ENGINE - FAN INLET TEMPERATURE SENSOR								
74.025	4033T65P03 EGNK0998 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01</b>									
74-00-00-201	NO. 2 ENGINE - DETAILED INSPECTION OF THE CERAMIC ON THE HIGH VOLTAGE IGNITERS								
74.005	REF: See Workcard	MOS HRS/MSC ENC	1200	+40/-40			08-MAY-2020 4328:45 2850	(5528:45) 5528:45	5568:45
741002-001	NO. 2 ENGINE - IGNITION EXCITER								
74.010	9238M66P08 UNJW8924 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
741002-002	NO. 2 ENGINE - IGNITION EXCITER								
74.015	9238M66P08 UNJW8965 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
741015-001	NO. 2 ENGINE - (A) PLUG IGNITER								
74.020	4096T38P09 HH317 REF: See Workcard	MOS HRS/MSC ENC	O/C				18-SEP-2009 1139:33 898		



TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
741015-002	NO. 2 ENGINE - (B) PLUG IGNITER								
74.030	4096T38P09 HH319 REF: See Workcard	MOS HRS/MSC ENC	O/C				18-SEP-2009 1139:33 898		
743014-001	NO. 2 ENGINE - FAN INLET TEMPERATURE SENSOR								
74.025	PN SN-UNKNOWN REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 76 ENGINE CONTROLS</b>									
76-11-01-204 (s)	GENERAL VISUAL INSPECTION ENGINE THROTTLE PUSH/PULL CONTROL ASSEMBLY						PKG		
76.005	PKG 1200 REF: AMM 76 11 10 210 801	MOS HRS/MSC AFL	1200	+40/-40			08-MAY-2020 4328:45 2835		
761101-001	ENGINE THROTTLE QUADRANT								
76.010	C-88627-1 FR5446 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-APR-2006 23:48 15		
761104-001	NO. 1 CABLE, FWD THROTTLE								
76.015	TM432230-02-3 443 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-APR-2006 23:48 15		
761104-002	NO. 2 CABLE, FWD THROTTLE								
76.015	TM432230-02-3 422 REF: See Workcard	MOS HRS/MSC AFL	O/C				18-APR-2006 23:48 15		
761107-001	NO. 1 AFT THROTTLE-CONTROL CABLE PUSH/PULL UNIT								
76.020	601-90711-23 672 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761107-002	NO. 2 AFT THROTTLE-CONTROL CABLE PUSH/PULL UNIT								
76.020	601-90711-23 670 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761110-001	NO. 1 THROTTLE CONTROL ASSY CABLE								
76.025	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761110-002	NO. 2 THROTTLE CONTROL ASSY CABLE								
76.025	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761110-003	ENGINE THROTTLE PUSH/PULL LH CONTROL ASSY								
76.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761110-004	ENGINE THROTTLE PUSH/PULL RH CONTROL ASSY								
76.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761113-001	NO. 1 THROTTLE CONTROL GEARBOX								
76.035	2100140-007 3035 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761113-001A	FUNCTIONAL TEST NO. 1 THROTTLE CONTROL GEARBOX OF THE ENGINE THROTTLE CONTROL GEARBOX (76-11-00-101) (CMR**)								
	2100140-007 3035 REF: AMM 76 11 13 720 802	MOS HRS/MSC AFL	1600				08-MAY-2020 4328:45 2835	<b>5928:45</b>	

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
761113-002	NO. 2 THROTTLE CONTROL GEARBOX								
76.035	2100140-007 3034 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761113-002A	FUNCTIONAL TEST NO. 2 THROTTLE CONTROL GEARBOX OF THE ENGINE THROTTLE CONTROL GEARBOX (76-11-00-101) (CMR**)								
	2100140-007 3034 REF: AMM 76 11 13 720 802	MOS HRS/MSC AFL	1600				08-MAY-2020 4328:45 2835	<b>5928:45</b>	
761113-003	NO. 1 THROTTLE CONTROL ASSEMBLY								
76.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
761113-004	NO. 2 THROTTLE CONTROL ASSEMBLY								
76.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

**ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01**

76-11-00-201 (s)	NO. 1 ENGINE - FUNCTIONAL TEST GEARBOX ASSEMBLY						PKG		
76.005	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		

**ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01**

76-11-00-201 (s)	NO. 2 ENGINE - FUNCTIONAL TEST GEARBOX ASSEMBLY						PKG		
76.005	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		

**CHAPTER 77 ENGINE INDICATING**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
773101-001	NO. 1 ENGINE VIBRATION ACCELEROMETER								
77.005	600-59131-1 20636 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
773101-002	NO. 2 ENGINE VIBRATION ACCELEROMETER								
77.005	600-59131-1 20631 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
773104-001	ENGINE VIBRATION SIGNAL CONDITIONER								
77.010	601-50910-19 070499 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01</b>									
771002-001	NO. 1 ENGINE - CONTROLLER AMPLIFIER								
77.005	5071T98P05 LMDK3594 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01</b>									
771002-001	NO. 2 ENGINE - CONTROLLER AMPLIFIER								
77.005	5071T98P05 LMDK3589 REF: GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 78 EXHAUST</b>									
78-10-00-201 (s)	DETAILED INSPECTION EXHAUST NOZZLE ASSEMBLY						PKG		
78.005	PKG 6400 REF: AMM 78 10 04 220 801	MOS HRS/MSC AFL	6400	+40/-40			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-101	SPECIAL DETAILED INSPECTION OF THE AFT LUG OF THE MAIN TRACK OF THE THRUST REVERSER								
78.010		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-78-30-001</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
78-30-00-102	SPECIAL DETAILED INSPECTION OF THE MAIN TRACKS LOWER FLANGE OF THE THRUST REVERSER								
78.015		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-78-30-003</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
78-30-00-103	SPECIAL DETAILED INSPECTION MAIN UPPER AND LOWER PYLON TRACK								
78.020		MOS					07-MAR-2005		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-78-30-002</b>	HRS/MSC					0		
		AFL	7800				0		<b>7800</b>
78-30-00-202 (s)	LUBRICATION OF THE THRUST-REVERSER BALLSCREW ACTUATORS						PKG		
78.025	PKG 800	MOS					08-MAY-2020		
	<b>REF: AMM 12 20 04 640 824</b>	HRS/MSC	800	+40/-40			4328:45		
		AFL					2835		
78-30-00-203 (s)	VISUAL CHECK LUBRICATION OF THE THRUST-REVERSER FLEXSHAFTS						PKG		
78.030	PKG 2400	MOS					08-MAY-2020		
	<b>REF: AMM 12 20 04 640 814</b>	HRS/MSC	2400	+40/-40			4328:45		
		AFL					2835		
78-30-00-204 (s)	DETAILED INSPECTION OF THE FLEXSHAFT DRIVE						PKG		
78.035	PKG 2400	MOS					08-MAY-2020		
	<b>REF: AMM 78 32 07 220 801</b>	HRS/MSC	2400	+40/-40			4328:45		
		AFL					2835		
78-30-00-205 (s)	FUNCTIONAL TEST OF THE AUTO-THROTTLE RETARDER SYSTEM, THROTTLE LOCKS AND BELLCRANK						PKG		
78.040	PKG 3200	MOS					03-APR-2017		
	<b>REF: AMM 78 35 01 720 801</b>	HRS/MSC	3200	+40/-40			3041:45		
		AFL					2185		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-30-00-206 (s)	DETAILED INSPECTION OF THE MAIN PYLON TRACKS OF THE THRUST REVERSER						PKG		
78.045	PKG 96 REF: AMM 78 34 07 220 802	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
78-30-00-207 (s)	DETAILED INSPECTION OF THRUST REVERSER MAIN TRACKS						PKG		
78.050	PKG 96 REF: AMM 78 34 04 220 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
78-30-00-208 (s)	DETAILED INSPECTION OF THE ATTACHMENT FITTINGS FOR THE THRUST-REVERSER MAIN TRACKS						PKG		
78.055	PKG 96 REF: AMM 78 34 04 220 802	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
78-30-00-209 (s)	DETAIL INSPECTION OF SUPPORT FITTINGS OF THE T/R BALLSCREW ACTUATORS						PKG		
78.060	PKG 96 REF: AMM 78 32 04 220 801	MOS HRS/MSC AFL	96	+1m/-1m			16-JUN-2014 2304:15 1731		
+ 78-32-04-101	DISCARD OF LH 10 O'CLOCK GEARBOX-BALLSCREW ACTUATOR , PART NO. 228-58111-111 AND 228-58111-801								
<b>LIFE LIMIT</b>	3272570-6 14535 REF: AMM 78 32 04 000 801	MOS HRS/MSC AFL	50000				07-MAR-2005 0 0	<b>50000</b>	
+ 78-32-04-101	DISCARD OF LH 2 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801.								
<b>LIFE LIMIT</b>	3272570-6 14536 REF: AMM 78 32 04 000 801	MOS HRS/MSC AFL	50000				07-MAR-2005 0 0	<b>50000</b>	
+ 78-32-04-101	DISCARD OF LH 4 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801.								
<b>LIFE LIMIT</b>	3272570-6 14524 REF: AMM 78 32 04 000 801	MOS HRS/MSC AFL	50000				07-MAR-2005 0 0	<b>50000</b>	

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
+ 78-32-04-101	DISCARD OF LH 8 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801. 3272570-6 14533	MOS HRS/MSC	50000				07-MAR-2005 0		50000
<b>LIFE LIMIT</b>	<b>REF: AMM 78 32 04 000 801</b>	AFL					0		
+ 78-32-04-101	DISCARD OF R/H 10 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801. 3272570-6 14537	MOS HRS/MSC	50000				07-MAR-2005 0		50000
<b>LIFE LIMIT</b>	<b>REF: AMM 78 32 04 000 801</b>	AFL					0		
+ 78-32-04-101	DISCARD OF R/H 2 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801. 3272570-6 14532	MOS HRS/MSC	50000				07-MAR-2005 0		50000
<b>LIFE LIMIT</b>	<b>REF: AMM 78 32 04 000 801</b>	AFL					0		
+ 78-32-04-101	DISCARD OF RH 4 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801. 3272570-6 14534	MOS HRS/MSC	50000				07-MAR-2005 0		50000
<b>LIFE LIMIT</b>	<b>REF: AMM 78 32 04 000 801</b>	AFL					0		
+ 78-32-04-101	DISCARD OF RH 8 O'CLOCK GEARBOX-BALLSCREW ACTUATOR, PART NO. 228-58111-111 AND 228-58111-801. 3272570-6 14526	MOS HRS/MSC	50000				07-MAR-2005 0		50000
<b>LIFE LIMIT</b>	<b>REF: AMM 78 32 04 000 801</b>	AFL					0		
78-34-07-101	SPECIAL DETAILED INSPECTION OF ATTACHMENT FITTING OF MAIN TRACK OF THRUST REVERSER 78.065	MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	<b>REF: NDT ET-78-30-006</b>	AFL	7800				0		7800
78-34-07-102	DETAIL INSPECTION OF SUPPORT BED FOR UPPER/LOWER PYLON TRACK ON SERVICE PYLON 78.070	MOS HRS/MSC					07-MAR-2005 0		
<b>AIRWORTHINESS</b>	<b>REF: AMM 78 34 07 220 801</b>	AFL	7800				0		7800

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
78-ZL-00-201 (s)	GENERAL VISUAL INSPECTION TORQUE BOX OF THE THRUST REVERSER - INTERNAL LH						PKG		
78.075	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
78-ZL-00-202 (s)	GENERAL VISUAL INSPECTION TORQUE BOX OF THE THRUST REVERSER - INTERNAL RH						PKG		
78.080	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
78-ZL-00-203 (s)	GENERAL VISUAL INSPECTION EXHAUST NOZZLE FAIRING - ASSEMBLY LH						PKG		
78.085	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
78-ZL-00-204 (s)	GENERAL VISUAL INSPECTION EXHAUST NOZZLE FAIRING - ASSEMBLY RH						PKG		
78.090	PKG 48 REF: See Workcard	MOS HRS/MSC AFL	48	+1m/-1m			23-MAR-2018 3512:30 2441		
781001-001	NO. 1 TAILPIPE EXHAUST NOZZLE FAIRING								
78.095	228-50181-245 SB/RJ/2714 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
781001-002	NO. 2 TAILPIPE EXHAUST NOZZLE FAIRING								
78.095	228-50181-245 SBRJ2723 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
781004-001	NO. 1 ASSY EXHAUST NOZZLE								
78.100	228-50030-113 C2752 REF: See Workcard	MOS HRS/MSC AFL	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		



### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
781004-002	NO. 2 ASSY EXHAUST NOZZLE								
78.100	228-55030-113 C2750 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
783000-001	THRUST LH REVERSER								
78.105	228-50200-809 SBRJ1365 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
783000-002	THRUST RH REVERSER								
78.105	228-50200-810 SB/RJ/1364 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
783201-001	NO. 1 THRUST REVERSER PDU								
78.110	126758-8 3876 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783201-002	NO. 2 THRUST REVERSER PDU								
78.110	126758-8 3875 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-001	L/H 2 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.115	3272570-6 14536 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-002	L/H 4 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.120	3272570-6 14524 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783204-003	L/H 8 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.130	3272570-6 14533 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-004	L/H 10 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.135	3272570-6 14535 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-005	R/H 2 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.140	3272570-6 14532 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-006	R/H 4 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.145	3272570-6 14534 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-007	R/H 8 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.150	3272570-6 14526 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783204-008	R/H 10 O'CLOCK GEARBOX-BALLSCREW ACTUATOR								
78.155	3272570-6 14537 REF: See Workcard	MOS HRS/MSC AFL	H/T	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-001	1-RH ASSY SHAFT								
78.160	121754-2 120513012522 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		

### Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783207-002	1L/H ASSY SHAFT								
78.160	121754-2 120513012532 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-003	2R/H ASSY SHAFT								
78.165	121754-2 120513012530 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-004	2L/H ASSY SHAFT								
78.165	121754-2 120513012529 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-005	LH - ENGINE FLEX DRIVE ASSEMBLY SHAFT								
78.170	121754-3 120513012424 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-006	RH - ENGINE ASSY SHAFT								
78.170	121754-3 120513012419 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-007	LH - ENGINE FLEX DRIVE ASSEMBLY SHAFT								
78.175	121754-5 120513012559 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-008	RH - ENGINE ASSY SHAFT								
78.175	121754-5 120513012557 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
783207-009	LH - ENGINE FLEX DRIVE ASSEMBLY SHAFT								
78.180	121754-6 110513011710 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783207-010	RH - ENGINE ASSY SHAFT								
78.180	121754-6 110513012368 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			26-APR-2006 27:18 17		
783300-001	LEFT UPPER UPPER LH MODULE								
78.185	228-50100-399 SB/RJ/1355 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
783300-002	RIGHT UPPER UPPER RH MODULE								
78.185	228-50100-400 SBRJ1356 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
783300-003	LEFT LOWER LOWER LH MODULE								
78.190	228-50100-247 SB/RJ/1355 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
783300-004	RIGHT LOWER LOWER RH MODULE								
78.190	228-50100-248 SBRJ1356 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>ENGINE NO. 1 Model : CF-34-3B (CIMMS) Serial # 950335 Part # 6089T11G01</b>									
780002-001	NO. 1 ENGINE - EXHAUST FRAME								
78.005	5083T69G10 GGM933L1 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
<b>ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01</b>									
780002-001	NO. 2 ENGINE - EXHAUST FRAME								
	5083T69G10	MOS		N:0			07-MAR-2005		
78.005	GGM934RJ	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	ENC		N:0			0		
<b>CHAPTER 79 OIL</b>									
791110-001	OIL TANK								
	601-63200-77	MOS		N:0			07-MAR-2005		
79.005	4350531	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
791204-001	LUBRICATING SYSTEM PUMP								
	601-63901-1	MOS		N:0			07-MAR-2005		
79.010	11AY189	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
791207-001	ENGINE OIL LEVEL CONTROL								
	601-63903-9	MOS		N:0			07-MAR-2005		
79.015	1841	HRS/MSC	O/C	N:0			0		
	REF: GENERIC NO REF	AFL		N:0			0		
791216-001	NO. 1 OIL LEVEL PROBE								
	601-63903-15	MOS		N:0			07-MAR-2005		
79.020	3550	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		
791216-002	NO. 2 OIL LEVEL PROBE								
	601-63903-15	MOS		N:0			07-MAR-2005		
79.020	3553	HRS/MSC	O/C	N:0			0		
	REF: See Workcard	AFL		N:0			0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
791217-001	NO. 1 CHECK VALVE								
79.025	2810044-101 3831 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
791217-002	NO. 2 CHECK VALVE								
79.025	2810044-101 3833 <b>REF:</b> GENERIC NO REF	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
792119-001	SELECTOR - OIL REPL SYSTEM VALVE								
79.030	601-63902-1 04-120614 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
793004-001	NO. 1 ENGINE OIL PRESSURE SWITCH								
79.035	1153P0012 4663 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
793004-002	NO. 2 ENGINE OIL PRESSURE SWITCH								
79.035	1153P0012 4661 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
793007-001	NO. 1 ENGINE OIL PRESSURE TRANSDUCER								
79.040	601-50919-9 6961-5-643 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
793007-002	NO. 2 ENGINE OIL PRESSURE TRANSDUCER								
79.040	601-50919-9 6961-5-614 <b>REF:</b> See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-00-00-203 (s)	NO. 1 ENGINE - VISUAL CHECK OIL FILTER IMPENDING BYPASS INDICATOR						PKG		
79.005	PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
79-00-00-204 (s)	NO. 1 ENGINE - DISCARD OIL FILTER ENGINE OIL FILTER ELEMENT						PKG		
79.010 <b>LIFE LIMIT</b>	PN PKG 1600 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	1600	+40/-40			08-MAY-2020 4328:45 2850		
79-00-00-205 (s)	NO. 1 ENGINE - FUNCTIONAL TEST OIL FILTER IMPENDING BYPASS SENSOR						PKG		
79.015	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
79-00-00-206 (s)	NO. 1 ENGINE - FUNCTIONAL TEST ENGINE MASTER CHIP DETECTOR						PKG		
79.020	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
79-00-00-207 (s)	NO. 1 ENGINE - VISUAL CHECK C-SUMP DRAIN OUTLET						PKG		
79.025	PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
79-00-00-208	NO. 1 ENGINE - DETAILED INSPECTION C-SUMP SCAVENGE SCREENS (PRE GE SB-79-0018).								
79.030	REF: See Workcard	MOS HRS/MSC ENC	N/A				07-MAR-2005 0 0		
790001-001	NO. 1 ENGINE - OIL FILTER								
79.040	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C				07-MAR-2005 0 0		

# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
791012-001	NO. 1 ENGINE - LUBE & SCAVENGE PUMP								
79.045	6087T04P06 NMADC177 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
791014-001	NO. 1 ENGINE - A-SUMP SCAVENGE PUMP								
79.050	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
791020-001	NO. 1 ENGINE - HEAT EXCHANGER								
79.055	6087T05P02 SCKB3004 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
792110-001	NO. 1 ENGINE - OIL FILTER BYPASS SENSOR								
79.060	4060T64P01 APFM2517 REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			03-APR-2017 3041:45 2204		

**ENGINE NO. 2 Model : CF-34-3B (CIMMS) Serial # 950336 Part # 6089T11G01**

79-00-00-203 (s)	NO. 2 ENGINE - VISUAL CHECK OIL FILTER IMPENDING BYPASS INDICATOR						PKG		
79.005	PKG 600 REF: See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
79-00-00-204 (s)	NO. 2 ENGINE - DISCARD OIL FILTER ENGINE OIL FILTER ELEMENT						PKG		
79.010	PN PKG 1600 SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	1600	+40/-40			08-MAY-2020 4328:45 2850		
<b>LIFE LIMIT</b>									
79-00-00-205 (s)	NO. 2 ENGINE - FUNCTIONAL TEST OIL FILTER IMPENDING BYPASS SENSOR						PKG		
79.015	PKG 3200 REF: See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		



# Status Report

**CL-604 S/N 5613 (RA-67228): 4650:45 HRS, 2986 AFL as of 10-Jan-2021**
**Owner/Operator: LLC AVIASERVICE**
**Report Date: 11-JAN-2021**

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
79-00-00-206 (s)	NO. 2 ENGINE - FUNCTIONAL TEST ENGINE MASTER CHIP DETECTOR						PKG		
79.020	PKG 3200 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	3200	+40/-40			03-APR-2017 3041:45 2204		
79-00-00-207 (s)	NO. 2 ENGINE - VISUAL CHECK C-SUMP DRAIN OUTLET						PKG		
79.025	PKG 600 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	600	+40/-40			08-MAY-2020 4328:45 2850		
79-00-00-208	NO. 2 ENGINE - DETAILED INSPECTION C-SUMP SCAVENGE SCREENS (PRE GE SB-79-0018).								
79.030	<b>REF:</b> See Workcard	MOS HRS/MSC ENC	N/A				07-MAR-2005 0 0		
790001-001	NO. 2 ENGINE - OIL FILTER								
79.040	PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
791012-001	NO. 2 ENGINE - LUBE & SCAVENGE PUMP								
79.045	PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
791014-001	NO. 2 ENGINE - A-SUMP SCAVENGE PUMP								
79.050	PN SN-UNKNOWN <b>REF:</b> See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		
791020-001	NO. 2 ENGINE - HEAT EXCHANGER								
79.055	6087T05P02 SCKB2991 <b>REF:</b> See Workcard	MOS HRS/MSC ENC	O/C		N:0 N:0 N:0		07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
792110-001	NO. 2 ENGINE - OIL FILTER BYPASS SENSOR								
79.060	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC ENC	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
<b>CHAPTER 80 STARTING</b>									
80-11-00-201	SERVICE AIR TURBINE STARTER OIL SUPPLY								
80.005	REF:	MOS HRS/MSC AFL	N/A				25-MAR-2016 2657:18 1997		
80-11-00-202 (s)	DETAILED INSPECTION OF THE DRAIN PLUG MAGNETIC CHIP DETECTOR								
80.010	PKG 600 REF: AMM 80 11 01 220 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
80-11-00-203 (s)	DISCARD OF THE AIR TURBINE STARTER (ATS) OIL.								
DISCARD	PKG 600 REF: AMM 80 11 01 680 801	MOS HRS/MSC AFL	600	+40/-40			08-MAY-2020 4328:45 2835		
801101-001	NO. 1 ENGINE AIR STARTER								
80.015	3505188-9 4144 REF: See Workcard	MOS HRS/MSC AFL	O/C	O:0 O:0 O:0			25-OCT-2007 410:30 368		
801101-002	NO. 2 ENGINE AIR STARTER								
80.015	3505188-9 6268 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801105-001	NO. 1 ENGINE AIR START VALVE								
80.020	898930-10 3906 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		

TASK NO	TASK DESCRIPTION PART/SERIAL	UNIT	INTERVAL	TIME SINCE	ADJ	WARR EXP	COMPLIANCE	NEXT DUE (ENG/APU) A/C	MAX LIMIT
801105-002	NO. 2 ENGINE AIR START VALVE								
80.020	898930-10 3913 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801107-001	NO. 1 N1 SPEED SWITCH								
80.025	128646-6 22755 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801107-002	NO. 2 N1 SPEED SWITCH								
80.025	128646-6 22810 REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801108-001	NO. 1 PRESSURE SPEED SWITCH								
80.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801108-002	NO. 2 PRESSURE SPEED SWITCH								
80.030	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801109-001	NO. 1 ATS VALVE								
80.035	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		
801109-002	NO. 2 ATS VALVE								
80.035	PN SN-UNKNOWN REF: See Workcard	MOS HRS/MSC AFL	O/C	N:0 N:0 N:0			07-MAR-2005 0 0		