





1. Approving Competent Authority / Country <b>EASA</b>		2. <b>AUTHORISED RELEASE CERTIFICATE</b> <b>EASA FORM 1</b>			3. Form Tracking Number <b>AWM-21-109</b>	
4. Organization Name and Address  <b>LEONARDO MALAYSIA SDN. BHD.</b> LOT 1 & 2, HELICOPTER CENTER SULTAN ABDUL AZIZ SHAH AIRPORT 47200 SUBANG, SELANGOR DARUL EHSAN, MALAYSIA.				5. Work Order / Contract / Invoice <b>4802570090</b>		
6. Item	7. Description	8. Part Number	9. Quantity	10. Serial Number	11. Status/Work	
1	MAIN ROTOR BLADES	355A-11-0030-04	THREE	29576, 25635, 25215	REPAIRED	
12. Remarks CARRIED OUT DETAILED INSPECTION; REPLACED TIP CAP, BLADE BODY COVER, INBOARD & OUTBOARD TRIM TABS, TIP BALANCE WEIGHT POCKET COVER AND LEADING EDGE COVER; COMPLIED WITH SB139-617; PERFORMED COMPLETE REFINISH TO STANDARD PAINT SCHEME; PERFORMED STATIC BALANCE TO MASTER MOMENTS PER E.R.A. LMBRWS-080; ALL WORK CARRIED OUT (UNLESS OTHERWISE SPECIFIED) PER AS350, AS355 IETP, 40 <sup>TH</sup> ISSUE DATED 10 DECEMBER 2021, UNDER WORK ORDER NO. AWM-21-109, AT 456.35 HRS TSN.						
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> Approved design data and are in condition for safe operation <input type="checkbox"/> Non-approved design data specified in block 12				14a. <input checked="" type="checkbox"/> Part – 145.A.50 Release to Service <input type="checkbox"/> Other Regulation specified in block 12 Certifies that unless otherwise specified in Block 12 the work identified in block 11 and described in block 12, was accomplished in accordance with Part 145 and in respect to that work, the items are approved for release to service.		
13b. Authorized Signature:		13c. Approval / Authorization No.:	14b. Authorized Signature  	14c. Certificate / Approval Ref. No. <b>EASA.145.0838</b>		
13d. Name:		13e. Date (dd mmm yyyy):	14d. Name <b>EMLYN WILLIAMS</b>	14e. Date (dd mmm yyyy) <b>09 MARCH 2022</b>		

**User/Installer responsibilities**

- This certificate does not automatically constitute authority to install the item(s).
- Where the user/installer perform work in accordance with the regulations of an Airworthiness Authority different than the Airworthiness Authority specified in block 1, it is essential that the user/installer ensure that his/her Airworthiness Authority accepts items from the Airworthiness Authority specified in block 1.
- Statements 13a and 14a do not constitute installation certification. In all cases the aircraft maintenance record must contain an installation certification issued in accordance with the national regulations by user/installer before the aircraft may be flown.



### LOG CARD


### Section 4

Chapter n° 62

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTAWESTLAND GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Part n°

#### DIRECTIVES COMPLIANCE

MANDATORY DIRECTIVES					OPTIONAL DIRECTIVES				
DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)	DIRECTIVE NUMBER (47)	ISSUE (48)	DATE OF COMPLIANCE (49)	ORGANIZATION (50)	STAMP SIGNATURE (51)
SB 133-G17	FIRST	09 MAR 22	LEONARDO MALAYSIA						

Rev. 3

AQ 12-04



### LOG CARD

### Section 1

Chapter n° 62



NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTAWESTLAND GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Part n°

DESCRIPTION (1)	P/N (2)	S/N (3)	MANUFACTURER NAME (4)	ASSEMBLY DATE (5)	RETIREMENT LIFE (6)
MAIN ROTOR BLADES	355A11-0030-04	29576	AgustaWestland	JULY 15	4000 FH 2000 FH
		25635			RETIREMENT LIFE (11)
		25215			50200 Land. RETIREMENT LIFE (11)


NOTES (12)

#### ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL							
DATE (13)	A/C		ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
SEP. 15		31712	00.00	00.00	NEW	AW		09/sep	456:35	456:35	NEW	Blade Tip Found Damage.	ossar	

Rev. 3

AQ 12-04



## LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTAWESTLAND GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Part n°: 355A-11-0030-04

Serial n°: 29576, 25635, 25215

## Section 2

Chapter n° **62**


Part n° .....

### LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)

Rev. 3

AQ 12-04



## LOG CARD

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTAWESTLAND GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

## Section 3

Chapter n° **62**

Part n° .....

### ACTIVITY RECORD

DATE (40)	ASSY TOTAL TIME (41)	TASK (42)	ACTIVITY (43)	DATE (44)	ORGANIZATION (45)	STAMP AND SIGNATURE (46)
05 MAY 2020	456:35	BLADE TIP FOUND DAMAGED.	CARRIED OUT DETAILED INSPECTION; REPLACED TIP CAP, BLADE BODY COVER, INBOARD & OUTBOARD TRIM TABS, TIP BALANCE WEIGHT POCKET COVER AND LEADING EDGE COVER, COMPLIED WITH 98239-617; PERFORMED COMPLETE REFINISH TO STANDARD PAINT SCHEM. PERFORMED STATIC BALANCE TO MASTER MOMENTS PER E.R.A. LMBRW-080; ALL WORK CARRIED OUT (UNLESS OTHERWISE SPECIFIED) PER AS350 AS355 40TH ISSUE DATED 10 DECEMBER 2021, UNDER WORK ORDER NO. AWH-21-109, AT 456:35 HRS	09 MARCH 2022	LEONARDO MALAYSIA	<i>(Signature)</i>

Rev. 3

AQ 12-04