



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

MAINTENANCE DEPARTMENT					W/O №
AIRCRAFT					
Type	MSN	Tail №	FH	FC	Date
MD-83	N/A		N/A	N/A	21.09.2023
ENGINE					
Type	ENS	Position	FH	FC	Insp. Method
JT8D-219		2	42337	35818	Borescope inspection
Equipment Name	P/N	S/N			Station
Olympus	IV8535L2				FRU

RESULTS OF INSPECTION OR MEASUREMENT		DISCREPANCIES (IF ANY)	
Exterior Inspection		<i>Ok</i>	
Accessory Drive Gearbox		<i>Ok</i>	
Compressor Cases		<i>Ok</i>	
Exhaust Cases		<i>Ok</i>	
Exhaust Cone		<i>Ok</i>	
Nose coving		<i>Ok</i>	
Nose Bullet		<i>Removed</i>	
Inspector Signature		LIC/PK-nr:	GT 641 


	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

<i>SECTION</i>	INLET CASE AREA & FAN STATORS
----------------	-------------------------------

No obvious defects noted.

Suggested action.

None.



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

SECTION	C-1 BLADES
---------	------------

No obvious defects noted.

Suggested action.
None.



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form TMMD-10 Issue 01 Rev 00 July 2023
--	---	--

SECTION	C-6 BLADES
---------	------------

No obvious defects noted.

Suggested action.

None.




	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

SECTION	C-7 BLADES
----------------	-------------------

No obvious defects noted.

Suggested action.

None.



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

SECTION	COMBUSTION AREA
No obvious defects noted.	
Suggested action.	
None.	



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

SECTION	COMBUSTION AREA
No obvious defects noted.	
Suggested action.	
None.	



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form -MD-10
		Issue 01 Rev 00 July 2023

SECTION	T-1 VANES
---------	-----------

No obvious defects noted.

Suggested action.

None.



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form MD-10
		Issue 01 Rev 00 July 2023

SECTION	T-1 BLADES
No obvious defects noted.	
Suggested action.	
None.	



	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form -MD-10
		Issue 01 Rev 00 July 2023

SECTION	T-2 VANES
---------	-----------

No obvious defects noted.

Suggested action.

None.




	BORESCOP INSPECTION PROTOCOL - Engine Borescope inspection	Form ...-MD-10
		Issue 01 Rev 00 July 2023

SECTION	T-2 BLADES
---------	------------

No obvious defects noted.

Suggested action.

None.



SECTION	T-4 BLADES
No obvious defects noted.	
Suggested action. None.	



SECTION	EXHAUST CASES
No obvious defects noted.	
Suggested action. None.	



The contents of this report are based on attentive inspection and review. It is exclusive of any damage not detectable without removal and disassemble of the unit. The engines inspected were prepared for borescope by the facility named above under job site and returned to original condition by the same facility. Maintenance Manual pages attached to this report if any are uncontrolled and are for general reference only. Verify limits with current MM effective for this engine and or aircraft.

Position Technician

Signature  Date 21.09.23