

Service Report



Report Header Information

Work Order	110040220	Dealer Code	J261	Manufacturer	Caterpillar Inc.
Employee ID	9954	Service Date	7/4/2017	Model	3516
Customer		Customer Equipment Number		Customer PO	
Serial Number	SSP00115				
SMU	1 Hours	Equipment Location	PORT KLANG FREE ZONE (PKFZ)		
IN Date		Promise Date		OUT Date	
Instructions	TO CARRY OUT GENSET VISUAL INSPECTION & DOWNLOAD ECM HISTORY DATA				

Repair Background

Segment No:	01:
Customer Complaint	Request Tractors Malaysia to verify Gensets new/unused.
Cause of Failure	None.
Resultant Damage	None.
Repair Process Comments	<p>SCOPE OF WORKS:</p> <p>1) TO CARRY OUT TA1 VISUAL INSPECTION TO ASSESS ENGINE CONDITION</p> <p>2) CONFIRM ENGINE SERIAL NUMBER & SMU</p> <p>3) HOOK UP TO ET LAPTOP AND DOWNLOAD STATUS REPORT</p> <p>4) TO OPEN UP ENGINE SIDE COVER AND INSPECT INTERNAL COMPONENTS</p> <p>.</p> <p>ENGINE WILL NOT BE START UP AND ANY DEFECTS OR FAULTS UPON STARTING UP WILL NOT BE CONFIRMED DURING THIS EXERCISE</p>

Customer Signature	Technician Signature
--------------------	----------------------


File Attachments

Name	Size	Modified	Title	Description
SAM_3582.JPG	2207716	7/4/2017 2:47 PM	ENGINE S/N PLATE	
SAM_3599.JPG	2199688	7/4/2017 2:51 PM	GENERATOR S/N PLATE	
SAM_3583.JPG	2266027	7/4/2017 2:48 PM		
SAM_3584.JPG	2252448	7/4/2017 2:48 PM		
SAM_3588.JPG	2247644	7/4/2017 2:49 PM		
SAM_3590.JPG	2301181	7/4/2017 2:49 PM		
SAM_3593.JPG	2204842	7/4/2017 2:50 PM		
SAM_3668.JPG	2198779	7/4/2017 3:32 PM	FROM SIDE COVER	
SAM_3669.JPG	2210945	7/4/2017 3:32 PM	FROM SIDE COVER	
SAM_3670.JPG	2182704	7/4/2017 3:32 PM	FROM SIDE COVER	

Title: ENGINE S/N PLATE

7/4/2017 2:47 PM

Description:



Title: GENERATOR S/N PLATE

7/4/2017 2:51 PM

Description:



Title:
7/4/2017 2:48 PM
Description:



Title:
7/4/2017 2:48 PM
Description:



Title:
7/4/2017 2:49 PM
Description:



Title:
7/4/2017 2:49 PM
Description:




Title:
7/4/2017 2:50 PM
Description:



Title: FROM SIDE COVER

7/4/2017 3:32 PM


Description:



Title: FROM SIDE COVER

7/4/2017 3:32 PM

Description:



Title: FROM SIDE COVER

7/4/2017 3:32 PM

Description:

