

Total Time:	11909.5
Total Cycles/Landings:	9431
Engine 1:	11806.9
Engine 2:	11632.1
Date:	4/13/2020

Inspection	Complied With:	Next Due:	Hours/Time Remaining:
Inspection B1-B12	11374.9	12175.9	266.4
Inspection C1-C12	10536.5	12136.5	227
Inspection D1-D12	10536.5	13736.5	1827
Inspection E1-E12	28-Nov-18	18-Nov-19	-147
Inspection F1-F12	28-Nov-18	28-Nov-20	229
Inspection G	28-Nov-18	28-Nov-22	959
Inspection 400 Hour Detailed Walk-Around	11601.7	12001.7	92.2
No. 1 Engine - MPI	11369.1	13469.1	1662.2
No. 2 Engine - MPI	11632.1	13732.1	2100
No. 1 Engine - CZI	11632.1	15569.1	3762.2
No. 2 Engine - CZI	11632.1	15824.3	4192.2
96 Month X-Ray Center Fuselage	28-Aug-13	28-Aug-21	502
96 Month Wing Links	28-Nov-18	28-Nov-26	2420
96 Month Detail Inspect Ventral	28-Nov-18	28-Nov-26	2420
96 Month X-Ray Horizontal	28-Aug-13	28-Aug-21	502
96 Month Wing Internal	23-Sep-14	23-Sep-22	893
48 Month Wing Leading Edges	28-Nov-18	28-Nov-22	959
Landing Gear	7943	12943	3512
Landing Gear	23-Jul-11	23-Jul-23	