



DET NORSKE VERITAS

**SURVEY REPORT, 3<sup>rd</sup> Part.**

**Object:** One (1) Desalination unit  
9000010447

**Type:** MT 50T SRH

**Manufacturer:** ENWA AB, Hisings Backa, Sweden

**Man. Order no.:** 50572

**Id. no:** 9000010447

**Purchaser:** Enwa Norge AS

**Purch. Order no.:** 50572

At the request of Messrs. ENWA AB, the undersigned surveyor attended their workshop on the 2<sup>nd</sup> of December, 2013, in order to witness FAT test of a.m. unit.

The unit was running for approximately 10 minuts.

No leakes or defects could be seen at a test pressure of 70 BAR

Following equipment was not tested during the FAT:

- Sandfilter and back flushing equipment.
- Dosing units.
- Mineral Filter N-40

For identification, the unit was marked: NV GOT 130014.

Gothenburg, Sweden

.....  
Ulf Winnes  
Senior Surveyor





DET NORSKE VERITAS

**SURVEY REPORT, 3<sup>rd</sup> Part.**

**Object:** One (1) Desalination unit  
9000010448

**Type:** MT 50T SRH

**Manufacturer:** ENWA AB, Hisings Backa, Sweden

**Man. Order no.:** 50572

**Id. no:** 9000010448

**Purchaser:** Enwa Norge AS

**Purch. Order no.:** 50572

At the request of Messrs. ENWA AB, the undersigned surveyor attended their workshop on the 2<sup>nd</sup> of December, 2013, in order to witness FAT test of a.m. unit.

The unit was running for approximately 10 minutes.

No leaks or defects could be seen at a test pressure of 70 BAR

Following equipment was not tested during the FAT:


- Sandfilter and back flushing equipment.
- Dosing units.
- Mineral Filter N-40

For identification, the unit was marked: NV GOT 130015.

Gothenburg, Sweden

.....  
Ulf Winnes  
Senior Surveyor





DET NORSKE VERITAS

**SURVEY REPORT, 3<sup>rd</sup> Part.**

**Object:** One (1) Desalination unit  
9000010449

**Type:** MT 50T SRH

**Manufacturer:** ENWA AB, Hisings Backa, Sweden

**Man. Order no.:** 50572

**Id. no:** 9000010449

**Purchaser:** Enwa Norge AS

**Purch. Order no.:** 50572

At the request of Messrs. ENWA AB, the undersigned surveyor attended their workshop on the 2<sup>nd</sup> of December, 2013, in order to witness FAT test of a.m. unit.

The unit was running for approximately 10 minuts.

No leakes or defects could be seen at a test pressure of 70 BAR

Following equipment was not tested during the FAT:

- Sandfilter and back flushing equipment.
- Dosing units.
- Mineral Filter N-40

For identification, the unit was marked: NV GOT 130016.

Gothenburg, Sweden

.....  
Ulf Winnes  
Senior Surveyor

