

# **Relatório de Boroscopia Industrial**

---

**Turbina TG02 - 18/02/2025**


---

## **Relatório de Boroscopia Industrial**

---

# Turbina TG 02 - 18/02/2025

## CÂMARA DE COMBUSTÃO




## ENTRADA DE AR



## PIRÔMETRO



## S1



**Turbina TG 02 - 18/02/2025**

S2



S3



A close-up photograph of a white surface, likely a wall or ceiling, showing significant water damage. The surface is covered in a mottled, brownish stain, particularly concentrated in the center and along the edges. There are also some darker, more localized spots and areas of discoloration. The overall texture appears slightly rough and uneven due to the damage.



S4

